

ASS. REC BY

REF CS/MSG17023645/Gvel3n2

Submitted by

GQ

ASSIGNMENT (Office)

Merimen

From (Person)

Catherine Thia

MSG

Date/Time 13/12/17 @ 10:17am

Estimated Cost

Bill to

OD / TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLN1735R

Insured

SJD565Y

at Workshop m/s

S Three Automotive

Tel

62841542

of Blk 8 Sin Ming Ind. Est, #01-64/66

Policy No. B29040710TMC

Claim No. 540454

Sum Insured

Excess

Make of Veh:

D.O.A. 10/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsed

Date/Time 11:17am @ 13/12/17

Person Contacted

Yen jen / Joey

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLN1735R - NBA/MSG17023419/Y

D.O.A: 10/12/2017

SJD565Y - NBA/MSG17023419/Y

D.O.A: 10/12/2017

15/12/17

Send preli revised by merimen

9/14/18

@ 9pm Joey said they submit LS \$4800

REF: MSIG

ASSIGNMENT

From: Date: 13/12/17

Estimated Cost:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: SLN1735R
at Workshop m/s S Three Automotive
of BIK & Sin Ming Ind. Es / #01-64

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR. Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'wps

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLN1735R Yr Regn: 25 Apr 2017

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: chevrolet cruze cc: 1598

Colour: silver A/C Insured / Std / NI / NA

Sp Reading: 7828 T.Radio: Insured / Std / NI / NA

Eng/No:

C/No: KL1JA69E96K351376

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: 205/60R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

R/Bal: 8 mm R/Bal: 8 mm

L/Bal: 8 mm L/Bal: 8 mm

D.O.A. D.O.I. 13-12-17

Survey held at: w/s 5:30pm

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/4 finalised \$2650 with Joy (Red 8683.80, 77%)

RECEIVED: 8 APR 2018

18/4 check with vern. date of accident is 10/12/2017

Date/Time: File Pass to?

☐ : Preli. Report☐ : Final Report

Date/Time: File Return to?

18/4 - typist

Report Format:

Lump Sum / I.B.I. (\$) 2650/2

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Weekend (\$)

Survey Fee:

Transportation

Phone

Other

Total

300

10

310

Survey Department Check List (Case Handler)

Reference No.: CS/MSG17023645/1v d3

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

18/4/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17023645/Gvd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 13-12-2017	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJD 565Y	Veh. Inspected	SLN 1735R	
Policy No.	B29040710TMC	Coverage (\$)	0.00	
Claim No.	540454	Excess (\$)	0.00	
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	13/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/12/2017	Inspection Date	13/12/2017	
Survey held at	S THREE AUTOMOTIVE & RECOVERY PTE LTD BLK 8 SIN MING IND EST #01-64/66 SINGAPORE 575643			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Catherine Thia Shi Yi	Date: 15 Dec 2017

Preliminary Advice

Insured Vehicle No	: SJD565Y	Accident Date	: 10/12/2017
TP Vehicle No	: SLN1735R	Assignment Date	: 13/12/2017
Make	: CHEVROLET CRUZE NB	Est. Duration of Repair	: 4.00
Date of Inspection	: 13/12/2017		
Inspection At	: S THREE AUTOMOTIVE RECOVERY PTE LTD (HQ) BLK 8 SIN MING INDUSTRIAL ESTATE, #01-64/66 SECTOR C SINGAPORE 575643		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,333.80
Revised Amount	:S\$	2,734.90
Check Items (Estimated)	:S\$	4,181.20
Total	:S\$	6,916.10
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2017		13 Dec 2017 10:17 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	SIME DARBY SERVICES PTE LTD , Co. Reg. No.: 197501065W		
Main Claimant:	NATIONAL CAR RENTAL PTE LTD , Co. Reg. No.: 196100157E		
Vehicle Reg. No.:	SLN1735R	Date of Loss:	10/12/2017 14:00 - :59
Claim Type:	TP / 540454	Policy/Cover Note No.:	B29040710TMC (Third Party Only) Coverage: 01/10/2017 - 30/09/2018
Vehicle Reg. No. (Insured):	SJD565Y	Policy No. (Claimant):	
		Excess:	
Repairer:	S Three Automotive Recovery Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate, #01-64/66 Sector C, 575643 Sin Ming - Tel: 62841542 / 62841575		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/12/2017]		
Driver/Custodian (Insured):	HUI JOON THOE(XU JUNTAO) (), NRIC: S7402784I, Tel: +6598243828		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Veron Chen (LKKAUTO)

From: Chhia Nyuk Pui <NyukPui_Chhia@sg.msig-asia.com>
Sent: Monday, 9 April 2018 3:02 PM
To: Serene Chui Yoke Har
Cc: chris; Admin-D (LKKAUTO); Veron Chen (LKKAUTO)
Subject: RE: Your ref: M540454; Our ref:CS/1212/17/S3 MC/MC Suit No. 5212/2018

Dear Serene

**WITHOUT PREJUDICE
SAVE AS TO COSTS**

MC/MC Suit No. 5212/2018

Thanks for your email.

We shall make offer soon.

Best Regards,

Chhia Nyuk Pui
Senior Executive, Claims Services
Direct line +65 6594 2521 | Direct fax +65 6643 1349 | nyukpui_chhia@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on @MSIG_SG

A member of **MS&AD** INSURANCE GROUP

From: Serene Chui Yoke Har [mailto:serene@libertylaw.com.sg]
Sent: Monday, April 09, 2018 2:41 PM
To: Chhia Nyuk Pui <NyukPui_Chhia@sg.msig-asia.com>
Cc: chris <chris@libertylaw.com.sg>
Subject: Your ref: M540454; Our ref:CS/1212/17/S3 MC/MC Suit No. 5212/2018

**WITHOUT PREJUDICE
SAVE AS TO COSTS**

MC/MC Suit No. 5212/2018

We refer to your email and our telephone conversation of today.

I am forwarding you my emails below addressed to Ms Catherine Thia on 19 March 2018 and 3 April 2018 for your easy reference.

Kindly let us hear from you **by 11 April 2018**

Thank you & Kind Regards,

Serene

DID: 3152 0980

LIBERTY LAW PRACTICE LLP

10 Hoe Chiang Road, #13-03A Keppel Towers, Singapore 089315

Tel : (65) 6223 6787 | Fax : (65) 6223 7262

web: www.libertylaw.com.sg

Privileged and/or confidential information may be contained in this email or its attachments. If you are not the intended recipient, you must not disclose, copy or distribute the contents therein or take any action in reliance of such contents. Communication of any information in this email or its attachments to an unauthorized person is prohibited.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 9 April 2018 2:44 PM
To: 'Chhia Nyuk Pui'
Cc: Admin-D (LKKAUTO)
Subject: RE: Your ref: CS/1212/17/S3. Our ref: 540454 (OIV: SJD565Y)

Dear Nyuk Pui,

Content noted.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chhia Nyuk Pui [mailto:NyukPui_Chhia@sg.msig-asia.com]
Sent: Monday, 9 April 2018 2:12 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Subject: FW: Your ref: CS/1212/17/S3. Our ref: 540454 (OIV: SJD565Y)

Hi Veron


Please let us have your Final Report urgently as we have received Writ of Summon.

Thanks.

Chhia Nyuk Pui
Senior Executive, Claims Services
Direct line +65 6594 2521 | Direct fax +65 6643 1349 | nyukpui_chhia@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on  [@MSIG_SG](https://www.facebook.com/MSIG_SG)

A member of **MS&AD** INSURANCE GROUP

From: Chhia Nyuk Pui
Sent: Monday, April 09, 2018 2:10 PM
To: 'chris@libertylaw.com.sg' <chris@libertylaw.com.sg>
Subject: Your ref: CS/1212/17/S3. Our ref: 540454 (OIV: SJD565Y)

Dear Sir/Madam

Without Prejudice
Save as to Costs

We refer to your letter dated 03.04.18.

We are reviewing the claim and kindly hold hands from proceeding further. Meanwhile, please let us have copy of 10 days' notice for our record.


Thank you.

Chhia Nyuk Pui

Senior Executive, Claims Services

Direct line +65 6594 2521 | Direct fax +65 6643 1349 | nyukpui_chhia@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on  [@MSIG_SG](https://twitter.com/MSIG_SG)

A member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	0157E
Vehicle Details	
Vehicle No.	SLN1735R
Vehicle to be Exported	No
Intended De-registration Date	14 Dec 2017
Vehicle Make	CHEVROLET
Vehicle Model	CRUZE NB 1.6D 6AT
Primary Colour	Silver
Manufacturing Year	2016
Engine No.	F16D4161890363
Chassis No.	KL1JA69E9GK351376
Maximum Power Output	86.0 kW (115 bhp)
Open Market Value	\$14,317.00
Original Registration Date	25 Apr 2017
First Registration Date	25 Apr 2017
Transfer Count	0
Actual ARF Paid	\$14,317.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	24 Apr 2027
PARF Rebate Amount	\$10,737.00
Intended COE Rebate Details	
COE Expiry Date	24 Apr 2027
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$52,000.00
COE Rebate Amount	\$48,677.00
Total Rebate Amount	\$59,414.00

The information contained herein is correct as at 14 Dec 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/12/2017 10:41
Date Of Accident	09/12/2017 14:50
Exact Location Of Accident	CARPARK EXIT GREAT WORLD CITY KIM SENG PARADE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN1735R
Insured/Policyholder	
Name Of Registered Owner	NATIONAL CAR RENTALS PTE LTD
Co Reg No	196100157E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98371901
Alternative Phone No	OFFICE-98371901

Vehicle Particulars

Manufacturer	CHEVROLET
Model	CRUZE-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	SAINT ANDREW MACDONALD
NRIC No	S2762968G
Date Of Birth	18/12/1964
Occupation	OUTDOOR
Date Of Driving Pass	14/08/2009
Driving Experience	8 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98371701
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	25A KING ALBERT PARK SINGAPORE
Postcode	598310
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJD565Y
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	HUI JOON THOE
NRIC/Passport Number	S7402784I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was exiting the car park of Great World City.
 I was stopped at the white line waiting for
 on traffic to clear so I could safely merge.
 The driver behind me proceeded to hit the
 rear of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

S THREE AUTOMOTIVE RECOVERY PTE LTD

Blk 8 Sin Ming Industrial Estate
#01-64/66 Singapore 575643
Tel : 6284 1542 / 6284 1575
Fax : 6487 5315
sthreeautomotive@gmail.com

TO :

ATT : MOTOR CLAIM DEPT.

T/P VEH. NO. : SJD565Y

ESTIMATE REPORT 1st QUOTATION

JOB NO. : _____

OWNER'S PARTICULAR

NAME : NATIONAL CAR RENTALS PTE LTD

CONTACT :

ADDRESS :

LICENSE NO. : SLN1735R TRANS.

CHASSIS NO. :

MAKE / MODEL : CHEVROLET CRUZE

ENGINE NO. :

OWNER'S INSURER : NTUC INSURANCE

JOB-CODE : TP S/A :

ACCIDENT DATE : 09-Dec-17

CLAIM DETAIL

MATERIALS	QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR DIS P	REV. PRICE
1 BOOTLID INNER LOCK X NN	1.00	\$ 248.00	X	10.00 \$ 223.20	Y	X
2 BOOTLID EMBLEM "LOGO" /	1.00	\$ 47.00	/	10.00 \$ 42.30	Y	/
3 BOOTLID EMBLEM "TURBO" /	1.00	\$ 23.00	/	10.00 \$ 20.70	Y	/
4 BOOTLID EMBLEM CRUZE /	1.00	\$ 26.00	/	10.00 \$ 23.40	Y	/
5 BOOTLID EMBLEM LS /	1.00	\$ 30.00	/	10.00 \$ 27.00	Y	/
6 BOOTLID EMBLEM "CHEROVOLT" /	1.00	\$ 48.00	/	10.00 \$ 43.20	Y	/
7 BOOTLID CATCH X NN	1.00	\$ 120.00	X	10.00 \$ 108.00	Y	X
8 BOOTLID RUBBER BEADING / TN	1.00	\$ 200.00	/	10.00 \$ 180.00	Y	/
9 REAR BUMPER / RE	1.00	\$ 937.00	/	10.00 \$ 843.30	Y	/
10 REAR BUMPER TOP PLASTIC BEAM X NN	1.00	\$ 108.00	75 X	10.00 \$ 97.20	Y	X
11 REAR BUMPER BRACKET LH /	1.00	\$ 20.00	/	10.00 \$ 18.00	Y	/
12 REAR BUMPER BRACKET RH /	1.00	\$ 20.00	/	10.00 \$ 18.00	Y	/
13 REAR BUMPER RETAINER LH /	1.00	\$ 20.00	/	10.00 \$ 18.00	Y	/
14 REAR BUMPER RETAINER RH /	1.00	\$ 20.00	/	10.00 \$ 18.00	Y	/
15 REAR BUMPER TOWING COVER X NN	1.00	\$ 95.00	X	10.00 \$ 85.50	Y	X
16 REAR BUMPER CHROME RH /	1.00	\$ 195.00	75	10.00 \$ 175.50	Y	/
17 REAR BUMPER CHROME LH /	1.00	\$ 195.00	75	10.00 \$ 175.50	Y	/
18 REAR BUMPER CHROME CENTRE /	1.00	\$ 220.00	75	10.00 \$ 198.00	Y	/

19	REAR BUMPER NO PLATE LAMP RH	X NN	1.00	\$	110.00	10.00	\$	99.00	Y	X
20	REAR BUMPER NO PLATE LAMP LH	X NN	1.00	\$	110.00	10.00	\$	99.00	Y	X
21	REAR BUMPER REINFORCEMENT	X BT	1.00	\$	643.00	10.00	\$	578.70	Y	/
22	REAR END PANEL	X Repair	1.00	\$	576.00 X	10.00	\$	518.40	Y	X
23	REAR END PANEL GARNISH	X re	1.00	\$	40.00	10.00	\$	36.00	Y	/
24	TAILLAMP LH	X { NN	1.00	\$	610.00	10.00	\$	549.00	Y	X
25	TAILLAMP RH	X { NN	1.00	\$	610.00	10.00	\$	549.00	Y	X
26	REAR BUMPER CENTRE BRACKET	X NN	1.00	\$	80.00	10.00	\$	72.00	Y	X
27	BOOTLID LAMP LH	X { NN	1.00	\$	485.00	10.00	\$	436.50	Y	X
28	BOOTLID LAMP RH	X { NN	1.00	\$	485.00	10.00	\$	436.50	Y	X
29	REVERSE SENSOR HOLDER	X { NN	4.00	\$	480.00	10.00	\$	432.00	Y	X
30	KEYLESS CONTROL UNIT	X DM	1.00	\$	481.00	10.00	\$	432.90	Y	/

TOTAL (PARTS) :

7282.00

6553.80

2251.7

SPECIAL NETT ITEM

1	REAR BUMPER CLIPS	/ rec	1.00	80.00	0.00	/ 80.00	Y	40
2	REAR END PANEL SEALANT	X { NN	1.00	80.00	0.00	80.00	Y	X
3	REVERSE CAMERA	X { NN	1.00	680.00	0.00	680.00	Y	X
4	REVERSE SENSOR -ORIGINAL	X { NN	1.00	1160.00	0.00	1160.00	Y	X

TOTAL (PARTS) :

2000.00

2000.00

40

LABOUR

1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA	1.00	1000.00	0.00	1000.00	Y	400
2	TO SPRAY PAINTING ON ACCIDENT AREA	1.00	1000.00	0.00	1000.00	Y	400-600
3	CHECK & REPAIR WIRING SYSTEM	1.00	120.00	0.00	120.00	Y	30
4	RESPRAY TUFF KOTE ON ACCIDENT AREA	1.00	180.00	0.00	180.00	Y	X NN
5	R&R CARPET & TRIM TO ASSIST REPAIR	1.00	180.00	0.00	180.00	Y	260
6	R&R BOOTLID COMPONENTS	1.00	180.00	0.00	180.00	Y	X NN
7	R&R REAR REVERSE SENSOR	1.00	120.00	0.00	120.00	Y	40

TOTAL (LABOUR) :

2780.00

2780.00

930

TOTAL PARTS & LABOUR

12062.00

11333.80

3321.7
20%: 2650

EXCESS : : S\$ _____

NO. OF DAY : 4

RE-SURVEY : BEFORE / AFTER PAINTING 0

PART-BY-PART OR LUMP-SUM : S\$ _____

DATE OF SURVEY : 13/12/17

SURVEY BY : Gue Qiang

CONTACT NO : _____

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17023645/GVD3N2

Date: 18/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B29040710TMC
Claimant Vehicle No :	SLN1735R	Insured Vehicle No :	SJD565Y
Date of Loss:	10/12/2017	Nature of Claim:	TP
		Claim No:	540454

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN1735R	Engine No:	F16D4161890363
Make & Model:	CHEVROLET CRUZE NB, 1.4 D 6 (A)	Chassis No:	KL1JA69E9GK351376
Reg. Date:	25/04/2017 (Man. Year: 2016)	Odometer:	7828 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,553.80	2,391.70	6,162.10	72.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,780.00	930.00	1,850.00	66.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,333.80	3,321.70	8,012.10	70.69
Approved Total (Overridden) (S\$)		2,650.00		
(S\$)	11,333.80	2,650.00	8,683.80	76.62
+ GST 7.00/7.00% (S\$)	793.37	185.50	607.87	76.62
Nett Amount (S\$)	12,127.17	2,835.50	9,291.67	76.62

INSPECTION

Date of Assignment: 13/12/2017

Date Inspected: 13/12/2017 Inspected At:

S Three Automotive Recovery Pte Ltd (HQ)

Blk 8 Sin Ming Industrial Estate, #01-

64/66 Sector C

Singapore 575643

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2018)
Parts: 143	CHEVROLET CRUZE NB 1.4 D 6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLN1735R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID INNER LOCK	Not Necessary	248.00 FL	*- FL
2	1		*BOOTLID EMBLEM LOGO	Necessary	47.00 FL	*47.00 FL
3	1		*BOOTLID EMBLEM TURBO	Necessary	23.00 FL	*23.00 FL
4	1		*BOOTLID EMBLEM CRUZE	Necessary	26.00 FL	*26.00 FL
5	1		*BOOTLID EMBLEM LS	Necessary	30.00 FL	*30.00 FL
6	1		*BOOTLID EMBLEM CHEVROLET	Necessary	48.00 FL	*48.00 FL
7	1		*BOOTLID CATCH	Not Necessary	120.00 FL	*- FL
8	1		*BOOTLID RUBBER BEADING	Torn	200.00 FL	*189.00 FL
9	1		*REAR BUMPER	Deformed	937.00 FL	*937.00 FL
10	1		*REAR BUMPER TOP PLASTIC BEAM	Not Necessary	108.00 FL	*- FL
11	1		*REAR BUMPER BRACKET LH	Cracked	20.00 FL	*20.00 FL
12	1		*REAR BUMPER BRACKET RH	Cracked	20.00 FL	*20.00 FL
13	1		*REAR BUMPER RETAINER LH	Necessary	20.00 FL	*20.00 FL
14	1		*REAR BUMPER RETAINER RH	Necessary	20.00 FL	*20.00 FL
15	1		*REAR BUMPER TOWING COVER	Not Necessary	95.00 FL	*- FL
16	1		*REAR BUMPER CHROME RH	Necessary	195.00 FL	*75.00 FL
17	1		*REAR BUMPER CHROME LH	Necessary	195.00 FL	*75.00 FL
18	1		*REAR BUMPER CHROME CENTRE	Necessary	220.00 FL	*75.00 FL
19	1		*REAR BUMPER NO PLATE LAMP RH	Not Necessary	110.00 FL	*- FL
20	1		*REAR BUMPER NO PLATE LAMP LH	Not Necessary	110.00 FL	*- FL
21	1		*REAR BUMPER REINFORCEMENT	Bent	643.00 FL	*643.00 FL
22	1		*REAR END PANEL	Repair	576.00 FL	*- FL
23	1		*REAR END PANEL GARNISH	Deformed	40.00 FL	*40.00 FL
24	1		*TAILLAMP LH	Not Necessary	610.00 FL	*- FL
25	1		*TAILLAMP RH	Not Necessary	610.00 FL	*- FL
26	1		*REAR BUMPER CENTRE BRACKET	Not Necessary	80.00 FL	*- FL
27	1		*BOOTLID LAMP LH	Not Necessary	485.00 FL	*- FL
28	1		*BOOTLID LAMP RH	Not Necessary	485.00 FL	*- FL
29	4		*REVERSE SENSOR HOLDER	Not Necessary	480.00 FL	*- FL
30	1		*KEYLESS CONTROL UNIT	Damaged	481.00 FL	*325.00 FL
31	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*40.00 FS
32	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
33	1		*REVERSE CAMERA	Not Necessary	680.00 FS	*- FS
34	1		*REVERSE SENSOR-ORIGINAL	Not Necessary	1,160.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,282.00	2,653.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	728.20	261.30
Total Parts (\$\$)	8,553.80	2,391.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN & PANEL BEAT ACCIDENT AREA	New	1,000.00	400.00
2	TO SPRAY PAINTING ON ACCIDENT AREA	New	1,000.00	400.00
3	CHECK & REPAIR WIRING SYSTEM	New	120.00	30.00
4	RESPRAY TUFF KOTE ON ACCIDENT AREA	New	180.00	-
5	R&R CARPET & TRIM TO ASSIST REPAIR	New	180.00	60.00
6	R&R BOOTLID COMPONENTS	New	180.00	-
7	R&R REAR REVERSE SENSOR	New	120.00	40.00
Gross Labour Cost (S\$)			2,780.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >