



Your Ref: AEMD/105/009/2017/141

Date: 15th December 2017

Our Ref: CS1/SPF17023646/K1vbs2

M/s Automotive Engineering & MGT Division

Accident Claim Section
(Singapore Police Force)
1 Mount Pleasant Road
Blk 8 Old Police Academy
Singapore 298333

Attn: Abdul Rahman

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SHD 8578G
INSURED VEHICLE: QX 1153G
ACCIDENT DATE: 07/09/2017

We thank you for your instruction on 13/12/2017.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHD 8578G from M/s Vicom Ltd.
- b) Singapore Accident Statement of Vehicles SHD 8578G.
- c) Colour damaged vehicle photographs of SHD 8578G.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SHD 8578G
Make & Model	: Hyundai I40
Year of Registration	: 2016
Chassis Number	: KMHLB41UMGU093762
Engine Capacity	: 1685cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.