

INS. CASE OWNER:

CC 4 / LPC170

23667

M/K 3 m2

LKK:
IDAC:

Surveyor:

MA CF

DOI:

12-12-17

Date / Time:

12-12-17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

STJ 7667 G

Name of Insured:

Md. Faizal Bin Muhammad

Insured Tel No.:

HP:

81834905

Excess Sec II :SS

D.O.A.:

5/12/2017

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

17/17117/VPOS/020255

Policy No.:

Z17VP 050137-19

Make / Model:

my Lancer - 1.5 (A)

Place of Accident:

steven Rd before Robin close
→ Scotts Rd

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Lam Chew



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

14/12

2018

02/02/2018:

28/8/18

10/10/18

11/10/18

05/07/19

06/07/19

STJ 7667 G - X

OI is making claim against TP.

Lane 1 - straight lane / Lane 2-3 - merging lane.

FILES REVIEWED. LANC of accident on merging lane.

TP changed lane. Lane 1 - straight lane, Lane 2-3

merging lane. Based on both accident reports and

sketch plan, accident occurred on the middle lane.

Negotiate 50/50 settlement.

File pass to typist type report

Email to LPC to seek mandate

30/7/18

Email from LPC approve mandate

5 x 180

- group for offer to TP.

- TP accepted offer.

- all docs in OK state.

- to close.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

02/02/2018

After call ltr to OI:

Documentation Check List:

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

13/12

Sent By:

Hui

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

151

SS

2,820.34

3 days)

Reduction:

34

%

Email

Call

FINAL SETTLEMENT

Date/Time:

05/07/19

Confirm with:

Hui

Email

Call

Final Liability:

%

50

(Assessed)

BOLA S/N No.:

-

-

-

If NO or B 28, Ass. Lia:

Repair Cost:

\$3,017.76

SS

1,508.88

Loss of Rental (LOR):

1900

SS

450.00

(5 days)

X

\$180.00

Loss of Use (LOU):

-

SS

-

(5 x days)

Loss of Income (LOI):

-

SS

-

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search:

-

SS

-

Medical:

-

SS

-

Disbursement:

-

SS

-

Legal Cost:

-

SS

-

(e.g. Tow/Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$450.00

Total:

\$3,917.76

SS

1,958.88

Global Sum SS:

1,958.88

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

1,958.88

Name 1:

KUM CHOW MOTOR WORKSHOP

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

Surveyor


REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No. _____
 at Workshop mis KUM CHEN
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 2.8% % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No. SKM7672R Yr Regn: APR 2017
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: TOYOTA LEXUS 2010 c.c. 2672
 Colour: D. Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 65 960 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: JTJFA11A402451497

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 235/60/18
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front _____ Rear _____
 R/Bal. 8 mm R/Bal. 8 mm
 L/Bal. 8 mm L/Bal. 8 mm
 D.O.A. 5/12/2017 D.O.I. 12/12/2017

Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/11/18 Confirm 2.8% \$2820.34 with 3 working days

180 - \$11643 &
29.1)

Date/Time: File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time: File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ Site Insp (\$ _____)

☐ Interview (\$ _____)

☐ Tech. Invs (\$ _____)

☐ Weekend (\$ _____)

☐ 3 + RS \$ _____

☐ Photos

☐ Other

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC17023667/M1ka3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 13-12-2017		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJT 7667G	Veh. Inspected	SKM 7672R
	Policy No.	Z17VP050137-19	Coverage (\$)	0.00
	Claim No.	17/17/17/VP05/020255	Excess (\$)	0.00
	Assign From		Assign Date	13/12/2017
2. Vehicle Particulars & Condition				
	Make & Model	c.c 0		
	Engine No.	HIDDEN		
	Chassis No.	Year of Reg.		
	Odometer	Colour		
	Brakes	Steering		
	General	Modification		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	05/12/2017	Inspection Date	13/12/2017
	Survey held at	KUM CHEW MOTOR WORKSHOP 160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08

SIN MING AUTOCITY, SINGAPORE 575722.

Tel No. : 64536256/64563715 Fax No. : 64557754

E-Mail : kumchew1@singnet.com.sg

GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

LONPAC INSURANCE BHD

100, BEACH ROAD #19-00 SHAW TOWER
SINGAPORE 189702

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62963767

Estimate : ES004248

Date : 12/12/2017

Vehicle Num. : SKM 7672 R

Make/Model : LEXUS RX270

Chassis/Eng# :

Accident Date : 05/12/2017

Claim No. :

Reference : KC/TP7672/1712-02

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | |
|----|-------|----------------------------------|
| 1. | 1 PC | LIST ITEMS : |
| 2. | 2 PCS | REAR BUMPER |
| 3. | 1 PC | REAR BUMPER RETAINER |
| 4. | 1 PC | REAR BUMPER REFLECTOR - RH |
| 5. | 1 PC | REAR BUMPER REINFORCEMENT |
| 6. | 1 PC | REAR BUMPER LOWER GARNISH - R/H |
| 6. | 1 PC | REAR BUMPER REVERSE SENSOR - R/H |

List TotalS\$:

10.00% Discount S\$:

LABOUR :

TO PULL, KNOCK ON ACCIDENT PORTION & CHANGE ABOVE PART.

TO SPRAY & PAINT ON ACCIDENT PORTION.

TO ANTI-RUST REAR AFFECTED AREAS:

TO CHECK WIRING FUNCTIONS.

TO DISMANTLE & FIX REVERSE SENSOR.

Labour Total S\$:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Is subject to final approval from Insurance Company

Acknowledged by Repairer

Date:

chk pm
106.72
853.93
213.44
494.30
496.18
519.88
421.96

2,999.69

299.97

2,699.72

250 350.00

500 680.00

X120.00

30 85.00

40 50.00

1,285.00

SingDollars : Three Thousand Nine Hundred Eighty-Four & Cents Seventy-Two Only

Total S\$: 3,984.72

4,295.84

KUM CHEW MOTOR WORKSHOP

Xlat Author
PIP Regan
Before paint photo
LKK Auto Mkt.
13/12/2017
3w/ days

ZAINI

KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08
 SIN MING AUTOCITY, SINGAPORE 575722.
 Tel No. : 64536256/64563715 Fax No. : 64557754
 E-Mail : kumchew1@singnet.com.sg
 GST Reg.No. : M90367665T Buss. Reg. No. : 52865130K

LONPAC INSURANCE BHD
 100, BEACH ROAD #19-00 SHAW TOWER
 SINGAPORE 189702

Attention : Motor Claim Department
 Contact : 62507388 Fax No. : 62963767

Supplementary Estimate : ES004249

Date : 13/12/2017
 Vehicle Num. : SKM 7672 R
 Make/Model : LEXUS RX270
 Chassis/Eng# :
 Accident Date : 05/12/2017
 Claim No. :
 Reference : KC/TP7672/1712-02
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1 PC	LIST ITEMS :		
2.	1 PC	REAR BUMPER SPONGE		
		REAR FENDER INNER GARNISH - RH		
		List Total S\$:		345.69
		10.00% Discount S\$:		34.57
				311.12

P/P \$ 2820.34

3w/ days

FAXED

15/12/2017

SingDollars : Three Hundred Eleven & Cents Twelve Only

Total S\$: 311.12

KUM CHEW MOTOR WORKSHOP

To: Mr Ma

From: Kum Chew

Thank you

11/2/17 14/2/17

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 12 December, 2017 9:36 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: PRE-REPAIR SURVEY OF SKM7672R
Attachments: 12122017092702.pdf

9.51am @ 12/12/17

Our Ref : 17/17/17/VP05/020255

Vehicle In
person @ Mdm. Lim
Arrange on 13/12/17

Dear Catherine,

We attached a copy of fax from Kum Chew Motor Workshop for your attention.

Please proceed to conduct a pre-repair survey.

For your information, our insured is claiming against the driver of SKM7672R.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Our Ref : KC/TP7672/1712-02

Your Ref :

Date : 12/12/2017

M/s. Comfortdelgro Rent-A-Car Pte Ltd
C/o. Kum Chew Motor Workshop
160, Sin Ming Drive #05-08
Sin Ming Autocity
Singapore 575722.

To : Lonpac Insurance Bhd

FAX : 62963767/62962706.

ATTENTION : MOTOR CLAIMS DEPT

Dear Sir/Madam,

ACCIDENT INVOLVING SKM 7672 R & SJT 7667 G ALONG STEVENS ROAD
AFTER BUKIT TIMAH ROAD JUNCTION ON 05/12/2017.

I am/We are the owner of vehicle no. SKM 7672 R was involved in the said accident
with your insured's vehicle no. SJT 7667 G.

As the accident was caused solely by the carelessness of your insured's driver. Therefore
I/we are holding your good selves responsible for my loss/damage.

My/Our vehicle is now presently laying at KUM CHEW MOTOR WORKSHOP at 160,
Sin Ming Drive, Sin Ming Autocity, Singapore 575722. Tel : 64536256 & Fax No.
64557754.

Kindly send your assessors to inspect my/our vehicle at the said workshop within the next
forty-eight (48) hours from the date hereby, failing which I/we shall have no alternative
but to instruct our repairers to proceed with the necessary repairs without delay and the
final repair bill will be forward to you for settlement.

I/We enclosed herewith a copy of SAS Statement for your reference. Looking forward to
your kind assistance and co-operative in this matter.

Yours faithfully,

.....
Encl.

Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 13 December, 2017 4:01 PM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: PRE-REPAIR SURVEY OF SKM7672R
Attachments: 13122017155813.pdf

Follow Up Flag: Follow up
Flag Status: Completed

Categories: HMK

Dear Mei Kwan,

We attached a copy of insured's GIA report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, 13 December, 2017 3:56 PM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; ERIC WOO JUN KIAT; ONG LI LI; Zaini (LKK Auto); Hsiao Tong (LKKAUTO); Admin A
Subject: RE: PRE-REPAIR SURVEY OF SKM7672R

WITHOUT PREJUDICE

Your ref: 17/17/17/VP05/020255
LKK ref: CC4/LPC17023667/M1ka3

Dear Sir/ Madam,

Enclosed revert of vehicle: SKM 7672R

Date of survey: 13.12.2017

Number of days: 3 days

We have not authorized repairs.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report

Kindly let us have a copy of your insured's GIA report for our necessary action.

VVL

Hsiao Tong (LKKAUTO)

From: kumchew1 <kumchew1@singnet.com.sg>
Sent: Tuesday, 22 January 2019 3:03 PM
To: Hsiao Tong (LKKAUTO)
Subject: FW: RE : ACCIDENT INVOLVING SKM 7672 R & SJT 7667 G ON 05/12/2017.

Hi Ms Hsiao Tong,

Refer to the above matter.

We understand Ms Vivian on maternity leave.

Can provide us break down if accept 50/50 liability and Comfortdelgro would like to know how many days surveyor recommended.

Please assist.

Thanks & Best Regards,
Mdm Lim

Hsiao Tong (LKKAUTO)

From: kumchew1 <kumchew1@singnet.com.sg>
Sent: Tuesday, 22 January 2019 12:39 PM
To: Vivian Lau (LKKAUTO)
Subject: RE: RE : ACCIDENT INVOLVING SKM 7672 R & SJT 7667 G ON 05/12/2017.

Hi Ms Vivian,

Sorry for late reply.

Please to inform you if agreed liability 50%, can you let us have the break down.

Our insured Comfortdlegro would like to know how many days surveyor recommended.

Your early revert is much appreciated.

Thanks & Best Regards,
Mdm Lim

-----Original Message-----

From: Vivian Lau (LKKAUTO) [mailto:vivianlau@lkkauto.com]
Sent: Thursday, October 11, 2018 11:44 AM
To: kumchew1
Cc: Admin A
Subject: RE: RE : ACCIDENT INVOLVING SKM 7672 R & SJT 7667 G ON 05/12/2017.

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING SKM 7672R & SJT 7667G ON 05/12/2017.

We refer to the above matter

We are of the opinion that this is a case of conflicting versions. There is no conclusive evidence to substantiate either's parties version. Enclosed herewith a copy of our insured's accident report for your perusal.

Strictly without admission of liability whatever, but with a view towards a resolutions of your client's claim in the above matter without resort to litigation and not jeopardizing our insured claim against the liable party, we are prepared to offer 50% to your client's claim.

For a quick and amicable settlement, our principal offer to settle global sum at S\$ 1,950.00

Kindly confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | <mailto:Vivianlau@lkkauto.com%7C> fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: kumchew1 [mailto:kumchew1@singnet.com.sg]
Sent: Tuesday, 28 August, 2018 2:52 PM
To: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>
Subject: RE : ACCIDENT INVOLVING SKM 7672 R & SJT 7667 G ON 05/12/2017.

Hi Ms Vivan,

Refer to our tele-conversation earlier.

Please find attached for you to make necessary action.

In the meantime, kindly process our client's claim at your earliest convenience.

Your early revert is much appreciated.

Thanks & Best Regards,

Mdm Lim



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC17023667/M1ha3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555		Date : 18-07-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJT 7667G	Veh. Inspected	SKM 7672R	
Policy No.	Z17VP050137-19	Coverage (\$)	0.00	
Claim No.	17/17/17/VP05/020255	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	12/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA LEXUS RX270	c.c	2672	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTJZA11A402451497	Colour	DARK BLUE	
Odometer	65960	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/60 R18	PIRELLI	8 mm	
L/H Front Tyre	235/60 R18	PIRELLI	8 mm	
R/H Rear Tyre	235/60 R18	PIRELLI	8 mm	
L/H Rear Tyre	235/60 R18	PIRELLI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/12/2017	Inspection Date	13/12/2017	
Survey held at	KUM CHEW MOTOR WORKSHOP 160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 7672R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TORN	853.93	853.93
2	REAR BUMPER RETAINER @\$106.72	O/S DISTORTED / N/S SERVICEABLE	213.44	106.72
1	REAR BUMPER REFLECTOR -RH	CRACKED	494.30	494.30
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	496.18	-
1	REAR BUMPER LOWER GARNISH -R/H	SERVICEABLE	519.88	-
1	REAR BUMPER REVERSE SENSOR R/H	SHORTED	421.96	421.96
1	REAR BUMPER SPONGE (ADDITIONAL)	TORN	149.98	149.98
1	REAR FENDER INNER GARNISH -RH (ADDITIONAL)	DISTORTED	195.71	195.71
	LESS 10% DISCOUNT		-334.54	-222.26
			3,010.84	2,000.34
LABOUR				
	TO PULL ,KNOCK ON ACCIDENT PORTION & CHARGE ABOVE PART.		350.00	250.00
	TO SPRAY & PAINT ON ACCIDENT PORTION.		680.00	500.00
	TO ANTI-RUST REAR AFFECTED AREAS.	NOT NECESSARY	120.00	-
	TO CHECK WIRING FUNCTIONS.		85.00	30.00
	TO DISMANTLE & FIX REVERSE SENSOR.		50.00	40.00
			1,285.00	820.00
GRAND TOTAL			4,295.84	2,820.34
RECOMMENDED COST OF REPAIRS				2,820.34

Report Ref No. CC4/LPC17023667/M1ha3n2

MA CHIN FOOK

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.