

12/03/2001

DNR 3 days

X

ASS: REQ BY

REF: CS3/AIG/17023670/Wd301

Special Instruction

Surveyor: Wilson

ASSIGNMENT (Office)

Mainmen

From (Person): Chin Lee Yingof AIGDate/Time 11:05am @ 13/12/17

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No:

SGT6194X

Insured:

SLR8079J

at Workshop m/s

Prestige Auto

Tel:

9021 0057

of

191 Tanjong Katong Road, 436993

Policy No:

Claim No:

CL/171224/T/PA.sg

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 12/12/17

CA / REV / REP. / REV 24 HRS

'wp)

H.O.D. Endorsement

Date/Time 11:16am @ 13/12/17

Person Contacted

EricVehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SGT6194X - XSLR8079J - XDismantle: 14/12/2017After Repair: 19/12/2017



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG17023670/Wd3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 13-12-2017



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLR 8079J	Veh. Inspected	SGT 6194X
Policy No.		Coverage (\$)	0.00
Claim No.	CL/171224/T/PA.sg	Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	13/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--


5. General Information

Accident Date	12/12/2017	Inspection Date	13/12/2017
Survey held at	PRESTIGE AUTO 191 TANJONG KATONG ROAD SINGAPORE 436993		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE SLR8079J AND SGT6194X ON 12/12/2017**

From: Chin, Lee-Ying
To: assignments, Admin A
Cc: Fong, Andy-SY
Sent: Wednesday, 13 December, 2017 11:05:58 AM
Attachments:  SLR8079J-PRI.TIF

Hi LKK,

Kindly assist to survey, vehicle is in.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

CATHERINE LIM LLC

林 ADVOCATES & SOLICITORS
梁 NOTARY PUBLIC - 公証官
玲 COMMISSIONER FOR OATHS - 宣誓官
林
00 CATHERINE C. LIM
玲 DIRECTOR
LLB (HONS) SINGAPORE - 法律系-律師
M.B.A. (BUSINESS LAW) - 商業系-碩士

20 Havelock Road #03-01
Central Square Singapore 059765
UEN No. 201310922K
GST Registration No. 201310922K
Tel: (65) 6438 5500
Fax: (65) 6438 0111
www.catherinelimllc.com
Email: info@catherinelimllc.com
CATHERINE LIM LLC is a law corporation
with limited liability

Our Ref: CL/171224/T/PA.sg
Your Ref: SLR 8079J

Date: 12 December 2017

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way
#07-16
Singapore 079120
Attn: Motor Claims Department

via fax: 6415 3727 & By Hand

Huang WeiQuan
Blk 440B Fernvale Link
#21-163
Singapore 792440

CERTIFICATE OF POSTING
(Please be informed that all supporting documents
have been forwarded to your insurer.)

Dear Sir

**RE: NOTICE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO
PRE-ACTION PROTOCOL FOR NON-INJURY MOTOR ACCIDENT CLAIMS (NIMA)**

**ACCIDENT INVOLVING SGT 6194X / SLR 8079J ON 12.12.2017 ALONG SLIP ROAD OF UPPER
SERANGOON ROAD TOWARDS HOUGANG AVE 3**

We are instructed by James S Transport Services to notify you of a road traffic accident involving our client's
vehicle No. SGT 6194X and vehicle No. SLR 8079J driven by you at the material time. A copy of the Singapore
Accident Statement and/or Police Report is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the
damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you/your
insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you/your
insurer within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please let us know your appointed surveyor.

Venue: Prestige Auto
191 Tanjong Katong Road
Singapore 436993

Contact: 9021 0057 Fax: 6842 3217

Yours faithfully



Enc
cc: clients

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

--

--

Case Handler

Date

*C: Critical *N: Non-Critical

(01)Bent (02)Dented (03)Distorted (04)Cracked (05)Cut (06)Scratched
(07)Deformed (08)Shrunk (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Replace (✓) (2)Repair (3)Check (4)Not Consistent (X)

Rear Portion

Vehicle No: **SGT 6194 X**

NAC	INC	Item	CON	ACQ	QTY
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	WP	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	SHO	✓	
1159	993327	Rear End Panel	R		
1160	993339	Rear End Panel Top Garnish	DD	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CRA	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CRA	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	R		
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding	Welding	✓	
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	BT	✓	
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	ACQ	QTY
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993491	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1135	990247	Sacker			

29/1/2018

No of Items: _____

Assessor: _____

4 Days Repair

* D.O.A → 12/12/2017

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 0064B

Vehicle Details

Vehicle No.: SGT6194X

Vehicle to be Exported: Yes

Intended De-registration Date: 29 Jan 2018

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.6 AUTO

Primary Colour: Silver

Manufacturing Year: 2006

Engine No.: 3ZZ4634063

Chassis No.: MR053ZEC107142380

Maximum Power Output: 81.0 kW (108 bhp)

Open Market Value: \$15,355.00

Original Registration Date: 18 Apr 2007

First Registration Date: 18 Apr 2007

Transfer Count: 1

Actual ARF Paid: \$16,891.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 17 Apr 2022

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$25,115.00

COE Rebate Amount: \$21,193.00

Total Rebate Amount: \$21,193.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 29 Jan 2018

OK

* M.V → \$33,605

** Net Value → \$12,412

A-Assurance
Assurance in Insurance

Car Insurance Expiring?
We get you the cheapest insurance renewal
Click to get quote




Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Only \$106K! Guaranteed 4/2008 Tivoli 1.6A. Price Nego



Only \$106K! Guaranteed 4/2008 Tivoli 1.6A.
Price Nego. Direct Owner. No Accidents.
Call 9778 1234



Browse by Category ▾

◀ Back (1 2) Next ▶








Sort by Date Posted ▾

20 results/page ▾

37 vehicles

toyota altis

A car for sale

Image	Model	Price	Depreciation	Registered	Eng Cap	Mileage	Veh Type	Remarks
Search Selection	toyota altis	Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Toyota Corolla Altis 1.6A (COE till 09/2022)	\$35,800	\$7,750 /yr	12-Sep-2007	1,598 cc	158,000 km	Sedan	Available
One Year Warranty! With Official Warranty Certificate For Peace Of Mind, Our Company Renew Coe Cars For Sale Base On Car Conditions Not On Ownership, Fully Refurbished, New Paintwork, Accident Free, W...								
Carway								
Posted: 29-Jan-2018 Tags: 2007 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota								
	Toyota Corolla Altis 1.6A (COE till 09/2022)	\$56,800	\$5,910 /yr	07-Sep-2007	1,598 cc	-	Sedan	Available
Most Popular Mid Size Family Sedan. Flexible In House Loan Packages Available, Low Maintenance Cost, Low Fuel Consumption, Consignment Car, Call Us Now For Viewing Appointment.								
Car Search								
Posted: 28-Jan-2018 Tags: 2007 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota								
	Toyota Corolla Altis 1.6A (COE till 04/2022)	\$32,800	\$7,740 /yr	26-Apr-2007	1,598 cc	143,000 km	Sedan	Available
Good Condition. Well Maintenance. Smooth Engine. Just Replacement Of Front And Real Car Break Pad And Battery On Dec 2017. Car Serviced In Dec 2017. Free 6 Pieces Engine Air Intake Filter. Free 3 Pcs ...								
Posted: 28-Jan-2018 Tags: 2007 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota								
	Toyota Corolla Altis 1.6A (COE till 06/2026)	\$47,800	\$5,680 /yr	17-Oct-2006	1,598 cc	150,000 km	Sedan	Available
Lowest Depreciation! Toyota Corolla Altis 1.6 Auto! Beautiful Elegant Maroon Red Colour. Comfortable, Reliable Ride, Fuel Saving, Low Cheap Maintenance. Loan/Trade In Welcome. Call Us Now!								
Posted: 28-Jan-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota								
Car Buying	Car Selling	Car Aftermarket						
Car Ownership	On The Move	Lifestyle						
	Toyota Corolla Altis 1.6A (COE till 06/2021)	\$23,800	\$6,960 /yr	28-Aug-2006	1,598 cc	122,000 km	Sedan	Available
(COE Cars Specialist). 1 Owner Only. Genuine Low Mileage. 10%-20% Driveaway. Bank Loan /In House Loan Available. Excellent Condition. Clean And Neat Interior. No Repairs Needed. Please Call For Viewin...								
Posted: 27-Jan-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota								
	Toyota Corolla Altis 1.6A (COE till 06/2021)	\$23,899	\$7,020 /yr	26-Jun-2006	1,598 cc	128,000 km	Sedan	Available
\$3000 Down Payment, Low Mileage, Popular Choice For Daily Use! Excellent Fuel Efficiency With Ample Space For Passengers And Boot Storage. Well Maintained By Previous Owner. Clean And Neat Interior! B...								
Posted: 27-Jan-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota								
	Toyota Corolla Altis 1.6A (COE till 04/2020)	\$18,800	\$8,350 /yr	14-May-2005	1,598 cc	143,000 km	Sedan	Available
aintain, Immaculate Condition, Fuel Efficient And Reliable, In House Loan And Bank Loan Available, Trade In Are Welcome, Call Or Visit Our om For Viewing.								



Motor Universe Credit Pte Ltd

Posted: 26-Jan-2018 Tags: 2005 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 06/2022) **\$39,800** **\$9,070 /yr** **20-Jun-2007** **1,598 cc** **103,000 km** **Sedan** **Available**

100% Accident Free, New 5 Year COE, Low Mileage, Original Paint, Smooth And Quiet Engine, Tip Top Condition And Clean Interior, Flexible In House Loan Available Up To 90%, Please Call For Viewing.

CONSIDERMENT

Posted: 25-Jan-2018 Tags: 2007 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 02/2021) **\$23,800** **\$7,810 /yr** **15-Feb-2006** **1,598 cc** **147,000 km** **Sedan** **Available**

"One Year In-House Warranty!" With Official Warranty Certificate For A Peace Of Mind, Fully Refurbished, New Paintwork, Accident Free, Wear And Tear Replaced, \$485 Low Monthly Installment, 10% Down Pa...

Carway

Posted: 25-Jan-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 05/2027) **\$59,800** **\$6,400 /yr** **22-Jun-2007** **1,598 cc** **109,483 km** **Sedan** **Available**

Brand New Paintwork. Showroom Condition. Regularly Serviced. No Repair Needed. Powerful Yet Fuel Efficient And Durable Toyota VVTI Engine. Digital Aircon With Auto Climate Control. Dual Airbags. Multi...

DIRECT OWNER

Posted: 22-Jan-2018 Tags: 2007 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 01/2022) **\$31,800** **\$7,970 /yr** **25-Jan-2007** **1,598 cc** **182,036 km** **Sedan** **Available**

Beautiful Metallic Silver. Careful Owners. Only \$3,180 Down Payment. Up To 90% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivalled War...

Classic Credit Pte Ltd

Posted: 21-Jan-2018 Tags: 2007 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 09/2020) **\$19,800** **\$7,500 /yr** **19-Sep-2005** **1,598 cc** **-** **Sedan** **Available**

Well Maintained, Low Depreciation And Value For Your Money, Excellent Condition! Extended Warranty Available! Let This Reliable Yet Value For Money Sedan Give You A Comfortable And Enjoyable Ride. Buy...

Dickson Automobile

Posted: 20-Jan-2018 Tags: 2005 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 08/2021) **\$26,800** **\$7,470 /yr** **25-Sep-2006** **1,598 cc** **-** **Sedan** **Available**

Up To 90% Loan! Well Maintained By Previous Owner. Fuel Economy Yet Powerful Drive And Durability. Beautiful Condition. Call Now!

Posted: 18-Jan-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 12/2021) **\$28,500** **\$7,360 /yr** **14-Dec-2006** **1,598 cc** **-** **Sedan** **Available**

Elegant Beige, Flexible In-house Loan Packages Available, Low Maintenance Cost, Low Fuel Consumption, Very Well Maintained.

Prime Motor & Leasing

Posted: 18-Jan-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 02/2022) **\$29,838** **\$7,390 /yr** **12-Feb-2007** **1,598 cc** **-** **Sedan** **Available**

2.98% Interest Rates. Loan Up To 54 Months! Well Taken Care By Previous Owner. Original Paint With Beige Interior. 2 Years Free Servicing. Non Smoker Unit. Well Maintained Engine And Transmission In G...

Posted: 18-Jan-2018 Tags: 2007 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A Elegance (COE till 08/2022) **\$33,166** **\$7,320 /yr** **10-Aug-2007** **1,598 cc** **131,000 km** **Sedan** **Available**

Most Popular Mid Size Family Sedan With Low Mileage Done! COE Till Aug 2022 With Excellent Pristine Exterior And Very Well Kept Interior. Smooth And Quiet Engine In Tip Top Condition. Guaranteed Accid...

Posted: 17-Jan-2018 Tags: 2007 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE till 01/2022) **\$29,838** **\$7,460 /yr** **29-Jan-2007** **1,598 cc** **142,000 km** **Sedan** **Available**

Agent Unit! 1 Owner! Free 2 Years Car Service! Full Agent Service! Well Taken Care By Previous Owner. Original Paint With Beige Interior. Non Smoker Unit. Well Maintained Engine And Transmission In Go...

Posted: 17-Jan-2018 Tags: 2007 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

Toyota Corolla Altis 1.6A (COE till 03/2026) **\$53,800** **\$6,610 /yr** **22-Mar-2006** **1,598 cc** **-** **Sedan** **Available**

To \$7000 Drive Away! 1 To 1 Exchange Available! Monthly From \$594. Guaranteed Approval! All Our Cars Have Undergone A Workshop Check.



Buy With Trust And Assurance! Expect Only Honest Deals! Call...

Posted: 14-Jan-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE \$25,800 \$6,470 /yr 25-Jan-2007 1,598 cc - Sedan Available till 01/2022)

Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

Boeki Auto & Marine

Posted: 13-Jan-2018 Tags: 2007 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A (COE \$22,800 \$7,220 /yr 28-Mar-2006 1,598 cc - Sedan Available till 03/2021)

Flexible In House Loan Packages Available, Low Maintenance Cost, Low Fuel Consumption, Consignment Car, Call Us Now For Viewing Appointment.

Car Search

Posted: 12-Jan-2018 Tags: 2006 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

1/29

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Price

For old advertisements, view Expired ads

« Back (1 2) Next »

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used toyota altis, toyota altis Singapore, used toyota altis Singapore, used toyota altis, used vehicles Singapore or even buy used toyota altis Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
 - New Car
 - Used Car
 - Sell Car
 - Motoring Directory
 - Products Guide
 - Article
 - Forum
 - Tool & Tip
- About Us
 - Careers
 - Contact Us
 - Sitemap

© 2004-2018 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/12/2017 14:18
Date Of Accident	12/12/2017 08:45
Exact Location Of Accident	SLIP RD OF UPP SERANGOON RD TOWARDS HOUGANG AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGT6194X
Insured/Policyholder	
Name Of Registered Owner	JAMES S TRANSPORT SERVICES
Co Reg No	53360064B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81893030
Alternative Phone No	OFFICE-81893030

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS
Exact Purpose for which vehicle was being used at time of accident	LIMOUSINE SERVICE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company


Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5089844749
Cover Note Number	COMPREHENSIVE

Driver

Name of Driver	SOO CHIENG CHAI, JAMES
NRIC No	S1707386I
Date Of Birth	15/12/1965
Occupation	INDOOR
Date Of Driving Pass	24/04/1985
Driving Experience	32 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81893030
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was making a left turn at the slip road from Upper serangoon road towards hougang ave 3. upon reaching the give way lines, I slow down and stopped to give way to vehicles on the main road of Hougang ave 3. After stopping for a few seconds, suddenly there is an impact from my vehicle A's rear then i realized that vehicle B had hit onto my vehicle A's rear portion. No injuries reported at the scene.

Declaration

I/We declare the foregoing particulars are true in every respect.

12/12/2017 14:20
Policyholder's Signature / Date & Time

12/12/2017 14:20
Driver's Signature (If driver is not the policyholder) / Date & Time

Aaron Chuah (S991802)
Customer Care Executive
Motor Service Centre
Witnessed by Reporting Centre Personnel

Address	BLK 959 HOUGANG STREET 91 #13-288
Postcode	530959
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - SOLE PROPRIETOR
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was making a left turn at the slip road from Upper serangoon road towards hougang ave 3. upon reaching the give way lines, I slow down and stopped to give way to vehicles on the main road of Hougang ave 3. After stopping for a few seconds, suddenly there is an impact from my vehicle A's rear then i realized that vehicle B had hit onto my vehicle A's rear portion. No injuries reported at the scene.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLR8079J
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	HUANG WEI QUAN
NRIC/Passport Number	S8219950J
Contact Number	97575440
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan Pg. 1

INCOME MOTOR SERVICE CENTRE

Vehicle No: SGT6194X

Report Date & Start Time: 12/12/17 / 14:20

Report No. MT: _____

D.O.A 12/12/2017
Time: 0845 hrs
hrs

Make / Model: TOYOTA COROLLA / Reporting Type: _____ End Time: _____

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.

12/12/17 / 14:20
Policyholder's Signature / Date & Time

12/12/17 / 14:20
Driver's Signature (If driver is not the policyholder) / Date & Time

Aaron Chuah (S991802) 
Customer Care Executive
Motor Service Centre
Witnessed by Reporting Centre Personnel

Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Dec 2017 Edit Reg		13 Dec 2017 00:00 Edit Adj Rpt	\$S\$0.00 Edit Estimates	\$S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	HUANG WEI QUAN, ID: S8219950J		
Main Claimant:	JAMES S TRANSPORT SERVICES, Co. Reg. No.: 53360064B		
Vehicle Reg. No.:	SGT6194X	Date of Loss:	12/12/2017 08:00 - :59
Claim Type:	TP / 2974771477SG	Policy/Cover Note No.:	1700046224 (Comprehensive)
Vehicle Reg. No. (Insured):	SLR8079J	Policy No. (Claimant):	
		Excess:	
Repairer:	Prestige Auto () 191 Tanjong Katong Road, 436993 Katong - Tel: 90210057/62574781		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 26/01/2018]		
Claimant's Solicitor:	CATHERINE LIM LLC - Tel: 6438 5500		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (18/01/2018): Request for TP GIA Report

































ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGT6194X (2974771477SG)**
[SLR8079J]
TP
JAMES S TRANSPORT SERVICES
Dec 12 2017 8:00AM
[HUANG WEI QUAN]
Prestige Auto

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser <input type="button" value="v"/>	
Assessment Reports						1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print		
1	18/01/18 16:28	Accident Statement From:SC - Reg. No: SLR8079J, Claimant: HUANG WEIQUAN		Load HTM			
Photos/Images						3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	26/01/18 15:18	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>		
2	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
3	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
4	26/01/18 15:18	Chassis Number		Load JPG	<input checked="" type="checkbox"/>		
5	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
6	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
7	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
8	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
9	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
10	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
11	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
12	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
13	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
14	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
15	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
16	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
17	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
18	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
19	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
20	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
21	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
22	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
23	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
24	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
25	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
26	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
27	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
28	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
29	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
30	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		
31	26/01/18 15:18	General View		Load JPG	<input checked="" type="checkbox"/>		

32	26/01/18 15:18	General View	1	Load JPG	✓
33	26/01/18 15:18	General View	1	Load JPG	✓
34	26/01/18 15:18	General View	1	Load JPG	✓
35	26/01/18 15:18	General View	1	Load JPG	✓
36	26/01/18 15:18	General View	1	Load JPG	✓
37	26/01/18 15:18	General View	1	Load JPG	✓
38	26/01/18 15:18	General View	1	Load JPG	✓
39	26/01/18 15:18	General View	1	Load JPG	✓
40	26/01/18 15:18	General View	1	Load JPG	✓
41	26/01/18 15:18	General View	1	Load JPG	✓
42	26/01/18 15:18	General View	1	Load JPG	✓
43	26/01/18 15:18	General View	1	Load JPG	✓
44	26/01/18 15:18	General View	1	Load JPG	✓
45	26/01/18 15:18	General View	1	Load JPG	✓
46	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
47	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
48	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
49	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
50	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
51	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
52	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
53	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
54	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
55	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
56	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
57	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
58	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
59	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
60	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
61	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
62	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
63	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
64	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
65	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
66	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
67	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
68	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
69	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
70	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
71	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
72	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
73	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
74	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
75	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
76	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
77	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
78	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
79	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
80	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓
81	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	✓

82	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
83	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
84	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
85	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
86	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
87	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
88	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
89	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
90	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
91	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
92	26/01/18 15:21	Photographs of Damaged Parts	1	Load JPG	<input checked="" type="checkbox"/>
93	26/01/18 15:22	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
94	26/01/18 15:22	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
95	26/01/18 15:22	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
96	26/01/18 15:22	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
97	26/01/18 15:22	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
98	26/01/18 15:22	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
99	26/01/18 15:22	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
100	26/01/18 15:22	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
101	26/01/18 15:22	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
102	26/01/18 15:22	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
103	26/01/18 15:22	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
104	26/01/18 15:22	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
105	26/01/18 15:22	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
106	26/01/18 15:22	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
107	26/01/18 15:22	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
108	26/01/18 15:22	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	19/01/18 09:34	TP GIA	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17023670/WD3E2

Date: 31/01/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700046224
 Claimant Vehicle No: SGT6194X Insured Vehicle No: SLR8079J
 Date of Loss: 12/12/2017 Nature of Claim: TP Claim No: 2974771477SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGT6194X
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4634063
 Reg. Date: 18/04/2007 (Man. Year: 2006) Chassis No: MR053ZEC107142380
 Colour: Silver Odometer: 237456 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16
 Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm
 Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/12/2017
 Date Inspected: 13/12/2017 Inspected At: Prestige Auto
 191 Tanjong Katong Road
 Singapore 436993
 Estimated Period of Repair: 4.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Warped	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REVERSE SENSOR	Shorted	0.00 F	*- F
4	1		*REAR END PANEL	Repair	0.00 F	*- F
5	1		*REAR END PANEL TOP GARNISH	Dented	0.00 F	*- F
6	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
7	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
8	1		*BOOTLID	Repair	0.00 F	*- F
9	1		*BOOTLID WEATHERSTRIP	Distorted	0.00 F	*- F
10	1		*BOOTLID LOCK	Bent	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >