



# LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883  
ROB No: 532967931 . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liubro@ymail.com

Invoice/Ref No: GBC8263R171211

## Estimate

<b>Customer</b>		<b>Date:</b>	12-12-17
<b>Name:</b>	AXA Insurance Singapore Pte Ltd	<b>Vehicle No:</b>	GBC8263R
<b>Address:</b>	Motor Claims Department 8 Shenton Way #27-01 AXA Tower Singapore 068811	<b>Model/Make:</b>	Toyota Hiace Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Lh Door <i>wd</i>	\$ 1,568.80	
2	Door Rubber <i>nr</i>	\$ 245.70	X
3	Door Glass <i>deep cut</i>	\$ 508.50	
4	Door Glass Outer Moulding <i>cut</i>	\$ 172.45	
5	Door Side Mirror <i>3 no</i>	\$ 845.10	
6	Head Lamp <i>one</i>	\$ 930.70	
5	Head Lamp Clip 1 set <i>nr</i>	\$ 65.00	X
7	Bumper <i>nr/10.1</i>	\$ 726.80	
7	Bumper Clips 1 set <i>nr</i>	\$ 48.00	
8	Bumper Bracket <i>one</i>	\$ 215.60	
9	"Corporate" Advertisement Sticker <i>nr</i>	\$ 300.00	SN 2205.N
10	Door "ROC" Sticker <i>nr</i>	\$ 50.00	SN 305.N
	To check all wiring & electrical component for proper function	\$ 50.00	- 20
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 400.00	- 300
	To putty & spray painting & including touch up paint on accident affected area	\$ 400.00	- 300
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 80.00	- 30
	To remove, replace and transfer door panel, fitting and mechanisms	\$ 80.00	- 50

Total Parts & Labour of estimate for damaged vehicle \$ 6,756.65

Total amount in Part By Part / Lump Sum Basis for repaired vehicle \$ -

SDLS: \_\_\_\_\_



M/s Liu's Brother Auto Engrg Wks

P- 4426.45  
3319.83  
4269.83

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

*Not Attached*  
*nr*  
*2/5 \$ 3400 / 2*  
*3 days*  
*13/1/17*  
*Take photos After repair*