

22/03/2002

ASS. REC. BY:

REF: CS3/AIG 17023705/ sd362

VHK &amp; days

Special Instruction:

Survivor: SebastianASSIGNMENT (Office)From (Person): Chin Lee Ying

of

AIGDate/Time: 3:40pm @ 13/12/2017

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XD 32854

Insured:

GBC 6067 D

at Workshop m/s

Lim joo Kim Trading

Tel:

6367 1772

of

Blk 6 Kranji Loop # 01-27, 739542

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/12/2017

CA / REV / REP. / REV 24 HRS

(up)14/12/2017 @ after 10:30 am

H.O.D. Endorsement:

Date/Time:

5:21pm @ 13/12/17

Person Contacted:

IreneVehicle: IN ~~OUT~~

Date/Time	Action/Instruction (X) Estimate
	<u>XD 32854 - CC3 / AXA / 14011041 / King 3q2</u>
	<u>GBC 6067 D - x</u>
	<u>After repair: 21.12.2017</u>

REF

AIG

## ASSIGNMENT

Form

Date

14/12/17

Estimated Cost

OD TP WS TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No

XD 32854

at Workshop no

Lim Joo Kim Trading

Blk 6, Kranji Loop # 01-27, 739542

Insured

Policy No

Claims No

Sum Insured

Excess

(Client's Record)

Make of Veh

After 10.30am.

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Sal or Market Value

CACC Accident Report

Consistent? Yes or No

GIA PR Seen

Consistent? Yes or No

Est. Repairs

days

Res

Yes or No

Cum Sum

%

Save

Yes or No

QA / REV / REP / 24 HRS

wp

Date

Person Contacted

Vehicle IN / OUT

Date Time

Action / Instruction

14/12/17

No Estimate.

JSP No

XD 32854

JSP Ref

10/11/2008

Type M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Private/Mover /

Trailer or

Make

Hino 541 BEKA.

12713

Colour

White.

A/C Insured / Std / Nil / NA

Se Reading

745 703

T Radio Insured / Std / Nil / NA

Eng/No

C.No

J40517 BEKA XXX 16456

Gen Cond Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size

F: 295 / 80 R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli.

Front

Rear

R/Bal

6

mm

R/Bal

6

mm

L/Bal

6

mm

L/Bal

6

mm

D.O.A

11/12/2017.

D.O.A

14/12/2017. 12:14pm

Surveyed at

Lim Joo Kim.

Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt &amp; Rt o/s

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 25 JAN 2018

Date Time For Pass out



Prelim. Report

20 25012018



Final Report

Date Time For Return

Days Of Repair

7

Resurvey No. of Trips

Driver Fee

Toll / Road

Fuel / Oil

Food

Tools

Other

Add Fee:



Site Insp

\$



Interview

\$



Photograph

\$



Test

\$

Report Format

PRS.

Cum Sum M.E.F.

180

20

200



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG17023705/Sd3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 13-12-2017



Code : AIG

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBC 6067D	Veh. Inspected	XD 3285U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	13/12/2017

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--	--




### 5. General Information

Accident Date	11/12/2017	Inspection Date	
Survey held at	LIM JOO KIM TRADING CO BLK 6 #01-27 KRANJI LOOP SINGAPORE 739542		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED  
VEHICLE GBC6067D AND XD3285U ON 11/12/2017**

From: Chin, Lee-Ying  
To: assignments, Admin A  
Cc: Fong, Andy-SY  
Sent: Wednesday, 13 December, 2017 3:41:42 PM  
Attachments:  2802\_001.pdf  2895\_001.pdf  2914\_001.pdf

---

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947 | Fax +(65) 6835 7416  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths  
Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON  
WONG KENG LEONG RAYNEY  
AUDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALLI D/O MUNIANDY  
SEGA PARAM  
TIWARY ANURADHA  
SHARON PARWANI  
ONG BOCK KEE  
ANG KIM NOI DIANE  
RAVENDRA KRISHNASAMY  
ROCHE ENG KENG LOON  
TAY HAO RAN  
JANICE HAN JIA LIN

Unique Entity Number :200721148H  
✓ **HEAD OFFICE**: 133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413

Branch: 490 Toa Payoh Lorong 6  
#03-11 HDB Hub  
Singapore 310490

**HEAD OFFICE**

TEL : (65) 65342811 (Hunting)  
FAX ✓ : (65) 65356802 (General)  
: (65) 65355905 (Litigation)  
E-mail : [jactan@visionlawllc.com](mailto:jactan@visionlawllc.com)

**BRANCH**

TEL : 65 63580703  
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.Ins.L1.105262.17 (sj)  
Your Ref: GBC 6067 D

13 December 2017

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
**Attention: Motor Claims Department**

BY FAX: 6415-3727  
Email: [yokeshi.chan@aig.com](mailto:yokeshi.chan@aig.com)  
Email: [noormariesa.abukassim@aig.com](mailto:noormariesa.abukassim@aig.com)

Dear Sirs,

**ACCIDENT INVOLVING XD 3285 U & GBC 6067 D ON 11 DECEMBER 2017 ALONG PIONEER CRESCENT AT ABOUT 1530 HOURS  
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email dated 13 December 2017 informing that your wish to conduct a pre-repair survey on our client's vehicle XD 3285 U.

Please be informed that the said vehicle can be inspected at:

Lim Joo Kim Trading Co  
Block 6 Kranji Loop  
#01-27  
Singapore 739542  
Ms Irene (6367 1772)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

Anjalli M  
(Head Office)

**FOR SURVEYOR**

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :  
(Name & Signature)

Date & Time of Inspection :

cc: XD 3285 U – By fax: 6367-1773 only

**NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.**

#### CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

# VEHICLE LORRY (FRT)

## Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1004	991300	Frt Bumper	BT	✓	
2001	991477	Frt Bumper Upper			
2002	991387	Frt Bumper Lower			
2003	991449	Frt Bumper Side Cover			
2004	991443	Frt Bumper Side			
2005	991325	Frt Bumper Bracket			
2006	991433	Frt Bumper Reinforcement	BT	✓	
2005	991466	Frt Bumper Signal Lamp			
2007	995100	Frt LH Bumper Fog Lamp Cover			
2007	991355	Frt RH Bumper Fog Lamp Cover			
2007	995079	Frt LH Bumper Fog Lamp			
2007	995080	Frt RH Bumper Fog Lamp			
2007	991793	Frt Grille			
2007	991328	Frt Grille Emblem			
2006	990247	Frt Grille Sticker			
2007	991799	Frt Grille Chrome Moulding			
2007	991891	Frt Panel Lower Beam	BT	✓	
2008	991874	Frt Lower Panel			
2009	991328	Frt Panel Emblem			
2010	990247	Frt Panel Sticker			
2011	991893	Frt Panel Garnish	CRK	✓	
2011	991222	Frt Apron Panel			
2012	991527	Frt Corner Panel		R	
2013	991532	Frt Corner Panel Signal Lamp			
2014	995245	Frt Signal Lamp LH			
2015	995246	Frt Signal Lamp RH	CRK	✓	
2015	995153	Frt LH Headlamp Assy			
2015	991821	Frt RH Headlamp Assy	CRK	✓	
2015	995088	Frt LH Side Lamp			
2015	995089	Frt RH Side Lamp			
2016	992149	Frt Wiper Panel			
2017	995043	Frt Wiper Nozzle (Head lamp)	DMG	✓	
2017	992140	Frt Wiper Arm			
2017	992142	Frt Wiper Blade			
2018	992145	Frt Wiper Link			
2019	992148	Frt Wiper Motor (Head lamp)	DMG	✓	
2019	995045	Wiper Panel Garnish			
2019	992093	Frt Windscreen			
2019	992097	Frt Windscreen Rubber	NEC	✓	
2019	992098	Frt Windscreen Sealant	NEC	✓	
2020	992114	Frt Windscreen Outer Pillar		R	
2021	992113	Frt Windscreen Inner Pillar		R	
2021	991019	ERP Bracket			
2021	991020	ERP Unit			
2022	991958	Frt Side Mirror (Big)	2 RH	✓	
2023	991959	Frt Side Mirror (Small)	ms	✓	
2024	991962	Frt Side Mirror (Round)		✓	
2025	995015	Frt Wing Mirror Stay			
2025	992013	Frt Support Panel			
2025	990248	Bonnet			
2025	990287	Bonnet Lock			
2025	990273	Bonnet Hinge			
2025	990305	Bonnet Rubber			
2025	990119	Air Con Condenser			
2025	990122	Air Con Fan Assy			
2025	990149	Air Con Liquid Pipe			
2025	995066	Air Con Receiver Drier			
2025	995074	Radiator			
2025	992738	Radiator Cowling			
2025	992742	Radiator Fan Assy			
2025	992758	Radiator Hose Top			
2025	992741	Radiator Expansion Tank			
2026	992596	Oil Cooler			
2026	994431	Power Steering Cooler Pipe			
2026	990151	Air Duct			
2026	990070	Air Cleaner Assy			
2026	990219	Battery			
2026	990223	Battery Bracket			

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990945	Engine Mounting			
2027	991500	Frt Cabin Assy			
2028	991501	Frt Cabin Mounting			
2029	991502	Frt Cabin Rear Panel			
2029	991520	Frt LH Chassis Member			
2029	991520	Frt RH Chassis Member			
2029	990728	Frt Vertical Cross Member			
2029	991863	Frt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
2031	990427	Brake Master Pump Assy			
2031	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
2034	994483	Steering Wheel Airbag			
2034	994483	Steering Wheel Airbag Sensor			
2034	990029	Airbag Control Unit			
2034	991922	Frt RH Seat Belt Assy			
2034	995182	Frt LH Seat Belt Assy			
2034	990753	Dashboard Assy			
2034	992282	Glove Box Cover			
2034	992281	Glove Box Compartment			
2034	995070	Frt LH Fender			
2034	995072	Frt LH Fender Inner Panel			
2034	991740	Frt LH Fender Inner Shield			
2034	995179	Frt LH Mudflap			
2035	994966	Frt LH Wheel Guard			
2035	995170	Frt LH Wheel Rim			
2035	995065	Frt LH Tyre			
2035	995071	Frt RH Fender			
2035	991739	Frt RH Fender Inner Panel			
2035	991740	Frt RH Fender Inner Shield			
2035	991884	Frt RH Mudflap			
2036	994966	Frt RH Wheel Guard			
2036	992087	Frt RH Wheel Rim			
2036	995065	Frt RH Tyre			
2036	995326	Frt LH Door			
2036	995140	Frt LH Door Protector			
2036	995104	Frt LH Door Hinge			
2036	995142	Frt LH Door Wing Mirror			
2036	995103	Frt LH Door Glass			
2036	991595	Frt LH Door Glass Regulator			
2036	991596	Frt LH Door Glass Regulator Motor			
2036	991662	Frt LH Door Rubber			
2036	991636	Frt LH Door Outer Handle			
2036	991617	Frt LH Door Inner Trim Board			
2036	995327	Frt RH Door		R	
2036	991654	Frt RH Door Protector			
2036	991601	Frt RH Door Hinge Signal Lamp	CRK	✓	
2036	991685	Frt RH Door Wing Mirror			
2036	991584	Frt RH Door Glass			
2036	991595	Frt RH Door Glass Regulator			
2036	991596	Frt RH Door Glass Regulator Motor			
2036	991662	Frt RH Door Rubber			
2036	991636	Frt RH Door Outer Handle			
2036	991617	Frt RH Door Inner Trim Board			
2037	991644	Frt Door Frt Pillar			
2038	991657	Frt Door Rear Pillar			
2039	992072	Frt Wheel Arch Panel			
2040	992069	Frt Wheel Arch Panel Garnish	SCR	✓	
2041	991996	Frt Step Panel	CRK	✓	
2042	994498	Frt Step Panel Top Garnish	CRK	✓	
2043	994495	Frt Step Panel Inner Garnish Reflector	SCR	✓	
2043	995053	Wiper Washer Tank			
2043	990247	Sticker			

No of Items: \_\_\_\_\_ Assessor: \_\_\_\_\_

7 days  
23/1/18  
J. Smith

# Survey Department Check List (Case Handler)

Reference No.:

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all information created by the assignment team are ACCURATE

**(1) Office Assign Form**

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

**(2) System - (Views/Merimen)**

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

**(3) Workshop Estimate/Assignment Form**

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days


**(4) System - (Views/Merimen)**

- C Resurvey photo Uploaded

--	--	--	--

Check By: 







  
Case Handler Date

\*C: Critical \*N: Non-Critical

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/12/2017 10:09
Date Of Accident	11/12/2017 16:30
Exact Location Of Accident	ALONG PIONEER CRESCENT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD3285U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WIZE OPTIONS PTE LTD
Co Reg No	199802951K
Email Address	WOPTIONS@YAHOO.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62615518

### Vehicle Particulars

Manufacturer	HINO
Model	SH1EEKA
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	P1502537
Cover Note Number	CN826213

### Driver

Name of Driver	KWEK TECK SONG
NRIC No	S1134153E
Date Of Birth	28/05/1955
Occupation	OUTDOOR
Date Of Driving Pass	13/11/1984
Driving Experience	33 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91064153
Fax Number	
Contact Number	
EMail Address	NOEMAIL



Address BLK 749 WOODLANDS CIRCLE #03-616  
Postcode 730749  
Was driver an employee of the Insured's Company YES  
If No, Relationship of the Driver with the Insured  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Was any body injured in the Accident? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

AS PER SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC6067D  
Vehicle Make/Model/Colour  
Details Of Properties  
Name of Driver ALIMRAN MD AMIN  
NRIC/Passport Number S8005131Z  
Contact Number 91907524

Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### Details of Witness

Name  
Phone Number  
Email Address

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRC/PIN No.:

Yvonne Toh

# Accident Sketch Plan Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident Date & Time: 11/Dec/2019, 9 30pm

Accident Location: Along Pioneer Crescent.

I was driving along the mentioned. While making a turn into Allied Yard 2, Veh B suddenly drove towards my direction and collided into my vehicle. The driver of Veh B did not stop and left the scene. About 20 mins later, the driver of Veh B returned to the scene and we exchanged contact.

I also have a trailer attached to my vehicle at the point of accident. Trailer TRB 5764 Y under AXA insurance, Policy no. VFX/P0231159.

☐ Reporting Only ☐ Own Damage ☐ Third Party ☒ Claim at other workshop (OD/TP)

## DECLARATION

I/We, the foregoing particulars are true in every respect.

\* IMPORTANT NOTE:  
You have been advised by the reporting shop to the extent that you wish to claim against your own policy (Own Damage Claim), please go to POLICE/INSURANCE (P-I) shop to make the claim within the stipulated time frame from the day of accident.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre/Personnel's Signature  
Name:  
NRIC/FIN No.:

Yvonne Toh

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Dec 2017 <a href="#">Edit Reg</a>		13 Dec 2017 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:		FEDERAL EXPRESS(SINGAPORE), Co. Reg. No.: -							
Main Claimant:		-							
Vehicle Reg. No.:		XD3285U	Date of Loss:	11/12/2017 15:00 - :59					
Claim Type:		TP / 2237861367SG	Policy/Cover Note No.:	0999994900 (Third Party Only)					
Vehicle Reg. No. (Insured):		GBC6067D	Policy No. (Claimant):						
		Excess:							
Repairer:		Lim Joo Kim Trading Co (HQ) Blk 6, Kranji Loop, #01-27, 739542 Kranji - Tel: 63671772							
Handling Insurer:		AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Chuan] Kian-Chuan.Chan@aig.com							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 22/01/2018]							
Claimant's Solicitor:		VISION LAW LLC - Tel: 65342811							
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (12/01/2018): Request for TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*XD3285U (2237861367SG)**  
**[GBC6067D]**


TP

-
































**Dec 11 2017 3:00PM**  
**[FEDERAL EXPRESS(SINGAPORE)]**  
**Lim Joo Kim Trading Co**

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<a href="#">Upload Video</a>	<a href="#">Upload Audio</a>	<b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/>	
----------------------------------	--	-------------------------------	------------------------------------	------------------------------	------------------------------	--	--

<b>Assessment Reports</b>					1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print	
1	12/01/18 11:23	<b>Accident Statement</b> From: SC - Reg. No: GBC6067D, Claimant: FEDERAL EXPRESS (SINGAPORE) PTE LTD		Load HTM		

<b>Photos/Images</b>					3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
2	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
3	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
4	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
5	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
6	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
7	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
8	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
9	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
10	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
11	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
12	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
13	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
14	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
15	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
16	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
17	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
18	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
19	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
20	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
21	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
22	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
23	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
24	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
25	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
26	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
27	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
28	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
29	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
30	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	
31	11/01/18 16:28	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>	

32	11/01/18 16:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	11/01/18 16:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	11/01/18 16:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	11/01/18 16:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	11/01/18 16:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	11/01/18 16:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	11/01/18 16:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	11/01/18 16:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	11/01/18 16:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	11/01/18 16:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	11/01/18 16:28	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	11/01/18 16:28	Odometer Reading	1	Load JPG	<input checked="" type="checkbox"/>
44	11/01/18 16:28	Chassis Number	1	Load JPG	<input checked="" type="checkbox"/>
45	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
46	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
47	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
48	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
49	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
50	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
51	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
52	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
53	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
54	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
55	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
56	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
57	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
58	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
59	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
60	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
61	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
62	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
63	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
64	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
65	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
66	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
67	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
68	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
69	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
70	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
71	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
72	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
73	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
74	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>
75	17/01/18 14:34	Photo After Spray	1	Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17023705/SD3E2

Date: 26/01/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994900  
**Claimant Vehicle No :** XD3285U **Insured Vehicle No :** GBC6067D  
 Date of Loss: 11/12/2017 Nature of Claim: TP Claim No: 2237861367SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XD3285U**  
 Make & Model: HINO 700 SERIES, 12.9 D FS1ETMA (A) Engine No: E13CUN13016  
 Reg. Date: 10/11/2008 (Man. Year: 2008) Chassis No: JHDSH1EEKXXX10456  
 Colour: White Odometer: 745703 km  
 Engine Capacity: 12913 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5  
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 13/12/2017  
 Date Inspected: 14/12/2017 Inspected At: Lim Joo Kim Trading Co (HQ)  
 Blk 6, Kranji Loop, #01-27  
 Singapore 739542  
 Estimated Period of Repair: 7.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Bent	0.00 F	*- F
2	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
3	1		*FRT PANEL LOWER BEAM	Bent	0.00 F	*- F
4	1		*FRT PANEL GARNISH	Cracked	0.00 F	*- F
5	1		*FRT CORNER PANEL	Repair	0.00 F	*- F
6	1		*FRT SIGNAL LAMP RH	Cracked	0.00 F	*- F
7	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
8	1		*FRT WIPER NOZZLE (HEAD LAMP)	Damaged	0.00 F	*- F
9	1		*FRT WIPER MOTOR (HEADLAMP)	Damaged	0.00 F	*- F
10	1		*FRT WINDSCREEN RUBBER	Necessary	0.00 F	*- F
11	1		*FRT WINDSCREEN SEALANT	Necessary	0.00 F	*- F
12	1		*FRT WINDSCREEN OUTER PILLAR	Repair	0.00 F	*- F
13	1		*FRT WINDSCREEN INNER PILLAR	Repair	0.00 F	*- F
14	1		*FRT SIDE MIRROR (BIG) RH}	Missing	0.00 F	*- F
15	1		*FRT SIDE MIRROR (SMALL) }		0.00 F	*- F
16	1		*FRT SIDE MIRROR (ROUND) }		0.00 F	*- F
17	1		*FRT RH DOOR	Repair	0.00 F	*- F
18	1		*FRT RH DOOR SIGNAL LAMP	Cut	0.00 F	*- F
19	1		*FRT WHEEL ARCH PANEL GARNISH	Scratched	0.00 F	*- F
20	1		*FRT STEP PANEL	Cracked / Cut	0.00 F	*- F
21	1		*FRT STEP PANEL TOP GARNISH	Cracked	0.00 F	*- F
22	1		*FRT STEP PANEL REFLECTOR (RH)	Scratched	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >