

22/03/2002

ASS. REC. BY:

REF: C3/CTI17023729/Svd3e2

Special Instruction:

Surveyor: Sebastian**ASSIGNMENT (Office)**From (Person): Irene Tay

of

CTIDate/Time: 10:16am @ 14/12/17

Estimated Cost:

Bill to:

OD (TP) WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDK989S

Insured:

PC1044L

at Workshop m/s

Trans Eurokars

Tel:

6360 2846

of

12 Sungei Kadut Avenue, 729648

Policy No:

DMB1SN1682911701

Claim No:

SNM17D07019C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 8/12/2017

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:27am @ 14/12/17

Person Contacted:

EvaVehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SDK989S - xPC1044L-NS/INCISU14215/K1/bn2D.O.A: 20/08/201529/3/18Final fig \$32,220.88 confirmed by email (Ref 4028.24, 11/18)

REF: CTI

ASSIGNMENT

From: _____ Date: 14/12/2017

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDK 989 MS

at Workshop m/s Stuttgart

of 12 Sungen Kadut Ave

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Eva

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDK 989 S Yr Regn: 17/10/2017

Type: (M) Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Porsche 718 Cayman S cc 2497

Colour: White A.C: Insured / Std / NI / NA

Sp.Reading: 467 T.Radio: Insured / Std / NI / NA

Eng/No: _____

C.No: WPO ZZZ 98 ZH S Z80947*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: ND / S/Rim / STD A/Rim or

Tyre Size: F: 255/35 ZR20

R: 265/35 ZR20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pirelli

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>8/12/2017</u>	D.O.I. <u>14/12/2017</u>

Survey held at Transkrukar

Des. of Damages: Frt / Rear / O/S / (N/S) / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

2/4/2018

REC-11-17-2018

Date/Time: File Pass to?

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 10Resurvey No. of Trip: -

Survey Fee:

Transportation:

Photos:

Others:

Add Fee: ☐ : Site Insp \$☐ : Interview \$☐ : Techn. Insp \$☐ : Weekend \$Report Format: merimenLump Sum / I.B.I. \$ 32,220.88

220

220

Survey Department Check List (Case Handler)

Reference No. : CS/CTI17023729/Srds
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 29/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17023729/Svd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 14-12-2017	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PC 1044L	Veh. Inspected	SDK 989S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	IRENE TAY	Assign Date	14/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	08/12/2017	Inspection Date	14/12/2017
Survey held at	TRANS EUROKARS PTE LTD 12 SUNGEI KADUT AVE SINGAPORE 729648		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Dec 2017		14 Dec 2017 17:21 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:			
Main Claimant:	TAY HSIANG KEE, ID: S7405083B		
Vehicle Reg. No.:	SDK989S	Date of Loss:	08/12/2017 07:00 - :59
Claim Type:	TP / SNM17D07019C02	Policy/Cover Note No.:	DMB1SN1682911701
Vehicle Reg. No. (Insured):	PC1044L	Policy No. (Claimant):	SD17V12307
		Excess:	S\$0.00
Repairer:	Trans Eurokars Pte Ltd () NO. 5 UBI CLOSE, SINGAPORE, 408605 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 26/12/2017]		
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMENDATION		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Thursday, 14 December, 2017 10:16 AM
To: eva.kok@eurokars.com.sg; assignments@lkkauto.com
Cc: rickteo@eurokars.com.sg; tommywoon@eurokars.com.sg;
stanley@eurokars.com.sg; janice.syn@porsche.com.sg; assignments@lkkauto.com
Subject: CTP REF NO. PC1044L E REF NO. SDK989S - ACCIDENT INVOLVING PC1044L AND
SDK989S ON 08 DECEMBER 2017

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter and the email below.

Please assist to get your surveyor to liaise with Eurokars.

Regards

Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: eva.kok@eurokars.com.sg [mailto:eva.kok@eurokars.com.sg]
Sent: Wednesday, 13 December, 2017 1:37 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Cc: rickteo@eurokars.com.sg; tommywoon@eurokars.com.sg; stanley@eurokars.com.sg;
janice.syn@porsche.com.sg
Subject: RE: CTP REF NO. PC1044L E REF NO. SDK989S - ACCIDENT INVOLVING PC1044L AND SDK989S ON 08
DECEMBER 2017

Dear Irene,

We choose LKK for survey vehicle above.

Vehicle already in workshop, please assist assign as soon as possible.

Thanks

Eva Kok
Insurance Claims Officer
Trans Eurokars Pte Ltd
12 Sungei Kadut Avenue
Singapore 729648
Dir: +65 6360 2846 | Fax: +65 6369 3003 | Email: eva.kok@eurokars.com.sg
Website: www.eurokarsgroup.com

*****DISCLAIMER*****

This email and any attachments there to be intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group.

Any use of the information contained herein (including, but not limited to, total or partial reproduction, communication, or dissemination in any form) by persons other than the intended recipient(s) is prohibited. If you have received this email in error, please notify the sender immediately and delete it.

From: Irene Tay [<mailto:irene.tay@sg.cntaiping.com>]

Sent: Wednesday, December 13, 2017 10:36 AM

To: Eva Kok <eva.kok@eurokars.com.sg>

Subject: CTP REF NO. PC1044L E REF NO. SDK989S - ACCIDENT INVOLVING PC1044L AND SDK989S ON 08 DECEMBER 2017

Without Prejudice
Save As To Costs

Dear Sir/Mdm,

We refer to your pre-repair survey request / email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

Here are the list of surveyors ;

Tay Beng Hee
See Chew Seng
Dereck Oh Siong Wee
Kalvin Ang
Bryan Ang
Steven Foong
Adrian Ling
Marcus Chua
Kenneth Kong
Henry Ng

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Irene Tay

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3, Anson Road, #16-00

Springleaf Tower,

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389-6192

Fax: 6224 7175

Email: claimsdept@sg.cntaiping.com

Email: irene.tay@sg.cntaiping.com

Website: www.sg.cntaiping.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/12/2017 12:32
Date Of Accident	08/12/2017 07:10
Exact Location Of Accident	PENANG ROAD SLIP ROAD INTO CLEMENCUE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDK989S
Insured/Policyholder	
Name Of Registered Owner	TAY HSIANG KEE
NRIC No	S7405083B
Email Address	VWFT10@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91801679
Alternative Phone No	OFFICE-91801679

Vehicle Particulars

Manufacturer	PORSCHE
Model	718 CAYMAN S
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD17V12307
Cover Note Number	

Driver

Name of Driver	TAY HSIANG KEE
NRIC No	S7405083B
Date Of Birth	10/01/1974
Occupation	INDOOR
Date Of Driving Pass	06/09/1994
Driving Experience	23 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91801679
Fax Number	
Contact Number	OFFICE-91801679
EEmail Address	VWFT10@GMAIL.COM

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

I was driving along the said location, slip road into CLEMENCEAU ave, I was on the outer lane, As both vehicle was making a turn, vehicle b was making a wide turning, driving in between two lane and cutting into my lane. The rear right of vehicle b came in contact onto my left portion and scrape thru the front side. Damages as stated. The said driver accept liabilities and inform me verbally to claims insurance

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PC1044L

Vehicle Make/Model/Colour KING LONG/XMQ6118K MMC/WHITE

Details Of Properties

Name of Driver LIM HEE WANG

NRIC/Passport Number S7480267G

Contact Number 90061351

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1


Details of Witness

Name

Phone Number

Email Address

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was driving along the said location, slip road into CLEMENCEAU ave, I was on the outer lane, As both vehicle was making a turn, vehicle b was making a wide turning, driving in between two lane and cutting into my lane. The rear right of vehicle b came in contact onto my left portion and scrape thru the front side. Damages as stated. The said driver accept liabilities and inform me verbally to claims insurance

Taxi Voucher No.:

Are you claiming your own insurance policy for the repair of your vehicle?

No, Claim 3rd party

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMAD HELMY BIN ALEHAM

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

Date/Time:

STUTTGART AUTO
NO:12 SUNGEI KADUT AVE (S) 729648 (FAX NO. 63602899)
ESTIMATED COST OF REPAIRS

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909		NAME : Mdm Tay Hsiang Kee ADDRESS : 17 Evelyn Road #29-07 Singapore 309306	WIP : 29981 DATE: 11/12/2017
ATTN. : MOTOR CLAIMS	TEL :		
FAX :			
VEH NO : SDK989S	DATE IN : 8/12/2017	CONTACT PERSON : TOMMY	63602447
CHASSIS NO : WP0ZZZ98ZHS280947	MILEAGE :	TYPE OF CLAIM : TP AGAINST PC1044L	
MODEL : 718 Cayman S	DATE REG : 17/10/2017	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY	PART NO	(NETT) PRICES
1	Wing Prime coated ✓ <i>Cut DT</i>	1	P982-821-021- Y-GRV	\$ 1,812.70 ✓
2	WHEEL-HOUSING LINER ? <i>Cut</i>	1	P981-504-503-01-	\$ 433.20 ✓
3	Sill cover Prime coated ✓ <i>Cut Rocker panel</i>	1	P982-853-563- -G2X	\$ 1,051.80 ✓
4	Ventilation grille ✓ <i>Cut</i>	1	P982-853-189- -OK1	\$ 334.30 ✓
5	MOUNTING PARTS ✓ <i>NEC</i>	2	P981-504-597-00-	\$ 131.60 ✓
6	FIXING CLIP ✓ <i>NEC</i>	8	P999-507-999-40-	\$ 42.40 ✓
7	CLIP ✓ <i>NEC</i>	8	P999-702-403-40-	\$ 59.20 ✓
8	clip ✓ <i>NEC</i>	8	P999-591-413-40-	\$ 20.00 ✓
9	FIXING CLIP ✓ <i>NEC</i>	8	P999-507-999-40-	\$ 42.40 ✓
10	RIVET ✓ <i>NEC</i>	2	P999-591-712-40-	\$ 3.60 ✓
11	FIXING CLIP ✓ <i>NEC</i>	1	P981-505-719-01-	\$ 36.10 ✓
12	DOOR ✓ <i>Cut</i>	1	P982-831-051- Y-GRV	\$ 2,327.40 ✓
13	P9P1-837-111- -1E0/CAP ✓ <i>NEC NN</i>	1	P9P1-837-111-B -	\$ 31.70 X
14	CAP ✓ <i>NEC NN</i>	1	P9P1-837-111-A -1E0	\$ 21.90 X
15	ROOF FRAME SEAL ✓ <i>NEC</i>	1	P981-537-481-01-	\$ 499.70 ✓
16	GASKET ✓ <i>Door Rubber NEC</i>	1	P981-537-377-02-	\$ 812.20 ✓
17	CLIP ✓ <i>NEC</i>	5	P999-507-304-41-	\$ 24.50 ✓
18	GASKET ✓ <i>NEC Window mounting</i>	1	P991-537-085-01-03C	\$ 439.30 ✓
19	Supporting bow ? <i>DM</i>	1	P982-837-885-C -	\$ 366.00 ✓
20	Support ✓ <i>Cut</i>	1	P9P1-837-161- -	\$ 47.60 ✓
21	Desk pad ✓ <i>Cut</i>	1	P9P1-837-209- -	\$ 29.60 ✓
22	Door handle ✓ <i>Cut</i>	1	P9P1-837-165- Y-	\$ 320.50 ✓
23	INSULATION DOOR ✓ <i>NEC</i>	1	P997-556-531-01-	\$ 62.50 ✓
24	Mirror housing Prime coate ✓ <i>Cut</i>	1	P982-858-653-A -G2X	\$ 419.20 ✓
25	WIRING HARNESS ✓ <i>DMG</i>	1	P982-972-235-G -	\$ 294.70 ✓
26	Mirror base ✓ <i>DMG</i>	1	P982-858-317-C -	\$ 967.60 ✓
27	ADJUSTING MOTOR ✓ <i>DMG</i>	1	P7PP-959-578-E -	\$ 455.40 ✓
28	Mirror glass ✓ <i>CRK</i>	1	P982-857-521-E -	\$ 1,465.30 ✓
29	DOOR MIRROR Side Mirror Base Cover ✓ <i>CRK</i>	1	P982-857-185-C -OK1	\$ 764.10 ✓
30	Light ✓ <i>DMG</i>	1	P9P9-949-133- -	\$ 201.80 ✓
31	Gasket ✓ <i>NEC</i>	1	P982-857-555- -	\$ 40.50 ✓
32	MIRROR BASE ✓ <i>CRK</i>	1	P982-857-109- -OK1	\$ 36.80 ✓
33	MIRROR BASE ✓ <i>CRK</i>	1	P982-857-112- -OK1	\$ 45.70 ✓
34	Gasket ✓ <i>NEC</i>	1	P982-857-679- -	\$ 48.70 ✓
35	Mirror base ✓ <i>CRK</i>	1	P982-857-539- -	\$ 268.10 ✓
36	REPAIR KIT ✓ <i>NEC</i>	1	P982-898-813- -	\$ 22.30 ✓
37	P991-631-255-05-/INDICATOR LIGHT (LH) ✓ <i>Cut</i>	1	P991-631-255-06-	\$ 232.80 ✓
38	Disc wheel Brilliant chrom ✓ <i>Cut</i>	1	P982-601-025-H -88Z	\$ 6,925.10 ✓

			Total Parts	\$ 21,138.30
			LESS 10%	\$ 2,113.83
			Nett Total Parts	\$ 19,024.47
	Labour Description			
1	TO REMOVE DAMAGED & AFFECTED BODY PARTS, 1400/day REPLACE AFFECTED BODY PARTS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE.			
				\$ 8400.00 ✓ 6300
2	TO SPRAY PAINT FRT LH FENDER, FRT LH DOOR, 1000/panel LH SIDE SKIRT, WING MIRROR HOUSING LH & AFFECTED PORTIONS.			
				\$ 4500.00 ✓ 4000
3	TO CARRY OUT BODY CAVITY PRESERVATION TO ALL AFFECTED AREAS.			
				\$ X 500.00
4	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FUNCTION ABILITY INCLUDING PARKING ASSIST SENSORS.			
		NETT		\$ 380.00 ✓ 250
5	TO REMOVE, REPLACE, REFIT DOORS INCLUDE TRANSFER WINDOW MECHANISM FROM DAMAGE DOOR TO NEW DOOR & CHECK FUNCTION ABILITY			
		NETT		\$ 1,400.00 ✓ 700
6	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT ACCORDING TO SPECIFICATIONS.			
		NETT	✓	\$ 680.00 ✓
7	TO REMOVE REPLACE REFIT TYRES & RIMS @ \$60/-			
			EC	
8	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR.			
		NETT	✓	\$ 600.00 ✓
9	TOWING CHARGES			
			✓	\$ 300.00 ✓
10	SUNDRIES.			
			✓	\$ 100.00 50
			TOTAL LABOUR	\$ 16,860.00
			TOTAL PARTS	\$ 19,024.47
			GRAND TOTAL	\$ 35,884.47

Please note that this is **only an estimate**, base on our visual inspection. However should there be any additional work be found necessary in the course of repair and thus additional parts, materials and labor cost will be deemed necessary, you will be inform accordingly prior to any action taken. In view of this, expected delays will be indvitable and therefore additional working days will be required. As such the loss of use and other incidentals will be adjusted accordingly.

10 days. 36,249.12

Prepared By

Sebastian. 14/12/2017
- Part by part repair.
- Question Mark Item Photo.
- Photo Before Paint
90036121

Acknowledge By

sebastianyeang@lkkauto.com

- LKK Auto Considers hence notify the Repairs of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SUPPLEMENTARY PARTS					
1	RETAINING STRIP	NEC	1	P982-854-943	\$ 41.00
2	RUBBER PLY	NEC	2	P991-537-557-00	\$ 35.40
3	DOOR WINDOW GLASS	SR	1	P981-542-511-01	\$ 262.10
4					
				Total Parts	\$ 21,423.20
				LESS 10%	\$ 2,142.32
				Nett Total Parts	\$ 19,280.88
					\$ 21,138.30
					\$ 2,113.83
					\$ 19,024.47
	Labour Description				
1	TO REMOVE DAMAGED & AFFECTED BODY PARTS, REPLACE AFFECTED BODY PARTS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE.				\$ 6,300.00
					\$ 8,400.00
2	TO SPRAY PAINT FRT LH FENDER, FRT LH DOOR, LH SIDE SKIRT, WING MIRROR HOUSING LH & AFFECTED PORTIONS.				\$ 4,000.00
					\$ 4,500.00
3	TO CARRY OUT BODY CAVITY PRESERVATION TO ALL AFFECTED AREAS.				\$ -
					\$ 500.00
4	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FUNCTION ABILITY INCLUDING PARKING ASSIST SENSORS.				\$ 250.00
					\$ 380.00
5	TO REMOVE, REPLACE, REFIT DOORS INCLUDE TRANSFER WINDOW MECHANISM FROM DAMAGE DOOR TO NEW DOOR & CHECK FUNCTION ABILITY				\$ 700.00
					\$ 1,400.00
6	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT ACCORDING TO SPECIFICATIONS.				\$ 680.00
					\$ 680.00
7	TO REMOVE REPLACE REFIT TYRES & RIMS @ \$60/-				\$ 60.00
8	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR.				\$ 600.00
					\$ 600.00
9	TOWING CHARGES				\$ 300.00
					\$ 300.00
10	SUNDRIES.				\$ 50.00
					\$ 100.00
				TOTAL LABOUR	\$ 12,940.00
				TOTAL PARTS	\$ 19,280.88
				GRAND TOTAL	\$ 32,220.88
				GST 7 %	\$ 2,255.46
				TOTAL AFTER GST	\$ 34,476.34

STUTTGART AUTO
NO:12 SUNGEI KADUT AVE (S) 729648 (FAX NO. 63602899)
FINALIZATION COST OF REPAIRS

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909		NAME : Mdm Tay Hsiang Kee ADDRESS : 17 Evelyn Road #29-07 Singapore 309306	WIP : 29981 DATE: 11/12/2017
ATTN. : MOTOR CLAIMS	TEL :		
FAX :			
VEH NO :	SDK989S	DATE IN :	8/12/2017
CHASSIS NO :	WP0ZZZ98ZHS280947	MILEAGE :	
MODEL :	718 Cayman S	DATE REG.:	17/10/2017
		CONTACT PERSON :	TOMMY 63602447
		TYPE OF CLAIM :	TP AGAINST PC1044L
		POLICY NO. :	

NATURE OF WORKS					
S/NO	Parts Description	QTY	PART NO	REVISED	(NETT) PRICES
1	Wing Prime coated ✓ DT	1	P982-821-021- Y-GRV	\$ 1,812.70	\$ 1,812.70
2	WHEEL-HOUSING LINER Cut	1	P981-504-503-01-	\$ 433.20	\$ 433.20
3	Sill cover Prime coated Cut	1	P982-853-563- -G2X	\$ 1,051.80	\$ 1,051.80
4	Ventilation grille Cut	1	P982-853-189- -OK1	\$ 334.30	\$ 334.30
5	MOUNTING PARTS NEC	2	P981-504-597-00-	\$ 131.60	\$ 131.60
6	FIXING CLIP NEC	8	P999-507-999-40-	\$ 42.40	\$ 42.40
7	CLIP NEC	8	P999-702-403-40-	\$ 59.20	\$ 59.20
8	clip	8	P999-591-413-40-	\$ 20.00	\$ 20.00
9	FIXING CLIP	8	P999-507-999-40-	\$ 42.40	\$ 42.40
10	RIVET NEC	2	P999-591-712-40-	\$ 3.60	\$ 3.60
11	FIXING CLIP	1	P981-505-719-01-	\$ 36.10	\$ 36.10
12	DOOR Cut	1	P982-831-051- Y-GRV	\$ 2,327.40	\$ 2,327.40
13	P9P1-837-111- -1E0/CAP NEC	1	P9P1-837-111-B -	\$ -	\$ 31.70
14	CAP NEC	1	P9P1-837-111-A -1E0	\$ -	\$ 21.90
15	ROOF FRAME SEAL NEC	1	P981-537-481-01-	\$ 499.70	\$ 499.70
16	GASKET NEC	1	P981-537-377-02-	\$ 812.20	\$ 812.20
17	CLIP NEC	5	P999-507-304-41-	\$ 24.50	\$ 24.50
18	GASKET NEC	1	P991-537-085-01-03C	\$ 439.30	\$ 439.30
19	Supporting bow DMG	1	P982-837-885-C -	\$ 366.00	\$ 366.00
20	Support Cut	1	P9P1-837-161- -	\$ 47.60	\$ 47.60
21	Desk pad Cut	1	P9P1-837-209- -	\$ 29.60	\$ 29.60
22	Door handle Cut	1	P9P1-837-165- Y-	\$ 320.50	\$ 320.50
23	INSULATION DOOR NEC	1	P997-556-531-01-	\$ 62.50	\$ 62.50
24	Mirror housing Prime coate Cut	1	P982-858-653-A -G2X	\$ 419.20	\$ 419.20
25	WIRING HARNESS DMG	1	P982-972-235-G -	\$ 294.70	\$ 294.70
26	Mirror base DMG	1	P982-858-317-C -	\$ 967.60	\$ 967.60
27	ADJUSTING MOTOR DMG	1	P7PP-959-578-E -	\$ 455.40	\$ 455.40
28	Mirror glass CRK	1	P982-857-521-E -	\$ 1,465.30	\$ 1,465.30
29	DOOR MIRROR CRK Side Mirror Base Color	1	P982-857-185-C -OK1	\$ 764.10	\$ 764.10
30	Light DMG	1	P9P9-949-133- -	\$ 201.80	\$ 201.80
31	Gasket NEC	1	P982-857-555- -	\$ 40.50	\$ 40.50
32	MIRROR BASE CRK	1	P982-857-109- -OK1	\$ 36.80	\$ 36.80
33	MIRROR BASE CRK	1	P982-857-112- -OK1	\$ 45.70	\$ 45.70
34	Gasket NEC	1	P982-857-679- -	\$ 48.70	\$ 48.70
35	Mirror base CRK	1	P982-857-539- -	\$ 268.10	\$ 268.10
36	REPAIR KIT NEC	1	P982-898-813- -	\$ 22.30	\$ 22.30
37	P991-631-255-05-/INDICATOR LIGHT (LH) Cut	1	P991-631-255-06-	\$ 232.80	\$ 232.80
38	Disc wheel Brilliant chrom Cut	1	P982-601-025-H -88Z	\$ 6,925.10	\$ 6,925.10
SUPPLEMENTARY PARTS					
1	RETAINING STRIP NEC	1	P982-854-943	\$ 41.00	

2	RUBBER PLY	Misc	2	P991-537-557-00	\$	35.40	
3	DOOR WINDOW GLASS	Sck	1	P981-542-511-01	\$	262.10	
4.							

NUMBER OF WORKING DAYS: 12 WORKING DAYS(EXCLUDE PREPAING ESTIMATE, WAITING FOR PARTS,SURVEY, AUTHORIZATION,SATURDAY,SUNDAY AND PUBLIC HOLIDAY)

LOSS OF USE : \$180.00 x 54 DAYS = \$9,720.00

GIA SEARCH FEES ; \$2.00

STUTTGART AUTO
NO:12 SUNGEI KADUT AVE (S) 729648 (FAX NO. 63602899)
FINALIZATION COST OF REPAIRS

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909		NAME : Mdm Tay Hsiang Kee	WIP : 29981
ATTN. : MOTOR CLAIMS		ADDRESS : 17 Evelyn Road #29-07 Singapore 309306	DATE: 11/12/2017
FAX :		TEL :	
VEH NO :	SDK989S	DATE IN : 8/12/2017	CONTACT PERSON : TOMMY 63602447
CHASSIS NO :	WP0ZZZ98ZHS280947	MILEAGE :	TYPE OF CLAIM : TP AGAINST PC1044L
MODEL :	718 Cayman S	DATE REG.: 17/10/2017	POLICY NO. :

NATURE OF WORKS

S/NO	Parts Description	QTY	PART NO	REVISED	(NETT) PRICES
1	Wing Prime coated	1	P982-821-021- Y-GRV	\$ 1,812.70	\$ 1,812.70
2	WHEEL-HOUSING LINER	1	P981-504-503-01-	\$ 433.20	\$ 433.20
3	Sill cover Prime coated	1	P982-853-563- -G2X	\$ 1,051.80	\$ 1,051.80
4	Ventilation grille	1	P982-853-189- -OK1	\$ 334.30	\$ 334.30
5	MOUNTING PARTS	2	P981-504-597-00-	\$ 131.60	\$ 131.60
6	FIXING CLIP	8	P999-507-999-40-	\$ 42.40	\$ 42.40
7	CLIP	8	P999-702-403-40-	\$ 59.20	\$ 59.20
8	clip	8	P999-591-413-40-	\$ 20.00	\$ 20.00
9	FIXING CLIP	8	P999-507-999-40-	\$ 42.40	\$ 42.40
10	RIVET	2	P999-591-712-40-	\$ 3.60	\$ 3.60
11	FIXING CLIP	1	P981-505-719-01-	\$ 36.10	\$ 36.10
12	DOOR	1	P982-831-051- Y-GRV	\$ 2,327.40	\$ 2,327.40
13	P9P1-837-111- -1E0/CAP	1	P9P1-837-111-B -	\$ -	\$ 31.70
14	CAP	1	P9P1-837-111-A -1E0	\$ -	\$ 21.90
15	ROOF FRAME SEAL	1	P981-537-481-01-	\$ 499.70	\$ 499.70
16	GASKET	1	P981-537-377-02-	\$ 812.20	\$ 812.20
17	CLIP	5	P999-507-304-41-	\$ 24.50	\$ 24.50
18	GASKET	1	P991-537-085-01-03C	\$ 439.30	\$ 439.30
19	Supporting bow	1	P982-837-885-C -	\$ 366.00	\$ 366.00
20	Support	1	P9P1-837-161- -	\$ 47.60	\$ 47.60
21	Desk pad	1	P9P1-837-209- -	\$ 29.60	\$ 29.60
22	Door handle	1	P9P1-837-165- Y-	\$ 320.50	\$ 320.50
23	INSULATION DOOR	1	P997-556-531-01-	\$ 62.50	\$ 62.50
24	Mirror housing Prime coate	1	P982-858-653-A -G2X	\$ 419.20	\$ 419.20
25	WIRING HARNESS	1	P982-972-235-G -	\$ 294.70	\$ 294.70
26	Mirror base	1	P982-858-317-C -	\$ 967.60	\$ 967.60
27	ADJUSTING MOTOR	1	P7PP-959-578-E -	\$ 455.40	\$ 455.40
28	Mirror glass	1	P982-857-521-E -	\$ 1,465.30	\$ 1,465.30
29	DOOR MIRROR	1	P982-857-185-C -OK1	\$ 764.10	\$ 764.10
30	Light	1	P9P9-949-133- -	\$ 201.80	\$ 201.80
31	Gasket	1	P982-857-555- -	\$ 40.50	\$ 40.50
32	MIRROR BASE	1	P982-857-109- -OK1	\$ 36.80	\$ 36.80
33	MIRROR BASE	1	P982-857-112- -OK1	\$ 45.70	\$ 45.70
34	Gasket	1	P982-857-679- -	\$ 48.70	\$ 48.70
35	Mirror base	1	P982-857-539- -	\$ 268.10	\$ 268.10
36	REPAIR KIT	1	P982-898-813- -	\$ 22.30	\$ 22.30
37	P991-631-255-05-/INDICATOR LIGHT (LH)	1	P991-631-255-06-	\$ 232.80	\$ 232.80
38	Disc wheel Brilliant chrom	1	P982-601-025-H -88Z	\$ 6,925.10	\$ 6,925.10

AUTHORIZATION, SATURDAY, SUNDAY AND PUBLIC HOLIDAY)

LOSS OF USE : \$180.00 x 54 DAYS = \$9,720.00

GIA SEARCH FEES ; \$2.00

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 29 March 2018 3:16 PM
To: Mei Kwan (LKKAUTO); Sebastian Yeang (LKK Auto); jessicahs@eurokars.com.sg
Cc: eva.kok@eurokars.com.sg; CS A Team; Admin A; SUR; stanley@eurokars.com.sg
Subject: RE: finalization CHINA TP - SDK989S.xls *** LKK REF: CS/CTI17023729/Svd3

Dear Jessica,

Without Prejudice

Confirmed COR: \$32,220.88 before GST

No of days: 10 days

Final invoice and all supporting documents sent over to China TaiPing Insurance

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAUTO)

Sent: Thursday, 29 March 2018 11:27 AM

To: stanley@eurokars.com.sg; Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>

Cc: eva.kok@eurokars.com.sg; jessicahs@eurokars.com.sg; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: finalization CHINA TP - SDK989S.xls *** LKK REF: CS/CTI17023729/Svd3

Dear Sir /Madam,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CS/CTI17023729/Svd3	Veron

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: stanley@eurokars.com.sg [<mailto:stanley@eurokars.com.sg>]

Sent: Wednesday, 28 March, 2018 2:49 PM

To: Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Cc: eva.kok@eurokars.com.sg; jessicahs@eurokars.com.sg

Subject: RE: finalization CHINA TP - SDK989S.xls

Dear LKK and Team

Please assist to expedite finalization process. Thanks!



Thanks and regards

Stanley Ngu

Manager

Body & Paint Division

Eurokars Group of Companies

(Porsche, Rolls Royce, Mini, Mazda, McLaren)

Eurokars Centre

12 Sungei Kadut Avenue

Singapore 729648

Tel: +65 63633003

DID: +65 63602845

Fax: +65 63602899

From: Jessica Harry Shastri

Sent: Wednesday, 28 March 2018 10:39 AM

To: Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>

Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Eva Kok <eva.kok@eurokars.com.sg>;

Stanley Ngu <stanley@eurokars.com.sg>

Subject: RE: finalization CHINA TP - SDK989S.xls

Dear Veron/ Sebastian,

4th Reminder

The below matter refers.

We have not receive the confirmation yet till today. If no confirmation receive by today, we will deal with insurance directly.

Thank you very much.

Regards,

Jessica Shastri

Admin Executive – Insurance Claims

Eurokars Group of Companies

(Porsche, Rolls Royce, Saab, Mini, Mazda, Mc.Laren)

Eurokars Centre

12 Sungei Kadut Avenue
Singapore 729648
Tel: +65 63633003
DID: +65 63602863
Fax: +65 63602899

From: Jessica Harry Shastri
Sent: Monday, March 26, 2018 9:10 AM
To: 'Sebastian Yeang (LKK Auto)' <SebastianYeang@lkkauto.com>
Cc: 'CS A Team' <cs-a@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>; Eva Kok <eva.kok@eurokars.com.sg>; Stanley Ngu <stanley@eurokars.com.sg>; Claims Service Team <cst@axa.com.sg>
Subject: RE: finalization CHINA TP - SDK989S.xls

Dear Veron/ Sebastian, **3rd Reminder**

The below matter refers.

We have not receive the confirmation yet till today.

Thank you very much.

Regards,
Jessica Shastri
Admin Executive – Insurance Claims
Eurokars Group of Companies
(Porsche, Rolls Royce, Saab, Mini, Mazda, Mc.Laren)
Eurokars Centre
12 Sungei Kadut Avenue
Singapore 729648
Tel: +65 63633003
DID: +65 63602863
Fax: +65 63602899

From: Jessica Harry Shastri
Sent: Thursday, March 22, 2018 8:56 AM
To: 'Sebastian Yeang (LKK Auto)' <SebastianYeang@lkkauto.com>
Cc: 'CS A Team' <cs-a@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>; Eva Kok <eva.kok@eurokars.com.sg>; Stanley Ngu <stanley@eurokars.com.sg>
Subject: RE: finalization CHINA TP - SDK989S.xls

Dear Veron/ Sebastian, **2nd Reminder**

The below matter refers.

Please let us have closure of this case by this week if we do not hear from you we will deal with insurer directly.

Thank you very much.

Regards,
Jessica Shastri
Admin Executive – Insurance Claims
Eurokars Group of Companies

(Porsche, Rolls Royce, Saab, Mini, Mazda, Mc.Laren)
Eurokars Centre
12 Sungei Kadut Avenue
Singapore 729648
Tel: +65 63633003
DID: +65 63602863
Fax: +65 63602899

From: Jessica Harry Shastri
Sent: Tuesday, March 20, 2018 9:19 AM
To: 'Sebastian Yeang (LKK Auto)' <SebastianYeang@lkkauto.com>
Cc: 'CS A Team' <cs-a@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>; Eva Kok <eva.kok@eurokars.com.sg>
Subject: RE: finalization CHINA TP - SDK989S.xls

Dear Sebastian/Veron,

Please let us have the confirmation by this week.

Thank you very much.

Regards,
Jessica Shastri
Admin Executive – Insurance Claims
Eurokars Group of Companies
(Porsche, Rolls Royce, Saab, Mini, Mazda, Mc.Laren)
Eurokars Centre
12 Sungei Kadut Avenue
Singapore 729648
Tel: +65 63633003
DID: +65 63602863
Fax: +65 63602899

From: Jessica Harry Shastri
Sent: Thursday, March 15, 2018 10:06 AM
To: Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>
Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Eva Kok <eva.kok@eurokars.com.sg>
Subject: finalization CHINA TP - SDK989S.xls

Dear Sebastian,

Please find our computation attached for your agreement.
COR: \$32,220.88 before GST
12 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Appreciate your confirming the above as soon as possible.

Thank you very much.

Regards,
Jessica Shastri
Admin Executive – Insurance Claims

Eurokars Group of Companies
(Porsche, Rolls Royce, Saab, Mini, Mazda, Mc.Laren)
Eurokars Centre
12 Sungei Kadut Avenue
Singapore 729648
Tel: +65 63633003
DID: +65 63602863
Fax: +65 63602899

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Dec 2017		14 Dec 2017 17:21 Edit Adj Rpt	S\$32,220.88 Edit Estimates	S\$32,220.88 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	TAY HSIANG KEE, ID: S7405083B		
Vehicle Reg. No.:	SDK989S	Date of Loss:	08/12/2017 07:00 - :59 [1 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM17D07019C02	Policy/Cover Note No.:	DMB1SN1682911701
Vehicle Reg. No. (Insured):	PC1044L	Policy No. (Claimant):	SD17V12307
		Excess:	S\$0.00
Repairer:	Trans Eurokars Pte Ltd () NO. 5 UBI CLOSE, SINGAPORE, 408605 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 26/12/2017]		
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMENDATION		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDK989S (SNM17D07019C02)**

[PC1044L]

TP

TAY HSIANG KEE

Dec 8 2017 7:00AM

[-]

Trans Eurokars Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View In Browser	
Video			1 per page	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	08/12/17 12:35	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
Assessment Reports			1 per page	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	08/12/17 12:44	Accident Statement	Load HTM	☐
Photos/Images			3 per page	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	08/12/17 12:37	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	08/12/17 12:37	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	08/12/17 12:39	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	08/12/17 12:39	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	08/12/17 12:39	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
6	08/12/17 12:39	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
7	08/12/17 12:39	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
8	08/12/17 12:39	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
9	08/12/17 12:39	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
10	08/12/17 12:39	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
11	08/12/17 12:39	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
12	08/12/17 12:39	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
13	08/12/17 12:39	Driving License [Linked Accident Report Documents]	Load JPG	☒
14	08/12/17 12:39	Driving License [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/12/17 13:37	General View	Load JPG	☒
2	18/12/17 13:37	General View	Load JPG	☒
3	18/12/17 13:37	General View	Load JPG	☒
4	18/12/17 13:37	General View	Load JPG	☒
5	18/12/17 13:37	General View	Load JPG	☒
6	18/12/17 13:37	General View	Load JPG	☒
7	18/12/17 13:37	General View	Load JPG	☒
8	18/12/17 13:37	General View	Load JPG	☒
9	18/12/17 13:37	General View	Load JPG	☒
10	18/12/17 13:37	General View	Load JPG	☒

Video			1 per page	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
11	18/12/17 13:37	General View	 Load JPG	☒
12	18/12/17 13:37	General View	 Load JPG	☒
13	18/12/17 13:37	General View	 Load JPG	☒
14	18/12/17 13:37	General View	 Load JPG	☒
15	18/12/17 13:37	General View	 Load JPG	☒
16	18/12/17 13:37	General View	 Load JPG	☒
17	18/12/17 13:37	General View	 Load JPG	☒
18	18/12/17 13:37	General View	 Load JPG	☒
19	18/12/17 13:37	General View	 Load JPG	☒
20	18/12/17 13:37	General View	 Load JPG	☒
21	18/12/17 13:37	General View	 Load JPG	☒
22	18/12/17 13:37	General View	 Load JPG	☒
23	18/12/17 13:37	General View	 Load JPG	☒
24	18/12/17 13:37	General View	 Load JPG	☒
25	18/12/17 13:37	General View	 Load JPG	☒
26	18/12/17 13:37	General View	 Load JPG	☒
27	18/12/17 13:37	General View	 Load JPG	☒
28	18/12/17 13:37	General View	 Load JPG	☒
29	18/12/17 13:37	General View	 Load JPG	☒
30	18/12/17 13:37	General View	 Load JPG	☒
31	18/12/17 13:37	General View	 Load JPG	☒
32	18/12/17 13:37	General View	 Load JPG	☒
33	18/12/17 13:37	General View	 Load JPG	☒
34	18/12/17 13:37	General View	 Load JPG	☒
35	18/12/17 13:37	General View	 Load JPG	☒
36	18/12/17 13:37	General View	 Load JPG	☒
37	18/12/17 13:37	General View	 Load JPG	☒
38	18/12/17 13:37	General View	 Load JPG	☒
39	18/12/17 13:37	General View	 Load JPG	☒
40	18/12/17 13:37	General View	 Load JPG	☒
41	18/12/17 13:37	General View	 Load JPG	☒
42	18/12/17 13:37	General View	 Load JPG	☒
43	18/12/17 13:37	General View	 Load JPG	☒
44	18/12/17 13:37	General View	 Load JPG	☒
45	18/12/17 13:37	General View	 Load JPG	☒
46	18/12/17 13:37	General View	 Load JPG	☒
47	18/12/17 13:37	General View	 Load JPG	☒
48	18/12/17 13:37	General View	 Load JPG	☒
49	18/12/17 13:37	General View	 Load JPG	☒
50	18/12/17 13:37	General View	 Load JPG	☒
51	18/12/17 13:37	General View	 Load JPG	☒
52	18/12/17 13:37	General View	 Load JPG	☒
53	18/12/17 13:37	General View	 Load JPG	☒
54	18/12/17 13:37	General View	 Load JPG	☒
55	18/12/17 13:37	General View	 Load JPG	☒
56	18/12/17 13:37	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/12/17 17:22	EMAIL FROM TE(1)	 Load PDF	
2	14/12/17 17:22	EMAIL FROM TE(2)	 Load PDF	

Video			1 per page	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	08/12/17 12:37	Sketch Plan [Linked Accident Report Documents]	Load JPG	☒
2	08/12/17 12:37	Common Statement [Linked Accident Report Documents]	Load TIFF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/04/18 11:09	Supplementary	Load PDF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	08/12/17 12:35	Video - Accident	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	08/12/17 12:44	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	08/12/17 12:37	Accident Photo	Load JPG	☒
2	08/12/17 12:37	Accident Photo	Load JPG	☒
3	08/12/17 12:39	Accident Photo	Load JPG	☒
4	08/12/17 12:39	Accident Photo	Load JPG	☒
5	08/12/17 12:39	Accident Photo	Load JPG	☒
6	08/12/17 12:39	Accident Photo	Load JPG	☒
7	08/12/17 12:39	Accident Photo	Load JPG	☒
8	08/12/17 12:39	Accident Photo	Load JPG	☒
9	08/12/17 12:39	Accident Photo	Load JPG	☒
10	08/12/17 12:39	Accident Photo	Load JPG	☒
11	08/12/17 12:39	Accident Photo	Load JPG	☒
12	08/12/17 12:39	Accident Photo	Load JPG	☒
13	08/12/17 12:39	Driving License	Load JPG	☒
14	08/12/17 12:39	Driving License	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AJAX MARS PTE LTD (Bukit Merah)	Thumbnail	Print
1	08/12/17 12:37	Sketch Plan	Load JPG	☒
2	08/12/17 12:37	Common Statement	Load TIFF	

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17023729/SVD3E2

Date: 04/04/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN1682911701

Claimant Vehicle No : SDK989S Insured Vehicle No : PC1044L

Date of Loss: 08/12/2017 Nature of Claim: TP Claim No: SNM17D07019C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDK989S**

Make & Model: PORSCHE CAYMAN, Engine No: 005636

Reg. Date: 17/10/2017 (Man. Year: 2016) Chassis No: WP0ZZZ98ZHS280947

Colour: White Odometer: 467 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35Z R20 Rear Tyre Size: 265/35Z R20

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,429.12	19,330.88	98.24	0.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,820.00	12,890.00	3,930.00	23.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	36,249.12	32,220.88	4,028.24	11.11
+ GST 7.00/7.00% (S\$)	2,537.44	2,255.46	281.98	11.11
Nett Amount (S\$)	38,786.56	34,476.34	4,310.22	11.11

INSPECTION

Date of Assignment: 14/12/2017

Date Inspected: 14/12/2017 Inspected At: Trans Eurokars Pte Ltd
12 SUNGEI KADUT AVE
SINGAPORE 729648

Estimated Period of Repair: 10.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Apr 2018)
Parts: M1-COUPE PORSCHE CAYMAN (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SDK989S)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WING PRIME COATED	Dented	1,812.70 FL	*1,812.70 FL
2	1		*WHEEL-HOUSING LINER	Cut	433.20 FL	*433.20 FL
3	1		*SILL COVER PRIME COATED	Cut	1,051.80 FL	*1,051.80 FL
4	1		*VENTILATION GRILLE	Cut	334.30 FL	*334.30 FL
5	2		*MOUNTING PARTS	Necessary	131.60 FL	*131.60 FL
6	8		*FIXING CLIP	Necessary	42.40 FL	*42.40 FL
7	8		*CLIP	Necessary	59.20 FL	*59.20 FL
8	8		*CLIP	Necessary	20.00 FL	*20.00 FL
9	8		*FIXING CLIP	Necessary	42.40 FL	*42.40 FL
10	2		*RIVET	Necessary	3.60 FL	*3.60 FL
11	1		*FIXING CLIP	Necessary	36.10 FL	*36.10 FL
12	1		*DOOR	Cut	2,327.40 FL	*2,327.40 FL
13	1		*P9P1-837-111- -1E0/CAP	Not Necessary	31.70 FL	*- FL
14	1		*CAP	Not Necessary	21.90 FL	*- FL
15	1		*ROOF FRAME SEAL	Necessary	499.70 FL	*499.70 FL
16	1		*GASKET	Necessary	812.20 FL	*812.20 FL
17	5		*CLIP	Necessary	24.50 FL	*24.50 FL
18	1		*GASKET	Necessary	439.30 FL	*439.30 FL
19	1		*SUPPORTING BOW	Damaged	366.00 FL	*366.00 FL
20	1		*SUPPORT	Cut	47.60 FL	*47.60 FL
21	1		*DESK PAD	Cut	29.60 FL	*29.60 FL
22	1		*DOOR HANDLE	Cut	320.50 FL	*320.50 FL
23	1		*INSULATION DOOR	Necessary	62.50 FL	*62.50 FL
24	1		*MIRROR HOUSING PRIME COATE	Cut	419.20 FL	*419.20 FL
25	1		*WIRING HARNESS	Damaged	294.70 FL	*294.70 FL
26	1		*MIRROR BASE	Damaged	967.60 FL	*967.60 FL
27	1		*ADJUSTING MOTOR	Damaged	455.40 FL	*455.40 FL
28	1		*MIRROR GLASS	Cracked	1,465.30 FL	*1,465.30 FL
29	1		*SIDE MIRROR BASE COVER	Cracked	764.10 FL	*764.10 FL
30	1		*LIGHT	Damaged	201.80 FL	*201.80 FL
31	1		*GASKET	Necessary	40.50 FL	*40.50 FL
32	1		*MIRROR BASE	Cracked	36.80 FL	*36.80 FL
33	1		*MIRROR BASE	Cracked	45.70 FL	*45.70 FL
34	1		*GASKET	Necessary	48.70 FL	*48.70 FL
35	1		*MIRROR BASE	Cracked	268.10 FL	*268.10 FL
36	1		*REPAIR KIT	Necessary	22.30 FL	*22.30 FL
37	1		*P991-631-255-05-/INDICATOR LIGHT (LH)	Cut	232.80 FL	*232.80 FL
38	1		*DISC WHEEL BRILLIANT CHROM	Cut	6,925.10 FL	*6,925.10 FL
39	1		*RETAINING STRIP	Necessary	41.00 FL	*41.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	2		*RUBBER PLY	Necessary	35.40 FL	*35.40 FL
41	1		*DOOR WINDOW GLASS	Scratched	262.10 FL	*262.10 FL
42	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					21,576.80	21,473.20
- List Item Discount on L Items 10.00/10.00% (\$\$)					2,147.68	2,142.32
Total Parts (\$\$)					19,429.12	19,330.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE DAMAGED & AFFECTED BODY PARTS, REPLACE AFFECTED BODY PARTS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE	New	8,400.00	6,300.00
2	TO SPRAY PAINT FRT LH FENDER, FRT LH DOOR, LH SIDE SKIRT, WING MIRROR HOUSING LH & AFFECTED PORTIONS	New	4,500.00	4,000.00
3	TO CARRY OUT BODY CAVITY PRESERVATION TO ALL AFFECTED AREAS	New	500.00	0.00
4	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FUNCTION ABILITY INCLUDING PARKING ASSIST SENSORS	New	380.00	250.00
5	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT ACCORDING TO SPECIFICATIONS	New	680.00	680.00
6	TO REMOVE REPLACE REFIT TYRES & RIMS @ \$60/-	New	60.00	60.00
7	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR	New	600.00	600.00
8	TOWING CHARGES	New	300.00	300.00
9	TO REMOVE, REPLACE, REFIT DOORS INCLUDE TRANSFER WINDOW MECHANISM FROM DAMAGE DOOR TO NEW DOOR & CHECK FUNCTION ABILITY	New	1,400.00	700.00
Gross Labour Cost (\$\$)			16,820.00	12,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >