

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
<input type="checkbox"/>	10	1			FRT FOGLAMP COVER LH			Serviceable	0				0
<input type="checkbox"/>	11	1			FRT FOGLAMP CVR CHROM MLDG LH			Serviceable	0				0
<input type="checkbox"/>	12	2			FRT BUMPER SIDE RETAINER			Necessary	0				0
<input type="checkbox"/>	13	1			FRT HEADLAMP LH			Cracked	0				0
<input type="checkbox"/>	14	1			FRT HEADLAMP BALLAST LH			Serviceable	0				0
<input type="checkbox"/>	15	1			FRT HEADLAMP NOZZLE LH			Serviceable	0				0
<input type="checkbox"/>	16	1			FRT HEADLAMP NOZZLE COVER LH			Cut	0				0
<input type="checkbox"/>	17	1			FRT HEADLAMP TOP PANEL (LH)			Serviceable	0				0
<input type="checkbox"/>	18	1			FRT FENDER LH			Buckled	0				0
<input type="checkbox"/>	19	1			FRT FENDER INNERSHIELD (LH FRT)			Deformed	0				0
<input type="checkbox"/>	20	1			FRT FENDER INNERSHIELD (LH REAR)			Deformed	0				0
<input type="checkbox"/>	21	1			FRT FENDER INNERSHIELD COVER LH			Serviceable	0				0
<input type="checkbox"/>	22	10			FRT FENDER INNERSHIELD CLIP			Necessary	0				0

Detailed Assessment

Inspection Date *

12/14/2017



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

215/55R17

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Spare wheel

Rear Tyre Size

215/55R17

FNOL INFORMATI... 11 DAIRY FARM HEIGHTS, 677661,
Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Residential

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Married

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S7064430D

CATEGORY Make

POLICY INFORMAT... VOLKSWAGEN

CATEGORY Date of Birth

ASSESSMENT INFO...

VOLKSWAGEN

FNOL INFORMATI... December 16, 1970

CATEGORY Model

Model

POST SURVEY INF...

POLICY INFORMAT... PASSAT 1.8 TSI

CATEGORY Age

ASSESSMENT INFO...

PASSAT B8 1.8 TFSI AT 3G24JZ

FNOL INFORMATI... 47

CATEGORY Type

Type

POST SURVEY INF...

POLICY INFORMAT...

CATEGORY Occupation

ASSESSMENT INFO...

FNOL INFORMATI... Unknown

CATEGORY Type of Paint

Type of Paint

POST SURVEY INF...

POLICY INFORMAT...

CATEGORY Education Qualification

ASSESSMENT INFO...

FNOL INFORMATI... Other

CATEGORY Chassis No

Chassis No

POST SURVEY INF...

POLICY INFORMAT... WWWZZ3CZGE160744

CATEGORY Driving Experience

Accelerated survey and authorize

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Additional Instructions

excess: Nil

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
--------------	--------------	------------------	-----------------	--------	-------	-------

ONG Birdie	12/14/17 10:25 AM	1170	1170	Open	Share	<input type="button" value="Clone"/>
------------	-------------------	------	------	------	-------	--------------------------------------

Accelerated survey and authorize

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Documents

History

Invoices

Messages

Notes

Assessment

Metrics

excess: Nil

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	
PART INVOICES.pdf	Invoice	Spare Part / Accessories Supplier	LOW Garnet	June 12, 2018
RESURVEY PHOTOS.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	January 16, 2018