

15/5/2018

INS. CASE OWNER:

CC3 / LPC170 23747, Flea3A2

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

15/12/17  
17/12/17(HONG KONG - 63/MS61503274/11/15/16 : DOA 23/1/18)  
SJP 4575D, X

17.5.18

FILE PASS TO TYPST TO PREPARE REPORT.

RECEIVED 17 MAY 2018

RECEIVED 28 JUN 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time: 15/12/17

Sent By: HMK.

FINALIZATION

Date/Time: 3.4.18

Confirm with:

Confirm by: AUK

Repair Cost:

PIP S\$1,998.10

( 3 )

days) Reduction:

59 %

Email

Call

FINAL SETTLEMENT

Date/Time: 28.6.18

Confirm with: GARY

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

15

If NO or B 28, Ass. Lia:

Repair Cost:

W/LH

S\$ 2,157.97

OLD CHANGED LANE.

Loss of Rental (LOR):

S\$ 1,539.16

( 14 )

days) x +109.94

Loss of Use (LOU):

S\$ -

(\$

x

days)

Loss of Income (LOI):

S\$ 560.00

(\$ 40

x 14

days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☒ [Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 4,339.13

Global Sum S\$:

FINAL PAYMENT

Date/Time: 28.6.18

Confirm with: GARY

Email

Call

Payee 1:

S\$ 4,339.13

Name 1:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT  
29/6/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Surveyor **Kalvin**

REF:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop no: \_\_\_\_\_  
 of: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bel. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: **SHP 11915** Regn: **14 Kc 216**  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / 0 / Prime Mover /  
 Truck / Trailer or  
 Make: **Hyundai** **230** cc **1582**  
 Colour: **Silver** A/C 0 / Std / NI / NA  
 Sp Reading: **47858** T Radio: 0 / Std / NI / NA  
 Eng No: \_\_\_\_\_  
 C No: **TMA 281ukHJ 117505**  
 Gen. Cond: Good / 0 / Poor / Burnt  
 Steering: 0 / Jammed / Leaked / Burnt or  
 Brake: 0 / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / 0 A/Rim or  
 Tyre Size: F: **195 / 65R15**  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **Hankook**  
 Front: **7** mm Rear: **7** mm  
 R.Bal: **7** mm L.Bal: **7** mm  
 D.O.A: **12/12/17** D.O.I: **13/12/17**  
 Survey held at: **Pre-Lia**  
 Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or  
**n/s Front**  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time: \_\_\_\_\_ Action / Instruction

P/P: +1998.10 CRED: +2,391.44 59%

**Lamp**  
**P/P**

Date/Time File Pass to: ☐ : Preli. Report  
☐ : Final Report

Date/Time File Return to:

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

18 - 45 - 50

Photo:

Chart:

|  |
|--|
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |

Add Fee: ☐ : Site Insp \$

☐ : Interview \$

☐ : Technician \$

☐ : Weekend \$

Report Format:

Lump Sum / I.B.I: \$



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                                         |                             |                                                                                     |  |
|-------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------------------|-------------------------------------------------------------------------------------|--|
| LONPAC INSURANCE BHD                                                                                                                      |                                                                                         | Ref : CC3/LPC17023747/K1ea3 |                                                                                     |  |
| 300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555                                                                                 |                                                                                         | Date : 14-12-2017           |  |  |
|                                                                                                                                           |                                                                                         | Code : LPC2                 |                                                                                     |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                                         |                             |                                                                                     |  |
| Insured Veh.                                                                                                                              | SJP 4575D                                                                               | Veh. Inspected              | SHD 1191J                                                                           |  |
| Policy No.                                                                                                                                | Z17VP05015394                                                                           | Coverage (\$)               | 0.00                                                                                |  |
| Claim No.                                                                                                                                 | 17/17/17/VP05/020277                                                                    | Excess (\$)                 | 0.00                                                                                |  |
| Assign From                                                                                                                               |                                                                                         | Assign Date                 | 14/12/2017                                                                          |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                                         |                             |                                                                                     |  |
| Make & Model                                                                                                                              |                                                                                         | c.c                         | 0                                                                                   |  |
| Engine No.                                                                                                                                | HIDDEN                                                                                  | Year of Reg.                |                                                                                     |  |
| Chassis No.                                                                                                                               |                                                                                         | Colour                      |                                                                                     |  |
| Odometer                                                                                                                                  | -                                                                                       | Steering                    |                                                                                     |  |
| Brakes                                                                                                                                    |                                                                                         | Modification                |                                                                                     |  |
| General                                                                                                                                   |                                                                                         |                             |                                                                                     |  |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                                         |                             |                                                                                     |  |
|                                                                                                                                           | Size                                                                                    | Make                        | Balance                                                                             |  |
| R/H Front Tyre                                                                                                                            |                                                                                         |                             | mm                                                                                  |  |
| L/H Front Tyre                                                                                                                            |                                                                                         |                             | mm                                                                                  |  |
| R/H Rear Tyre                                                                                                                             |                                                                                         |                             | mm                                                                                  |  |
| L/H Rear Tyre                                                                                                                             |                                                                                         |                             | mm                                                                                  |  |
| <b>4. Description of Damages</b>                                                                                                          |                                                                                         |                             |                                                                                     |  |
|                                                                                                                                           |                                                                                         |                             |                                                                                     |  |
| <b>5. General Information</b>                                                                                                             |                                                                                         |                             |                                                                                     |  |
| Accident Date                                                                                                                             | 12/12/2017                                                                              | Inspection Date             | 13/12/2017                                                                          |  |
| Survey held at                                                                                                                            | PREMIER AUTOMOTIVE SERVICES PTE LTD<br>23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443 |                             |                                                                                     |  |
| <b>5a. Remarks</b>                                                                                                                        |                                                                                         |                             |                                                                                     |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                         |                             |                                                                                     |  |



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA  
Our ref: CC3/LPC17023747/K1ea3

Date: 15.12.2017

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHD 1191J**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 13.12.2017 at the premises of M/s Premier Automotive Services Pte Ltd - Changi have the following to report:-

|                          |       |          |
|--------------------------|-------|----------|
| Workshop Estimate Amount | : S\$ | 4,889.54 |
| Revised Estimate Amount  | : S\$ | 1,998.10 |
| "Check" Items Amount     | : S\$ | 1,872.06 |
| Market Value             | : S\$ | -        |
| LTA Reimbursement Value  | : S\$ | -        |
| Nett Value               | : S\$ | -        |

Description of Damage:  
The vehicle sustained damages at the  
N/S Front Portion



Comments/Present Status:  
Damages Consistent  
Estimated normal period for repairs: 3.0 day

Yours faithfully,

KALVIN ANG  
Licensed Appraiser

## Mei Kwan (LKKAUTO)

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Friday, 15 December, 2017 11:39 AM  
**To:** Mei Kwan (LKKAUTO)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Direct Settlement - Accident Involving SJP4575D (OI : LPC - TBA) AND SHD1191J (TP : LKK REF - CC3/LPC17023747/K1ea3) on 12.12.2017  
**Attachments:** 15122017113512.pdf  
  
**Follow Up Flag:** Follow up  
**Flag Status:** Completed  
  
**Categories:** HMK

Our Ref : 17/17/17/VP05/020277

Dear Mei Kwan,

We attached a copy of insured's GIA report for your attention.

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]  
**Sent:** Friday, 15 December, 2017 11:19 AM  
**To:** MT\_Claim\_SG  
**Cc:** GERALD POH WEE BIN; ONG LI LI; ERIC WOO JUN KIAT; Asher Sng (LKKAUTO); Vic (LKKAUTO); Admin A  
**Subject:** Direct Settlement - Accident Involving SJP4575D (OI : LPC - TBA) AND SHD1191J (TP : LKK REF - CC3/LPC17023747/K1ea3) on 12.12.2017

### WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHD 1191J at M/s Premier Automotive Services Pte Ltd - Changi.

Enclosed for your perusal is:

- TP GIA report
- Estimated cost of repair
- Preliminary Advice
- Photographs of TP vehicle in its damaged condition

|                                                                                                        |                                     |
|--------------------------------------------------------------------------------------------------------|-------------------------------------|
|  <b>PREMIER TAXIS</b> | <b>HIRE / RELIEF / SUPER RELIEF</b> |
| VEHICLE NO.                                                                                            | SHD 1191J                           |
| CONTACT NO                                                                                             | 9113 3108                           |
| NEW MAILING ADDRESS<br>(if any)                                                                        |                                     |

**REPUBLIC OF SINGAPORE**  
IDENTITY CARD NO. S2005241D



Name

NG NGIAP KUI  
@NG YIAK KUI

黄若葵

Race

CHINESE

Date of Birth

30-03-1951

Sex

M

Country of Birth

INDONESIA



**REPUBLIC OF SINGAPORE DRIVING LICENCE**



Licence Number: S2005241D

Name

NG NGIAP KUI

Birth Date: 30 Mar 1951

Issue Date: 07 Feb 2003



1095258



APIC No: S2005241D

Blood Group

B+

Date of issue

08-07-1993

Address

APT BLK 56 CHAI CHEE DRIVE  
#02-140  
SINGAPORE 1646

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

|          |                                                                                          | PASS DATE   |
|----------|------------------------------------------------------------------------------------------|-------------|
| Class 2B | Motorcycles not exceeding 200 cc                                                         | 04 Mar 1977 |
| Class 2A | Motorcycles between 201 cc and 400 cc                                                    | 04 Mar 1977 |
| Class 2  | Motorcycles exceeding 400 cc                                                             | 04 Mar 1977 |
| Class 3  | Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms | 07 Dec 1973 |

NP 428A



**Land Transport Authority**



**VOCATIONAL LICENCE**

Licence No: S2005241D

Name: NG NGIAP KUI

Issue Date: 20/5/2011

Please visit [www.lta.gov.sg](http://www.lta.gov.sg) to check the status of this vocational licence

**Certificate of Insurance**

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

**Certificate Number** : 5095103893

**Cover** : Third Party

1. Index mark and Registration Number of Vehicle

: **SHD1191J**

Chassis Number

: TMAD281UVHJ117505

2. Name of Policyholder

: PREMIER TAXIS PTE. LTD.

3. Effective Date of Insurance

: 20 Oct 2017

4. Expiry Date of Insurance

: 19 Oct 2018

5. Persons or Classes of Persons entitled to drive\*

(a) The Policyholder.

(b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use\*

(a) Use as a Taxi.

(b) Use for social domestic and pleasure purposes.

**This Policy does not cover**

(a) Use for racing, pace-making, reliability trial or speed-testing.

(b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I) : N/A

EXCESS (SECTION II) : S\$3,500

INSURE WITH COE : N/A

HIRE PURCHASE COMPANY : N/A

SUM INSURED : N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)

Date of Issue : 16 Oct 2017 17:13 hrs

**For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED**

**Countersigned By:**



**Authorised Officer**



**Chief Executive**



**Enquire Vehicle Registration Details****Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H  
Owner ID Type: Company  
Owner Name: PREMIER TAXIS PTE. LTD.  
Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443  
Mailing Address: -  
Birth Date: -

**Vehicle Particulars**

Vehicle No.: SHD1191J  
Previous Vehicle No.: -  
Effective Date of Ownership: 14 Dec 2016  
Original Regn Date: 14 Dec 2016  
Registration Date: 14 Dec 2016  
Year of Manufacture: 2016  
Vehicle Type: Public Transport Taxi (Motor Car)  
Vehicle Scheme: Taxi (Company)  
Vehicle Attachment 1: Air-Con (Taxi)  
Vehicle Attachment 2: -  
Vehicle Attachment 3: -  
Vehicle Make: HYUNDAI  
Vehicle Model: I30 GDH 1.6 TCI 5DR DCT  
Primary Colour: Silver  
Secondary Colour: -  
Passenger Capacity: 4  
Chassis No.: TMAD281UVHJ117505  
Engine No.: D4FBGZ088802  
Engine Capacity/Power Rating: 1582 cc / -  
Maximum Power Output: 100.0 kW (134 bhp)  
Propellant: Diesel  
Max Unladen Weight: 1496 kg  
Maximum Laden Weight: 1940 kg  
Open Market Value: S20,105.00  
PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 13 Dec 2024  
Minimum PARF Benefit: S7,588.00  
No. of Transfers: 0  
IU Label No.: 1050694182  
COE No.: 2018121401003878K  
COE Expiry Date: 13 Dec 2024  
COE Category: A - Car (up to 1600cc & 97kW (130bhp))  
COE Registration Category: A - Car (up to 1600cc & 97kW (130bhp))  
Quota Premium (QP) / Prevailing Quota Premium: - / \$51,271.00  
PQP Paid: S41,017.00  
QP (Regn Cat): -  
OPC Cash Rebate Eligibility: No



**Enquire Vehicle Registration Details****Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H  
Owner ID Type: Company  
Owner Name: PREMIER TAXIS PTE. LTD.  
Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443  
Mailing Address: -  
Birth Date: -

**Vehicle Particulars**

Vehicle No.: SHD1191J  
Previous Vehicle No.: -  
Effective Date of Ownership: 14 Dec 2016  
Original Regn Date: 14 Dec 2016  
Registration Date: 14 Dec 2016  
Year of Manufacture: 2016  
Vehicle Type: Public Transport Taxi (Motor Car)  
Vehicle Scheme: Taxi (Company)  
Vehicle Attachment 1: Air-Con (Taxi)  
Vehicle Attachment 2: -  
Vehicle Attachment 3: -  
Vehicle Make: HYUNDAI  
Vehicle Model: I30 GDH 1.6 TCI 5DR DCT  
Primary Colour: Silver  
Secondary Colour: -  
Passenger Capacity: 4  
Chassis No.: TMAD281UVHJ117505  
Engine No.: D4FBGZ088802  
Engine Capacity/Power Rating: 1582 cc / -  
Maximum Power Output: 100.0 kW (134 bhp)  
Propellant: Diesel  
Max Unladen Weight: 1496 kg  
Maximum Laden Weight: 1940 kg  
Open Market Value: S20,105.00  
PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 13 Dec 2024  
Minimum PARF Benefit: S7,588.00  
No. of Transfers: 0  
IU Label No.: 1050694182  
COE No.: 2016121401003878K  
COE Expiry Date: 13 Dec 2024  
COE Category: A - Car (up to 1600cc & 97kW (130bhp))  
COE Registration Category: A - Car (up to 1600cc & 97kW (130bhp))  
Quota Premium (QP) / Prevailing Quota Premium: - / \$51,271.00  
PQP Paid: S41,017.00  
QP (Regn Cat): -  
OPC Cash Rebate Eligibility: No

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

13-Dec-17

## ESTIMATE REPAIR BILL FOR HYUNDAI I30 WAGON REGN NO: SHD 1191 J

|      |                                 |    |          |
|------|---------------------------------|----|----------|
| 1 pc | Front bumper                    | \$ | 811.11   |
| 1 pc | Front bumper n/s side bracket ? | \$ | 32.51    |
| 1 pc | Front n/s fender                | \$ | 514.02   |
| 1 pc | Front n/s fender inner shield x | \$ | 176.72   |
| 1 pc | Front n/s lower arm ?           | \$ | 811.34   |
| 1 pc | Front n/s shock absorber ?      | \$ | 611.56   |
| 1 pc | Front n/s tie rod end ?         | \$ | 72.50    |
| 1 pc | Front n/s stabilizer link ?     | \$ | 88.50    |
| 1 pc | Front n/s ball joint ?          | \$ | 91.90    |
| 1 pc | Front n/s rim ?                 | \$ | 246.00   |
| 1 pc | Front n/s kunckle bearing       | \$ | 385.76   |
|      |                                 | \$ | 3,841.92 |
|      | Less 20%                        | \$ | 768.38   |
|      |                                 | \$ | 3,073.54 |

### S/NETT

|       |                                                                                                                                                         |    |            |
|-------|---------------------------------------------------------------------------------------------------------------------------------------------------------|----|------------|
| 1 set | Front bumper clips                                                                                                                                      | \$ | 48.00      |
| 1 set | Front n/s fender inner shield clips x                                                                                                                   | \$ | 28.00      |
| 1 pc  | Front n/s fender sticker                                                                                                                                | \$ | 30.00      |
|       | Sundry                                                                                                                                                  | \$ | 50.00 20   |
|       | To check for wheel alignment                                                                                                                            | \$ | 60.00      |
|       | To dismantle and replace the front n/s undercarriage                                                                                                    | \$ | 250.00 x   |
|       | To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the front n/s undercarriage | \$ | 700.00 400 |
|       | To putty and spray painting on the front bumper, front n/s fender                                                                                       | \$ | 400.00 360 |
|       | To apply rustproofing on the repaired and replaced panels                                                                                               | \$ | 250.00 20  |
|       | <b>Total</b>                                                                                                                                            | \$ | 4,889.54   |

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal work (e.g. welding) is allowed
- Supplier's warranty (if any) must be resurveyed and is subject to approval from Insurance Company

Signature:

Date:

K. L. L. 16/12/17  
13/12/17 1135hrs  
3 Rm.  
P.P.P.  
Before Paint P.Lto

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

13-Dec-17

## ESTIMATE REPAIR BILL FOR HYUNDAI I30 WAGON REGN NO: SHD 1191 J

|      |                                          |             |
|------|------------------------------------------|-------------|
| 1 pc | Front bumper — <i>Patel</i>              | \$ 811.11   |
| 1 pc | Front bumper n/s side bracket <i>Xm</i>  | \$ 32.51    |
| 1 pc | Front n/s fender — <i>Patel</i>          | \$ 514.02   |
| 1 pc | Front n/s fender inner shield <i>Xsm</i> | \$ 176.72   |
| 1 pc | Front n/s lower arm <i>Xm</i>            | \$ 811.34   |
| 1 pc | Front n/s shock absorber <i>Xm</i>       | \$ 611.56   |
| 1 pc | Front n/s tie rod end <i>Xm</i>          | \$ 72.50    |
| 1 pc | Front n/s stabilizer link <i>Xm</i>      | \$ 88.50    |
| 1 pc | Front n/s ball joint <i>Xm</i>           | \$ 91.90    |
| 1 pc | Front n/s rim <i>Xsm</i>                 | \$ 246.00   |
| 1 pc | Front n/s kunckle bearing <i>Xm</i>      | \$ 385.76   |
|      |                                          | <hr/>       |
|      |                                          | \$ 3,841.92 |
|      | Less 20%                                 | \$ 768.38   |
|      |                                          | <hr/>       |
|      |                                          | \$ 3,073.54 |

### S/NETT

|       |                                               |          |
|-------|-----------------------------------------------|----------|
| 1 set | Front bumper clips — <i>Patel</i>             | \$ 48.00 |
| 1 set | Front n/s fender inner shield clips <i>Xm</i> | \$ 28.00 |
| 1 pc  | Front n/s fender sticker — <i>Patel</i>       | \$ 30.00 |

Sundry *Patel*

To check for wheel alignment

To dismantle and replace the front n/s undercarriage

To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the front n/s undercarriage

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplier (parts & labour) must be resurveyed and is subject to final approval from Insurance Company

Signature:  
Date:

\$ 50.00 *20*

\$ 60.00 *—*

\$ 250.00 *Xm*

\$ 700.00 *400*

To putty and spray painting on the front bumper, front n/s fender

\$ 400.00 *360*

To apply rustproofing on the repaired and replaced panels

\$ 250.00 *20*

Total

\$ 4,889.54

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

*Patel PIP \$1998.10/3 bp*  
*3/4/8*

*K. L. K. K. K.*  
*13/12/17 1135hr*  
*3 bp*  
*PIP*  
*Before Paint P Lto*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                         |                               |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-------------------------------|-------------------------------------------------------------------------------------|
| LONPAC INSURANCE BHD                                                                                                                   |                                                                                         | Ref : CC3/LPC17023747/K1ea3n2 |                                                                                     |
| 300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555                                                                              |                                                                                         | Date : 03-07-2018             |  |
|                                                                                                                                        |                                                                                         | Code : LPC2                   |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                         |                               |                                                                                     |
| Insured Veh.                                                                                                                           | SJP 4575D                                                                               | Veh. Inspected                | SHD 1191J                                                                           |
| Policy No.                                                                                                                             | Z17VP05015394                                                                           | Coverage (\$)                 | 0.00                                                                                |
| Claim No.                                                                                                                              | 17/17/17/VP05/020277                                                                    | Excess (\$)                   | 0.00                                                                                |
| Assign From                                                                                                                            |                                                                                         | Assign Date                   | 13/12/2017                                                                          |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                         |                               |                                                                                     |
| Make & Model                                                                                                                           | HYUNDAI I30                                                                             | c.c                           | 1582                                                                                |
| Engine No.                                                                                                                             | HIDDEN                                                                                  | Year of Reg.                  | 2016                                                                                |
| Chassis No.                                                                                                                            | TMAD281UVHJ117505                                                                       | Colour                        | SILVER                                                                              |
| Odometer                                                                                                                               | 47858                                                                                   | Steering                      | IN ORDER                                                                            |
| Brakes                                                                                                                                 | IN ORDER                                                                                | Modification                  | STANDARD ALLOY RIM                                                                  |
| General                                                                                                                                | FAIR                                                                                    |                               |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                         |                               |                                                                                     |
|                                                                                                                                        | Size                                                                                    | Make                          | Balance                                                                             |
| R/H Front Tyre                                                                                                                         | 195/65 R15                                                                              | HANKOOK                       | 7 mm                                                                                |
| L/H Front Tyre                                                                                                                         | 195/65 R15                                                                              | HANKOOK                       | 7 mm                                                                                |
| R/H Rear Tyre                                                                                                                          | 195/65 R15                                                                              | HANKOOK                       | 7 mm                                                                                |
| L/H Rear Tyre                                                                                                                          | 195/65 R15                                                                              | HANKOOK                       | 7 mm                                                                                |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                         |                               |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S FORNT PORTION.<br>DAMAGES SEE DETAILS.                                                        |                                                                                         |                               |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                         |                               |                                                                                     |
| Accident Date                                                                                                                          | 12/12/2017                                                                              | Inspection Date               | 13/12/2017                                                                          |
| Survey held at                                                                                                                         | PREMIER AUTOMOTIVE SERVICES PTE LTD<br>23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443 |                               |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                         |                               |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                         |                               |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                         |                               |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                         | <b>3 Working Days</b>         |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1191J

| Qty                                | Description of Parts                                                                                                                                        | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                                                                                                                                                             |               |                           |                   |
| 1                                  | FRONT BUMPER                                                                                                                                                | DEFORMED      | 811.11                    | 811.11            |
| 1                                  | FRONT BUMPER N/S SIDE BRACKET                                                                                                                               | SERVICEABLE   | 32.51                     | -                 |
| 1                                  | FRONT N/S FENDER                                                                                                                                            | DENTED        | 514.02                    | 514.02            |
| 1                                  | FRONT N/S FENDER INNER SHIELD                                                                                                                               | SERVICEABLE   | 176.72                    | -                 |
| 1                                  | FRONT N/S LOWER ARM                                                                                                                                         | SERVICEABLE   | 811.34                    | -                 |
| 1                                  | FRONT N/S SHOCK ABSORBER                                                                                                                                    | SERVICEABLE   | 611.56                    | -                 |
| 1                                  | FRONT N/S TIE ROD END                                                                                                                                       | SERVICEABLE   | 72.50                     | -                 |
| 1                                  | FRONT N/S STABILIZER LINK                                                                                                                                   | SERVICEABLE   | 88.50                     | -                 |
| 1                                  | FRONT N/S BALL JOINT                                                                                                                                        | SERVICEABLE   | 91.90                     | -                 |
| 1                                  | FRONT N/S RIM                                                                                                                                               | SERVICEABLE   | 246.00                    | -                 |
| 1                                  | FRONT N/S KNUCKLE BEARING                                                                                                                                   | SERVICEABLE   | 385.76                    | -                 |
|                                    | LESS 20% DISCOUNT                                                                                                                                           |               | -768.38                   | -265.03           |
|                                    |                                                                                                                                                             |               | 3,073.54                  | 1,060.10          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |                                                                                                                                                             |               |                           |                   |
| 1                                  | SET FRONT BUMPER CLIPS (SN)                                                                                                                                 | NECESSARY     | 48.00                     | 48.00             |
| 1                                  | SET FRONT N/S FENDER INNER SHIELD CLIPS (SN)                                                                                                                | NOT NECESSARY | 28.00                     | -                 |
| 1                                  | FRONT N/S FENDER STICKER (SN)                                                                                                                               | NECESSARY     | 30.00                     | 30.00             |
| 1                                  | SUNDRY (SN)                                                                                                                                                 | NECESSARY     | 50.00                     | 20.00             |
|                                    |                                                                                                                                                             |               | 156.00                    | 98.00             |
| <b><u>LABOUR</u></b>               |                                                                                                                                                             |               |                           |                   |
|                                    | TO CHECK FOR WHEEL ALIGNMENT .                                                                                                                              |               | 60.00                     | 60.00             |
|                                    | TO DISMANTLE AND REPLACE THE FRONT N/S UNDERCARRIAGE .                                                                                                      | NOT NECESSARY | 250.00                    | -                 |
|                                    | TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .INCLUDING TO KNOCK - OUT ,STRAIGHTEN ,REPAIR, RESHAPE OF THE FRONT N/S UNDERCARRIAGE . |               | 700.00                    | 400.00            |
|                                    | TO PUTTY AND SPRAY PAINTING ON THE FRONT BUMPER ,FRONT N/S FENDER .                                                                                         |               | 400.00                    | 360.00            |
|                                    | TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.                                                                                                  |               | 250.00                    | 20.00             |
|                                    |                                                                                                                                                             |               | 1,660.00                  | 840.00            |

Report Ref No. CC3/LPC17023747/K1ea3n2



|                             |  |          |          |
|-----------------------------|--|----------|----------|
| GRAND TOTAL                 |  | 4,889.54 | 1,998.10 |
| RECOMMENDED COST OF REPAIRS |  |          | 1,998.10 |

Report Ref No. CC3/LPC17023747/K1ea3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.