

ASS. REC. BY:

REF: CS/FCI 17023762/Kvd3n2 Special Instructions

Surveyor:

CWS

Kenneth

ASSIGNMENT (Office)

From (Person):

Gileen Lee

of

FCI

Date/Time

2:14pm @ 14/12/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGN925A

Insured:

SHD 4208B

at Workshop m/s

BH Auto

Tel:

6559 8944

of

BLK 1 Sin Ming Ind. Est Sec. C # 01-115

Policy No:

Claim No:

D17011501MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/12/17

CA / REV / REP. / REV 24 HRS 'up'

18.12.17

H.O.D. Endorsement:

Date/Time:

2:23pm @ 14/12/17

Person Contacted:

Wen Chen

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SGN925A - X

SHD 4208B - X

20/12/17

Email preli revised to FCI

13/23-01

L1 Pm 816501

Cabin by email

(Recl 1668.07, 50%)

ASS. REC. BY:

REF: POZ/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s BH

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 2014.1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGN 925A Yr Regn: 10.16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS 4/1/17 c.c. 1500Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 24110 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MN TBBABIT 7 8 0027476

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 7 mmL/Bal. 6 mm L/Bal. 7 mmD.O.A. 1.12.17 D.O.I. 18/12/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

NIS 14

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/12 File pass to Customer

RECEIVED 23 FEB 2018

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

Days Of Repair: 4Resurvey No. of Trip: -2) 33p - typist

Report Format :

CWSLump Sum / I.B.I. (\$) 1650/2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S - RS \$

Photos

Others

TOTAL

1305011191



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023752/Kvd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4208B	Veh. Inspected	SGN 925A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17011501MFSH	Excess (\$)	0.00	
Assign From	CWS (EILEEN LEE)	Assign Date	14/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/12/2017	Inspection Date		
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D17011501MFSH
Our ref: CS/FCI17023752/Kvd3

Date : 20/12/2017

The Motor Claims Department
M/s First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SGN 925A


We thank for your instruction on 14/12/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18/12/2017 at the premises of M/s BH AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$3,318.07
Revised Estimate Amount	: S\$2,080.35
"Check" Items Amount	: S\$19.25
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s front portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

Survey Department Check List (Case Handler)

Reference No. : 03/PC17023752/Krd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 23/5/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C

GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	13-12-2017	Our Ref No. D17011501MFSH
Accident Date	11-12-2017	Claim Type. Third Party
Insured Vehicle	SHD4208B	Third Party Vehicle. SGN925A
Survey Location	BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115	
Contact Person.	JACELYN LOH	
Contact No.	65598944/ 0	Fax No. 65153144
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	BH AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231872)



PRI Documents



Close



PRI Header Details

Claim No	D17011501MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & BH AUTO
Workshop Name	BH AUTO SERVICES PTE LTD (Contact Person : JACELYN LOH)	Survey Location & Contact Details	BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-1: Mobile: 0 , Phone: 65598944 , Fax: 65153144 EmailId: JACELYN.LOH@BHAUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD4208B	TP Vehicle No	SGN925A
PRI Recieved Date	14-12-2017 11:36:11 AM	Surveyor Appointed Date	14-12-2017 02:13:24 PM	Surveyor Accept Date	14-12-2017 0.

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	14-12-2017	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 20 December, 2017 9:55 AM
To: 'Claim Workflow System'
Cc: EILEENLEE@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011501MFSH/1, SGN 925A
Attachments: SGN 925A PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SGN 925A
Date of survey: 18/12/2017
Number of days:4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 14 December, 2017 2:26 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011501MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not In workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Thursday, 14 December, 2017 2:13 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; EILEENLEE@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011501MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	2138A

Vehicle Details

Vehicle No.	SGN925A
Vehicle to be Exported	No
Intended De-registration Date	13 Dec 2017
Vehicle Make	NISSAN
Vehicle Model	SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR
Primary Colour	Brown
Manufacturing Year	2016
Engine No.	HR16990082B
Chassis No.	MNTBBAB17Z0027476
Maximum Power Output	85.0 kW (113 bhp)
Open Market Value	\$16,910.00
Original Registration Date	19 Oct 2016
First Registration Date	19 Oct 2016
Transfer Count	1
Actual ARF Paid	\$16,910.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	18 Oct 2026
PARF Rebate Amount	\$12,682.00

Intended COE Rebate Details

COE Expiry Date	18 Oct 2026
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$51,507.00
COE Rebate Amount	\$45,567.00
Total Rebate Amount	\$58,249.00

The information contained herein is correct as at 13 Dec 2017

OK



Username / Email Add

password

Connect [Sign Up New Account](#) [Forgot Password](#)

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2005 SsangYong Musso Double Cab, Manual At \$20.8k



Good Running Condition. CCE
 Till 10 July 2020. Can Extend Till
 2025.
 Direct Owner. [StarAC](#)

PRIME MOTOR & LEASING

(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Sort by Date Posted

20 results/page

11 vehicles

nissan SYLPHY 1.6

Basic Search

Price: Any price
 Fuel: Any fuel
 Category: All categories

Depre: Any depre
 Mileage: Any
 Scheme: All schemes

Reg Date: Any date
 OMV: Any
 Dealer: Any Dealer

Eng Cap: Any
 Gear: Any Gear
 Location: Any

Veh Type: All types
 Past Owners: Any
 Status: Any status

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

**Nissan Sylphy 1.6A Premium**

\$83,800

\$9,100 /yr

04-Apr-2016

1,598 cc

38,000 km

Sedan

Available

Most Popular Nissan Sedan For Your Family. Well Maintained And Fully Serviced With Agent Tan Chong. Still Under 5 Years Warranty Unlimited Mileage By Tan Chong Motor. Beautiful Original Paintwork With...

Henly Enterprises Co

Posted: 09-Dec-2017

Tags: 2016 Nissan Sylphy, 2016 Nissan Sylphy, Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Sylphy, Used Nissan

**Nissan Sylphy 1.6A Premium**

\$84,800

\$8,870 /yr

21-Jul-2016

1,598 cc

12,000 km

Sedan

Available

Graded A by **STP**

Car Serviced And Under Warranty By Agent. STA 120 Points Evaluated Graded A. Up To 90% Loan! Flexible Repayment With Our In-House Financing. Owning A Car Is So Much Easier With Us. View To Believe. Ca...

Universe Motoring

Posted: 01-Dec-2017

Tags: 2016 Nissan Sylphy, 2016 Nissan Sylphy, Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Sylphy, Used Nissan

**Nissan Sylphy 1.6A (OPC)**

\$74,888

\$8,240 /yr

18-Jan-2016

1,598 cc

7,400 km

Sedan

Available

A Signature Series Delivering Utmost Comfort To Both Driver And Passengers. Fully Agent Maintained With Records To Prove. 4 More Free Servicing And Remaining Valid Warranty With Tan Chong Motors. Able...

Posted: 27-Nov-2017

Tags: 2016 Nissan Sylphy, 2016 Nissan Sylphy, Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Sylphy, Used Nissan

**Nissan Sylphy 1.6A Premium**

\$93,800

\$10,370 /yr

07-Mar-2016

1,598 cc

16,000 km

Sedan

Available

Trade In And In House Loans Available! Still Under 5 Years Warranty Unlimited Mileage By Tan Chong Motor. Original Paintwork! Astonishing Red With Grey Interior! Well Maintained Interior And Exterior!...

Quality Motor Trading Enterprise

Posted: 26-Nov-2017

Tags: 2016 Nissan Sylphy, 2016 Nissan Sylphy, Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Sylphy, Used Nissan

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

[Buy Tyres Online!](#)[Latest Special Offers from Tyrepat!](#)**Nissan Sylphy 1.6A Premium**

-

N.A

26-May-2016

1,598 cc

-

Sedan

SOLD

Fully Agent Maintained! Agent Warranty! Car In Original Condition, Paintwork/Leather! Reliable And Fuel Efficient! Accident Free! Flexible Loan Options Available. Please Call The Named Sales Person, R...

Hua Yang Credit Pte Ltd

Posted: 02-Dec-2017

Tags: 2016 Nissan Sylphy, 2016 Nissan Sylphy, Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Sylphy, Used Nissan

**Nissan Sylphy 1.6A**

-

N.A

18-Jan-2016

1,598 cc

-

Sedan

SOLD

Low Mileage, Agent Maintain Unit That Come With Agent Warranty, 100% Accident Free, Nothing To Be Afraid Buying A Pre-Owned Nissan Unit That Certified By Themselves.

Posted: 29-Nov-

2016 Nissan Sylphy, 2016 Nissan Sylphy, Nissan Sylphy, Nissan Sylphy, Nissan, Sylphy, Sylphy, Used

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

Not Authorised
1.31
Recovery by painting

First Capital Insurance Ltd

30 Robinson Road

#16-01 City House

Singapore (068877)

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6507 3848 Fax : 6507 3849

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SGN925A

MODEL : NISSAN SYLPHY

POLICY NO : GA207634/1

CHASSIS NO : MNTBBAB17Z0027476

YEAR OF MANUFACTURE : 2016

DATE / TIME OF ACCIDENT: 13/12/2017 Time: 2115Hrs ALONG JUNCTION OF

THIRD PARTY VEHICLE NO: SHD4469P

Date: 13/12/2017

Page : 1 of 2

SOMERSET RD & GRANGE RD

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Net	Amount
		S\$	S\$	S\$
1	HEADLAMP LH	462.40		462.40 ✓
2	HEADLAMP BRACKET LH	27.50		27.50 X
3	FRONT FENDER LH	672.10		672.10 ✓
4	FRONT FENDER SHIELD LH	101.90		101.90 X
5	FRONT FENDER SIGNAL LAMP LH	42.20		42.20 X
6	FRONT BUMPER	476.50		476.50 ✓
7	FRONT BUMPER SIDE RETAINER LH	21.50		21.50 ✓
8				

Sub-Total: 1,804.10

Less: 30% discount - 541.23

Total Parts after 30% discount: 1,262.87

Special Nett Items

1	Front Bumper Clips	10	4.76	47.60 ✓
2	Front Fender Clips	10	4.76	47.60 X
3	Front Wheel Rim	1		- X
4	Anti-Rust Coating	1	80.00	80.00 301
				175.20

Total Parts: 1,438.07

Labour Charges For RH Side Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	600.00	400
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	800.00	440
3	Provide skill labour to disconnect and check electrical wiring	60.00	20
4	Provide skill labour to remove and replace/refit front left undercarriage.	280.00	X
5	Provide skill labour to check and re-adjust rear wheel alignment	60.00	X
6	Provide skill labour to remove and replace wheel rim with balancing	80.00	X

Total Labour:

1,880.00

Total Parts & Labour:

3,318.07

GST 7%

232.26

Grand Total:

3,550.33

Estimate Repair Duration

4 5 days

ACCIDENT VEHICLE OF : SGN 925A

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: Anthony

Survey attended by:

Name : Kenneth

Company : LKK

Date : 18/12/17

Time : 12pm

Contact No : 96910663

Email : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17023752/Kvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-02-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4208B	Veh. Inspected	SGN 925A	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011501MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	14/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MNTBBAB17Z0027476	Colour	METALLIC GREY	
Odometer	24110	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/60 R16	BRIDGESTONE	7 mm	
L/H Rear Tyre	195/60 R16	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/12/2017	Inspection Date	18/12/2017	
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGN 925A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HEADLAMP LH	CUT	462.40	462.40
1	HEADLAMP BRACKET LH	TO REPAIR SEE LABOUR	27.50	-
1	FRONT FENDER LH	BENT	672.10	672.10
1	FRONT FENDER SHIELD LH	SERVICEABLE	101.90	-
1	FRONT FENDER SIGNAL LAMP LH	SERVICEABLE	42.20	-
1	FRONT BUMPER	BUCKLED	476.50	476.50
1	FRONT BUMPER SIDE RETAINER LH	DISTORTED	21.50	21.50
	LESS 30% DISCOUNT		-541.23	-489.75
			1,262.87	1,142.75
SPECIAL NETT ITEMS				
10	FRONT BUMPER CLIPS @\$4.76 (SN)	NECESSARY	47.60	47.60
10	FRONT FENDER CLIPS @\$4.76 (SN)	NOT NECESSARY	47.60	-
1	FRONT WHEEL RIM (NPA)(SN)	SERVICEABLE	-	-
			95.20	47.60
LABOUR				
	ANTI-RUST COATING.		80.00	30.00
	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS,PANEL BEAT,CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF HEADLAMP BRACKET LH.		600.00	400.00
	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES.		800.00	440.00
	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING.		60.00	20.00
	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE/REFIT FRONT LEFT UNDERCARRIAGE.	NOT NECESSARY	280.00	-
	PROVIDE SKILL LABOUR TO CHECK AND RE-ADJUST REAR WHEEL ALIGNMENT.	NOT NECESSARY	60.00	-

Report Ref No. CS/FCI17023752/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE WHEEL RIM WITH BALANCING.	NOT NECESSARY	80.00	-
			1,960.00	890.00
GRAND TOTAL			3,318.07	2,080.35
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,650.00

Report Ref No. CS/FCI17023752/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.