

2017/2018

ASS: REC BY

REF: CS/MSG17023777 / Ard3⁵²

Special Instruction:

Surveyor:

Adnan

ASSIGNMENT (Office)

From (Person):

Menmen

Fievel Foo

of

MSIG

Date/Time

14/12/17 @ 11:51am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ 3404D

Insured:

GBF 3169Y

at Workshop m/s

T & C Automotive

Tel:

9007 5148

of

1 kaki Bukit Ave 6 # 01-49, 417883

Policy No:

B28864251MKF

Claim No:

540573

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/12/2017

CA / REV / REP. / REV 24 HRS

'wp'

R.O.D. Endorsement:

Date/Time:

1:48pm @ 14/12/17

Person Contacted:

Ah Chye

Vehicle:

IN OUT

Date/Time

Action/Instruction

(✓)

Estimate

SKQ 3404D - NA / MSG17023619 / 24

D.O.A : 12/12/17

GBF 3169Y - NA / MSG17023619 / 24

D.O.A : 12/12/17

28/12/17

pending estimate from repairer.

confirm L / i \$ 3500 @ 6 days (Red: \$: \$ 4848.40, 58%.)

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKQ3404D Yr Regn: 01 / 09Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Jazz C.C. 1497Colour: Grey A/C: Insured / Std / Nil / NASp. Reading: 261519 T. Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/45R16R: 205/45R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Fulker.

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 14/12/12Survey held at Paya ubiDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP ms/g. <u>TP and C</u>

RECEIVED 20 SEP 2018

Date/Time, File Pass to?

1) typid

Date/Time, File Return to?

2) _____

☐ : Preli. Report
☒ : Final Report
Days Of Repair: 6Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ - RS \$

) Photo

) Others

TOTAL

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech Invs (\$☐ Weekend (\$Report Format: TRLump Sum / LB: (\$) 4138 3500

150
10



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17023777/Ard3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 14-12-2017	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 3169Y		Veh. Inspected	SKQ 3404D
Policy No.	B28864251MKF		Coverage (\$)	0.00
Claim No.	540573		Excess (\$)	0.00
Assign From	MERIMEN (FIEVEL FOO)		Assign Date	14/12/2017
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer			Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/12/2017		Inspection Date	14/12/2017
Survey held at	T & C AUTOMOTIVE NO.1 KAKI BUKIT AVENUE 6 #01-71 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est-Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Dec 2017		14 Dec 2017 11:51 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	SINGAPORE GENERAL HOSPITAL PTE LTD , Co. Reg. No.: 198703907Z		[Created by insurer]
Main Claimant:	SH INTEGRATED SERVICES PTE. LTD. , Co. Reg. No.: 200516248Z		
Vehicle Reg. No.:	SKQ3404D	Date of Loss:	12/12/2017 09:00 - :59
Claim Type:	TP / 540573	Policy/Cover Note No.:	B28864251MKF (Comprehensive)
Vehicle Reg. No. (Insured):	GBF3169Y	Policy No. (Claimant):	Coverage: 01/12/2017 - 30/11/2018
		Excess:	
Repairer:	T & C Automotive (HQ) 1 KAKI BUKIT AVE 6,, #01-49, AUTOBAY, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wen Yao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/12/2017]		
Driver/Custodian (Insured):	TAN TOH CHEOW (), NRIC: S1074411C, Tel: +6581251847		
Adj Asg. Remarks:	request Adrian Ling for survey		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

CrossBORDERS LLC

REG/CS/PAY/FA

13 DEC 2017

Advocates & Solicitors | Commissioner for Oaths | Notary Public

Our Ref: AJ.tk.TC (SKQ3404D)
Your Ref: GBF3169Y

13 December 2017

MSIG Insurance (Singapore) Pte Ltd
16 Raffles Quay
#24-01 Hong Leong Building
Singapore 048581
Attn: Motor Claims Department

BY FAX: 6225 7402 ONLY

URGENT

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR
CLAIMANT: SH INTEGRATED SERVICES PTE. LTD.
TRAFFIC ACCIDENT ON 12 DECEMBER 2017 AT 11:15 HRS ALONG JALAN BUKIT
MERAH TOWARDS TELOK BLANGAH ROAD INVOLVING VEHICLES NO. SKQ3404D
& GBF3169Y**

We are instructed by SH Integrated Services Pte. Ltd. to notify you of a road accident on 12 December 2017 at about 11:15 hrs along Jalan Bukit Merah towards Telok Blangah Road involving our clients' vehicle registration number SKQ3404D and vehicle registration number GBF3169Y driven by your insured at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our clients' vehicle has been damaged. Before our clients proceeds to repair the damaged vehicle, please let us know within 2 working days (excluding any intervening Saturday, Sunday and Public Holiday) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our clients shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Venue: T & C Automotive
Address: 1 Kaki Bukit Avenue 6
#01-49 Autobay @ Kaki Bukit
Singapore 417883
Contact: Ah Chye (9007 5148)

Please liaise with the above workshop directly.

Yours faithfully

Amerjeet Singh

Email: corene@crossbordersllc.com /
huiting@crossbordersllc.com

encs

**PLEASE LET US KNOW THE DATE
OF THE PRE-REPAIR INSPECTION**

CONFIDENTIALITY CAUTION
THIS DOCUMENT IS FOR THE ADDRESSEE(S) ONLY AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE
SUBJECT TO LEGAL PRIVILEGE. IF YOU HAVE RECEIVED THIS IN ERROR, PLEASE CONTACT US IMMEDIATELY.

CrossBORDERS LLCA LIMITED LIABILITY CORPORATION, REGISTRATION NUMBER 201305284K
GST REGISTRATION NUMBER 201305284KMAIN OFFICE
133 NEW BRIDGE ROAD
#23-03/04/05
CHINATOWN POINT
SINGAPORE 059413
TEL: 6438 1323
FAX: 6438 2313BRANCH OFFICE
1 JALAN BERSIH
#03-12 NEW WORLD CENTRE
SINGAPORE 209037PLEASE SEND ALL
CORRESPONDENCES TO
THE MAIN OFFICEWE DO NOT ACCEPT
SERVICE BY FAX

Print Sent Message

This mail is associated with :

***SKQ3404D (540573)**
[GBF3169Y]

TP

SH INTEGRATED SERVICES PTE. LTD.
Dec 12 2017 9:00AM
[SINGAPORE GENERAL HOSPITAL PTE LTD]
T & C Automotive

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 28/12/2017 17:01 PM.
To fievel_foo@sg.msg-asia.com
Subject SKQ3404D (540573)

Dear Fievel,

Please be informed that we have inspected the vehicle **SKQ 3404D** on 14/12/2017.

We are pending estimate from repairer.

Thank you.

Regards,
Janice

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/12/2017 14:23
Date Of Accident	12/12/2017 11:15
Exact Location Of Accident	JALAN BUKIT MERAH TOWARDS TELOK BLANGAH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ3404D
Insured/Policyholder	
Name Of Registered Owner	SH INTEGRATED SERVICES PTE. LTD.
Co Reg No	200516248Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62855880

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ-1.5 1.5L MT ABS D/AB HID 2WD 5DR (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPC16S018776
Cover Note Number	

Driver

Name of Driver	CHEA WAI LOONG
NRIC No	S8856979B
Date Of Birth	11/06/1988
Occupation	INDOOR
Date Of Driving Pass	25/03/2010
Driving Experience	7 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92958585
Fax Number	
Contact Number	
Email Address	WAILOONG61@GMAIL.COM

Address	BLK 749 WOODLANDS CIRCLE # 07-608 SINGAPORE
Postcode	730749
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH STATEMENT RECORDED BY JIA MIN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 67415336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF3169Y
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1

Name	CHEA WAI LOONG
------	----------------

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SKQ3404D

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

TAN JUI SIANG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SKQ3404D

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

12/12/17
1.08pm

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Jia Min

Sketch Plan #2

SKETCH PLAN

Vehicle No
A-SKQ3404D
B-6EF3169Y

Telok Blangoh Road

Jln Bukit Merah

Legend

Vehicle A

Bike A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I enter to Telok Blangoh Road from Jalan Bukit Merah and I stopping before white line until road clear. One green commercial van hit back suddenly while I waiting.

We went down to check and exchange particular data to 1 another.

DECLARATION

I/We declare the foregoing particulars are true in every respect. Please be advised that your insurer may have a 14 day clause whereby the claim against your policy must be made within the stipulated timeframe from the date of occurrence. Kindly check your policy for more details.

Policyholder's Signature

Date & Time: 12/12/17

Signature

Driver's Signature

(If driver is not the policyholder)

Date & Time

1.08pm

Reporting Centre Personnel's Signature

Name

NRIC/FIN No.:

Ja Min

DRIVER NRIC & LICENCE Pg. 1

REPUBLIC OF SINGAPORE DRIVING LICENCE S8856979B  CHEA WAI LOONG Birth Date: 11 Jun 1988 Valid Until: 16 Mar 2019 DDZ405842F	REPUBLIC OF SINGAPORE IDENTITY CARD NO. S8856979B  Name: CHEA WAI LOONG 謝 錄 澄 Race: CHINESE Date of birth: 11-06-1988 Sex: M Country/Place of birth: MALAYSIA 9349445
--	---

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES: <table border="1"> <thead> <tr> <th>Class</th> <th>Description</th> <th>Effective Date</th> </tr> </thead> <tbody> <tr> <td>Class 2B</td> <td>Motorcycles <= 200 cc</td> <td>25 Mar 2010</td> </tr> <tr> <td>Class 3</td> <td>Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg</td> <td>25 Mar 2010</td> </tr> </tbody> </table> Licence No: S8856979B NP 428A	Class	Description	Effective Date	Class 2B	Motorcycles <= 200 cc	25 Mar 2010	Class 3	Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg	25 Mar 2010	9349445  NRIC No: S8856979B  Nationality: MALAYSIAN Date of Issue: 31-10-2014 Address: APT BLK 749 WOODLANDS CIRCLE #07-608 SINGAPORE 730749
Class	Description	Effective Date								
Class 2B	Motorcycles <= 200 cc	25 Mar 2010								
Class 3	Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg	25 Mar 2010								

ERGO

CERTIFICATE OF INSURANCE
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1960 (MALAYSIA)

CERTIFICATE NO. DMPC16S018776	C16060875
Type of CI: Private Vehicle	
Cover: Comprehensive	
DO210 DAVERIE AGENCY PTE LTD	
1) Registration No. of Vehicle: SKG3404D	
2) Name of Policyholder: SH INTEGRATED SERVICES PTE LTD	
3) Commencement Date of Insurance: 02/01/2017	
4) Expiry Date of Insurance: 01/01/2018	
5) Persons or Classes of Persons entitled to drive: (1) Any person who is driving on the Policyholder's order or permission	
Excess (Section 1): S\$500.00	
Uninsured Drivers (Section 1): Additional: S\$500.00	
Non-Auto Workshops (Section 1): Additional: S\$300.00	
Windscreen: S\$100.00	
Young & Inexp Drivers (Section 1): S\$3,000.00	
6) Name of Insured/Contingent/ Hire Purchase Owner: NA	
7) Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.	
And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.	
8) Limitations as to Use: (1) Use only for social domestic and pleasure purposes. (2) Use for Policyholder's business. This Policy does not cover: (1) Use for hire or reward, racing, pace-making, reliability trial or speed-testing. (2) Use for the carriage of goods other than samples in connection with any trade or business. (3) Use for any purpose in connection with the Motor Trade.	
Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings (for Items 7 & 8).	

WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Counter-signed by
DAVERIE AGENCY PTE LTD



For and on behalf of
ERGO Insurance Pte. Ltd.



00210/13/12/2016.11.31.39

DAVERIE AGENCY PTE LTD
 BLOCK 238 HOUGANG AVENUE 1
 #02-304 SINGAPORE 530238
 TEL: 6287 2718 FAX: 6287 0818

AUTHORIZED SIGNATURE

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



ESTIMATE

T & C AUTOMOTIVE

NO. 1 KAKI BUKIT AVENUE 6, #01-49 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

Date: 13/12/2017

TP MS16
Janice

Vehicle Number: SKQ3404D

Chassis Number: JHMG885095201627

S/No.	Descriptions	Qty	Unit Price	Amount
1	Parts Rear bumper <i>behind</i>	1	\$440.30	\$440.30 ✓
2	Rear bumper clip <i>new</i>	8	\$5.00	\$40.00 <i>30</i>
3	Rear bumper side retainer RH <i>new</i>	1	\$16.50	\$16.50 ✓
4	Rear bumper side retainer LH <i>new</i>	1	\$16.50	\$16.50 ✓
5	Rear bumper lower pad <i>behind</i>	1	\$115.00	\$115.00 ✓
8	Tow hook cover <i>new</i>	1	\$13.40	\$13.40 ✓
9	Tail lamp RH <i>new</i>	1	\$206.20	\$206.20 ✓
10	Tail lamp LH <i>new</i>	1	\$206.20	\$206.20 ✓
11	Tail lamp panel RH <i>new</i>	1	\$133.70	\$133.70 ✓
12	Tail lamp panel LH <i>new</i>	1	\$133.70	\$133.70 ✓
13	Tail gate <i>new</i>	1	\$771.50	\$771.50 ✓
14	Tail gate garnish <i>new</i>	1	\$110.10	\$110.10 ✓
15	Tail gate absorber <i>new</i>	2	\$136.20	\$272.40 ✓
16	Tail gate hinges <i>new</i>	2	\$31.00	\$62.00 ✓
17	Tail gate wiper motor <i>new</i>	1	\$238.00	\$238.00 ✓
18	Tail gate trim board <i>new</i>	1	\$100.20	\$100.20 ✓
19	Tail gate weatherstrip <i>new</i>	1	\$92.30	\$92.30 ✓
20	Tail gate lock <i>new</i>	1	\$189.50	\$189.50 ✓
21	Tail gate lower catch <i>new</i>	1	\$27.50	\$27.50 ✓
22	Tail gate "Jazz" emblem <i>new</i>	1	\$26.20	\$26.20 ✓
23	Tail gate "H" logo <i>new</i>	1	\$25.00	\$25.00 ✓
24	Rear windscreen moulding <i>new</i>	2	\$36.50	\$73.00 ✓
25	Rear end panel <i>new</i>	1	\$276.50	\$276.50 ✓
26	Rear end panel garnish <i>new</i>	1	\$60.80	\$60.80 ✓
27	Rear end panel garnish clip <i>new</i>	8	\$5.00	\$40.00 <i>10</i>
28	Number plate lamp <i>new</i>	1	\$33.20	\$33.20 ✓
29	Spare tyre panel <i>new</i>	1	\$737.00	\$737.00 ✓
30	Spare tyre foam <i>new</i>	1	\$190.70	\$190.70 ✓
31	Spare tyre tool box <i>new</i>	1	\$114.60	\$114.60 ✓
32	Rear fender LH <i>new</i>	1	repair	repair ✓
33	Rear fender trimboard RH <i>new</i>	1	\$204.30	\$204.30 ✓
34	Rear fender trimboard LH <i>new</i>	1	\$204.30	\$204.30 ✓
35	Trimboard clip <i>new</i>	21	\$5.00	\$105.00 <i>30</i>
36	Exhaust silencer <i>new</i>	1	\$486.50	\$486.50 ✓
37	Exhaust silencer chrome <i>new</i>	1	\$85.90	\$85.90 ✓

\$5,848.00

Less 20%

\$1,169.60

Sub Total 1

\$4,678.40

S/Nett

1	Rear number plate <i>new</i>	1	\$35.00	\$35.00 ✓
2	Rear number plate casing <i>new</i>	1	\$35.00	\$35.00 ✓
3	Sealant <i>new</i>	1	\$80.00	\$80.00 <i>60</i>
4	Reverse sensor (set) <i>new</i>	1	\$260.00	\$260.00 <i>200</i>
Sub-Total 2				\$410.00

S/No.	Descriptions	Qty	Unit Price	Amount
	Labour			
1	Panel beating to remove and replace, to knock and reshape damaged parts.			\$1,200.00 <i>80</i>
2	To putty and spray paint the repaired and replaced parts, cleaning and sanding of surfaces, final polishing and waxing.			\$1,200.00 <i>80</i>
3	Re-wiring.			\$90.00 <i>30</i>
4	Anti-rust undercoat.		<i>1900</i>	\$120.00 <i>40</i>
5	Remove and replace rear exhaust silencer.			\$250.00 <i>x</i>
6	Remove and refit rear windscreen glass.			\$120.00 <i>✓</i>
7	Remove and refit rear wheelhouse inner garnish, floor carpet & upholstery to facilitate repair.			\$280.00 <i>60</i>
			Labour	\$3,260.00
8	To remove reverse sensor	<i>100</i> <i>50</i>		
			Total	\$8,348.40

total 2397.28

4/5 3.5/c

06 days

8448.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Dec 2017		14 Dec 2017 11:51 Edit Adj Rpt	S\$3,500.00 Edit Estimates	S\$3,500.00 View Rpt		Pending for Survey Report Cancel Case

Main		Reference		Claim Details		Documents		Show All
------	--	-----------	--	---------------	--	-----------	--	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SINGAPORE GENERAL HOSPITAL PTE LTD, Co. Reg. No.: 198703907Z		
Main Claimant:	SH INTEGRATED SERVICES PTE. LTD., Co. Reg. No.: 200516248Z		
Vehicle Reg. No.:	SKQ3404D	Date of Loss:	12/12/2017 09:00 - :59 [107 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 540573	Policy/Cover Note No.:	B28864251MKF (Comprehensive) Coverage: 01/12/2017 - 30/11/2018
Vehicle Reg. No. (Insured):	GBF3169Y	Policy No. (Claimant):	
		Excess:	
Repairer:	T & C Automotive (HQ) 1 KAKI BUKIT AVE 6,, #01-49, AUTOBAY, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wen Yao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Imm.Advice due 15/12/2017]		
Driver/Custodian (Insured):	TAN TOH CHEOW (), NRIC: S1074411C, Tel: +6581251847		
Adj Asg. Remarks:	request Adrian Ling for survey		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKQ3404D (540573)**
[GBF3169Y]
TP
SH INTEGRATED SERVICES PTE. LTD.
Dec 12 2017 9:00AM
[SINGAPORE GENERAL HOSPITAL PTE LTD]
T & C Automotive

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/12/17 17:46	Accident Statement From: SC - Reg. No: GBF3169Y, Claimant: SINGAPORE GENERAL HOSPITAL PTE LTD	 Load HTM	☐

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/08/18 17:58	General View	 Load JPG	☒
2	30/08/18 17:58	General View	 Load JPG	☒
3	30/08/18 17:58	General View	 Load JPG	☒
4	30/08/18 17:58	General View	 Load JPG	☒
5	30/08/18 17:58	General View	 Load JPG	☒
6	30/08/18 17:58	General View	 Load JPG	☒
7	30/08/18 17:58	General View	 Load JPG	☒
8	30/08/18 17:58	General View	 Load JPG	☒
9	30/08/18 17:58	General View	 Load JPG	☒
10	30/08/18 17:58	General View	 Load JPG	☒
11	30/08/18 17:58	General View	 Load JPG	☒
12	30/08/18 17:58	General View	 Load JPG	☒
13	30/08/18 17:58	General View	 Load JPG	☒
14	30/08/18 17:58	General View	 Load JPG	☒
15	30/08/18 17:58	General View	 Load JPG	☒
16	30/08/18 17:58	General View	 Load JPG	☒
17	30/08/18 17:58	General View	 Load JPG	☒
18	30/08/18 17:58	General View	 Load JPG	☒
19	30/08/18 17:58	General View	 Load JPG	☒
20	30/08/18 17:58	General View	 Load JPG	☒
21	30/08/18 17:58	General View	 Load JPG	☒
22	30/08/18 17:58	General View	 Load JPG	☒
23	30/08/18 17:58	General View	 Load JPG	☒
24	30/08/18 17:58	General View	 Load JPG	☒
25	30/08/18 17:58	General View	 Load JPG	☒
26	30/08/18 17:58	General View	 Load JPG	☒
27	30/08/18 17:58	General View	 Load JPG	☒
28	30/08/18 17:58	General View	 Load JPG	☒
29	30/08/18 17:58	General View	 Load JPG	☒
30	30/08/18 17:58	General View	 Load JPG	☒
31	30/08/18 17:58	General View	 Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
32	30/08/18 17:58	General View	 Load JPG	✓
33	30/08/18 17:58	General View	 Load JPG	✓
34	30/08/18 17:58	General View	 Load JPG	✓
35	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
36	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
37	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
38	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
39	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
40	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
41	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
42	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
43	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
44	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
45	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
46	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
47	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
48	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
49	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
50	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
51	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
52	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
53	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
54	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
55	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
56	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
57	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
58	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
59	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
60	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
61	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
62	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
63	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
64	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
65	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
66	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
67	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
68	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
69	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
70	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
71	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
72	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
73	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
74	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
75	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
76	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
77	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
78	30/08/18 17:58	Reinspection Photo	 Load JPG	✓
79	30/08/18 17:58	Reinspection Photo	 Load JPG	✓

Assessment Reports			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
Documentation			1 per page ▼	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/12/17 17:46	SKQ3404D E-FILE, DL, IC & CERT OF INS From: SC - Reg. No: GBF3169Y, Claimant: SINGAPORE GENERAL HOSPITAL PTE LTD	 Load PDF	
2	13/12/17 17:52	PRI from Crossborders LLC	 Load PDF	
3	14/12/17 11:52	Survey Agree on SJE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17023777/ARD3S2
Date: 28/09/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B28864251MKF
Claimant Vehicle No: SKQ3404D Insured Vehicle No: GBF3169Y
Date of Loss: 12/12/2017 Nature of Claim: TP Claim No: 540573

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKQ3404D
Make & Model: HONDA JAZZ, 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A) Engine No: L15A71001964
Reg. Date: 02/01/2009 (Man. Year: 2008) Chassis No: JHMGE88509S201627
Colour: Grey Odometer: 261519 km
Engine Capacity: 1497 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45R16 Rear Tyre Size: 205/45R16
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,088.40	2,497.28	2,591.12	50.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,360.00	1,900.00	1,460.00	43.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,448.40	4,397.28	4,051.12	47.95
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	8,448.40	3,500.00	4,948.40	58.57

INSPECTION

Date of Assignment: 14/12/2017
Date Inspected: 14/12/2017 Inspected At: T & C Automotive (HQ)
1 KAKI BUKIT AVE 6., #01-49, AUTOBAY
Singapore 417883
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Sep 2018)

Parts: 144 HONDA JAZZ 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKQ3404D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	440.30 FL	*440.30 FL
2	8		*REAR BUMPER CLIP	Necessary	40.00 FL	*30.00 FL
3	1		*REAR BUMPER SIDE RETAINER RH	Necessary	16.50 FL	*16.50 FL
4	1		*REAR BUMPER SIDE RETAINER LH	Necessary	16.50 FL	*16.50 FL
5	1		*REAR BUMPER LOWER PAD	Deformed	115.00 FL	*115.00 FL
6	1		*TOW HOOK COVER	Not Necessary	13.40 FL	*- FL
7	1		*TAIL LAMP RH	Not Necessary	206.20 FL	*- FL
8	1		*TAIL LAMP LH	Cracked	206.20 FL	*206.20 FL
9	1		*TAIL LAMP PANEL RH	Not Necessary	133.70 FL	*- FL
10	1		*TAIL LAMP PANEL LH	Not Necessary	133.70 FL	*- FL
11	1		*TAIL GATE	Dented	771.50 FL	*771.50 FL
12	1		*TAIL GATE GARNISH	Not Necessary	110.10 FL	*- FL
13	2		*TAIL GATE ABSORBER	Not Necessary	272.40 FL	*- FL
14	2		*TAIL GATE HINGES	Not Necessary	62.00 FL	*- FL
15	1		*TAIL GATE WIPER MOTOR	Cracked	238.00 FL	*238.00 FL
16	1		*TAIL GATE TRIM BOARD	Not Necessary	100.20 FL	*- FL
17	1		*TAIL GATE WETATHERSTRIP	Cut	92.30 FL	*92.30 FL
18	1		*TAIL GATE LOCK	Damaged	189.50 FL	*189.50 FL
19	1		*TAIL GATE LOWER CATCH	Not Necessary	27.50 FL	*- FL
20	1		*TAIL GATE JAZZ EMBLEM	Necessary	26.20 FL	*26.20 FL
21	1		*TAIL GATE H LOGO	Not Necessary	25.00 FL	*- FL
22	2		*REAR WINDSCREEN MOULDING	Necessary	73.00 FL	*73.00 FL
23	1		*REAR END PANEL	Dented	276.50 FL	*276.50 FL
24	1		*REAR END PANEL GARNISH	Deformed	60.80 FL	*60.80 FL
25	8		*REAR END PANEL GARNISH CLIP	Necessary	40.00 FL	*10.00 FL
26	1		*NUMBER PLATE LAMP	Not Necessary	33.20 FL	*- FL
27	1		*SPARE TYRE PANEL	Repair	737.00 FL	*- FL
28	1		*SPARE TYRE FOAM	Not Necessary	190.70 FL	*- FL
29	1		*SPARE TYRE TOOL BOX	Not Necessary	114.60 FL	*- FL
30	1		*REAR FENDER LH (NPA)	Not Necessary	0.00 FL	*- FL
31	1		*REAR FENDER TRIMBOARD LH	Not Necessary	204.30 FL	*- FL
32	1		*REAR FENDER TRIMBOARD LH	Deformed	204.30 FL	*204.30 FL
33	1		*TRIMBOARD CLIP	Necessary	105.00 FL	*30.00 FL
		21pcs				
34	1		*EXHAUST SILENCER	Not Necessary	486.50 FL	*- FL
35	1		*EXHAUST SILENCER CHROME	Not Necessary	85.90 FL	*- FL
36	1		*REAR NUMBER PLATE	Not Necessary	35.00 FS	*- FS
37	1		*REAR NUMBER PLATE CASING	Not Necessary	35.00 FS	*- FS
38	1		*SEALANT	Necessary	80.00 FS	*60.00 FS
39	1		*SET REVERSE SENSOR	Damaged	260.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$) 6,258.00 3,056.60

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 20.00/20.00% (\$\$)					1,169.60	559.32
Total Parts (\$\$)					5,088.40	2,497.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING TO REMOVE AND REPLACE, TO KNOCK AND RESHAPE DAMAGED PARTS.	New	1,200.00	800.00
2	TO PUTTY AND SPRAY PAINT THE REPAIRED AND REPLACED PARTS, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING.	New	1,200.00	800.00
3	RE-WIRING.	New	90.00	30.00
4	ANTI-RUST UNDERCOAT.	New	120.00	40.00
5	REMOVE AND REPLACE REAR EXHAUST SILENCER.	New	250.00	0.00
6	REMOVE AND REFIT REAR WINDSCREEN GLASS.	New	120.00	120.00
7	REMOVE AND REFIT REAR WHEELHOUSE INNER GARNISH, FLOOR CARPET & UPHOLSTERY TO FACILITATE REPAIR.	New	280.00	60.00
8	TO REMOVE REVERSE SENSOR.	New	100.00	50.00
Gross Labour Cost (S\$)			3,360.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >