



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving TPVD KAWASAKI KRRZX150 (FV4606P)

Date of Loss 3 December 2017

Time of Loss 20.45

Loss Description SLN8765H (INSD) C/W FV4606P

Comment

Workshop Details

Total Rebate Amount 0

Nett Loss Amount \$0.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work completion * 298



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	FV4606P	Purchase Date	dd/mm/yyyy
Registration State	SINGAPORE	Registration Date *	01/08/2002
Mileage	41790	Age of Vehicle	15

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2010	2002
Make	MERCEDES	KAWASAKI
Model	E200	KRRZX150

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	BIN SYED HUSSIN SYED MUSA	
Date of Birth	19 May 1992	dd/mm/yy
Age	26	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		▼
Type of Paint		
Chassis No	WDD2120482A188078	KR150KA55675
Engine No	27186030046779	HIDDEN
Engine Capacity		148
Sum Insured	0	0
Market Value	0	0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	▼
Driving Experience	0	
Driver License #		
License Type		▼
License Issue Date		dd/mm/yy 
License Expiration Date		dd/mm/yy 
Address	BLK 134 BEDOK NORTH STREET 2, 460134, Singapore	
Address type	Personal Correspondence	▼

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	
Marital status	Unknown	
Identification #	S9220053A	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

13/12/2017



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

90/80-17

Rear Tyre Size

100/80-17

Front left side

DUNLOP3mm

Rear left side

DUNLOP3mm

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%		Salvage%	
Discount%	10	Settlement%	100

Paint Labour/Material Ratio

Paint Labour Ratio	20	Paint Material Ratio	80
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save

Assessment Details

General & Workshop Details																
Vehicle & Driver Details																
Vehicle Condition																
Taxes & Ratio																
Parts & Labour																
Miscellaneous																
Summary																
Parts																
Add Approve Deny Submit All																
	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			FRONT HEADLAMP			Broken	265		10		238.5	Reviewing	
		2	1			HEADLAMP STAY / BRACKET			Bent	250		10		225	Reviewing	
		3	2			FRONT SIGNAL LAMP			Broken	60		10		108	Reviewing	
		4	1			FRONT COWLING			Cracked	255		10		229.5	Reviewing	
		5	1			AIR INTAKE - 2PCS			Cracked	60		10		54	Reviewing	
		6	1			HANDLE BAR - 2PCS			Bent	65		10		58.5	Reviewing	
		7	1			FRONT MUDGUARD			Cracked	95		10		85.5	Reviewing	
		8	1			SET FORK TUBE			Bent	480		10		432	Reviewing	
		9	1			FORK BRACKET			Bent	165		10		148.5	Reviewing	
		10	1			FRONT RIM			Repair	0	0	0	0	0	Deny	
		11	1			RIM AXLE			Serviceable	0	0	0	0	0	Deny	
		12	1			METER ASSY			Broken	425		10		382.5	Reviewing	
		13	1			VISOR / WINDSHIELD			Cracked	65		10		58.5	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		14	1			FRONT RH FAIRING			Damaged	165		10		148.5	Reviewing	
		15	1			FRONT BRAKE DISC			Serviceable	0	0	0	0	0	Deny	
		16	1			FRONT RH LOWER FAIRING			Cracked	165		10		148.5	Reviewing	
		17	1			BRAKE PEDAL			Bent	75		10		67.5	Reviewing	
		18	1			FOOTREST RH			Broken	40		10		36	Reviewing	
		19	1			FOOTREST BRACKET			Serviceable	0	0	0	0	0	Deny	
		20	1			EXHAUST PIPE			Bent	285		10		256.5	Reviewing	
		21	1			TAIL FAIRING			Damaged	135		10		121.5	Reviewing	
		22	1			REAR SIGNAL			Cracked	75		10		67.5	Reviewing	
		23	1			HEADLAMP STAY HALOGEN			Serviceable	0	0	0	0	0	Deny	
		24	1			TAIL COVER GARNISH			Damaged	185		10		166.5	Reviewing	
		25	1			REAR MUDGUARD			Serviceable	0	0	0	0	0	Deny	
		26	1			TAIL CENTRE COVER			Serviceable	0	0	0	0	0	Deny	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TOWING FEE	40	0	0	Reviewing		

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		2		REMOVE & REPLACE NECESSARY PARTS ALIGN & ETC	250	0	0	Reviewing		
		3		REMOVE & REPLACE FORK TUBE, FORK OIL SEAL, TOP UP OIL, RIM ETC	100	0	0	Reviewing		
		4		SUPPLY BODY DECAL STICKER	100	0	0	Reviewing		
		5		RE-ALIGN FRONT BODY FRAME	150	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	DAYS OF REPAIR : 4 DAYS	Reviewing			
☐		2	FRONT NUMBER PLATE	Reviewing	10	NECESSARY	
☐		3	BULB	Reviewing	15	BROKEN	

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount

\$3,698.00

Claim Amount

\$3,698.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$3,033.00	\$3,033.00
Labour	\$640.00	\$640.00
Miscellaneous	\$25.00	\$25.00

Submit for Review

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

Submit All

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐		1	FINAL LUMP SUM	Reviewing	2950		

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Claim Amount

\$2,950.00

Claim Amount

\$2,950.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Miscellaneous	\$2,950.00	\$2,950.00

Submit for Review