

Surveyor
Merimen

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

MSG

Date/Time: 15/12/17 @ 11:42am

Estimated Cost:

Bill to:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 7598R

Insured:

SLM 9806Y

at Workshop m/s

Pegasus Engineering

Tel:

68681846

of

51 Defu Lane 10, 539216

Policy No:

28795104MCX

Claim No:

546525

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/12/2017

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time:

12:18pm @ 15/12/17

Person Contacted:

Sharon

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLL 7598R -x
	SLM 9806Y -x
20/12/17	Send preli revised by merimen

Surveillance

REF:

14516/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD (TP) WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: 522 7598R
 at Workshop m/s pagosus
 of _____
 Insured: SLM 98054
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: _____ Consistent? : Yes or No
 GLA / PR Seen: 2 Consistent? : Yes or No
 Est. Repairs: 2 days Res.: Yes or No
 Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 522 7598R Yr Regn: 3 17
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: mazda 3 C/C 1496
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 57336 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JM6BN22A8H/0145342
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: _____ R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front 6 mm Rear 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 8/1/17 D.O.I. 19/12/17

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
19/12/17 confirmed f. rel by 01400 with Sam (Red 1896.80, 571)

RECEIVED 20 DEC 2017

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation

Site Inso (\$)

Photos

Other

TOTAL

200
10
210

Add Fee:

☐ : Site Inso (\$)
☐ : Inter/lew (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Report Format :

merimen

Lump Sum / I.B.I. (\$

1400/2

Survey Department Check List (Case Handler)

Reference No.: **CS/MSG/7023819/Urdb**
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form					
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: **VERON** **20/12/17**
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Dec 2017		15 Dec 2017 11:42 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SKYWAY MOTOR PTE LTD, Co. Reg. No.: 199904194N		
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Vehicle Reg. No.:	SLL7598R	Date of Loss:	08/12/2017 14:00 - :59
Claim Type:	TP / 540525	Policy/Cover Note No.:	28795104MCX (Comprehensive) Coverage: 08/08/2017 - 07/08/2018
Vehicle Reg. No. (Insured):	SLM9806Y	Policy No. (Claimant):	
		Excess:	S\$700.00
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/12/2017]		
Adj Asg. Remarks:	CLIENT REQUEST Marcus Chua for survey.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17023819/Uvd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 15-12-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLM 9806Y	Veh. Inspected	SLL 7598R
Policy No.	28795104MCX	Coverage (\$)	0.00
Claim No.	540525	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	15/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	08/12/2017	Inspection Date
Survey held at	51 DEFU LANE 10	
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 20 Dec 2017

Preliminary Advice

Insured Vehicle No	: SLM9806Y	Accident Date	: 08/12/2017
TP Vehicle No	: SLL7598R	Assignment Date	: 15/12/2017
Make	: MAZDA MAZDA5	Est. Duration of Repair	: 2.00
Date of Inspection	: 19/12/2017		
Inspection At	PEGASUS ENGINEERING & TRADING PTE LTD (HQ) 51 DEFU LANE 10 SINGAPORE 539216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,296.80
Revised Amount	:S\$	1,400.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,400.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	7200G

Vehicle Details

Vehicle No.	SLL7598R
Vehicle to be Exported	Yes
Intended De-registration Date	11 Dec 2017
Vehicle Make	MAZDA
Vehicle Model	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour	Grey
Manufacturing Year	2017
Engine No.	P520432696
Chassis No.	JM6BN22A8H0145342
Maximum Power Output	88.0 kW (118 bhp)
Open Market Value	\$14,688.00
Original Registration Date	09 Mar 2017
First Registration Date	09 Mar 2017
Transfer Count	0
Actual ARF Paid	\$9,688.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	08 Mar 2027
PARF Rebate Amount	\$7,266.00

Intended COE Rebate Details

COE Expiry Date	08 Mar 2027
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$48,401.00
COE Rebate Amount	\$38,720.00
Total Rebate Amount	\$45,986.00

The information contained herein is correct as at 11 Dec 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/12/2017 15:31
Date Of Accident	08/12/2017 14:05
Exact Location Of Accident	JUNCTION OF WOODLANDS AVE 4 AND WOODLANDS AVE 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL7598R
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98235248

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA 3 4-DOOR SEDAN 1.5L SP. 6EAT
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	MTGRAB20170457

Driver

Name of Driver	HAMZAH BIN ALIMAN
NRIC No	S1157718J
Date Of Birth	12/11/1956
Occupation	OUTDOOR
Date Of Driving Pass	01/12/1977
Driving Experience	40 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96697173
Fax Number	
Contact Number	
Email Address	HAM3AH.ALIMAN@YAHOO.COM

Address	BLOCK 828 WOODLANDS STREET 81 #01-74
Postcode	730828
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 08.12.2017 at about 1405 hours, I was driving my vehicle (A: SLL7598R) along junction of Woodlands Avenue 4 towards Woodlands Avenue 5. The traffic light was green, I was waiting the clearance at the Woodlands Avenue 5. Out of sudden, I felt an impact from my rear and realized that vehicle (B: SLM9806Y) hit onto the rear portion of my vehicle. Vehicle A: no passenger onboard. Vehicle B: no passenger onboard.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM9806Y
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	FREDDY
NRIC/Passport Number	
Contact Number	90065174
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.


(e) the information so collected under (d) above may be shared / disclosed:

- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.

Reporting Centre Personnel's Signature
Name: Yang Jing
NRIC/FIN No.: 9390752c

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GIA Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Yang Jing
NRIC/FIN No.: 7390752C



Messrs Grab Rentals Pte Ltd

Estimate To Repair Mazda 3 Sedan 1.5
 Vehicle No : SLL7598R
 Chassis No : JM6BN22A8H0145342

Not About
 the photo. Behn/pahy.
 18/12/17
 2 day.
 P/P 1400/2

Third Party Insurer : MSIG
 Insured's Veh No : SLM9806Y
 Date of accident : 08.12.2017

Date 12.12.2017

LKK Marcus
 19/12/17 @ 0915 hrs

Pages : 1 of 1

S/No	Quantity	Description	Unit price	Amount
LIST ITEMS				
1	1 pc	rear bumper 20/ee	\$ 1,075.00	\$ 1,075.00
2	2 ps	rear bumper reflector 11	\$ 55.00	\$ 110.00
3	1 pc	rear bumper tow cover o/s 11	\$ 17.00	\$ 17.00
4	2 ps	rear bumper side retainer 11	\$ 92.00	\$ 184.00
5	2 ps	rear bumper side holder 11	\$ 74.00	\$ 148.00
6	4 ps	rear bumper side holder rivets 11	\$ 6.00	\$ 24.00
7	1 pc	rear bumper reinforcement 11	\$ 538.00	\$ 538.00
8	10 ps	rear bumper clip 11	\$ 5.00	\$ 50.00
				\$ 2,146.00
Less 20%				\$ 429.20
				\$ 1,716.80
SPECIAL NETT ITEMS				
9	1 set	rear bumper parking sensor 11	\$ 450.00	\$ 450.00
				\$ 450.00
LABOUR & MISC. CHARGES				
1		To reinstall of rear bumper parking sensor.	\$ 120.00	\$ 120.00
2		To check electrical lighting concerned.	\$ 60.00	\$ 60.00
3		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 400.00	\$ 400.00
4		Putty and spray painting of the affected portion.	\$ 550.00	\$ 550.00
				\$ 1,130.00
Grand total				\$ 3,296.80

Confirm with Marcus

P/P 1400.00

19/12/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17023819/UVD3N2

Date: 26/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28795104MCX
Claimant Vehicle No :	SLL7598R	Insured Vehicle No :	SLM9806Y
Date of Loss:	08/12/2017	Nature of Claim:	TP
		Claim No:	540525

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL7598R	Engine No:	P520432696
Make & Model:	MAZDA 3, 1.5 SEDAN L SP.6EAT (A)	Chassis No:	JM6BN22A8H0145342
Reg. Date:	09/03/2017 (Man. Year: 2017)	Odometer:	57336 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,166.80	900.00	1,266.80	58.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	500.00	630.00	55.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,296.80	1,400.00	1,896.80	57.53
+ GST 7.00/7.00% (S\$)	230.78	98.00	132.78	57.54
Nett Amount (S\$)	3,527.58	1,498.00	2,029.58	57.53

INSPECTION

Date of Assignment:	15/12/2017	
Date Inspected:	19/12/2017	Inspected At:
		Pegasus Engineering & Trading Pte Ltd (HQ)
		51 DEFU LANE 10
		Singapore 539216

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Dec 2017)
Parts: 143	MAZDA 3 1.5 SEDAN L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL7598R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Deformed	1,075.00 FL	*1,075.00 FL
2	2		*REAR BUMPER REFLECTOR	Not Necessary	110.00 FL	*- FL
3	1		*REAR BUMPER TOW COVER O/S	Not Necessary	17.00 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER	Not Necessary	184.00 FL	*- FL
5	2		*REAR BUMPER SIDE HOLDER	Not Necessary	148.00 FL	*- FL
6	4		*REAR BUMPER SIDE HOLDER RIVETS	Not Necessary	24.00 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Not Necessary	538.00 FL	*- FL
8	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
9	1		*SET REAR BUMPER PARKING SENSOR	Serviceable	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,596.00	1,125.00
- List Item Discount on L Items 20.00/20.00% (S\$)	429.20	225.00
Total Parts (S\$)	2,166.80	900.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	50.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
3	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	400.00	180.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	550.00	250.00
Gross Labour Cost (S\$)			1,130.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >