



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2015 SUBARU FORESTER 2.0 (SKX1302R)

Date of Loss

December 3, 2017

Time of Loss

22.45

Loss Description

SHD1138P (TP) HIT SKX1302R (INSD) INTO REAR

Comment

Workshop Details

Total Rebate Amount

10896

Nett Loss Amount

\$84,104.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

04/11/2018



Days of work completion *

20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SKX1302R

Purchase Date

mm/dd/yyyy



Registration State

SINGAPORE

Registration Date *

11/27/2015



Mileage

30618

Age of Vehicle

2

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2015

ASSESSMENT INFO...

2015

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

NG CHUN KIAT

CATEGORY Make

POLICY INFORMAT... SUBARU

ASSESSMENT INFO... SUBARU

CATEGORY Model

POLICY INFORMAT... FORESTER 2.0

ASSESSMENT INFO... FORESTER 2.0I-L CVT AWD SR

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... JF1SJ5KC5FG059783

POST SURVEY INF...

CATEGORY Date of Birth

FNOL INFORMATI... October 2, 1982

POST SURVEY INF... mm/dd/yyyy



CATEGORY Age

FNOL INFORMATI... 35

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO... JF1SJ5KC5FG059783

CATEGORY Engine No

POLICY INFORMAT... FB20Y089256

ASSESSMENT INFO... FB20Y089256

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1995

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 95000

FNOL INFORMATI... 14

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... mm/dd/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... mm/dd/yyyy

CATEGORY Address

FNOL INFORMATI... 123A DUNBAR WALK, 459430, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Residential

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Married

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

S8230451G

POST SURVEY INF...

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Detailed Assessment

Inspection Date *

12/15/2017



Total Loss

☒ Yes ☐ No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

225/60R17

Condition of Vehicle at time of survey

General condition

Good ▼

Steering (Serviceable)

☐ Yes ☒ No

Footbrake (Serviceable)

☐ Yes ☒ No

Handbrake (Serviceable)

☐ Yes ☒ No

Engine Modification

☐ Yes ☒ No

Pre-accident condition

Good ▼

Tyre Condition

Spare wheel

Rear Tyre Size

225/60R17

Front left side

YOKOHAMA9mm

Rear left side

YOKOHAMA9mm

Front right side

YOKOHAMA9mm

Rear right side

YOKOHAMA9mm

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add Approve Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
☐		1	1			R EXH CUTTER RH			Serviceable	0	0	0	0	0	Deny
☐		2	1			SKIRT COMPL R - END PANEL			Repair	0	0	0	0	0	Deny
☐		3	1			REAR BUMPER ASSY			Buckled	540		20		432	Reviewing
☐		4	1			BRKT SD R RH			Repair	0	0	0	0	0	Deny
☐		5	1			BRKT SD R LH			Repair	0	0	0	0	0	Deny
☐		6	1			BEAM COMPL R EU			Repair	0	0	0	0	0	Deny
☐		7	1			COVER HOOK R			Serviceable	0	0	0	0	0	Deny
☐		8	1			COVER HOOK R			Serviceable	0	0	0	0	0	Deny
☐		9	1			REFLEC AY RH			Cracked	20.4		20		16.32	Reviewing
☐		10	1			LENS & BODY COMPLRFR			Serviceable	0	0	0	0	0	Deny

Labour

Add Approve Deny

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
------	-------	-------------------------	-----------	------------	---------------	-------	-----------------	---------	--------

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		REPLACE / REPAIR REAR BUMPER END PANEL	280	0	0	Reviewing		
		2		RESPRAY REAR BUMPER AND END PANEL	840	0	0	Reviewing		
		3		CHECK LIGHTING AFTER REPAIR	30	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS OF
REPAIR : 3
DAYS

Reviewing



2

SUNDRIES

Reviewing

20

NECESSARY



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$1,618.32

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,150.00	\$1,150.00
Spare Parts	\$448.32	\$448.32
Miscellaneous	\$20.00	\$20.00

Submit for Review