

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

24/12
27/1/2017
Stampd copy
memory



GST REG. NO : M2 - 0020081 - X

ESTIMATE

15 DEC 2017

Estimate No.	: b1 45166	Page No. : 1 of 2
Date Estimated	: 15/12/2017	
Prepared By	: Chua Kee Sin	

- ESTIMATE REPAIR FOR - Seoul Precision Pte Ltd 1 Pemimpin Drive #10-02 One Pemimpin Singapore 576151	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLR156Y	GL97030	12/01/2017	730i	0

DESCRIPTION	VALUE
Replace front bonnet, front bumper and remove attachment etc include knock on accident dent	1700 2,550.00
Spray painting front bumper and bonnet	2102 2,336.00
To replace front PDC sensor wire harness including reset and checks for proper function.	226 266.00
To replace left headlight including program and conduct tests for proper function.	451 531.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
To carry out body cavity preservation. (Per panel).	100 118.00
To supply front emboss number plate.	NN X 83.00
Sundries.	? 150.00
Total Labour 1:	6,211.00

DESCRIPTION	QTY	PRIC	VALUE
ALUMINIUM BONNET	1	2,812.25	2,812.25
GUIDE LH BOTTOM	1	14.65	14.65
GUIDE RH BOTTOM	1	14.65	14.65
GUIDE TOP LH	1	30.50	30.50
GUIDE TOP RH	1	30.50	30.50
ADAPTER LH	1	73.30	73.30
FRT BOTTOM IMPACT ABSORBER	1	65.80	65.80
FRT BUMPER CARRIER	1	783.20	783.20
COVERING LH (M SW CHROM)	1	195.00	195.00
GRILLE AIR INLET LH (M)	1	82.55	82.55
LH SUPPORT FOG LAMP (M)	1	61.05	61.05

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45166
Date Estimated : 15/12/2017
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLR156Y	GL97030	12/01/2017	730i	0

DESCRIPTION	QTY	PRIC	VALUE
IMPACT ABSORBER TOP (M) ?	1	67.75	67.75
FRT BUMPER BOTTOM CARRIER (M) ?	1	430.80	430.80
FRT BUMPER PANEL PRIMED (M PDC/PMA) ? - TV	1	1,760.30	1,760.30
FRT BUMPER TOWING LUG COVER PRIMED ?	1	41.05	41.05
FRT LH GRILLE (BASIS) ?	1	170.65	170.65
EMBLEM GROMMET / AC	2	0.80	1.60
BMW EMBLEM - AC	1	67.80	67.80
LOCK LH ?	1	229.60	229.60
LOCK TOP PART ?	1	70.25	70.25
BOWDEN CABLE ?	1	41.00	41.00
COVERING CROSS MEMBER (ECE) ?	1	33.50	33.50
SEAL ENGINE HOOD FRT ?	1	77.35	77.35
LH HEADLIGHT LED AHL HIGH (ICON LIG - Cut	1	5,320.85	5,320.85
ULTRASONIC SENSOR BLACK ?	4	242.65	970.60
DECOUPING RING PDC TORQUE CONVERTER / AC	4	4.95	19.80

Total Parts : 13,466.35

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 08/1/18 Excess S\$ _____
Surveyor's Name Guo Qiang Sign _____
Surveyor's Tel 82880282 Authorised Yes / No _____
Authorised Date _____ Time _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No
Surveyor's E-mail Guo Qiang@lkkauto.com
No. of Working Days Recommend 5-6

refine paint photos.

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	6,211.00
Parts	:	13,466.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,377.41

Grand Total : 21,054.76

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **