

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E**15 DEC 2017**

Estimate No. : **b1 45166**
Date Estimated : **15/12/2017**
Prepared By : **Chua Kee Sin**

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Seoul Precision Pte Ltd
1 Pemimpin Drive
#10-02 One Pemimpin

Singapore 576151

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLR156Y	GL97030	12/01/2017	730i	0

DESCRIPTIONVALUE

Replace front bonnet, front bumper and remove attachment
etc include knock on accident dent

2,550.00

Spray painting front bumper and bonnet

2,336.00

To replace front PDC sensor wire harness including
reset and checks for proper function.

266.00

To replace left headlight including program
and conduct tests for proper function.

531.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

177.00

To carry out body cavity preservation.
(Per panel).

118.00

To supply front emboss number plate.

83.00

Sundries.

150.00

Total Labour 1: **6,211.00**

DESCRIPTIONQTYPRICVALUE

ALUMINIUM BONNET

1

2,812.25

2,812.25

GUIDE LH BOTTOM

1

14.65

14.65

GUIDE RH BOTTOM

1

14.65

14.65

GUIDE TOP LH

1

30.50

30.50

GUIDE TOP RH

1

30.50

30.50

ADAPTER LH

1

73.30

73.30

FRT BOTTOM IMPACT ABSORBER

1

65.80

65.80

FRT BUMPER CARRIER

1

783.20

783.20

COVERING LH (M SW CHROM)

1

195.00

195.00

GRILLE AIR INLET LH (M)

1

82.55

82.55



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45166
Date Estimated : 15/12/2017
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLR156Y	GL97030	12/01/2017	730i	0

DESCRIPTION	QTY	PRIC	VALUE
IMPACT ABSORBER TOP (M)	1	67.75	67.75
FRT BUMPER BOTTOM CARRIER (M)	1	430.80	430.80
FRT BUMPER PANEL PRIMED (M PDC/PMA)	1	1,760.30	1,760.30
FRT BUMPER TOWING LUG COVER PRIMED	1	41.05	41.05
FRT LH GRILLE (BASIS)	1	170.65	170.65
EMBLEM GROMMET	2	0.80	1.60
BMW EMBLEM	1	67.80	67.80
LOCK LH	1	229.60	229.60
LOCK TOP PART	1	70.25	70.25
BOWDEN CABLE	1	41.00	41.00
COVERING CROSS MEMBER (ECE)	1	33.50	33.50
SEAL ENGINE HOOD FRT	1	77.35	77.35
LH HEADLIGHT LED AHL HIGH (ICON LIG	1	5,320.85	5,320.85
ULTRASONIC SENSOR BLACK	4	242.65	970.60
DECOUPING RING PDC TORQUE CONVERTER	4	4.95	19.80

Total Parts : 13,466.35

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time _____ Excess S\$ _____

Surveyor's Name _____ Sign _____

Surveyor's Tel _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend _____

Labour 1	:	6,211.00
Parts	:	13,466.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,377.41
Grand Total	:	21,054.76