

Surveyor  
Meimien

Kenneth

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

15/12/17 @ 3:11 pm

Estimated Cost:

Bill to:

TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBG 8196E

Insured:

at Workshop m/s

BCC Automotive

Tel:

6552 5588

of

Blk 1, Sin Ming Ind. Est. Sec. C # 01-101, 575 636

Policy No:

DMCVSN1766611700

Claim No:

SNM17D07118C01

Sum Insured

Excess:

\$350-00

Make of Veh:

(Client's Record)

D.O.A.

13/12/2017

CA /  REV / REP. / REV 24 HRS

18/12/17

H.O.D. Endorsement:

Date/Time:

3:34pm @ 15/12/17

Person Contacted:

Cecilia

Vehicle:

IN  OUT

Date/Time	Action/Instruction	Estimate
	GBG 8196E -x	
19/12/17@	4.13pm revert to Chong Boon Sen via Meimien.	
20/12/17@	12.23pm Susan Teo informed C/A via Meimien.	
21/12/17@	9.39am Informed Cecilia C/A to Exs \$350 by email.	
	\$5790.76 email & confirmed (Fed \$2564.54, 31%)	

Sirivatt Kenneth

REF: CTI

ASSIGNMENT

From: \_\_\_\_\_ Date: 18/12/2017

Estimated Cost: \_\_\_\_\_

P / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBG 8196E

at Workshop m/s: BCC Automotive

of BIK 1, Sin Ming Ind. Est. Sec. C#01-101

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \$350.00

(Client's Record)

Make of Veh: \_\_\_\_\_

Veh No: GBG 8196E Yr Regn: 11, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Suzuki Every c.c. 658

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 881 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: DA 17V - 258036

Gen. Cond:  Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi:  Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: \_\_\_\_\_ R: 145/80R12

DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or \_\_\_\_\_

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$63K

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 1-B1 % 3 Val.: Yes or No

CA /  REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Front	Rear
R/Bal. <u>9</u> mm	R/Bal. <u>9</u> mm
L/Bal. <u>9</u> mm	L/Bal. <u>9</u> mm
D.O.A. <u>13/12/17</u>	D.O.I. <u>18/12/17</u>
Survey held at _____	<input checked="" type="checkbox"/>
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or <u>FR N/S</u>	
The U/C / Chassis frame / Body Structure affected due to collision.	

Date / Time	Action / Instruction
<u>19/12</u>	<u>File part to Catherine</u>

RECEIVED 16 APR 2018

Date/Time/ File Pass to?  : Preli. Report

11/14 Mr Ng  : Final Report

Date/Time/ File Return to? \_\_\_\_\_

Report Format: ACEP-OD

Lump Sum / I.B.I. (\$) 5798.76

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:  Site Insp (\$) \_\_\_\_\_

Interview (\$) \_\_\_\_\_

Tech. Invs (\$) \_\_\_\_\_

Weekend (\$) \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Photos: \_\_\_\_\_

Others: \_\_\_\_\_

TOTAL: 020

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Dec 2017		15 Dec 2017 15:11 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	M/S TAN KOK PENG PTE LTD, Co. Reg. No.: 201220180D		
Vehicle Reg. No.:	GBG8196E	Date of Loss:	13/12/2017 16:00 - :59
Claim Type:	OD / SNM17D07118C01	Policy/Cover Note No.:	DMCVSN1766611700 (Comprehensive)
		Excess:	S\$350.00
Repairer:	BCC Automotive Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate, Sector C #01-101, 575636 Sin Ming - Tel: 6552 5588		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/12/2017]		
Driver/Custodian:	YEO ENG KIAK (40 / Male), NRIC: S7776866A, Tel: +6591896601		
Adj Asg. Remarks:	SURVEY REVERT		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17023849/Kqd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 15-12-2017	
		Code : CTI	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	GBG 8196E
Policy No.	DMCVSN1766611700	Coverage (\$)	0.00
Claim No.	SNM17D07118C01	Excess (\$)	350.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	15/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	13/12/2017	Inspection Date	
Survey held at	BCC AUTOMOTIVE PTE LTD BLK 1 SIN MING INDUSTRIAL EST SECTOR C #01-101 SINGAPORE 575636.		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 21 December, 2017 9:39 AM  
**To:** cecilia@bcc.sg  
**Cc:** SUR  
**Subject:** VEHICLE GBG 8196E (DOA: 13/12/2017)

Dear Cecilia,

As spoken with you.

Instructed by our client China Taiping Insurance, please proceed to repair the insured vehicle **GBG 8196E (Excess \$350)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	15 Dec 2017 15:10	<b>Clm Veh Model Changed</b>	(203015) SUZUKI EVERY 660cc PA (DA64V) (M). Reg No: GBG8196E, Policy No: DMCVSN1766611700, Acct Date: 2017/12/13. Claim Type: OD, Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: BCC Automotive Pte Ltd (Sin Ming), Ins.Status => Incoming Claim. Created from SAS:MLHM17164470	[I] Chong Boon Sen
2	15 Dec 2017 15:10	<b>Clm Created</b>		[I] Chong Boon Sen
3	15 Dec 2017 15:11	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ):SURVEY REVERT	[I] Chong Boon Sen
4	15 Dec 2017 15:11	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2017/12/27	[I] Chong Boon Sen
5	15 Dec 2017 15:11	<b>Adj Mandate Set</b>	Approved:0.00.	[I] Chong Boon Sen
6	15 Dec 2017 15:35	<b>Assignment 1st Accessed</b>		[A] Nivitha Govindasamy
7	15 Dec 2017 16:01	<b>Adj Adjuster Assigned</b>	[None] -> KENNETH KONG	[A] Nivitha Govindasamy
8	19 Dec 2017 16:07	<b>Adj Rpt Initiated</b>		[A] SHIAU CHAN
9	19 Dec 2017 16:07	<b>Clm Details Notified</b>		[A] SHIAU CHAN
10	19 Dec 2017 16:10	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2017/12/27	[A] SHIAU CHAN
11	19 Dec 2017 16:13	<b>Adj Mandate Request</b>	Cur.Req:5790.76:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
12	20 Dec 2017 12:23	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2017/12/27	[I] Susan Teo
13	20 Dec 2017 12:23	<b>Adj Mandate Set</b>	Approved:4238.01.	[I] Susan Teo

### ACTIVITY

No record

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1673029	19/12/2017 16:07	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBG8196E		10.70

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chong Boon Sen

Date: 19 Dec 2017

**Preliminary Advice**

Vehicle No	: GBG8196E	Accident Date	: 13/12/2017
Make	: SUZUKI EVERY	Policy No.	: DMCVSN1766611700
Assignment Date	: 15/12/2017	Excess	: S\$350.00
Date of Inspection	: 18/12/2017	Est. Duration of Repair	: 6.00
Inspection At	: BCC AUTOMOTIVE PTE LTD (SIN MING) BLK 1 SIN MING INDUSTRIAL ESTATE, SECTOR C #01-101 SINGAPORE 575636		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,355.30
Revised Amount	:S\$	5,790.76
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,790.76

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	63,000.00
COE / PARF Rebate	:S\$	37,118.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,882.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0180D
Vehicle Details	
Vehicle No.:	GBG8196E
Vehicle to be Exported:	No
Intended De-registration Date:	19 Dec 2017
Vehicle Make:	SUZUKI
Vehicle Model:	EVERY PA 660 AUTO
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	R06A2135434
Chassis No.:	DA17V258036
Maximum Power Output:	-
Open Market Value:	\$12,868.00
Original Registration Date:	13 Nov 2017
First Registration Date:	13 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$644.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Nov 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$37,498.00
COE Rebate Amount:	\$37,118.00
<b>Total Rebate Amount:</b>	<b>\$37,118.00</b>

The information contained herein is correct as at 19 Dec 2017

OK



12/18/2017

E-FILE

Email Address : ENGIJAH@GMAIL.COM  
Address : I PROME ROAD  
Postcode : 523009  
Was driver an employee of the Insured's Company? YES  
If No, Relationship of the Driver with the Insured  
Vehicle Registration Number of Driver's Own Vehicle :  
-  
-  
-  
Insurance Company of Driver's Own Vehicle :  
-  
-  
-

**General Information of the Accident**

Type Of Accident : COLLISION - HEAD TO HEAD  
Weather Conditions : RAINING  
Road Surface : WET  
Other Information  
Was any foreign vehicle involved in this accident? NO  
Was any body injured in the Accident? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (including Driver) : 1

**Details of Police Action**

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of Intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

REFER TO SKETCH PLAN.

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

Vehicle Registration Number : FBF12738

Vehicle Make/Model/Colour

**Details Of Properties**

Name of Driver

NRIC/Passport Number

Contact Number : 96998368

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (including Driver)

**Details of Witness**

Name

Phone Number

Email Address

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 12 Dec 2017, about 6:30pm I was travelling on A77 out Burdell road towards Upper Benmore Road when I was stopping at the junction while checking on my right for on-coming traffic and I wanted to proceed across I thought the traffic was clear. I did not realised there was a motorbike on my left. He was not there when I stopped, <sup>at left</sup> the junction. He reached and went ahead of me probably while I checked on my right side. I hit him when I wanted to proceed to go out the junction. His bike is FB7 1293 S. He reported police ambulance were accessed but no further traffic police came straight after and told me there was no injury. I will not investigate, police asked me to exchange contact and settle my own car.

DECLARATION

I/we declare the following particulars are true to the best of my/our knowledge.

 



Police Officer's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Jenny Liu  
ID No./Phone: 990272784

12/12/2017  
1:25pm

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Officer.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms); which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

10/12/2014  
10:30am

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NIC/Alt ID:

Jenny Lim  
886272704

Licence Number: **S7776866A**  
 Name: **YEO ENG KIAK**  
 Birth Date: 10 Jul 1977  
 Issue Date: 09 Jan 2003

0001180128



REPUBLIC OF SINGAPORE  
 IDENTITY CARD NO. S7776866A



YEO ENG KIAK  
 楊英傑  
 CHINESE  
 10-07-1977 M  
 MALAYSIA

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	09 Jan 2003
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	09 Jan 2003

NP 426A

Licence No. S7776866A




S7776866A



MALAYSIAN  
 01-07-1977

PEOMERDAD  
 SINGAPORE 225 308  
 Licence No. S7776866A

**CERTIFICATE OF INSURANCE**

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)  
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960  
Road Transport Act, 1987 (Malaysia)  
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.	DMCVSN1766611700	Engine No :R06A2135434 Chassis No:DA17V258036
1. Index Mark and Registration Number of Vehicle	GBG8196E	
2. Name of Policy Holder	M/S TAN KOK PENG PTE LTD	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	13 NOVEMBER 2017	EXCESS SECT I .....S\$350.00 EX ON WINDSCREEN .....S\$100.00
4. Date of Expiry of Insurance	12 NOVEMBER 2018	
5. Persons or Classes of Persons entitled to drive *	ANY PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH THEIR PERMISSION.  PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.	
6. Limitations as to use: *	(1) USE IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS. (2) USE FOR THE CARRIAGE OF PASSENGERS (OTHER THAN FOR HIRE OR REWARD) IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS. (3) USE FOR SOCIAL, DOMESTIC OR PLEASURE PURPOSES. THE POLICY DOES NOT COVER. (1) USE FOR HIRE OR REWARD OR RACING, FACE-MAKING, RELIABILITY TRIAL OR SPEED TESTING. (2) USE WHILST DRAWING A TRAILER EXCEPT THE TOWING OF ANY ONE DISABLED MECHANICALLY PROPELLED VEHICLE.	

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

**I/We hereby Certify** that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).  
Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Countersigned By: Vitesse Solutions  
Authorised Officer

  
Authorised Signatory



# BCC AUTOMOTIVE PTE LTD

BLK 1 SIN MING IND. ESTATE  
 SECTOR C #101/103/105/107/109  
 SINGAPORE 575636  
 Tel: +65 6552 5588 Fax: +65 6552 7750  
 Email: enquiry@bcc.sg Website: www.bcc.sg

# QUOTATION

Company / GST Reg No : 200507063Z

Quotation No : **SMQ5395**

Quotation Date : **2017-12-14**

Vehicle Reg No : GBG8196E  
 Name : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
 Address : NA  
 Contact No : na  
 Email : na

Make & Model : SUZUKI - EVERY PA 660 AUTO  
 Chassis No : DA17V258036  
 Mileage : 880 KM  
 Officer-In-Charge : CHRIS  
 Page : 1 of 1

No	Description	Unit Price	Qty	Amount
1	FRONT BUMPER	770.30	1.00	770.30
2	FRONT BUMPER RETAINER LH	25.00	1.00	25.00
3	FRONT BUMPER RETAINER RH	25.00	1.00	25.00
4	FRONT BONNET	650.00	1.00	650.00
5	FRONT BONNET HINGE	70.00	1.00	70.00
6	A PILLAR (FRONT LH SIDE PANEL)	600.00	1.00	600.00
7	FRONT LH DOOR	1765.00	1.00	1,765.00
8	FRONT LH FENDER	500.00	1.00	500.00
9	FRONT LH WIPER PANEL BRACKET	70.00	1.00	70.00
10	FRONT LH FENDER SHIELD (WINDSHIELD)	75.00	1.00	75.00
11	HEADLAMP LH	600.00	1.00	600.00
12	HEADLAMP BRACKET LH	125.00	1.00	125.00
13	CLIPS	5.00	10.00	50.00
14	COMPANY STICKERS	80.00	1.00	80.00
15	TO SPRAY PAINT AT THE AFFECTED AREA	1400.00	1.00	1,400.00
16	TO PANEL BEAT AFFECTED AREA	1200.00	1.00	1,200.00
17	TO TRANSFER DOOR GLASS, WIRE HARNESS, DOOR LOCK	200.00	1.00	200.00
18	TO CHECK FRONT WIRING FUNCTIONALITY.	150.00	1.00	150.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Not Authorized  
 1-B-1  
 Missing B4 paint  
 Ex \$3500  
 85790-76  
 164162564315

Sub-Total : 8,355.30  
 Add GST 7% : 584.87  
**Estimated Total Amt (SGD) : 8,940.17**

**NOTE:**  
 1. This quotation is only the estimated cost of repair. Any additional works and parts be required during the course of repair, a supplementary quote will be submitted.  
 2. If you decide to terminate the repair after our diagnosis, a diagnostic fee will apply according to the job performed.

**CUSTOMER'S AUTHORISATION**  
 I agree to this quotation and hereby authorize to proceed with the above listed repairs.  
 CUSTOMER'S SIGNATURE \_\_\_\_\_  
 (& Co's Stamp, WHERE NECESSARY)

## LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI17023849/KQD3N2

**Date:** 17/04/2018

#### REFERENCE

<b>Insured/Claimant:</b>	M/S TAN KOK PENG PTE LTD	<b>Policy No:</b>	DMCVSN1766611700	<b>Claim No:</b>	SNM17D07118C01
<b>Date of Loss:</b>	13/12/2017	<b>Nature of Claim:</b>	OD		

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	GBG8196E	<b>Engine No:</b>	R06A2135434
<b>Make &amp; Model:</b>	SUZUKI EVERY, 660cc PA (DA64V) (M)	<b>Chassis No:</b>	DA17V258036
<b>Reg. Date:</b>	13/11/2017 (Man. Year: 2017)	<b>Odometer:</b>	881 km
<b>Colour:</b>	Silver		
<b>Engine Capacity:</b>	658 cc		
<b>Market Value/New Car Price:</b>	S\$63,000.00		
<b>Sum Insured (S\$):</b>	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

<b>General Condition:</b>	<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	Yes	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>

#### CONDITION OF TYRES

<b>Front Tyre Size:</b>	145/80 R12	<b>Rear Tyre Size:</b>	145/80 R12
<b>Front Left Side:</b>	Bridgestone 9 mm	<b>Rear Left Side:</b>	Bridgestone 9 mm
<b>Front Right Side:</b>	Bridgestone 9 mm	<b>Rear Right Side:</b>	Bridgestone 9 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,405.30	3,960.75	1,444.55	26.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,830.00	1,120.00	37.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,355.30</b>	<b>5,790.75</b>	<b>2,564.55</b>	<b>30.69</b>
<b>- Excess (S\$)</b>	<b>350.00</b>	<b>350.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>8,005.30</b>	<b>5,440.75</b>	<b>2,564.55</b>	<b>32.04</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>560.37</b>	<b>380.85</b>	<b>179.52</b>	<b>32.04</b>
<b>Nett Amount (S\$)</b>	<b>8,565.67</b>	<b>5,821.60</b>	<b>2,744.07</b>	<b>32.04</b>

#### INSPECTION

**Date of Assignment:** 15/12/2017

**Date Inspected:** 18/12/2017 **Inspected At:**

BCC Automotive Pte Ltd (Sin Ming)  
Blk 1 Sin Ming Industrial Estate, Sector  
C #01-101  
Singapore 575636

**Estimated Period of Repair:** 6.0 days

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



Different 1 cents-Finalise amount: \$5,790.76

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b>	(Last Synchronised: 17 Apr 2018)
<b>Parts:</b>	N/A SUZUKI EVERY 660cc PA (DA64V) (M) (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBG8196E)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	770.30 F	*770.30 FL
2	1		*FRONT BUMPER RETAINER LH	Distorted	25.00 F	*25.00 FL
3	1		*FRONT BUMPER RETAINER RH	Serviceable	25.00 F	*- FL
4	1		*FRONT BONNET	Bent	650.00 F	*650.00 FL
5	1		*FRONT BONNET HINGE	Repair	70.00 F	*- FL
6	1		*A PILLAR (FRONT LH SIDE PANEL)	Repair	600.00 F	*- FL
7	1		*FRONT LH DOOR	Dented	1,765.00 F	*1,765.00 FL
8	1		*FRONT LH FENDER	Bent	500.00 F	*500.00 FL
9	1		*FRONT LH WIPER PANEL BRACKET	Cracked	70.00 F	*70.00 FL
10	1		*FRONT LH FENDER SHIELD (WINDSHIELD)	Distorted	75.00 F	*75.00 FL
11	1		*HEADLAMP LH	Broken	600.00 F	*600.00 FL
12	1		*HEADLAMP BRACKET LH	Bent	125.00 F	*125.00 FL
13	10		*CLIPS	Necessary	50.00 F	*50.00 FL
14	1		*COMPANY STICKERS	Necessary	80.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,405.30</b>	<b>4,655.30</b>
- List Item Discount on L Items 0.00/15.00% (\$\$)	0.00	694.55
<b>Total Parts (\$\$)</b>	<b>5,405.30</b>	<b>3,960.75</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO SPRAY PAINT AT THE AFFECTED AREA	New	1,400.00	1,000.00
2	TO PANEL BEAT AFFECTED AREA	New	1,200.00	750.00
3	TO TRANSFER DOOR GLASS,WIRE HARNESS,DOOR LOCK	New	200.00	60.00
4	TO CHECK FRONT WIRING FUNCTIONALITY	New	150.00	20.00
<b>Gross Labour Cost (S\$)</b>			<b>2,950.00</b>	<b>1,830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >