

22/03/2002

ASS. REC. BY:

REF

(33/CTI17023871 / Mld3er)

Special Instruction:

merge &amp; durs

Supervisor:

Munnen

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

16/12/2017 @ 4:39pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKE 2149K

Insured:

SJF 6184M

at Workshop m/s

Celebrity Auto

Tel:

9022 2411

of

Blk 7 Sin Ming Sec C # 01-82, 5756 42

Policy No:

DMHCSN1715361700

Claim No:

SNM17007100 C02/4

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/12/2017

CA / REV / REP. / REV 24 HRS

'wp'

18/12/17

Blk 176 Sin Ming Drive #03-12/17

H.O.D. Endorsement:

Date/Time:

5:15pm @ 15/12/17

Person Contacted:

Lashley

Vehicle

IN/OUT

Date/Time	Action/Instruction	Estimate
	SKE 2149K - X	
	SJF 6184M - CS / LTP10020759 / Kfg	D.O.A: 13/12/2010

Surveyor

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKE2147K Yr Regn: \_\_\_\_\_  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: LEXUS C.C. 2500  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp.Reading: Black T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
 C/No: JTBK262105681390  
 Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Mic MIC  
 R: 245/45/27 DUN

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 8 mm R/Bal. 8 mm  
 L/Bal. 8 mm L/Bal. 8 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 6/12/2017

Survey held at Celebrity C 2.4pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No Document upon Survey.

2500-2800/-

-4 w days

Date/Time. File Pass to?

☐

: Preli. Report

1) 15 03 2018

☐

: Final Report

Date/Time. File Return to?

2) \_\_\_\_\_

Days Of Repair:

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

TOTAL

150

150



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI17023871/M1d3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 15-12-2017



Code : CTI

## 1. Policy Particulars :: (THIRD PARTY CLAIM)

Insured Veh.	SJF 6184M	Veh. Inspected	SKE 2149K
Policy No.	DMHCSN1715301700	Coverage (\$)	0.00
Claim No.	SNM17D07100C02/4	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	15/12/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	12/12/2017	Inspection Date	18/12/2017
Survey held at	BLK 176 SING MING DRIVE #03-12/17		
Repairer	CELEBRITY AUTO		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Dec 2017		15 Dec 2017 16:39 <a href="#">Assign</a>				<a href="#">New Assignment</a> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	OWESOME, Co. Reg. No.: 53324878K			[Created by insurer]
Main Claimant:	LEE ZHI KHIN, ID: S8000922D			
Vehicle Reg. No.:	SKE2149K	Date of Loss:	12/12/2017 15:00 - :59	
Claim Type:	TP / SNM17D07100C02/4	Policy/Cover Note No.:	DMHCSN1715301700 (Comprehensive)	
Vehicle Reg. No. (Insured):	SJF6184M	Policy No. (Claimant):	5082805628-01	
		Excess:	\$0.00	
Repairer:	Celebrity Auto (HQ) Blk 7 Sin Ming SECTOR C, #01-82, 575642 Sin Ming - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]			
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/12/2017]			
Driver/Custodian (Insured):	PHILIP YEE CHEUNG WAI (66 / Male), NRIC: S2000979I, Tel: +6590910099			
Adj Asg. Remarks:	NO ESTIMATES, ASSIGNED AS SJE FOR WP PRS			

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

### ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

**(1) Office Assign Form**

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

**(2) System - (Views/Merimen)**

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

**(3) Workshop Estimate/Assignment Form**

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days


**(4) System - (Views/Merimen)**

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

\*C: Critical \*N: Non-Critical

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Dec 2017		15 Dec 2017 16:39 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------















CLAIM SUBFOLDER DETAILS			[Created by Insurer]						
Insured:	OWESOME, Co. Reg. No.: 53324878K								
Main Claimant:	LEE ZHI KHIN, ID: S8000922D								
Vehicle Reg. No.:	SKE2149K	Date of Loss:	12/12/2017 15:00 - :59						
Claim Type:	TP / SNM17D07100C02/4	Policy/Cover Note No.:	DMHCSN1715301700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJF6184M	Policy No. (Claimant):	5082805628-01						
		Excess:	S\$0.00						
Repairer:	Celebrity Auto (HQ) Blk 7 Sin Ming SECTOR C, #01-82, 575642 Sin Ming - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 27/12/2017]								
Driver/Custodian (Insured):	PHILIP YEE CHEUNG WAI (66 / Male), NRIC: S2000979I, Tel: +6590910099								
Adj Asg. Remarks:	NO ESTIMATES. ASSIGNED AS SJE FOR WP PRS								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a> <a href="#">Compose Case Mail</a>						
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <input type="checkbox"/>			<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKE2149K (SNM17D07100C02/4)  
[SJF6184M]  
TP  
LEE ZHI KHIN  
Dec 12 2017 3:00PM  
[OWESOME]  
Celebrity Auto




Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	13/12/17 16:18	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	13/12/17 16:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	13/12/17 16:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	13/12/17 16:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	13/12/17 16:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	13/12/17 16:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	13/12/17 16:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	13/12/17 16:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	13/12/17 16:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	13/12/17 16:16	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/12/17 16:40	OI GIA REPORT	 Load PDF	
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	13/12/17 16:16	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	13/12/17 16:16	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/03/18 17:58	LKKPhotosIn6-1	 Load PDF	

## Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	13/12/17 16:18	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	13/12/17 16:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	13/12/17 16:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

3	13/12/17 16:16	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	13/12/17 16:16	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	13/12/17 16:16	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	13/12/17 16:16	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
7	13/12/17 16:16	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
8	13/12/17 16:16	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
9	13/12/17 16:16	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	13/12/17 16:16	Sketch Plan	1	Load TIF	
2	13/12/17 16:16	Sketch Plan #2	1	Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> <div style="text-align: right; margin-top: 5px;"> <span>^</span>  <span>v</span> </div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI17023871/M1D3E2

Date: 19/03/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMHCSN1715301700

Claimant Vehicle  
No: SKE2149KInsured Vehicle  
No: SJF6184M

Date of Loss: 12/12/2017

Nature of Claim: TP

Claim  
No: SNM17D07100C02/4

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKE2149K

Make &amp; Model: LEXUS IS, 250 LUXURY (A)

Engine No: 4GR0499275

Reg. Date: 18/07/2008 (Man. Year: 2008)

Chassis No: JTHBK262105081390

Colour: Black

Odometer: 137265 km

Engine Capacity: 2500 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	245/45 R17	Rear Tyre Size:	245/45 R17
Front Left Side:	Michelin 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 15/12/2017

Date Inspected: 18/12/2017 Inspected At:

Celebrity Auto (HQ)  
Blk 7 Sin Ming SECTOR C, #01-82  
Singapore 575642

Estimated Period of Repair: 4.0 days

Adjuster: MA CHIN FOOK

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 -\$2,800.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 19 Mar 2018)  
**Parts:** 143      LEXUS IS 250 LUXURY (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SKE2149K)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >