

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

# **SMRT Accident Vehicle Repair Estimates**

MS16

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Rea. No

SHC4919M

Ref. No

TAX/12/17/2077

Reg. Date

06/11/2015

Vehicle Type

: TAXI

Make

TOYOTA PRIUS

Model

**PRIUS** 

Name of Driver

: YOGENDRAN S/O SINGARAVELU

Type of Accident

: HEAD TO SIDE

Date / Time of Accident

: 13/12/2017 05:52:00 PM

Accident Reported Date / Time: 14/12/2017 12:00:00 AM

Surveyor is Required?

Yes

Survey by

Vehicle is Towed Back?

No

Towed Back Date/Time

Replacement Vehicle issued? :

Accident Repair Job Card No : 000024093603

Special Instruction to ARC, if any :

DROVE IN /SJL1324C - MSIG - LKK

Prepared Date

: 14/12/2017 10:48:24 AM





LKK Auto Consultants hence notify the Repairer of the following: To display damaged part(s) during resurve; · Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" t No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from insurance Comp Acknowledged by Recal Signature: Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: JTDKN36U405766676 Mileage 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC Adjusted by Surveyor, if applicable

845.00 0.00 Total Labout Charges Total Spray Painting Charges : 1,314.00 0.00

**Total Material Charges** 3,081.46 3,081.46 Other Charges 945.00 0.00

TOTAL 6,185.46 0.00 : **Lum Sum Total** 0.00 0.00 0.00 No. of Repair Days 5.00 4 days. Prepared / Adjusted By

: 14/12/2017 01:36:46 PM

Arc / Surveyor Sing Off Date 01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks

Prepared Date : 14/12/2017 01:36:46 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No Invoice No

Quotation Date : Invoice Date : Invoice Amount : Prepared Date:

TAX/12/17/2077 Page: 2

## Section D - Details of Repair Estimates

#### Part 1 - Labour Works

70.00 /
0.00
1

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	378.00	0.00 200
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00. 100
TO RESPRAY REAR DOOR RH	378.00	0.00 200
TO RESPRAY REAR FENDER RH	378.00	0.00 200
Total Spray Painting & Panel Beating	1,314.00	0.00

## Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 ×
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO TRANSFER DOOR MECHANISM	240.00	0.00 ×
TO REMOVE / REFIT SEAT	120.00	0.00 ×
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00 ×
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00 🗶
TO WASH AND VACUUM	60.00	0.00 ×
Total Other Costs	945.00	0.00

TAX/12/17/2077 Page:

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommer d	Surveyor Approved	Photos Attached
67001- 47070		6505528	DOOR FRT/RH	1	894.40	30.00	626.08	Replace	Replace R	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No
75851- 47900			MOULDING BODY, RH	1	673.60	30.00	471.52	Replace	Replace	No
67003- 47080		6505486	DOOR RR/RH	1	954.50	30.00	668.15	Replace	Replace R	No
			PIXEL STICKER	1	60.00	0.00	60.00	Replace	Replace /	No
61604- 47090			FENDER RR/RH	1	766.80	30.00	536.76	Replace	Replace	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
62710- 47130			QUARTER GLASS RR/RH	-1	846.50	30.00	592.55	Replace	Replace	No
	COMMO N		SEALANT W/SCREEN	-1	37.00	0.00	37.00	Replace	Replace	No
TOTAL MATERIALS								3,081.46	3,081.46	
TOTAL MATERIALS(Discounted)									3,081.46	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	ty List Price	Discount (%)	Final Price	ARC Check	Surveyor	LT Check
TOTAL SUPPLEMENTARY MATERIALS								CHECK	Crieck