

ASS. REC. BY:

REF: CS/FCI 17023897 / Krd302 Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Joanne Yong of FCIDate/Time: 10:18 am @ 18/12/17

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJL 6684E Insured: SHD 3157Xat Workshop m/s Alan's United Auto Tel: 64538686of Blk 7 Sin Ming Ind. Est. # 01-76Policy No: _____ Claim No: D17011549MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 14/12/17
(Client's Record)

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement: _____

Date/Time: 10:24 am @ 18/12/17 Person Contacted: Kenny Vehicle IN/OUT

Date/Time	Action/Instruction
	(✓) Estimate
	SJL 6684E - x
	SHD 3157X - CS/RST12020897 / H19k3 D.O.A: 25/10/2012
	Sent prel' to Joanne

ASS. REC. BY:

REF: 1621Kenneth**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Alan's

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STL 6684 E Yr Regn: 12, 08Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic c.c. 1900Colour: A. Black A/C: Insured / Std / NI / NASp. Reading: 256343 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 15D2 . 1404776Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/40R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 5 mmL/Bal. 5 mmD.O.A. 14/12/17

Rear

R/Bal. 4 mmL/Bal. 4 mmD.O.I. 18/12/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
19/12	File parts to Corbourn
	11 Dec 8363a email
	ad: 2256.48, 38%

RECEIVED 22 DEC 20

Date/Time, File Pass to?

☐ : Prel. Report1) typist☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5Resurvey No. of Trip: -Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format: TPLump Sum / T.B.I. (\$) 3650

100
50
23
273

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	15-12-2017	Our Ref No.	D17011549MFSH
Accident Date	14-12-2017	Claim Type.	Third Party
Insured Vehicle	SHD3157X	Third Party Vehicle.	SJL6684E
Survey Location	BLK 7 SIN MING INDUSTRIAL ESTATE #01-76		
Contact Person.	KENNY		
Contact No.	64538686/ 0	Fax No.	0
Survey Type	WITHOUT PREJUDICE:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ALAN'S UNITED AUTO PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	JOANNEY		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231941)



PRI Documents



Close



PRI Header Details

Claim No	D17011549MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & ALAN'S U
Workshop Name	ALAN'S UNITED AUTO PTE LTD (Contact Person : KENNY)	Survey Location & Contact Details	BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 Mobile: 0 , Phone: 64538686 , Fax: 0 EmailId: KENNYCHAN@ALANUTD.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD3157X	TP Vehicle No	SJL6684E
PRI Recieved Date	15-12-2017 04:20:18 PM	Surveyor Appointed Date	18-12-2017 10:17:31 AM	Surveyor Accept Date	18-12-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	18-12-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17023897/Krd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 18-12-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3157X	Veh. Inspected	SJL 6684E
Policy No.		Coverage (\$)	0.00
Claim No.	D17011549MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	18/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	14/12/2017	Inspection Date	18/12/2017
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011549MFSH

Our Ref: CS/FCI17023897/Krd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJL 6684E .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18/12/2017 at the premises of M/s ALAN'S UNITED AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 5,906.48 .
Revised Estimate Amount	: S\$ 4,592.12 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the o/s body.



Yours faithfully

KENNETH
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/12/2017 16:32
Date Of Accident	14/12/2017 17:40
Exact Location Of Accident	ALONG IN FRONT OF BLK 372 TAMPINES STREET 34
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL6684E
Insured/Policyholder	
Name Of Registered Owner	MOHAMMED MAZLAN BIN ABDUL AZIZ
NRIC No	S8131213C
Email Address	TOTALFOOTBALL1010@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96410878
Alternative Phone No	OTHERS-96410878

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100322799-05
Cover Note Number	

Driver

Name of Driver	MOHAMMED MAZLAN BIN ABDUL AZIZ
NRIC No	S8131213C
Date Of Birth	25/09/1981
Occupation	OUTDOOR
Date Of Driving Pass	08/02/2001
Driving Experience	16 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96410878
Fax Number	
Contact Number	OTHERS-96410878
Email Address	TOTALFOOTBALL1010@GMAIL.COM

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

15/12/17
16:32hrs
GIA/RC Sketch Plan Form, V3

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Poh Kwee Choo
S6840583A

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : Mohammed Mazlan Bin Abdul Aziz
Period of Insurance : 05 Dec 2017 To 04 Dec 2018
Engine No. : K20A5824964
Chassis No. : FD21404776

Vehicle No. : SJL6684E
Policy No. : 2100322799-05
Endorsement No. :
Issued Date : 01 Nov 2017

ABOUT THE COVER

Make/Model : HONDA CIVIC TYPE R
Engine Capacity/Tonnage : 1,998.00 CC
Driver Restriction : Named Driver Basis
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2008
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

- a) The Policyholder
- b) Any person who is named as a "named driver" under this Policy.

Age Condition : Not Applicable

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$2600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Mohammed Mazlan Bin Abdul Aziz - \$2600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorised Repairers (For claims related repairs)

Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 185), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1969 (Malaysia).

0000064000

DIRECT CLIENTS 014.95
 AIG BUILDING 78 SHENTON WAY #07-16
 SINGAPORE 079120

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SGPMLB

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHD3157X
Accident Date : 14-Dec-2017

No. : 05689

Date : 15-Dec-2017

Our Ref : 217194 (FIRST) / CHAN

PAGE : 1

MOHAMMED MAZLAN BIN ABDUL AZIZ
BLK 426A YISHUN AVENUE 11
#04-74
Singapore 761426

Not Authorised
Li By B3650
Penalty After Paint

ESTIMATED COST OF REPAIR FOR HONDA CIVIC TYPE R 2.0 SJL6684E

1 pc O/s door side mirror assy
1 pc O/s front door quater glass
1 pc O/s front quater glass mouldig
1 pc O/s front door
1 pc O/s front door rubber
1 pc O/s front door glass
1 pc O/s front door outer moulding
1 pc O/s rear door
1 pc O/s rear door glass
1 pc O/s rear door outer moulding

Br 682.70 ✓
CM 278.00 ✓
m 49.50 ✓
W *W* 841.30 ✓
W *W* 134.80 *501m 07.40sn*
W 478.10 ✓
m 96.00 ✓
W 1793.20 ✓
W 387.10 ✓
W 92.40 X

3,833.10

Less 20% : 766.62

1 pc Front o/s quater glass sealant
2 pcs O/s door solar film

@ S\$200.00

m 3,066.48 ✓
m 40.00 sn
m 400.00 sn
200sn
1,400.00 *800*

To putty and spray replaced parts

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

600
1,000.00

Total : S\$ 5,906.48

Singapore Dollars Five Thousand Nine Hundred
and Six and Cents Forty Eight Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023897/Krd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3157X	Veh. Inspected	SJL 6684E	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011549MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	18/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC (M)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	FD21404776	Colour	METALLIC BLACK	
Odometer	256343	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	DUNLOP	5 mm	
L/H Front Tyre	225/40 R18	DUNLOP	5 mm	
R/H Rear Tyre	225/40 R18	DUNLOP	4 mm	
L/H Rear Tyre	225/40 R18	DUNLOP	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/12/2017	Inspection Date	18/12/2017	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 6684E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	O/S DOOR SIDE MIRROR ASSY	BROKEN	682.70	682.70
1	O/S FRONT DOOR QUATER GLASS	CRACKED	278.00	278.00
1	O/S FRONT QUATER GLASS MOULDING	NECESSARY	49.50	49.50
1	O/S FRONT DOOR	DENTED	841.30	841.30
1	O/S FRONT DOOR GLASS	CUT	478.10	478.10
1	O/S FRONT DOOR OUTER MOULDING	DENTED	96.00	96.00
1	O/S REAR DOOR	DENTED	793.20	793.20
1	O/S REAR DOOR GLASS	CUT	387.10	387.10
1	O/S REAR DOOR OUTER MOULDING	SERVICEABLE	92.40	-
	LESS 20% DISCOUNT		-739.66	-721.18
			2,958.64	2,884.72
1	O/S FRONT DOOR RUBBER (50%) (SN)	CUT	134.80	67.40
	LESS 20% DISCOUNT		-26.96	-
			107.84	67.40
SPECIAL NETT ITEMS				
1	FRONT O/S QUATER GLASS SEALANT (SN)	NECESSARY	40.00	40.00
2	O/S DOOR SOLAR FILM @\$200.00 (SN)	NECESSARY	400.00	200.00
			440.00	240.00
LABOUR				
	TO PUTTY AND SPRAY REPLACED PARTS.		1,400.00	800.00
	TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS.		1,000.00	600.00
			-	-
			-	-
			2,400.00	1,400.00
GRAND TOTAL			5,906.48	4,592.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,650.00

Report Ref No. CS/FCI17023897/Krd3e2



Report Ref No. CS/FCI17023897/Krd3e2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.