

INS. CASE OWNER:

CC 3/QBE1702

3902, F1UBH02

LKK:

IDAC:

Surveyor:

Kalin

DOI:

ASSIGNMENT

15/12/17

Date / Time:

15/12/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLD 2999C

Claim No.:

VLO16988

Name of Insured:

LOW HOR WHEE, JASON

Policy No.:

8-V0015193-MVA

Insured Tel No.:

HP: 9669995

Make / Model:

HOWDY

Excess Sec II :S\$

D.O.A:

14/12/17

Place of Accident:

MARINA NEW UNE TRPS

Is driver the owner?

(YES/NO)

Nature of Accident:

MARINA BVD

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES/NO)

OIGIA REPORT YES/NO; TP GIA REPORT: YES/NO

Insured Liability:

%

Final? Yes/No

SH 7567T



INSRS:

WSP:

Tel:

Liability:

RMKS:

WME
W

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

14/12/17

TH

19/12/17 @ 3:15

Called OI, no response.

19/12/17 @ 4:40

OI called back and he confirmed the accident details. Informed IP claim and he agree to settle.

File pass to typist

Conflict of traffic light.

RECEIVED 02 APR 2010

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

> THIN By Email.

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

18/12/17

Sent By:

PM

REALIZATION

Date/Time:

Confirm with:

Confirm by:

Email

Call

Repair Cost:

S\$

(

days) Reduction:

%

FINAL SETTLEMENT

Date/Time:

27/3/18

Confirm with William

Email

Call

Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

NIL

Repair Cost:

S\$

3156.50

Loss of Rental (LOR):

S\$

517.12

(

4

days) 129.28

Loss of Use (LOU):

S\$

200.00

(\$

50

x

4

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

3878.97

Global Sum S\$:

3870.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

3870.00

Name 1:

COMFORTDELGR0 ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC3/QBE17023902/K1ub3

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 18-12-2017



Code : QBE

Policy Particulars :- THIRD PARTY CLAIM

1.

Insured Veh.	SLD 2995C	Veh. Inspected	SH 7567T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/12/2017

2.

Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3.

Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4.

Description of Damages

--	--

5.

General Information

Accident Date	14/12/2017	Inspection Date	15/12/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a.

Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/QBE17023902/K1ub3

Date: 18.12.2017

The Motor Claims Department
M/s QBE INSURANCE (INTERNATIONAL) LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.


SH7567T

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15.12.2017 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	5,518.74
Revised Estimate Amount	: S\$	4,055.78
"Check" Items Amount	: S\$	801.96
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
O/S Body



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 3 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Shu Pei (LKKAUTO)

From: Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>
Sent: Tuesday, 19 December, 2017 9:07 AM
To: Shu Pei (LKKAUTO)
Cc: Jas Khine (LKKAUTO); Thin Thin (LKKAUTO); Admin A; Joyce Foo
Subject: RE: Direct Settlement - Accident Involving SLD2995C (OI : QBE - VC010988) AND SH7567T (TP : LKK REF - CC3/QBE17023902/K1ub3) on 14.12.2017
Attachments: SAS2325802.pdf

Dear Shu Pei,

Our claim ref : VC010988

Attached GIA report.

Thanks,

Syaheeda Othman
Senior Executive, Claims
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd
DID: +6477 1130 Fax : +6533 3270
Email: syaheeda.othman@qbe.com
Visit us on the web at www.qbe.com.sg

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Monday, 18 December, 2017 5:34 PM
To: Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>; Jenny Toh <jenny.toh@qbe.com>
Cc: Jas Khine (LKKAUTO) <jaskhine@lkkauto.com>; Thin Thin (LKKAUTO) <thinthin@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving SLD2995C (OI : QBE - TBA) AND SH7567T (TP : LKK REF - CC3/QBE17023902/K1ub3) on 14.12.2017

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SH 7567T at M/s ComfortDelGro Engineering Pte Ltd - Loyang.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

QBS

DOA: 14.12.17

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SH 7567T
MAKE : HYUNDAI
MODEL : i40

Date: 15.12.2017

Qty	Type	Unit Price	Amount
1	Front Door - RH		\$ 1,403.00
1	Front Door Outer Handle - RH		\$ 38.75
1	Front Door Gear / regulator - RH		\$ 785.50
1	Front Door Hinge Upper - RH		\$ 53.40
1	Front Door Hinge Lower - RH		\$ 53.40
1	Front Door Check - RH		\$ 110.15
1	Rear Door - RH		\$ 1,351.00
1	Rocker Panel Garnish - RH		\$ 483.60
SUB TOTAL			\$ 4,278.80
LESS 20%			855.76
DISCOUNTED TOTAL			\$ 3,423.04
1	Front Door Comfort Sticker		\$ 135.70
1	Rear Door APP Sticker		\$ 50.00
1	Advertisement - Front Door - RH		\$ 100.00
1	Advertisement - Rear Door - RH		\$ 100.00
LKK Auto Consultants hence notify the Repairer of the following:			
• To resurvey before/after spray painting			
• To display damaged parts during resurvey			
• Parts prices are subject to confirmation			\$ 385.70
• Third party survey is on a "Without Prejudice" basis			
• No illegal modification(s) is allowed			
• Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company			
1	Labour Charge		\$ 400
1	Panel Beating		\$ 600.00
1	Spray Painting Charge		\$ 600.00
1	Wiring Charge		\$ 50.00
1	Tuff Kote		\$ 100.00
2	Transfer of Doors	\$180.00	\$ 360.00
TOTAL LABOUR			\$ 1,710.00
ESTIMATE TOTAL			\$ 5,518.74

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Kalvin LKK
Acknowledged by Repairer
Signature: _____
Date: 15/12/17

3 Pys
LIS
After Repair photo

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 7567T
MAKE : HYUNDAI
MODEL : i40

Date: 15.12.2017

Qty	Type	Unit Price	Amount
1	Front Door - RH		\$ 1,403.00
1	Front Door Outer Handle - RH		\$ 38.75
1	Front Door Gear / regulator - RH		\$ 785.50
1	Front Door Hinge Upper - RH		\$ 53.40
1	Front Door Hinge Lower - RH		\$ 53.40
1	Front Door Check - RH		\$ 110.15
1	Rear Door - RH		\$ 1,351.00
1	Rocker Panel Garnish - RH		\$ 483.60
SUB TOTAL			\$ 4,278.80
LESS 20%			855.76
DISCOUNTED TOTAL			\$ 3,423.04
1	Front Door Comfort Sticker		\$ 135.70
1	Rear Door APP Sticker		\$ 50.00
1	Advertisement - Front Door - RH		\$ 100.00
1	Advertisement - Rear Door - RH		\$ 100.00
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged parts during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary dem(s) must be resurveyed and is subject to final approval from Insurance Company			\$ 385.70
1	Labour Charge		\$ 400
1	Panel Beating		\$ 600.00
1	Spray Painting Charge		\$ 600.00
1	Wiring Charge		\$ 50.00
1	Tuff Kote		\$ 100.00
2	Transfer of Doors		\$ 360.00
TOTAL LABOUR			\$ 1,710.00
ESTIMATE TOTAL			\$ 5,518.74

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

Fax :

Vehicle Reg No. : SH 7567T

Date of Accident: 14.12.2017

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- We confirm the estimates and finalized amount

Signature : _____
Name : Kahin
Date : 26/2/2

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours: Monday to Friday, 09:00 - 17:00
UEN: S68550020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MBHA 17164795-01 Vehicle Registration No: SLD 2995C
Name (as shown in NRIC): Low Chortgee Jason NRIC/FIN/Passport No: 88409737C
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address: _____ Singapore (-)
Contact (Tel): _____ Mobile No.: 165-96369995
Email Address: _____
Date of Accident: 14/12/17 Time of Accident: 16:50 HRS
Place of Accident: Marine View Link TWDS Marine BLVD
Insurance Company: OBE Insurance

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Amend Reporting to QD Claims.

Policyholder / Driver's Signature
Date:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD			Ref : CC3/QBE17023902/K1ub3n2	
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583			Date : 03-04-2018	
			Code : QBE	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLD 2995C	Veh. Inspected	SH 7567T	
Policy No.	8-V0015193-MVA	Coverage (\$)	0.00	
Claim No.	VC010988	Excess (\$)	0.00	
Assign From		Assign Date	15/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KMHLB41UMEU052851	Colour	BLUE	
Odometer	325626	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	7 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	7 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	7 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/12/2017	Inspection Date	15/12/2017	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7567T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR -RH	DENTED	1,403.00	1,403.00
1	FRONT DOOR OUTER HANDLE -RH	TO REPAIR SEE LABOUR	38.75	-
1	FRONT DOOR GEAR /REGULATOR -RH	SERVICEABLE	785.50	-
1	FRONT DOOR HINGE UPPER -RH	SERVICEABLE	53.40	-
1	FRONT DOOR HINGE LOWER -RH	SERVICEABLE	53.40	-
1	FRONT DOOR CHECK -RH	SERVICEABLE	110.15	-
1	REAR DOOR -RH	DENTED	1,351.00	1,351.00
1	ROCKER PANEL GARNISH -RH	TO REPAIR SEE LABOUR	483.60	-
	LESS 20% DISCOUNT		-855.76	-550.80
			3,423.04	2,203.20
SPECIAL NETT ITEMS				
1	FRONT DOOR COMFORT STICKER (SN)	NECESSARY	135.70	135.70
1	REAR DOOR APP STICKER (SN)	NECESSARY	50.00	50.00
1	ADVERTISEMENT -FRONT DOOR -RH (SN)	NECESSARY	100.00	100.00
1	ADVERTISEMENT -REAR DOOR -RH (SN)	NECESSARY	100.00	100.00
			385.70	385.70
LABOUR				
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF FRONT DOOR OUTER HANDLE -RH AND ROCKER PANEL GARNISH -RH .		600.00	400.00
	SPRAY PAINTING CHARGE.		600.00	540.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.		100.00	20.00
	TRANSFER OF DOORS.		360.00	100.00
			1,710.00	1,080.00
GRAND TOTAL			5,518.74	3,668.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,950.00

Report Ref No. CC3/QBE17023902/K1ub3n2



Report Ref No. CC3/QBE17023902/K1ub3n2

A handwritten signature in black ink, appearing to be 'W' followed by a stylized 'K'.

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

A handwritten signature in black ink, appearing to be 'Ho Leong Chuan'.

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.