

Surveyor:

Amk

DOI:

ASSIGNMENT


15/11/17

Date / Time :

15/11/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : YP 6431 U

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. : HP: 13/11/17

Make / Model :

Excess Sec II : S\$ D.O.A: 13/11/17

Place of Accident :

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :


OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SHC 2332 T

INSRS:
WSP: COHE 104ms.
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☐
	Authorisation To Act:	☐
	Release Voucher:	☐
	Final Repair Bill:	☐
	Car Rental Invoice:	☐
	Towing Invoice	☐
	LTA / GIA :	☐
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☐
	LOD	☐
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐
PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	S\$	(days) Reduction: %
		Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :
Repair Cost:	S\$	
Loss of Rental (LOR):	S\$	(days)
Loss of Use (LOU):	S\$	(\$ x days)
Loss of Income (LOI):	S\$	(\$ x days)
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]		
GIA/LTA Search	S\$	
Medical:	S\$	
Disbursement:	S\$	(e.g. Tow/ Independent)
Legal Cost	S\$	
Total:	S\$	Global Sum S\$:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	S\$	Name 1:
Payee 2: (Strike if N.A.)	S\$	Name 2:
Payee 3: (Strike if N.A.)	S\$	Name 3:

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
 Mailing + 65 6380 6280 Facsimile + 65 6260 9755

Workshops

59 Layan Drive Singapore 508980
 383 Sin Ming Drive Singapore 575717
 45 Pandan Road Singapore 609286
 322 Upper Road Singapore 738649

24 Senoko Loop Singapore 738156
 7 Sungai Kadut Way Singapore 726791
 6 Defu Avenue 1 Singapore 539537

Date/Time: 14.12.2017 16:16

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC No.305097899

OWNER

AS COMFORT TRANSPORTATION PTE LTD
 7010045
 OWNER NO. 383 SIN MING DRIVE
 ADDRESS Singapore SINGAPORE 575717
 65508755
 (R) (O)
 (P)

OUNT CARD NO.

REGN NO.

SHC2332T

MILEAGE

MAKE

HYUNDAI

FUEL

E.....1/2.....F

MODEL

SONATA

14.12.2017 11:55

DATE/TIME IN

YR OF MANU

07.10.2010

TARGET DATE

CHASSIS CODE

KMHET41VMAA794100

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 13.12.2017
 NATURE: 3P 13.12.17

/NO LABOR CODE DESCRIPTION

KEYED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Adgement Slip

Exit Pass

o.: SHC2332T

LIMITS

Vehicle No.:

SHC2332T

Service Advisor

Signature/Date

Name of Service Advisor

Date

Turned to Service Reception upon collection

To be kept by Security Guard