

CHUNNI MOTOR WORK
PTE LTD


GST REG NO. 200923110D

Date : 15.12.2017

To : Lonpac Insurance Bhd

No of Pages : 7pages

Re : Accident involving veh no: SHD 3207K & SGA 473E along
Buangkok Drive X Hougang Ave 6 on 14.12.2017



We refer to the above mention matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly arrange to survey at AMK Autopoint, BLK 10, #01-05/06, S568047

Tel : 6483 6016.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 65427162.

Thank you for your kind assistance.

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille			\$ 1,480.00
	Radiator Grille H Emblem			\$ 290.80
	Radiator Grille Chrome Moulding			\$ 395.50
	Front Bumper Cover			\$ 1,052.20
	Front Bumper Sponge			\$ 142.20
	Front Bumper Reinforcement			\$ 526.10
	Front Bumper Grille (LH)			\$ 285.50
	Front Bumper Grille Airduct (LH)			\$ 155.00
	Front Bumper Bracket Top (LH)			\$ 22.40
	Front Bumper Bracket (LH)			\$ 24.60
	Front Bumper Retainer Mounting			\$ 9.20
	Headlamp Support Top Cover			\$ 398.00
	Headlamp Support Panel Assy			\$ 1,067.50
	Headlamp (LH)			\$ 1,388.00
	Headlamp Halogen Bulb (LH)			\$ 14.40
	Front Fender (LH)			\$ 619.00
	Front Fender Shield (LH)			\$ 169.80
	Front Wheel Rim (LH)			\$ 351.90
	Front Wheel Hub Cap (LH)			\$ 150.70
	Front Wheel Bearing			\$ 258.50
	Front Shock Absorber (Assy) (LH)			\$ 342.20
	Front Shock Absorber Mounting (LH)			\$ 75.10
	Front Drive Shaft (LH)			\$ 1,069.55
	Rack & Pinion Assy			\$ 2,184.00
	STG Tie End			\$ 69.50
	Stabilizer Bar			\$ 252.30
	Stabilizer Bar Bush (LH)			\$ 16.10
	Stabilizer Bar Link			\$ 81.70
	Stabilizer Bracket			\$ 24.00
	Front Suspension Lower Arm (LH)			\$ 715.10
	Knuckle Arm (LH)			\$ 582.95
	Engine Under Cover			\$ 343.10
	Engine Crossmember			\$ 2,236.90
	ABS Sensor			\$ 261.50
	SUB TOTAL			\$ 17,055.30
	LESS 20%			\$ 3,411.06
	DISCOUNTED TOTAL			\$ 13,644.24

SHD 3207K

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Fender Advertisement Logo (LH)			\$ 100.00	Nett
	Front Tyre (LH)			\$ 216.00	Nett
				\$ 316.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	
	Spray Painting Charge			\$ 600.00	
	Wiring Charge			\$ 50.00	
	Tuff Kote			\$ 50.00	
	Towing Charge			\$ 50.00	
	Remove/Refix Undercarriage (FRT)			\$ 400.00	
	FRT Wheel Alignment			\$ 120.00	
	Remove/Refix Aircon & Refill Gas			\$ 150.00	
	TOTAL LABOUR			\$ 2,420.00	
	ESTIMATE TOTAL			\$ 16,380.24	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

MCD817164950-01 / ComfortDelGro Engineering Pte Ltd - Loyang
ENTRY DATE & TIME: 15/12/2017 12:00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 15/12/2017 12:00
Date Of Accident 14/12/2017 21:50
Exact Location Of Accident BUANGKOK DRIVE X HOUGANG AVE 6
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD3207K
Insured/Policyholder
Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
Co Reg No 199303821R
Email Address FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No
Alternative Phone No OFFICE-65508768

Vehicle Particulars

Manufacturer HYUNDAI
Model I40

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company FIRST CAPITAL INSURANCE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy YES
Policy Number D-1572701MFSH

Cover Note Number

Driver

Name of Driver THULASIDHARAN NAIR
NRIC No S1843746E
Date Of Birth 16/10/1963
Occupation OUTDOOR
Date Of Driving Pass 12/09/1991
Driving Experience 26 YEARS AND 3 MONTHS
Gender MALE
Mobile Number
Fax Number
Contact Number
EMail Address NOEMAIL

Address 60 GEYLANG BARHU 03-3311
 Postcode S330060
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS SEE ATTACHED (TYPE OF ACCIDENT - HEAD TO SIDE)

Attachment(s)


Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGA473E
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver LEE BIAW KOK
 NRIC/Passport Number S1136182Z
 Contact Number 90700532
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage LEFT REAR
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14/12/2017@21:50hrs,I was driving along Buangkok Drive junction of Hougang ave 6.With 1 male and 1 female passenger on board.I was on the extreme left lane,while travelling straight and traffic light was green.Suddenly veh (B) SGA 473E on my opposite make a right turn without give way to me and collided onto my taxi (A) front portion.My taxi (A) front portion was damaged.

Veh (B) SGA 473E male driver.Nric no:S 1136182Z.Hp:9070 0532.No injury in this accident.

Enclosed is a video footage to support my claims.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD

CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time: 15/12/2017

Driver's Signature
(If driver is not the policyholder)

Reporting Centre Personnel's Signature
Name: Lisa Diong

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time: 15/12/2017


Driver's Signature
(If driver is not the policyholder)
Date & Time: 15/12/2017@11:40hrs


Reporting Centre Personnel's Signature
Name: Lisa Diong
NRIC/FIN No.: -