

ASS. REC. BY:

REF: (S/ASM 170)3915/Uqber

Special Instruction:

Survivor:

ASSIGNMENT (Office)

Smart Claim

From (Person):

Jas Tan

of

BXA

Date/Time:

18-12-2017 11:06am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGM 1963M

Insured:

at Workshop m/s

SME Motor

Tel:

of

Blk 1 Kaki Bukit Ave 6 # 02-15

Policy No:

Claim No:

SGM00503

Sum Insured:

Excess:

500.00

Make of Veh:

(Client's Record)

D.O.A.

14-12-2017

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

18-12-2017 11:06am

Person Contacted:

Sebastian

Vehicle IN / OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	SGM 1963M - C/H / AXA 13011541 / Uqber2
19/12/17@	9.49am Informed Sebastian c/A # EX: \$500.
19/12/17@	9.55am revised to Jas Tan via Smart Claims.

EXP: 03062013

Surrogate *mercury*

REF:

*AXA*


*08/AXA17023915/Uq*

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To inspect Vehicle No: *SGM 1963m*  
at Workshop m/s: *Sme*  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: *500*  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: *34*  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: *5* days Res.: Yes or No  
Lump Sum: *1.31* % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS *10/2021*  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: *SGM 1963m* Yr Regn: *10 06*  
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or *CA*  
Make: *Toyota Estime* cc: *2362*  
Colour: *Silver* A/C: Insured / Std / NI / NA  
Sp. Reading: *117326* T. Radio: Insured / Std / NI / NA  
Eng. No: \_\_\_\_\_  
C/No: *ACR507024831*  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: *215/60R16*  
R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_  
R/Bal. *6* mm R/Bal. *6* mm  
L/Bal. *6* mm L/Bal. *6* mm  
D.O.A. *14/12/17* D.O.I. *18/12/17*  
Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
*O/S body, O/S rear*  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction *17A 21623*  
*3 yrs travel. Rep 820*

*16/1/18 confirmed L. ref. by 2526 with ANYing. (Redp 2790.07, 48/12) no lump sum*

*16/1/18 2 2 JAN 2018*

Date/Time File Pass to? ☐ : Preli. Report  
*17/1/18* ☐ : Final Report  
Date/Time File Return to?

Days Of Repair: *5*  
Resurvey No. of Trip: *1*

Survey Fee:	<i>150</i>
Transportation	
_____ S - P. _____ S	
Photos	
Others	
TOTAL	<i>150</i>

Add Fee: ☐ : Site Insp. *IS*  
☐ : Interview *IS*  
☐ : Technical *IS*  
☐ : Weekend *S*

Report Format: *Smart (leaving off)*  
Lump Sum / I.B.I.: *3 7576*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/AXA17023915/Uqb

8 SHENTON WAY #24-01  
AXA TOWERS SINGAPORE 068811

Date : 18-12-2017



Code : AXA2

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SGM 1963M
Policy No.	Coverage (\$)	0.00
Claim No. S7M005O3	Excess (\$)	500.00
Assign From SMART CLAIM (JAS TAN)	Assign Date	18/12/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date 14/12/2017	Inspection Date 18/12/2017
Survey held at SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883	

## 5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

# Survey Department Check List (Case Handler)

Reference No.: *CA/17023915/UG6*  
 Policy Type: *OD / TP / TP RES / TL / EVA*

*SEM 1963M*

Case Handler

Typist

**Admin** (*Cath*): Case handler to make sure all information created by the assignment team are **ACCURATE**.

## (1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			

**Surveyor** (*Navin*): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			

## (2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

<i>✓</i>			
----------	--	--	--

## (3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			
<i>✓</i>			

## (4) System - (Views/Merimen)

- C Resurvey photo Uploaded

<i>✓</i>			
----------	--	--	--

Check By:

*[Signature]* 19/1/18  
 Case Handler Date

\*C: Critical \*N: Non-Critical




## Service Request Details

Claim

S7M005O3

Reference

None 

Loss Date

December 14, 2017

Request Date

December 18, 2017

Due Date

December 26, 2017

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SGM1963M

Make

TOYOTA

## Service Address

1 Kaki Bukit Ave 6 #02-15, , 417883

## Primary Contact/Insured

KOK KUAN CHEONG  
18 JAGO CLOSE, 428434, Singapore, Singapore  
98368382

## Claim Handler

Jas TAN  
6568804844  
jas.tan@axa.com.sg

## Additional Instructions

-OD xs basic nil + unnamed \$500 = \$500 - workshop-SME

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S7M005O3

Date: 19<sup>th</sup> December 2017

Our Ref: CS/AXA17023915/Uqb

The Motor Claims Department  
AXA Insurance Singapore Pte L td

Attn: Jas Tan

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. SGM 1963M .**


We thank you for the instruction on 18/12/2017 .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/12/2017 (2.12pm) at the premises of M/s SME MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ <u>4,501.00</u> .
Revised Estimate Amount	: S\$ <u>2,526.00</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Total	: S\$ <u>2,526.00</u> .
Market Value	: S\$ <u>34,000.00</u> .
LTA Reimbursement Value	: S\$ <u>21,623.00</u> .
Nett Value	: S\$ <u>12,377.00</u> .

Description of Damage:

The vehicle sustained damages at the o/s body & o/s rear portion.



Comments/ Present Status:

Damages consistent.

Repair cost economical.

Estimated normal period for repairs: 5 working days.

We have authorised the repairs.

Yours faithfully

CHUA KANG SENG  
Licensed Appraiser

# Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7195I
Vehicle Details	
Vehicle No.:	SGM1963M
Vehicle to be Exported:	No
Intended De-registration Date:	18 Dec 2017
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA 2.4 A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	2AZC040941
Chassis No.:	ACR507024831
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$30,145.00
Original Registration Date:	11 Oct 2006
First Registration Date:	11 Oct 2006
Transfer Count:	0
Actual ARF Paid:	\$33,160.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	10 Oct 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$28,376.00
COE Rebate Amount:	\$21,623.00
Total Rebate Amount:	\$21,623.00

## Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.





## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/12/2017 12:06
Date Of Accident	14/12/2017 16:05
Exact Location Of Accident	JOO CHIAT & EAST COAST ROAD JUNCTION.
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGM1963M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHEONG KOK KUAN
NRIC No	S6827195I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98368382
Alternative Phone No	OFFICE-98368382

### Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA067878
Cover Note Number	

### Driver

Name of Driver	LEE HSUEH TING
NRIC No	S7226256E
Date Of Birth	20/07/1972
Occupation	INDOOR
Date Of Driving Pass	13/01/1993
Driving Experience	24 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97204836
Fax Number	
Contact Number	
EMail Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver
- 3 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time.

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Accident Sketch Plan Pg. 1



redefining / Insurance

Date: 15/10/07

To: Owner of Vehicle Number: SKM 1962M

The following has been advised to you via your workshop, SNE MOTOR PTE LTD through their staff, \_\_\_\_\_.

Please tick the applicable box if you had been advice on the content as seen below:

- ☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- ☐ You had been advised by the workshop on the liability and merits of the case accordingly.
- ☒ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- ☐ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- ☒ There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- ☒ The estimated waiting time for the spare parts to arrive is \_\_\_\_\_. The estimated arrival time does not include the repair period.
- ☐ You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.
- ☒ For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.
- For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using any combination of genuine original parts and/or original equipment manufacturer (OEM) parts.
- ☒ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ☐ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
- ☐ Others \_\_\_\_\_

Signed and acknowledge by:

X \_\_\_\_\_  
Name and signature of policyholder/authorised driver

\_\_\_\_\_  
Name and signature of workshop personnel including company stamp

VEHICLE NO.: SGM1963M  
 MAKE: TOYOTA  
 MODEL: ESTIMA  
 YEAR OF MAKE: 2006  
 CHASSIS NO.: ACR507024831  
 SUPPLIERS : HEXING

*all  
 Telungpho before party  
 18/12/17  
 21855 500  
 5 day*

S/N	Parts Description	QTY	Remarks	
PARTS				
1	REAR BUMPER <i>7011</i>	1	✓ \$215.00	
2	REAR BUMPER SIDE RETAINER SHORT <i>bul</i>	1	✓ \$30.00	
3	REAR BUMPER SIDE RETAINER LONG <i>bul</i>	1	✓ \$30.00	
4	REAR BUMPER CLIPS <i>ner</i>	10	✓ \$15.00	
5	REAR BUMPER TOW COVER <i>11</i>	1	\$15.00 X	
6	REAR FENDER INNER COWLING RH <i>11</i>	1	\$45.00 α	
7	INNER COWLING CLIPS <i>11</i>	10	\$15.00 α	
8	REAR FENDER PROTECTOR RH <i>g r e b</i>	1	✓ \$35.00	
9	FENDER PROTECTOR CLIPS <i>ner</i>	12	✓ \$24.00	
10	REAR DOOR RH <i>5.0500</i>	1	✓ \$520.00	
11	REAR DOOR TOP STICKER RH <i>ner</i>	4	✓ \$112.00	
12	REAR DOOR PROTECTOR RH <i>g r e b</i>	1	✓ \$185.00	
13	REAR FENDER RH <i>12</i>	1	\$340.00 α	
14	REAR FENDER GLASS MOULDING RH <i>111</i>	1	\$270.00 α	
TOTAL PARTS			\$1,851.00	
S/N				
1	REAR SPORT RIM RH <i>12</i>	1	\$250.00	
2	REAR FENDER GLASS GUM <i>111</i>	1	\$60.00 α	
TOTAL S/N			\$310.00	
LABOUR :				
1	WIRE CHECKING		\$20.00 ✓	
2	REMOVE & REFIX FENDER GLASS	<i>11</i>	\$120.00 α	
3	TRANSFER DOOR COMPONENT FROM OLD TO NEW		\$100.00 60	
4	LABOUR CHARGE		\$1,200.00	
5	SPRAY PAINTING		\$900.00	
TOTAL LABOUR			\$2,340.00	
<div><div>LKK Auto Consultants hence notify the Repairer of the following:</div><ul style="list-style-type: none"><li>• To resurvey before/after spray painting</li><li>• To display damaged part(s) during resurvey</li><li>• Parts prices are subject to confirmation</li><li>• Third party survey is on a "Without Prejudice" basis</li><li>• No illegal modification(s) is allowed</li><li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li></ul><div>Exempted from Repairer</div></div>			TOTAL	\$4,501.00
			GST 7%	\$315.07
				\$4,816.07

*1166*

*600  
 680  
 2526*



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403  
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /  
DAIHATSU / KIA / SUZUKI / HONDA  
TEL: 6291 2827 FAX: 6296 4390  
A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

**TAX INVOICE**

M/S: SME MOTOR PTE LTD

1 KAKI BUKIT AVE.6  
#02-15/16/17/18 AUTOBAY @KAKI BUKIT  
SINGAPORE 417883  
SGM1963M  
HAN

NO: DLI9197752  
PAGE: 1  
DATE: 29/12/2017  
A/C CODE: LDSM446  
TERMS: CR

Part No	Description	Location	Qty	Unit Price	Amount	
				SIN	SIN	
Our D/O No: DDO9020967						
1	T52159-28914	BUMPER RR	DB2D	1	215.00	215.00
2	T76917-28080	MUDGUARD RH	DU1AS2-3	1	35.00	35.00
3	T67003-28440	DOOR RR RH	DBEE5	1	520.00	520.00
4	T75931-28030	TAPE	DU1ADS16	1	28.00	28.00
5	T75933-28030	TAPE	DU1ADS4	1	28.00	28.00
6	T75937-28021	TAPE BLACK OUT	DU1ADS15	1	28.00	28.00
7	T75951-28031	TAIPE	DU1ADS12	1	28.00	28.00
8	T76915-28060	MUDGUARD SLIDE DOOR RH	DU1H21-14	1	185.00	185.00
Our D/O No: DDO9020972						
1	T76932-26010	CLIP (ORANGE)	DD1A144	12	2.00	24.00
2	T52155-28080	BUMPER RETAINER RR RH	DDS	1	30.00	30.00
3	T52155-28090	BUMPER RETAINER RR NO:2 RH	DDS	1	30.00	30.00
	T52161-16010-1	CLIP,RR BUMPER	DDS	10	1.50	15.00
TOTAL QUANTITY:			32	TOTAL	SIN 1,166.00	
				ADD GST @ 7%	81.62	
				GRAND TOTAL	SIN 1,247.62	

#02-18

Print / MT / 29/12/2017 4:24:47 PM

SALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY

Volkswagen

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

## General Details

### Involving

1 2006 TOYOTA ESTIMA 2.4 (SGM1963M)

### Date of Loss

December 14, 2017

### Time of Loss

16.05

### Loss Description

I INTENDED TO FILTER RIGHT BUT SUDDENLY VEHICLE B HIT ONTO MY VEHICLE RIGHT SIDES.

### Comment

## Workshop Details

### Total Rebate Amount

21623

### Nett Loss Amount

\$12,377.00

### Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

### Target Date of Completion \*

01/30/2018



### Days of work completion \*

43

...





# Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

## General Details

Involving  
1 2006 TOYOTA ESTIMA 2.4 (SGM1963M)

Date of Loss  
December 14, 2017

Time of Loss  
16.05

Loss Description  
I INTENDED TO FILTER RIGHT BUT SUDDENLY VEHICLE B HIT ONTO MY VEHICLE RIGHT SIDES.

Comment

## Workshop Details

Total Rebate Amount  
21623

Nett Loss Amount  
\$12,377.00

Assigned Workshop  
LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion \*  
01/30/2018

Days of work completion \*  
43



# Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

## Vehicle & Driver Details

Vehicle Registration#  
SGM1963M

Registration State  
SINGAPORE

Mileage  
117326

Purchase Date  
mm/dd/yyyy

Registration Date \*  
10/11/2006

Age of Vehicle  
11

CATEGORY	Manufacturing Year
POLICY INFORMATION	2006
ASSESSMENT INFORMATION	2006
CATEGORY	Make
POLICY INFORMATION	TOYOTA

CATEGORY

Model

POLICY INFORMATION

ESTIMA 2.4

ASSESSMENT INFORMATION

ESTIMA 2.4 A

CATEGORY

Type

POLICY INFORMATION

ASSESSMENT INFORMATION

CATEGORY

Type of Paint

POLICY INFORMATION

ASSESSMENT INFORMATION

CATEGORY

Chassis No

POLICY INFORMATION

ACR507024831

ASSESSMENT INFORMATION

ACR507024831

CATEGORY

Engine No

POLICY INFORMATION

2AZC040941

ASSESSMENT INFORMATION

2AZC040941

CATEGORY

Engine Capacity

POLICY INFORMATION

ASSESSMENT INFORMATION

2362



# Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

## Detailed Assessment

Inspection Date \*

12/18/2017

Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

500

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

## Condition of Vehicle at time of survey

General condition

Good ▾

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

-- none --

Tyre Condition

Age of Tyres

Front Tyre Size

215/60R16

Front left side

YOKOHAMA 6mm

Front right side

YOKOHAMA 6mm

Spare wheel

Rear Tyre Size

215/60R16



# Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

## Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Discount%

Salvage%

Settlement%

100

## Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Save

# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

☐

1

1

REAR BUMPER

Damaged

215

215

Reviewing

☐

2

1

REAR BUMPER SIDE RETAINER SHORT

Bent

30

30

Reviewing



3

1

REAR BUMPER SIDE RETAINER LONG

Bent

30



30

Reviewing



4

10

REAR BUMPER CLIPS

Necessary

1.5

15

Reviewing



5

1

REAR BUMPER TOW COVER

Serviceable

0

0

0

0

0

Deny



6

1

REAR FENDER INNER COWLING RH

Serviceable

0

0

0

0

0

Deny



7

10

INNER COWLING CLIPS

Serviceable

0

0

0

0

0

Deny



8

1

REAR FENDER PROTECTOR RH

Damaged

35

35

Reviewing



9

12

FENDER PROTECTOR CLIPS

Necessary

2

24

Reviewing



10

1

REAR DOOR RH

Damaged

520

520

Reviewing



11

4

REAR DOOR TOP STICKER RH

Necessary

28

112

Reviewing



12

1

REAR DOOR PROTECTOR RH

Damaged

185

185

Reviewing



13

1

REAR FENDER RH

Repair

0

0

0

0

0

Deny



14

1

REAR FENDER GLASS MOULDING RH

Serviceable

0

0

0

0

0

Deny



Labour



Add

Approve

Deny



1

WIRE CHECKING

20

0

0

Reviewing



2

REMOVE & REFIX FENDER GLASS

0

0

0

Deny

NOT NECESSARY





3

TRANSFER DOOR COMPONENT FROM  
OLD TO NEW

60

0

0

Reviewing



4

LABOUR CHARGE

600

0

0

Reviewing





5

SPRAY PAINTING

680

0

0

Reviewing



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Approve

Deny

Add



1

REAR SPORT RIM RH

Deny

0

REPAIR



2

REAR FENDER GLASS GUM

Deny

0

NOT NECESSARY





# Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount  
\$2,026.00

CATEGORY Spare Parts

ESTIMATE \$1,166.00

REVISED AMOUNT \$1,166.00

CATEGORY Labour

ESTIMATE \$1,360.00

REVISED AMOUNT \$1,360.00

CATEGORY Excess

ESTIMATE -\$500.00

REVISED AMOUNT -\$500.00

Submit for Review