

23/03/2001

ASS. REC. BY:

REF: CS/MSG17023917/11rd 3rd Special Instruction:

Surveyor: Tauhik
From (Person): Guo Liang

ASSIGNMENT (Office)

of MSIG

Date/Time: 15/12/17 @ 11:43am

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

Insured: Public Liability

To Inspect Vehicle No: SLP 2537D

Tel: 9116 5600

at Workshop m/s

Performance Motor

of

303 Alexandra Road

Policy No:

Claim No: MSC/M/17-000437

Sum Insured:

Excess:

D.O.A. 15/12/2017

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time: 12:00pm @ 15/12/17

Person Contacted:

Kalvin

Vehicle IN/OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/> Estimate
	<u>SLP 2537D - X</u>
	<u>Public Liability</u>
	<u>Sent poli thru email</u>

Signature: Taylor

REF: MSLG

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
✓	✓

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLP2537D Yr Regn: 2017 May

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: BMW 318i c.c. 1499

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 12338 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA8E320Y0A019939

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R17
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 15/10/17 @ 2pm

Survey held at PML

Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Estimate based on cash job repair, can't revised.
	Confirm \$11,909.50 @ 10 days
	Red: 8 (70.60, 2%)

[Signature]
28/5/2018

RECEIVED 28 MAY 2018

Date/Time, File Pass to? Preli. Report

1) thpct Final Report

Date/Time, File Return to? _____

2) _____

Report Format: FP

Lump Sum / I.B.I: (\$) 11909.50

Days Of Repair: 10

Resurvey No. of Trip: 1

Survey Fee:	<u>300</u>
Transportation	
Site Insp (\$)	
Interview (\$)	
Tech. Invs (\$)	
Weekend (\$)	
Photos	
Others	
TOTAL	<u>300</u>

Add Fee: Site Insp (\$) _____
 Interview (\$) _____
 Tech. Invs (\$) _____
 Weekend (\$) _____

Nivitha (LKK Auto)

From: Luo Guoliang <Guoliang_Luo@sg.msig-asia.com>
Sent: Friday, 15 December, 2017 11:43 AM
To: assignments@lkkauto.com
Cc: Chhia Nyuk Pui
Subject: WP Inspection of BMW car SLP2537D
Attachments: img-Z12103944-0001.pdf; SAS2323350 (incident report from TP).pdf; T212_L004_Incident Occurrence.pdf

Your Ref : Please advise
Our Ref : MSC/M/17-000437

Dear Ms Nivitha

We refer to our telephone conversation today.

As spoken, we would like to engage LKK to carry out a 'without prejudice' inspection survey of the third party car (SLP2537D).

The owner can only drive down to the workshop today at 2.00pm as she advise that she will not be in Singapore for a long period of time after today. Apologies for the short notice.

Attached are the relevant information/documents for your attention.

Please confirm the assignment as soon as possible.

Thank you.

Luo Guoliang
Senior Executive, Claims Services
D: +65 6643 1303 | F: +65 6827 2702 | guoliang_luo@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17023917/T1rd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 18-12-2017



Code : MSG

Policy Particulars :- THIRD PARTY CLAIM

1.	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SLP 2537D
	Policy No.		Coverage (\$)	0.00
	Claim No.	MSC/M/17-000437	Excess (\$)	0.00
	Assign From	LUO GUO LIANG	Assign Date	18/12/2017

Vehicle Particulars & Condition

2.	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			

Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm

Description of Damages

4.

General Information

5.	Accident Date	15/12/2017	Inspection Date	15/12/2017
	Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

Remarks

5a.

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Friday, March 23, 2018 11:11 AM
To: 'Luo Guoliang'; 'Chhia Nyuk Pui'
Subject: RE: WP Inspection of BMW car SLP2537D
Attachments: SLP 2537D .pdf

Dear Guo Liang,

Enclosed preliminary revised for **SLP 2537D**.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, December 15, 2017 11:58 AM
To: 'Luo Guoliang' <Guoliang_Luo@sg.msig-asia.com>; assignments <assignments@lkkauto.com>
Cc: 'Chhia Nyuk Pui' <NyukPui_Chhia@sg.msig-asia.com>; SUR <sur@lkkauto.com>
Subject: RE: WP Inspection of BMW car SLP2537D

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Luo Guoliang [mailto:Guoliang_Luo@sg.msig-asia.com]
Sent: Friday, 15 December, 2017 11:43 AM
To: assignments@lkkauto.com
Cc: Chhia Nyuk Pui
Subject: WP Inspection of BMW car SLP2537D

Your Ref : Please advise
Our Ref : MSC/M/17-000437

Dear Ms Nivitha

We refer to our telephone conversation today.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: MSC/M/17-000437
Our Ref: CS/MSG17023917/T1rd3

The Motor Claims Department
MSIG Insurance Pte Ltd

Without Prejudice

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SLP 2537D

We thank you for the instruction on 15/12/2017.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/12/2017 at the premises of M/s PERFORMANCE MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>12,098.60</u>
Revised Estimate Amount	: S\$ <u>12,098.60</u>
"Check" Items Amount	: S\$ _____
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____


Description of Damage:
The vehicle sustained damages
at the front and rear portion, o/s body
and rooftop.




Comments/ Present Status:
Damages Consistent.
Estimate amount not revised due to cash job repair
Repair day : 10 days

Yours faithfully
TAUFIKH
Automotive Assessor

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/12/2017 16:11
Date Of Accident	10/12/2017 13:30
Exact Location Of Accident	UPPER THOMSON RD (SLE) AFT JLN LEMBAH THOMSON
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP2537D
Insured/Policyholder	
Name Of Registered Owner	ELLY SOETANTO
NRIC No	S7074501A
Email Address	ELLY.SOETANTO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96526016
Alternative Phone No	OFFICE-96526016
Vehicle Particulars	
Manufacturer	BMW
Model	318i-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5091190836
Cover Note Number	
Driver	
Name of Driver	ELLY SOETANTO
NRIC No	S7074501A
Date Of Birth	28/12/1970
Occupation	INDOOR
Date Of Driving Pass	05/10/1998
Driving Experience	19 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96526016
Fax Number	
Contact Number	OFFICE-96526016
Email Address	ELLY.SOETANTO@GMAIL.COM

Address 10G BRADDELL HILL
 #22-27 BRADDELL VIEW
 Postcode 579726
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT BY FALLEN TREE / OTHER OBJECTS
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name QUEENSTOWN N.P.C
 Police Station Address ROAD: 3 QUEENSWAY #01-03 , POSTCODE: 149073 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-4719999 - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: EMAIL TO MOTOR
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver CHONG CHEN HOH
 NRIC/Passport Number S7885179A
 Contact Number 91592583
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage CEMENT STAINS FELL ONTO CAR
 No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 14/12/17 10:00am

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name: Hoo Joo

NRIC/FIN No.: 94111111

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to other report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 11/12/14 11:05

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name: Howard
NIC/FIN No: 544515838

Police Report



SINGAPORE
POLICE FORCE



01201712110230

1 of 2

Report No. 01201712110230

POLICE REPORT (NP299)

Police Station Of Origin
Queenstown N.P. 11
3 Queenway #01-01 SINGAPORE 148072
Tel No: 1800-4718988

Date/Time Report Made 11/12/2017 13:15	Wide Report No. 01201712110230	Station Diary No. 46
Name Of Informant ELLY SOFTANTO	Address 106 BRADDELL HILL #22-27 SINGAPORE 576728	
ID Type / ID No. NRIC NO / S7074521A	Contact No. Home/Office	Mobile 95528016
Nationality SINGAPORE CITIZEN	Email Address	
Occupation	Sex Female	Age 46
Household	Date of Birth 28/12/1972	Race Chinese
Institution/School Name	Language	
Date/Time Of Incident 10/12/2017 13:00 - 10/12/2017 14:00	Location Of Incident UPPER THOMSON ROAD SINGAPORE Infront of Kampung Chicken House	

Brief details.

On 10/12/2017 at between 1300hrs to 1400hrs. I was driving my car, SLP2537D, a blue BMW, along Upper Thomson Rd, in-front of Kampung Chicken House looking for a parking lot. My car was in a stationary position at that time.

Suddenly, I heard a loud "Bang" sound coming from my car rooftop. After I parked my car at a parking lot, I made a check-up on the exterior part of my car and discovered there were cement stains on it. I went to the construction site nearby to complain about the incident.

Signature Of Officer Recording The Report:
D/ Sgt HEIFI BIN SA RAHMAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
D/ Clerical Police Divisional Investigation Branch /
Insp LIM CHEE HONG
Contact No.: 67742000

Signature Of Informant:

Date/Time:
11/12/2017 13:15

Classification Of Case:

Authentication Stamp

Police Report



SINGAPORE
POLICE FORCE



1201712112005

2 of 2

POLICE REPORT (MP299)

CONTINUATION OF REPORT

Report No. D/2017/211/2005

I am making this report for insurance claim purposes

Subjects Involved	
Victim	
Person Name	ELLY SOETANTO (Informant)

Signature Of Officer Recording The Report: D/ Sgt HEIFIE NAB RAHMAN
Signature Of Informer: Not applicable
Officer In-Charge Of Case: D/ Command Police Division Investigation Branch / Insp LIM CHEE NING Contact No : 87740000
Authentication Stamp

Signature Of Informant
Date/Time: 11/12/2017 13:15
Classification Of Case

Police Report



SINGAPORE
POLICE FORCE



0020 7121 12032

1 of 2

Report No. D201712112032

POLICE REPORT (NP286)

Police Station Of Origin
Luton Road N.P.C.
3 Queanway #01-23 SINGAPORE 119075
Tel No. 1800 471 9999

Defecting Report Made 11/12/2017 13:03	File Report No.	Station Diary No. 42
Name Of Informant CHONG GUAN HOH	Address APT BLK 1083 CANBERRA WALK #1-03 SINGAPORE 752108	
ID Type - ID No. N.R.C NO / S7685179X	Contact No Home/Office	Mobile 81552583
Nationality SINGAPORE CITIZEN	Email Address	
Occupation Building and construction project manager	Sex	Age
Institution/School Name	Male	30
	Date of Birth	Race
	11/12/1978	Chinese
Date/Time Of Incident 10/12/2017 13:00 - 10/12/2017 14:00	Language English	
	Location Of Incident 0 UPPER THOMSON ROAD UPPER THOMSON MRT STATION SINGAPORE CONSTRUCTION SITE	

Brief details.

On 10/12/2017 at about 140hrs, my supplier contractor was washing the concrete pump cement hopper. Subsequently a lady driver, by the car registration number SFH254D, approached us. She told us that some cement splashed on her car. We made a check and discovered that indeed there is some cement stains on the roof, the right passenger and driver door side and bonnet of her car. I informed my higher ups about the matter and was advised to make a police report for insurance claims. The splashing

Signature Of Officer Recording The Report
D / Staff Sgt MOORHIDAYKA SIVAKANESAN

Signature Of Informant

Signature Of Interpreter
Not applicable

Date/Time
11/12/2017 13:03

Officer In Charge Of Case
D / Clement Police Division Investigation Branch /
Iras LIM CHEE NIKS
Contact No: 68727919

Classification Of Case:

Authentication Stamp



Police Report



SINGAPORE
POLICE FORCE



10707-10707-10707

2 of 2

POLICE REPORT (NP289)

CONTINUATION OF REPORT

Report No. D120171211-2032

If the informant or his car is unintentional.

Signature Of Officer Recording The Report
 D / SIAI SJI NOORH DAYAT BIN WAHID

Signature Of Interpreter
 Not applicable

Officer In-Charge Of Case
 D / C Senior Police Divisional Investigation Branch
 Insp L M CHEE NING
 Contact No : 68727819

Authentication Stamp

Signature Of Informant

Date/Time:
 11/12/2017 10:35

Classification Of Case:

SINGAPORE
POLICE FORCE

SIGNATURE

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

200, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190688 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190628 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45110
Date Estimated : 11/12/2017
Prepared By : Chua Kee Sin

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Elly Soetanto
10G Braddell Hill
#22-27

Singapore 579726

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP2537D	A019939	30/05/2017	318iA/4Dr	0

DESCRIPTION

To repair on front bonnet, front right door, rear right door, rear right fender, rear tailgate, roof top & replace on front & rear right door moulding

VALUE
/ 4,250.00

Painting on front bonnet, frt right door, rear right door, rear right fender, rear tail gate, roof top & rear right Rim

/ 6,209.00

Polishing all car
(BMW 1,2,3,4,X1,Z,13 Series)

/ 280.00

This quote is not for insurance purpose
this repair takes 10 working days

0.00

To check electrical wiring systems for proper function

/ 177.00

Sundries.

/ 150.00

Total Labour 1: 11,066.00

DESCRIPTION

LETTERING 318i
BADGE (BMW)
FRT RH DOOR COVER COLUMN B (GLAN)
FRT RH DOOR WINDOW GUIDE
FRT RH DOOR OUTER CHANNEL SEALING (RH SIDE FRAME FINISHER (GLANZSCHWAR
RR RH DOOR OUTER DUCT COVER (GLANZS
RR RH DOOR COVER COLUMN B (GLAN)
RH EXTERIOR COVER WINDOW GUIDE WEB
REAR RH DOOR WINDOW GUIDE

QTY	PRIC	VALUE
1	61.05	/ ne 61.05
1	67.80	69.50 ne 67.80
1	65.05	/ stained 65.05
1	95.95	nn X stained 95.95
1	111.90	100.40 stained 111.90
1	267.70	281.25 stained 267.70
1	120.40	/ stained 120.40
1	64.10	/ stained 64.10
1	60.25	/ stained 60.25
1	118.40	nn X stained 118.40

Total Parts : 1,032.60

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Eampong Arang Road
East Coast Centre
Singapore 438180
Tel: 63190888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45110
Date Estimated : 11/12/2017
Prepared By : Chua Kee Sin

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP2537D	A019939	30/05/2017	318iA/4Dr	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 15/12/17 @ _____ Excess S\$ _____
Surveyor's Name Taufikh. Sign *Taufikh*
Surveyor's Tel 97495749 Authorised Yes / No
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR / No PML Yes / No
Surveyor's E-mail taufikh @ lkharts.com
No. of Working Days Recommend 10 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

12/23 85

Labour 1	:	11,066.00
Parts	:	1,032.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	846.90
Grand Total	:	12,945.50

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Page No. :

Estimate No. : b1 45110
Date Estimated : 11/12/2017
Prepared By : Chua Kee Sin

REPAIR FOR -
Elly Soetanto
10G Braddell Hill
#22-27

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 579726

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	ORIGINAL PRICE	DISC. %	NETT
SLP2537D	A019939	30/05/2017	318iA/4Dr	0			
DESCRIPTION							
To replace front RH door cover column B and attachments, rear RH cover column B and attachments include making good the bonnet, front RH door, rear RH door, rear RH fender, boot lit, roof, rear RH rim and knocking out dents caused by the accident					4250.00		4,250.00
* To spray paint bonnet, front RH door, rear RH door, rear RH fender, boot lit, roof and rear RH rim					6209.00		6,209.00
To polish car					280.00		280.00
To check electrical wiring systems and lightings for proper function					177.00		177.00
Sundries.					150.00		150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
LETTERING 318i	61.05	1.00		61.05
# GROMMET *	0.75	2.00		1.50
BADGE (BMW)	69.50	1.00		69.50
FRT RH DOOR COVER COLUMN B (GLAN)	65.05	1.00		65.05
FRT RH DOOR OUTER CHANNEL SEALING (120.40	1.00		120.40
RR RH DOOR OUTER DUCT COVER (GLANZS	120.40	1.00		120.40
RH SIDE FRAME FINISHER (GLANZSCHWAR	281.25	1.00		281.25
RR RH DOOR COVER COLUMN B (GLAN)	64.10	1.00		64.10
RH EXTERIOR COVER WINDOW GUIDE WEB	60.25	1.00		60.25

SUPPLEMENTARY ITEMS

Total Labour :

11,066.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45110
Date Estimated : 11/12/2017
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Elly Soetanto
10G Braddell Hill
#22-27

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 579726

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SLP2537D	A019939	30/05/2017	318iA/4Dr	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# GROMMET *	0.75	2.00	<i>new</i>	1.50

Total Labour :
Total Parts : 1.50
Total Labour & Parts : 1.50



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17023917/T1rd3e2

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 01-06-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SLP 2537D
Policy No.		Coverage (\$)	0.00
Claim No.	MSC/M/17-000437	Excess (\$)	0.00
Assign From	LUO GUO LIANG	Assign Date	15/12/2017

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 318i	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBA8E320X0A019939	Colour	BLUE
Odometer	12338	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	DUNLOP	6 mm
L/H Front Tyre	225/50 R17	DUNLOP	6 mm
R/H Rear Tyre	225/50 R17	DUNLOP	6 mm
L/H Rear Tyre	225/50 R17	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY, FRONT, REAR AND ROOFTOP PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/12/2017	Inspection Date	15/12/2017
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 2537D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
1	LETTERING 318I (SN)	NECESSARY	61.05	61.05
1	BADGE (BMW) (SN)	NECESSARY	69.50	69.50
1	FRT RH DOOR COVER COLUMN B (GLAN) (SN)	STAINED	65.05	65.05
1	FRT RH DOOR WINDOW GUIDE (SN)	NOT NECESSARY	95.95	-
1	FRT RH DOOR OUTER CHANNEL SEALING (SN)	STAINED	120.40	120.40
1	RH SIDE FRAME FINISHER (GLANZSCHWAR) (SN)	STAINED	281.25	281.25
1	RR RH DOOR OUTER DUCT COVER (GLANZ) (SN)	STAINED	120.40	120.40
1	RR RH DOOR COVER COLUMN B (GLAN) (SN)	STAINED	64.10	64.10
1	RH EXTERIOR COVER WINDOW GUIDE WEB (SN)	STAINED	60.25	60.25
1	REAR RH DOOR WINDOW GUIDE (SN)	NOT NECESSARY	118.40	-
2	GROMMET @\$0.75 (ADDITIONAL) (SN)	NECESSARY	1.50	1.50
			1,207.85	993.50
LABOUR				
TO REPAIR ON FRONT BONNET, FRONT RIGHT DOOR, REAR RIGHT FENDER, REAR TAILGATE, ROOF TOP & REPLACE ON FRONT & REAR RIGHT DOOR MOULDING.			4,250.00	4,250.00
PAINTING ON FRONT BONNET, FRT RIGHT DOOR, REAR RIGHT DOOR, REAR RIGHT FENDER, REAR TAIL GATE, ROOF TOP & REAR RIGHT RIM.			6,209.00	6,209.00
POLISHING ALL CAR (BMW 1,2,3,4,X1,Z,I3 SERIES)			280.00	280.00
THE QUOTE IS NOT INSURANCE PURPOSE THIS REPAIR TAKES 10 WORKING DAYS. (NPA)			-	-
TO CHECK ELECTRICAL WIRING SYSTEMS FOR PROPER FUNCTION.			177.00	177.00
			10,916.00	10,916.00
GRAND TOTAL			12,123.85	11,909.50
RECOMMENDED COST OF REPAIRS				11,909.50

Report Ref No. CS/MSG17023917/T1rd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.