

INS. CASE OWNER:

CC 6/AIG170

25423, Akas 9

LKK:
IDAC:

ASSIGNMENT

DOI:

Date / Time:

Registered in Meritmen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time:

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: ? 02012018

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with Jason.

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. : 15

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

6420.00

Q20 changed lane and collided with TP

Loss of Rental (LOR):

S\$

300.00

(3 days)

X 100.00

Loss of Use (LOU):

S\$

-

(\$

x

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

6700.00

Global Sum S\$: 6700.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

6700.00

Name 1:

Kim Chwee Auto Pte Ltd

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

Payee 3: (Strike if N.A.)

S\$

-

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG17023923/Aka3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 18-12-2017	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh. SJY 9857K	Veh. Inspected	SLM 4741H
	Policy No.	Coverage (\$)	0.00
	Claim No.	Excess (\$)	0.00
	Assign From	Assign Date	18/12/2017
2. Vehicle Particulars & Condition			
	Make & Model	c.c	0
	Engine No. HIDDEN	Year of Reg.	
	Chassis No.	Colour	
	Odometer -	Steering	
	Brakes	Modification	
	General		
3. Conditions of Tyres			
	Size	Make	Balance
	R/H Front Tyre		mm
	L/H Front Tyre		mm
	R/H Rear Tyre		mm
	L/H Rear Tyre		mm
4. Description of Damages			
5. General Information			
	Accident Date 15/12/2017	Inspection Date	15/12/2017
	Survey held at KIM CHWEE AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262-D

Estimate : 20037

TPA15

Zaini

Date : 18.12.2017

Vehicle Num : ~~SLN474HH~~ SLN474HH

Make/Model : KIA SORENTO

Chassis/Engine no :

Accident Date : 15.12.2017

Claim No : 1217-20037

Reference :

Policy No :

KNAPH 818MH S329217

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Headlamp LH <i>est</i>	\$ 2,656.90 ✓
1 pc	Front fender LH <i>Bucleles</i>	\$ 480.70 ✓
1 pc	Front fender inner shield LH <i>Defend</i>	\$ 95.40 ✓
1 pc	Front fender arch garnish LH <i>bt</i>	\$ 347.50 ✓
1 pc	Front support panel <i>cut</i>	\$ 922.40 ✓
1 pc	Front grille <i>new</i>	\$ 455.70 X
1 pc	Front bumper corner parking sensor <i>Single</i>	\$ 227.50 ✓
1 pc	Front bumper lower garnish <i>not in</i>	\$ 372.50 X
1 pc	Front bumper <i>Defend</i>	\$ 741.70 ✓
1 pc	Front bumper reinforment <i>new</i>	\$ 315.70 X
1 pc	Front bumper fog lamp LH <i>cut</i>	\$ 321.30 ✓
1 pc	Front bumper fog lamp cover <i>new</i>	\$ 62.10 X
1 pc	Front bumper side retainer <i>2yd</i>	\$ 40.20 ✓
1 pc	Front bumper sponge <i>cut</i>	\$ 121.60 ✓
1 pc	Front bumper headlamp nozel motor <i>cut</i>	\$ 401.30 ✓ <i>258</i>
1 pc	Front bumper headlamp nozel motor cover <i>missing</i>	\$ 48.30 ✓
1 pc	Front sport rim <i>lt</i>	\$ 1,468.50 <i>452/20</i>
1 pc	Front shock absorber LH ?	\$ 419.00 ✓
1 pc	Front kunckle arm	\$ 357.00 X <i>6261-50 SN: H50</i>
1 pc	Front lower arm	\$ 474.00 ✓
1 pc	Front wheel bearing	\$ 279.00 X <i>563535</i>
List Item Total :		\$ 10,608.30
Discount 10 % :		\$ 1,060.83
		\$ 9,547.47

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262-D

Estimate : 20037

Date : 18.12.2017

Vehicle Num : SLN4741H

Make/Model : KIA SORENTO

Chassis/Engine no :

Accident Date : 15.12.2017

Claim No : 1217-20037

Qty	Particular	Amount S\$
<u>Nett Item :</u>		
1 pc	Front tyre <i>all 4</i>	\$ 550.00 <i>x</i>
1 set	Front bumper clip <i>2</i>	\$ 50.00 <i>30</i>
1 set	Front fender inner shield clip LH <i>2</i>	\$ 50.00 <i>30</i>
Nett Total :		\$ 650.00
<u>Labour Charge :</u>		
	To check wiring	\$ 80.00 <i>30</i>
	To apply anti rust chemical	\$ 50.00 <i>x</i>
	Remove and replace LH front suspension and under carriage <i>1380</i>	\$ 380.00 <i>x</i>
	To check wheel alignment	\$ 80.00 <i>✓</i>
	Remove and refix aircon condenser & refill aircon gas	\$ 150.00 <i>60</i>
	Remove and refix radiator	\$ 120.00 <i>60</i>
	To remove and replace spare part and panel beating	\$ 1,200.00 <i>750</i>
	To spray painting and etc	\$ 1,200.00 <i>400</i>
Labour Charge Total :		\$ 3,260.00

E & O . E

Total Amount \$ 13,457.47

total 7515.35

2/5 6K 052p

KIM CHWEE AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

61C

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

Date : 06.04.2018

AlG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

ACCIDENT INVOLVING VEHICLE: SLM4741H AND SJY9857K ON 15.12.2018

We are the authorized repair workshop for the owner of motor vehicle no: **SLM4741H**, which was involved in the captioned accident with your insured vehicle no: **SJY9857K**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$ 6,420.00
2) Loss Of Use Rental	\$ 300.00
3) GIA Search Fee	\$ 2.00
	<u><u>\$ 6,722.00</u></u>

We enclosed herewith the following documents to support the claims:

- | | |
|------------------------------------|----------------------------------|
| a) Final Repair Invoice | b) Vehicle Registration Log Card |
| c) Rental Agreement/Invoice | d) I/C & Driving Licence |
| e) Insurance Certificate | f) GIA Search Result/GIA Report |
| g) Letter of Authorisation, etc... | |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.

Yours faithfully,

Jason Tang (jason@fastechauto.com.sg)

For Kim Chwee Auto Pte Ltd



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG17023948/Uka3

05 JANUARY 2018

PIETER WILLEM JAN KEMPS

3 BUCKLEY ROAD
SINGAPORE 309752

Dear Sir/Madam,

ACCIDENT INVOLVING SJY 9857K / SLM 4741H / OTHERS ON 15.12.2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,



Zaini
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: Zaini@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)


AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Tang Tze Ling Melissa ("the third party claimant")
of 188 Keng Lee Road #18-03 5308414 (address),
owner of SLM 4741 H (vehicle no.) hereby authorize
KIM CHWE AUTO PTE LTD.
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SLM 4741 H that was
damaged pursuant to the accident which occurred on 15/12/2017 (date) along
Bukit Timah Rd Towards Woodlands (Before CTE) (location)
involving vehicle no/s SJY 9857 K ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 15th day of December (month) 20 17 (year)


Signed by "the third party claimant"



Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, KIM CHWEE AUTO PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for \$ 6,700.00 (Global Sum) for vehicle no. SLM 4741H that was damaged pursuant to the accident which occurred on 15/12/2017 (date) along BUKIT TIMAH RD TWDS WOODLANDS B4 CTE (location) involving vehicle no/s SJY 9857K.

This is pursuant to the inspection conducted on 15/12/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TANG TZE LING MELISSA ("the third party claimant") of vehicle no. SLM 4741H make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLM 4741H (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 6 (day) of 6 (month) 2019 (year)

LWP

Signed by appointed surveyor



Signed by "the workshop" (with chop)

TAX INVOICE

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

Tax Invoice : 20037

Date: 06.04.2018

Vehicle No: SLM4741H

Make/Model: KIA SORENTO

Chassis/Eng# :

Accident Date: 15.12.2017

Claim No : 1217-20037

:

	Amount
To proceed on lump sum repair	S\$ 6,000.00

E. & O. E.

Total : S\$ 6,000.00

GST @ 7% : S\$ 420.00

Amount Due : **S\$ 6,420.00**


for KIM CHWEE AUTO PTE LTD

All Invoices are subjected to GST

DYNAMIC CAR RENTAL

1 Kaki Bukit Ave 6 #01-46 Autobay

Singapore 417883

Tel No: 6741 7244 / 6746 5405 Fax No: 6745 8520 / 6746 5786

Co. Reg No: 52928467K

To: TANG TZE LING

Invoice : DCR-2017-12-34

Date : 18.12.2017

Agreement No : 19839

Payment Term: LOD

DESCRIPTION

AMOUNT

Rental charges for vehicle : SLH7586X (1217-20037) \$ 300.00

Rental Period from 15.12.2017 to 18.12.2017 .

E. & O. E.

Total \$ 300.00

NANCY LAM

for Dynamic Car Rental

Dynamic Car Rental

1 KAKI BUKIT AVENUE 6, #01-46/48/50 AUTOBAY, SINGAPORE 417883

TEL: (+65) 6741 7244, 6746 5405 FAX: (+65) 6745 8520, 6746 5786

Co. Reg. No. 52928467K

RENTAL TERMS AND CONDITIONS

No. 19839

Name: <u>Tang Tze Ling Melissa</u>			REG. No. <u>SLH 7586X</u>		MAKE MODEL: <u>Toyota Axio</u>	
ADDRESS			DIESEL		PETROL	
			E		1/4 1/2 3/4 F	
			KM IN		DATE & TIME IN <u>18/12/17 @ 3.31pm</u>	
			KM OUT		DATE & TIME OUT <u>15/12/17 @ 2.40pm</u>	
			KM DRIVEN		TIME USED	
NAMED DRIVER						
DRIVING LICENCE NO	DATE OF EXPIRY	PLACE OF ISSUE	HOURS		@ \$	
PASSPORT NO	DATE OF ISSUE	PLACE OF ISSUE	3 DAYS		@ \$ 100 300	
ADD NAMED DRIVER			WEEKS		@ \$	
DRIVING LICENCE NO	DATE OF EXPIRY	PLACE OF ISSUE	MONTHS		@ \$	
PASSPORT NO	DATE OF ISSUE	PLACE OF ISSUE	BY INITIALLING, RENTER AGREES TO PAY ADD FEE FOR COLLISION DAMAGES WAIVER (C.D.W.)		SUB-TOTAL 300	
IMPORTANT NOTES: This vehicle is licenced to carry 04 passengers only. No refund will be given for vehicle returns early. No refund will be given for period left in vehicle. Hirer is liable to pay first \$2000 under section I & II in any accident plus loss of earnings while damaged vehicle is under repair. Hirer is liable to pay all parking fee and traffic summonses. Vehicle return during office hour only. No Service on Public Holiday and Sunday. ADDITIONAL CONDITIONS: * Geographical areas: Singapore & West Malaysia. * Driver must be: a) 18 years old and above; b) holding a valid relevant class of driving license. * Additional Own Damage Excess of \$51,000 is applicable for any named/unnamed drivers who: a) age 22 to 23 years old; b) age 66 to 70 years old; c) with driving experience of 1 year to less than 2 years in Singapore on the relevant classes of driving license. * Additional All Claims excess of \$52,000 is applicable for any named/unnamed drivers who: a) is 18 years old to 21 years old and/or b) is 71 years old and above and/or c) with driving experience of less than 1 year on the relevant classes of driving license. * Upon returning the replacement vehicle, you must ensure that all expensive and important items to be removed away from this replacement vehicle. We'll will not be responsible for any reporting of such losses. * Hirer is liable to pay first \$2000 under section I & II in any accident plus loss of earning while damage vehicle is under repair. Hirer is responsible for Additional \$2,000.00 Excess to the THIRD PARTY DAMAGE / INJURY claims.			TOTAL RENTAL			
			DELIVERY FEE			
			COLLECTION FEE			
			PER DAY \$		PER WEEK \$	PER MONTH \$
BY INITIALLING, RENTER AGREES TO PAY ADD FEE FOR PERSONAL ACCIDENT INSURANCE (P.A.I.)			PER DAY \$		PER WEEK \$	PER MONTH \$
			PREPAYMENT		TOTAL CHARGE	
CHECK			DEPOSIT			
CASH			RECEIPT NO.		NETT CHARGE	
AMOUNT DUE / REFUND						

I HAVE READ THE TERMS AND CONDITIONS ON BOTH SIDES OF THIS RENTAL AGREEMENT AND AGREE THEREOF.

SIGNED BY THE PARTIES HERETO ON THE

DAY OF

X

DYNAMIC CAR RENTAL

X

RENTER'S/DRIVER'S SIGNATURE



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-17-189544

Date of Request: 15/12/2017

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 15/12/2017
Enquiry By KCA USER 1
TP Vehicle No. SJY9857K
Accident Date 15/12/2017

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-17-189544

Date of Request: 15/12/2017

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 15/12/2017
Enquiry By KCA USER 1
TP Vehicle No. SJY9857K
Accident Date 15/12/2017

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJY9857K	AIG Asia Pacific Insurance Pte. Ltd.	31/05/2017-30/05/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

































CLAIM SUBFOLDER TRACKING


























Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Dec 2017 Edit Reg		15 Dec 2017 00:00 Edit Adj Rpt	\$56,000.00 Edit Estimates	\$56,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	PIETER WILLEM JAN KEMPS , ID: S75893291								
Main Claimant:	TANG TZE LING, MELISSA , ID: S8434637C								
Vehicle Reg. No.:	SLM4741H	Date of Loss:	15/12/2017 10:00 - :59 [8 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6349812149SG	Policy/Cover Note No.:	2100469347 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJY9857K	Policy No. (Claimant):	2100505989-00000						
		Excess:							
Repairer:	Kim Chwee Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit, 417883 Eunos - Tel: 67465405/67417244								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 28/12/2017]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLM4741H (6349812149SG)
[SJY9857K]
TP
TANG TZE LING, MELISSA
Dec 15 2017 10:00AM
[PIETER WILLEM JAN KEMPS]
Kim Chwee Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	 Edit	
Assessment Reports			1 per page <input type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	19/12/17 12:44	Accident Statement <small>From: SC - Reg. No: SJY9857K, Claimant: PIETER WILLEM JAN KEMPS</small>	 Load HTML	
Photos/Images			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/03/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
2	24/03/18 15:35	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
3	24/03/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/03/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/03/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/03/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/03/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/03/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/03/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/03/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/03/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/03/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/03/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/03/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/03/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/03/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/03/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/03/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/03/18 15:35	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
21	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
22	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
23	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
24	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
25	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	24/03/18 15:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/12/17 14:22	TP GIA REPORT	 Load PDF	
2	05/04/18 20:37	TP ESTIMATE - MARKED	 Load PDF	
3	06/06/19 11:15	Email final letter to OI 17.5.19	 Load PDF	
4	06/06/19 11:15	Email to AIG to settle at best 28.5.19	 Load PDF	
5	19/06/19 09:24	WORKSHOP INVOICE	 Load PDF	
6	19/06/19 09:24	AUTHORISATION TO ACT FORM	 Load PDF	
7	19/06/19 09:24	Release Voucher	 Load PDF	
8	19/06/19 09:24	RENTAL RECEIPT	 Load PDF	
9	19/06/19 09:24	GIA SEARCH	 Load PDF	
10	19/06/19 09:24	LETTER TO OI	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</div> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJY9857K (Insd veh)	Model:	KIA SORENTO 2.2 D CRDI (A)
	SLM4741H (TP veh)		
Date of Accident:	15/12/2017		

Global Sum Settlement	:	<input checked="" type="checkbox"/> [X] Yes	<input type="checkbox"/> [] No	
Repair Estimate	: \$	14,399.49		
Final Repair Cost	: \$	6,700.00		
Loss of Use	: \$	days at \$0.00 per day		
Rental (if any)	: \$	3 days		
LTA / GIA Search Fee	: \$			
Others:	: \$			
	: \$			
Final Settlement Sum (Global Sum)	: \$	6,700.00		

Is Third Party Workshop GIA Registered? ☐ [] YES ☒ [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Kim Chwee Auto Pte Ltd	: \$	6,700.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

19 Jun
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17023923/AWA3Q2

Date: 19/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100469347
Claimant Vehicle No : SLM4741H **Insured Vehicle No :** SJY9857K
 Date of Loss: 15/12/2017 Nature of Claim: TP Claim No: 6349812149SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM4741H**
 Make & Model: KIA SORENTO, 2.2 D CRDi (A) Engine No: D4HBHH311560
 Reg. Date: 31/03/2017 (Man. Year: 2017) Chassis No: KNAPH81BMH5329217
 Colour: Grey Odometer: 10125 km
 Engine Capacity: 2199 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,197.47	6,145.35	4,052.12	39.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,260.00	1,380.00	1,880.00	57.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,457.47	7,525.35	5,932.12	44.08
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	13,457.47	6,000.00	7,457.47	55.42
+ GST 7.00/7.00% (S\$)	942.02	420.00	522.02	55.41
Nett Amount (S\$)	14,399.49	6,420.00	7,979.49	55.42
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,722.00		
Global Sum Settlement (S\$)		6,700.00		

INSPECTION

Date of Assignment: 15/12/2017
 Date Inspected: 15/12/2017 Inspected At:

Kim Chwee Auto Pte Ltd (HQ)
1 Kaki Bukit Avenue 6 #01-48,
AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP LH	Cut	2,656.90 FL	*2,656.90 FL
2	1		*FRONT FENDER LH	Buckled	480.70 FL	*480.70 FL
3	1		*FRONT FENDER INNER SHIELD LH	Deformed	95.40 FL	*95.40 FL
4	1		*FRONT FENDER ARCH GARNISH LH	Cut	347.50 FL	*347.50 FL
5	1		*FRONT SUPPORT PANEL	Cracked	922.40 FL	*922.40 FL
6	1		*FRONT GRILLE	Not Necessary	455.70 FL	*- FL
7	1		*FRONT BUMPER CORNER PARKING SENSOR	Damaged	227.50 FL	*227.50 FL
8	1		*FRONT BUMPER LOWER GARNISH	Not Necessary	372.50 FL	*- FL
9	1		*FRONT BUMPER	Deformed	741.70 FL	*741.70 FL
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	315.70 FL	*- FL
11	1		*FRONT BUMPER FOG LAMP LH	Cracked	321.30 FL	*321.30 FL
12	1		*FRONT BUMPER FOG LAMP COVER	Not Necessary	62.10 FL	*- FL
13	1		*FRONT BUMPER SIDE RETAINER	Damaged	40.20 FL	*40.20 FL
14	1		*FRONT BUMPER SPONGE	Cracked	121.60 FL	*121.60 FL
15	1		*FRONT BUMPER HEADLAMP NOZEL MOTOR	Cracked	401.30 FL	*258.00 FL
16	1		*FRONT BUMPER HEADLAMP NOZEL MOTOR COVER	Missing	48.30 FL	*48.30 FL
17	1		*FRONT SPORT RIM	Cut	1,321.65 FS	*450.00 FS
18	1		*FRONT SHOCK ABSORBER LH	Not Necessary	419.00 FL	*- FL
19	1		*FRONT KNUCKLE ARM	Not Necessary	357.00 FL	*- FL
20	1		*FRONT LOWER ARM	Not Necessary	474.00 FL	*- FL
21	1		*FRONT WHEEL BEARING	Not Necessary	279.00 FL	*- FL
22	1		*FRONT TYRE	Not Necessary	550.00 FS	*- FS
23	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
24	1		*SET FRONT FENDER INNER SHIELD CLIP LH	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	11,111.45	6,771.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	913.98	626.15
Total Parts (\$\$)	10,197.47	6,145.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO APPLY ANTI RUST CHEMICAL	New	50.00	0.00
3	REMOVE AND REPLACE LH FRONT SUAPENSION AND UNDER CARRIAGE	New	380.00	0.00
4	TO CHECK WHEEL ALIGNMENT	New	80.00	80.00
5	REMOVE AND REFIX AIRCON CONDENSER & REFILL AIRCON GAS	New	150.00	60.00
6	REMOVE AND REFIX RADIATOR	New	120.00	60.00
7	TO REMOVE AND REPLACE SPARE PART AND PANEL BEATING	New	1,200.00	750.00
8	TO SPRAY PAINTING AND ETC	New	1,200.00	400.00
Gross Labour Cost (S\$)			3,260.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >