

ASS. REC. BY:

REF:

CS/EG117023937/R1rd321

Special Instruction:

Surveyor: Raisal

ASSIGNMENT (Office)

From (Person): Yee Pei Li

of

EG1

Date/Time 11:57 am @ 18/12/17

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBA 7007G

Insured:

SGV 4683D

at Workshop m/s

SG 98 Motor

Tel:

6452 4898

of 31K 4001, AMK Ind. Prk I # 01-21

Policy No:

Claim No:

SGV 4683D / SE / PL

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

14/12/2017

CA / REV / REP. / REV 24 HRS

CWP

19/12/2017

H.O.D. Endorsement:

Date/Time:

12:20 pm @ 18/12/17

Person Contacted:

Rose

Vehicle ~~IN~~ / OUT

| Date/Time | Action/Instruction                  |
|-----------|-------------------------------------|
|           | (✓) Estimate                        |
|           | FBA 7007G - X                       |
|           | SGV 4683D - X                       |
|           |                                     |
|           |                                     |
|           | Confirm with Rose L/S \$3000.4 days |
|           | Red: \$3033.40, 50%.                |

REF.

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. **FBA 7007 G**at Workshop m/s **SG 98 Motor**of **4001 AMK Ind Bank 1**Insured **# 01-21**

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time Action / Instruction

20/12/2017 - Mileage Not Taken - Motor Faulty.

RECEIVED 05 JUL 2018

Veh No: **FBA 7007 G** /r Regn: **2014 Jan**Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Yamaha FZ 16** col: **153**Colour: **Black** A/C Insured / Std / NI / NASp. Reading: **Not Available** T-Radio: Insured / Std / NI / NA

Eng No: \_\_\_\_\_

C No: **ME121 L04BD 2039806**Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size F: **140/70/17**R: **140/70-17**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIRE SUMI / TOYO / YOKO or

Front

R/Bal: **4** mm R/Bal: **4** mm

L/Bal: \_\_\_\_\_ mm L/Bal: \_\_\_\_\_ mm

D.O.A: **14/12/17** D.O.A: **20/12/2017**Survey held at **SG 98 Motor**Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time File Pass to:

by **typut**

Date/Time File Return to:

☐ : Preli. Report☒ : Final ReportDays Of Repair: **4**Resurvey No. of Trip: **1**

Survey Fee:

Transportation:

Fuel &amp; AG: \$

Penalty:

Other:

Total:

Add Fee: ☐ Site Insp \$☐ Interview \$☐ Tech. Insp \$☐ Weekend \$Report Format: **TP**Lump Sum / L.S. (\$) **3000**

250

250

## Nivitha (LKK Auto)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Monday, 18 December, 2017 11:57 AM  
**To:** 'admin-d@lkkauto.com'  
**Subject:** OI : SGV4683D / TP : FBA7007G/LKK / DOA : 14.12.2017  
**Attachments:** SGV4683D - SAS.pdf; FBA7007G - SAS.pdf; FBA7007G - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **SG 98 MOTOR PTE LTD.**

ADDRESS : BLK 4001 ANG MO KIO INDUSTRIAL PARK 1  
#01-21  
SINGAPORE 569622

PERSON TO CONTACT : ROSE @ 6452 4898 / 9171 1655

ERGO OFFICER-IN-CHARGE : STEVE LIM

***Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Try to obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are our insured's and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

**Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI17023937/R1rd3

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 18-12-2017



Code : EGI

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | SGV 4683D      | Veh. Inspected | FBA 7007G  |
| Policy No.   |                | Coverage (\$)  | 0.00       |
| Claim No.    | SGV4683D/SE/pl | Excess (\$)    | 0.00       |
| Assign From  | YEE PEI LI     | Assign Date    | 18/12/2017 |

## 2. Vehicle Particulars & Condition

|              |        |              |
|--------------|--------|--------------|
| Make & Model | c.c    | 0            |
| Engine No.   | HIDDEN | Year of Reg. |
| Chassis No.  |        | Colour       |
| Odometer     | -      | Steering     |
| Brakes       |        | Modification |
| General      |        |              |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |
|--|
|  |
|--|

## 5. General Information

|                |   |                 |
|----------------|---|-----------------|
| Accident Date  | 14/12/2017  | Inspection Date |
| Survey held at | SG 98 MOTOR PTE LTD<br>BLK 4001 ANG MO KIO INDUSTRIAL PARK 1<br>#01-21 SINGAPORE 569622 |                 |

## 5a. Remarks

|  |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |  |
|----------------------------|--|
| Date Of Report             | 15/12/2017 15:56                           |
| Date Of Accident           | 14/12/2017 20:30                           |
| Exact Location Of Accident | JUNCTION WOODLANDS AVE 7 & WOODLANDS DR 72 |
| Country/State of Loss      | SINGAPORE                                  |

### DETAILS OF OWN VEHICLE

|                             |                              |
|-----------------------------|------------------------------|
| Vehicle Registration Number | FBA7007G                     |
| <b>Insured/Policyholder</b> |                              |
| Name Of Registered Owner    | SIMON SATISH LAZARUS         |
| NRIC No                     | S9711978C                    |
| Email Address               | SATISHKUMAR9711978@GMAIL.COM |
| Mobile Phone No             | (LOCAL) +65-87271549         |
| Alternative Phone No        | OTHERS-87271549              |

### Vehicle Particulars

|  |             |
|--|-------------|
| Manufacturer   | YAMAHA      |
| Model  | FZ 16       |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO          |
| If No, Please state action to be taken                                       | THIRD PARTY |
| Vehicle Category   | MOTORCYCLE  |

### Insurance Company

|                           |                         |
|---------------------------|-------------------------|
| Name of Insurance Company | AXA INSURANCE PTE LTD   |
| Type Of Coverage          | THIRD PARTY             |
| Fleet Policy              | NO                      |
| Policy Number             | AN3160469               |
| Cover Note Number         | 06/11/2017 - 05/11/2018 |

### Driver

|                      |                              |
|----------------------|------------------------------|
| Name of Driver       | SIMON SATISH LAZARUS         |
| NRIC No              | S9711978C                    |
| Date Of Birth        | 05/04/1997                   |
| Occupation           | INDOOR                       |
| Date Of Driving Pass | 23/10/2017                   |
| Driving Experience   | 0 YEAR AND 1 MONTH           |
| Gender               | MALE                         |
| Mobile Number        | (LOCAL) +65-87271549         |
| Fax Number           |                              |
| Contact Number       | OTHERS-87271549              |
| Email Address        | SATISHKUMAR9711978@GMAIL.COM |

Approximate Age

Injuries Sustain

LEFT LEG,RIGHT RIB & JAW

Injured person in which vehicle?

FBA7007G

Were seat belts worn?

Was injured conveyed to hospital by ambulance? YES

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# SINGAPORE POLICE FORCE



T/20171215/2008

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

1 of 4

Report No. T/20171215/2008

## REPORT OF A TRAFFIC ACCIDENT

|  |            |                              |  |                          |                            |
|--|------------|------------------------------|--|--------------------------|----------------------------|
| Date/Time Report Made:<br>15/12/2017 02:11 |            | Vide Report No.:             |  | Station Diary No.:<br>26 |                            |
| <b>Informant's Particulars</b>             |            |                              |  |                          |                            |
| Name of Informant:<br>SIMON SATISH LAZARUS |            |                              | Address:<br>APT BLK 796 WOODLANDS DRIVE 72 #03-41 SINGAPORE 730796 |                          |                            |
| ID Type / ID No.:<br>NRIC NO / S9711978C   |            |                              | Contact No.:<br>Home/Office: Mobile: 87271549                      |                          |                            |
| Nationality:<br>SINGAPORE CITIZEN          |            |                              | Email:   |                          |                            |
| Sex:<br>Male                               | Age:<br>20 | Date of Birth:<br>05/04/1997 | Type of Informant:<br>Rider  |                          |                            |
| Race:<br>Indian                            |            |                              | Language:  |                          | Institution / School Name: |
| Occupation:<br>PETROLEUM SURVEYOR          |            |                              | Driving Licence Information:<br>Class 2B Date of Expiry:           |                          |                            |

## General Information of the Accident

|   |                              |   |   |   |
|---|------------------------------|---|---|---|
| Type of Accident:   | Injury<br>Attended by Police | Drink<br>Drive:<br>No                       | Date/Time of<br>Accident:<br>14/12/2017 08:30 | Type of Location:<br>X-Junction         |
| Location:<br>Junction of Road 1 and Road 2<br>WOODLANDS DRIVE 73<br>WOODLANDS DRIVE 72<br>junction of Woodlands Avenue 7 and Woodlands Drive 72 |                              |   |   |   |
| Weather:<br>Clear   |                              | Road Surface:<br>Wet                        |   | Road Speed Limit:                       |
| Traffic Flow:   |                              | Traffic Control:<br>Traffic Light - Working |   | Traffic Volume:<br>Moderate             |
| Type of Collision:<br>Between Moving Vehicles - Head To Side  |                              |   |   | Anyone conveyed by<br>ambulance:<br>Yes |

## Details of Vehicle Involved

| Vehicle No | Type       | Make   | Model | Color | Condition            | No of Passenger |
|------------|------------|--------|-------|-------|----------------------|-----------------|
| FBA7007G   | Motorcycle | YAMAHA | FZ 16 | Black | Seriously<br>Damaged | 0               |
| SGV4683D   | Car        |        |       |       | Slightly<br>Damaged  | 0               |

## Details of Vehicle Insurance

| Vehicle No | Insurance Company               | Insurance No | Effective  | Expiry Date |
|------------|---------------------------------|--------------|------------|-------------|
| FBA7007G   | AXA INSURANCE SINGAPORE PTE LTD | AN3160469    | 06/11/2017 | 05/11/2018  |





**SINGAPORE  
POLICE FORCE**



T/20171215/2008

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

3 of 4

Report No. T/20171215/2008

CONTINUATION OF REPORT

# SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 669622

Tel: 6452 4898 Fax: 6452 4868

Email: sg\_motor\_enterprise@yahoo.com.sg

Date: 18 December 2017

To : LKK

By Fax: 6256-4315

Attn : Rasul

Tel : 90010068

VEHICLE NO : FBA 7007G

FZ 16 Yamaha

ACCIDENT DATE: 14 December 2017

| <u>Description</u>          | <u>Qty</u> | <u>Quotation \$</u>                     |
|-----------------------------|------------|---|
| 1 Handle Bar                | 1          | 150 235.00 <i>PA</i>                    |
| 2 Brake Lever               | 1          | 30 95.00 <i>SA</i>                      |
| 3 Clutch Lever              | 1          | 40 90.00 <i>SA</i>                      |
| 4 Mirror                    | 1 set      | 120 190.00 <i>SA</i>                    |
| 5 Meter Assy                | 1          | 450 550.00 <i>BA</i>                    |
| 6 Lamp Assy                 | 1          | 195.00 <i>X SA</i>                      |
| 7 Head Lamp                 | 1          | 250 350.00 <i>BA</i>                    |
| 8 Fork Tube                 | 1 set      | 360 600.00 <i>PA</i>                    |
| 9 Fork Under Bracket        | 1          | 195.00 <i>PA</i>                        |
| 10 Signal L/RH              | 2          | 120 190.00 <i>SA</i>                    |
| 11 Throttle Grip            | 1 set      | 290.00 <i>X SA</i>                      |
| 12 Front Mudguard           | 1          | 140 195.00 <i>SA</i>                    |
| 13 Front Cowling            | 1          | 200 275.00 <i>BA</i>                    |
| 14 Steering Cone Bearing    | 1          | 135.00 <i>SA</i>                        |
| 15 Tank Cover LH            | 1          | 120 190.00 <i>SA</i>                    |
| 16 Gear Pedal               | 1          | 50 75.00 <i>SA</i>                      |
| 17 Footrest Bracket         | 1          | 165.00 <i>X SA</i>                      |
| 18 Front Rim                | 1          | 350.00 <i>Repair</i> (100) <i>BT</i>    |
| 19 Front Wheel Axle         | 1          | 50 155.00 <i>SA</i> <i>Local repair</i> |
| 20 Exhaust Guard - Silver   | 1          | 450 259.00 <i>SA</i>                    |
| 21 Exhaust Guard - Black    | 1          | 250.00 <i>SA</i>                        |
| 22 Rear LH Tail Cover       | 1          | 165.00 <i>X SA</i>                      |
| 23 Rear LH Pillion Footrest | 1          | 95.00 <i>X SA</i>                       |
| 24 Main Stand               | 1          | 87.00 <i>Repair</i>                     |
| Sub-Total                   |            | 5,376.00                                |
| Less 10%                    |            | 537.60                                  |
| Sub-Total                   |            | 4,838.40                                |

VEHICLE NO : FBA 7007G

FZ 16 Yamaha

Nett items

- 1 IU unit
- 2 Ignition original key
- 3 Front number plate
- 4 Towing fee
- 5 Remove & replace necessary parts, align & etc
- 6 Remove & replace fork assy, top up fork oil & rim
- 7 Supply sticker

160.00 *sur*

290.00 *at*

15.00 *at*

~~80.00~~ *40*

~~350.00~~ *250*

~~220.00~~ *150*

~~80.00~~ *40*

Sub-Total

1,195.00

Nett Total

6,033.40

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion  
Thank you

SG 98 MOTOR PTE LTD

:LG

*Rasul*

*Hp 90010068*

*4 days*

*h/s*

*21/12/17 @ 0930*

*2754*

*1045*

*3799*

*20%*

*3039.20*

*413-3000*

*4 days*




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |   |                              |            |   |
|--|---|------------------------------|------------|---|
| ERGO INSURANCE PTE LTD   |   | Ref : CS/EGI17023937/R1rd3e2 |            |   |
| 5 TEMASEK BOULEVARD<br>#04-01 SUNTEC TOWER FIVE<br>SINGAPORE 038985  |   | Date : 11-07-2018            |            |  |
|  |   | Code : EGI                   |            |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |   |                              |            |   |
| Insured Veh.   | SGV 4683D   | Veh. Inspected               | FBA 7007G  |   |
| Policy No.   |   | Coverage (\$)                | 0.00       |   |
| Claim No.  | SGV4683D/SE/pl  | Excess (\$)                  | 0.00       |   |
| Assign From  | YEE PEI LI  | Assign Date                  | 18/12/2017 |   |
| <b>2. Vehicle Particulars &amp; Condition</b>  |   |                              |            |   |
| Make & Model   | YAMAHA FZ 16  | c.c                          | 153        |   |
| Engine No.   | HIDDEN  | Year of Reg.                 | 2014       |   |
| Chassis No.  | ME121C0GBD2039806   | Colour                       | BLACK      |   |
| Odometer   | -   | Steering                     | IN ORDER   |   |
| Brakes   | IN ORDER  | Modification                 | SPORTS RIM |   |
| General  | FAIR  |                              |            |   |
| <b>3. Conditions of Tyres</b>  |   |                              |            |   |
|  | Size  | Make                         | Balance    |   |
| R/H Front Tyre   | 140/70-17   | PIRELLI                      | 4 mm       |   |
| L/H Front Tyre   |   |                              | mm         |   |
| R/H Rear Tyre  | 140/70-17   | PIRELLI                      | 4 mm       |   |
| L/H Rear Tyre  |   |                              | mm         |   |
| <b>4. Description of Damages</b>   |   |                              |            |   |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION.<br>DAMAGES SEE DETAILS.  |   |                              |            |   |
| <b>5. General Information</b>  |   |                              |            |   |
| Accident Date  | 14/12/2017  | Inspection Date              | 20/12/2017 |   |
| Survey held at   | SG 98 MOTOR PTE LTD<br>BLK 4001 ANG MO KIO INDUSTRIAL PARK 1<br>#01-21 SINGAPORE 569622 |                              |            |   |
| <b>5a. Remarks</b>   |   |                              |            |   |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                              |            |   |
| <b>5b. Estimate Days of Repair</b>   |   |                              |            |   |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | <b>4 Working Days</b>        |            |   |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBA 7007G

| Qty | Description of Parts               | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b> |                      |                           |                   |
| 1   | HANDLE BAR                         | BENT                 | 235.00                    | 150.00            |
| 1   | BRAKE LEVER                        | SCRATCHED            | 95.00                     | 30.00             |
| 1   | CLUTCH LEVER                       | SCRATCHED            | 90.00                     | 40.00             |
| 1   | SET MIRROR                         | SCRATCHED            | 190.00                    | 120.00            |
| 1   | METER ASSY                         | BROKEN               | 550.00                    | 450.00            |
| 1   | LAMP ASSY                          | SERVICEABLE          | 195.00                    | -                 |
| 1   | HEAD LAMP                          | BROKEN               | 350.00                    | 250.00            |
| 1   | SET FORK TUBE                      | BENT                 | 600.00                    | 560.00            |
| 1   | FORK UNDER BRACKET                 | BENT                 | 195.00                    | 195.00            |
| 2   | SIGNAL L?RH                        | CRACKED              | 190.00                    | 120.00            |
| 1   | SET THROTTLE GRIP                  | SERVICEABLE          | 290.00                    | -                 |
| 1   | FRONT MUDGUARD                     | SCRATCHED            | 195.00                    | 140.00            |
| 1   | FRONT COWLING                      | BROKEN               | 275.00                    | 200.00            |
| 1   | STEERING CONE BEARING              | NECESSARY            | 135.00                    | 135.00            |
| 1   | TANK COVER LH                      | SCRATCHED            | 190.00                    | 120.00            |
| 1   | GEAR PEDAL                         | BENT                 | 75.00                     | 50.00             |
| 1   | FOOTREST BRACKET                   | SERVICEABLE          | 165.00                    | -                 |
| 1   | FRONT WHEEL AXLE                   | SCRATCHED            | 155.00                    | 50.00             |
| 1   | EXHAUST GUARD-SILVER }             | SCRATCHED            | 259.00                    | 450.00            |
| 1   | EXHAUST GUARD-BLACK }              | SCRATCHED            | 250.00                    | -                 |
| 1   | REAR LH TAIL COVER                 | SERVICEABLE          | 165.00                    | -                 |
| 1   | REAR LH PILLION FOOTREST           | SERVICEABLE          | 95.00                     | -                 |
| 1   | MAIN STAND                         | TO REPAIR SEE LABOUR | 87.00                     | -                 |
|     | LESS 10% DISCOUNT                  |                      | -502.60                   | -306.00           |
|     |                                    |                      | 4,523.40                  | 2,754.00          |
| 1   | FRONT RIM (LOCAL REPAIR)(SN)       | BENT                 | 350.00                    | 100.00            |
|     | LESS 10% DISCOUNT                  |                      | -35.00                    | -                 |
|     |                                    |                      | 315.00                    | 100.00            |

Report Ref No. CS/EGI17023937/R1rd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts  | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|-----------|---------------------------|-------------------|
|     | <b><u>SPECIAL NETT ITEMS</u></b>  |           |                           |                   |
| 1   | IU UNIT (SN)  | SCRATCHED | 160.00                    | 160.00            |
| 1   | IGNITION ORIGINAL KEY (SN)  | CUT       | 290.00                    | 290.00            |
| 1   | FRONT NUMBER PLATE (SN)   | BENT      | 15.00                     | 15.00             |
|     |   |           | 465.00                    | 465.00            |
|     | <b><u>LABOUR</u></b>  |           |                           |                   |
|     | TOWING FEE.   |           | 80.00                     | 40.00             |
|     | REMOVE & REPLACE NECESSARY PARTS,ALIGN & ETC.INCLUSIVE OF THE REPAIR OF MAIN STAND. |           | 350.00                    | 250.00            |
|     | REMOVE & REPLACE FORK ASSY,TOP UP FORK OIL & RIM.                                   |           | 220.00                    | 150.00            |
|     | SUPPLY STICKER.   |           | 80.00                     | 40.00             |
|     |   |           | 730.00                    | 480.00            |
|     | <b>GRAND TOTAL</b>  |           | <b>6,033.40</b>           | <b>3,799.00</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>         |           |                           | <b>3,000.00</b>   |

Report Ref No. CS/EG17023937/R1rd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.