



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS3/MSG17023946/M1d3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 18-12-2017	
		Code : MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SJB 2444K	Veh. Inspected	SKA 4948D
Policy No.	B27227899QMY	Coverage (\$)	0.00
Claim No.	541128	Excess (\$)	0.00
Assign From	MERIMEN (JASMINE LOK)	Assign Date	18/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/12/2017	Inspection Date	18/12/2017
Survey held at	MJE MOTOR BLK 7 SIN MING IND EST SEC C #01-96 SINGAPORE 575642		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Dec 2017		18 Dec 2017 11:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	MICHAEL ARTHUR ROCHE, ID: S26304191								
Main Claimant:	MO LIPING, ID: G1021417W								
Vehicle Reg. No.:	SKA4948D	Date of Loss:	15/12/2017 12:00 - :59						
Claim Type:	TP / 541128	Policy/Cover Note No.:	B27227899QMY (Comprehensive) Coverage: 04/01/2017 - 03/01/2018						
Vehicle Reg. No. (Insured):	SJB2444K	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82, 575642 Sin Ming - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/12/2017]								
Driver/Custodian (Insured):	PATRICIA NAH LI HUA MRS PATRICIA ROCHE (60 / Female), NRIC: S1240899D, Tel: +6597472300								
Adj Asg. Remarks:	THIRD PARTY PRE-REPAIR SURVEY								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Margaret Loh

From: Margaret Loh
Sent: Monday, 18 December, 2017 11:39 AM
To: 'Cheonghoh Law'
Cc: Jasmine Lok Kheng Kwei
Subject: RE: Accident involving SKB2444K & SKA4948D ON 15.12.2017

Hi Catherine,

Please be informed our insured vehicle number is SJB2444K

Best Regards

Margaret Loh
Admin Officer, Claims Services (Motor)
Direct line +65 6594 2553 | Direct fax +65 6225 7402 | margaret_loh@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Margaret Loh
Sent: Monday, 18 December, 2017 11:10 AM
To: 'Cheonghoh Law' <mail@cheonghoh.sg>
Cc: Jasmine Lok Kheng Kwei <jasmine_lok@sg.msig-asia.com>
Subject: RE: Accident involving SKB2444K & SKA4948D ON 15.12.2017

Dear Catherine,

We refer to your reply of even date.

We regret to inform you that we are unable to accept your nominated Single Joint Experts(SJE)

We will proceed to appoint the following surveyor, **M/s LKK Auto Consultant Pte Ltd** for your claim.

Please be informed that our surveyor will also be conducting the post repair inspection within the timeline stipulated under the protocol.

Thank you.

Best Regards

Margaret Loh
Admin Officer, Claims Services (Motor)
Direct line +65 6594 2553 | Direct fax +65 6225 7402 | margaret_loh@sg.msig-asia.com



Insurer Claims
Team of the Year
2016



A Member of **MS&AD** INSURANCE GROUP

From: Cheonghoh Law [<mailto:mail@cheonghoh.sg>]
Sent: Monday, 18 December, 2017 11:03 AM
To: Margaret Loh <margaret_loh@sg.msig-asia.com>
Cc: Jasmine Lok Kheng Kwei <jasmine_lok@sg.msig-asia.com>
Subject: Re: Accident involving SKB2444K & SKA4948D ON 15.12.2017

Dear Sirs,

We refer to the above matter and your email of even date.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your 10 appointed surveyors as stated in your aforesaid letter.

We are further instructed to append below our client's 10 proposed surveyors as follows:

- (1) Lee Kok Weng
- (2) Patrick Ng Kong Beng
- (3) Ang Guea Kiang
- (4) How Andrew
- (5) Chang Fuh Keong
- (6) Philip Foo
- (7) Ong Ah Keng, Kent
- (8) Ong Poh Meng
- (9) Ng Soon Aik Francis
- (10) Ng Soon Chuan Louis

If you are not agreeable to our list of surveyors above, kindly appoint your surveyor to proceed with the pre- repair survey and please be informed that our client's vehicle, SKA 4948 D is currently laying at our client's workshop, MJE Motor , Blk 7 Sin Ming Sector C #01-96 Singapore 575642.

Contact Person : Mr Michael Low / Jo
9107 6996 / 6454 2203

Please proceed to do the needful.

Thanks & regards
Catherine

CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05
Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 18 Dec 2017, at 10:35 AM, Margaret Loh <margaret_loh@sg.msig-asia.com> wrote:

Your Ref : LCH.lg/SJEM.70993.17
Our Ref : 541128

Dear Sirs,

We refer to your fax dated 18.12.2017.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection.

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert)

If not, you may wish to nominate any of the 9 surveyors listed below as the SJE, depending on their availability:

- 1) Adrian Ling
- 2) Kenneth Kong
- 3) Marcus Chua
- 4) Henry Ng
- 5) Lau Kwok Kwong
- 6) Frankie Pang
- 7) Ng You Han
- 8) Gary Soon
- 9) Chow Bo Xiong

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB: If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

Please let us know which workshop and contact person.

Thank you.

Best Regards

Margaret Loh

Admin Officer, Claims Services (Motor)

Direct line +65 6594 2553 | Direct fax +65 6225 7402 | margaret_loh@sg.msig-asia.com

<image013.png>

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore
048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G

| msig.com.sg <image014.png> <image015.png> <image016.png> <image017.png>

<image018.jpg>

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

--	--

Case Handler Date

*C: Critical *N: Non-Critical

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/12/2017 15:07
Date Of Accident	15/12/2017 13:30
Exact Location Of Accident	KALLANG ROAD TOWARDS VICTORIA ST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA4948D
Insured/Policyholder	
Name Of Registered Owner	MO LIPING
NRIC No	G1021417W
Email Address	DL56MLPSG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-87272675
Alternative Phone No	OFFICE-87272675
Vehicle Particulars	
Manufacturer	BMW
Model	325
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA300830/1
Cover Note Number	
Driver	
Name of Driver	MO LIPING
NRIC No	G1021417W
Date Of Birth	26/12/1987
Occupation	INDOOR
Date Of Driving Pass	24/10/2013
Driving Experience	4 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-87272675
Fax Number	
Contact Number	OFFICE-87272675
Email Address	DL56MLPSG@GMAIL.COM

Address 85 PHENG GECK AVE #01-19
 Postcode 346271
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - U-TURN
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJB2444K
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver PATRICIA NAH LI HUA
 NRIC/Passport Number S1240899D
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
RSIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 15/12/17 at about 1330 hrs I was driving along Kallang Rd towards Victoria St in lane two. Approaching the cross junction (as above), the traffic light was green and I proceeded straight. Suddenly, vehicle B, SJB 2444K make a U-turn on the opposite traffic and collided into the right of my vehicle. She was unable to see me as there was a vehicle on lane two waiting to turn left on clearance.

DECLARATION

I/We declare the foregoing particulars are true in every respect

[Signature]

Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

View Sent Message

This mail is associated with :

***SKA4948D (541128)**
[SJB2444K]

TP
MO LIPING
Dec 15 2017 12:00PM
[MICHAEL ARTHUR ROCHE]
Mje Motor

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 03/03/2018 12:05 PM.
To MSIG_JLKK
Subject Pre-repair Inspection

Dear Jasmine,

Refer to your assignment on 18.12.2017 at 11.16AM.

Please be informed that we have inspected the vehicle SKA 4948D on 18.12.2017 at 5.40PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,
Catherine Chong | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Dec 2017		18 Dec 2017 11:16 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	MICHAEL ARTHUR ROCHE, ID: S26304191			
Main Claimant:	MO LIPING, ID: G1021417W			
Vehicle Reg. No.:	SKA4948D	Date of Loss:	15/12/2017 12:00 - :59	
Claim Type:	TP / 541128	Policy/Cover Note No.:	B27227899QMY (Comprehensive) Coverage: 04/01/2017 - 03/01/2018	
Vehicle Reg. No. (Insured):	SJB2444K	Policy No. (Claimant):		
		Excess:	S\$1,000.00	
Repairer:	Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82, 575642 Sin Ming - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Imm.Advice due 19/12/2017]			
Driver/Custodian (Insured):	PATRICIA NAH LI HUA MRS PATRICIA ROCHE (60 / Female), NRIC: S1240899D, Tel: +6597472300			
Adj Asg. Remarks:	THIRD PARTY PRE-REPAIR SURVEY			

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS <input type="checkbox"/>										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SKA4948D (541128)**
[SJB2444K]
TP
MO LIPING
Dec 15 2017 12:00PM
[MICHAEL ARTHUR ROCHE]
Mje Motor

Upload Documents Upload Photos Compose New Letter			View	View in Browser ▼
Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/12/17 09:31	Video - Accident	Load MOV	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/02/18 20:06	General View	Load JPG	<input checked="" type="checkbox"/>
2	28/02/18 20:06	General View	Load JPG	<input checked="" type="checkbox"/>
3	28/02/18 20:06	General View	Load JPG	<input checked="" type="checkbox"/>
4	28/02/18 20:06	General View	Load JPG	<input checked="" type="checkbox"/>
5	28/02/18 20:06	General View	Load JPG	<input checked="" type="checkbox"/>
6	28/02/18 20:06	General View	Load JPG	<input checked="" type="checkbox"/>
7	28/02/18 20:06	General View	Load JPG	<input checked="" type="checkbox"/>
8	28/02/18 20:06	General View	Load JPG	<input checked="" type="checkbox"/>
9	28/02/18 20:06	General View	Load JPG	<input checked="" type="checkbox"/>
10	28/02/18 20:06	General View	Load JPG	<input checked="" type="checkbox"/>
11	28/02/18 20:06	General View	Load JPG	<input checked="" type="checkbox"/>
12	28/02/18 20:06	General View	Load JPG	<input checked="" type="checkbox"/>
13	28/02/18 20:06	General View	Load JPG	<input checked="" type="checkbox"/>
14	28/02/18 20:06	General View	Load JPG	<input checked="" type="checkbox"/>
15	28/02/18 20:06	General View	Load JPG	<input checked="" type="checkbox"/>
16	28/02/18 20:06	General View	Load JPG	<input checked="" type="checkbox"/>
17	28/02/18 20:06	General View	Load JPG	<input checked="" type="checkbox"/>
18	28/02/18 20:06	General View	Load JPG	<input checked="" type="checkbox"/>
19	28/02/18 20:06	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
20	28/02/18 20:06	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
21	28/02/18 20:06	General View	Load JPG	<input checked="" type="checkbox"/>
22	28/02/18 20:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
23	28/02/18 20:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
24	28/02/18 20:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
25	28/02/18 20:06	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	18/12/17 10:40	TP PRI	Load PDF	
2	18/12/17 10:42	E-FILE REPORT (SKA4948D)	Load PDF	
3	18/12/17 10:42	E-FILE REPORT (SJB2444K)	Load PDF	

4	18/12/17 10:43	Accident Sketch Plan From:SC - Reg. No: SJB2444K, Claimant: MICHAEL ARTHUR ROCHE		Load TIF	
5	18/12/17 11:15	TP LIST OF SJE & OUR REJECTION REPLY & NOMINATED LKK TO BE OUR SJE		Load PDF	
6	18/12/17 11:40	INFORM TP OUR CORRECT VEHICLE NO		Load PDF	
7	09/01/18 13:20	OI GIA & POLICE REPORT		Load PDF	
8	19/02/18 11:41	TP LOD, LTA/GIA SEARCH FEE, REPAIR BILL, RENTAL INVOICE & AGREEMENT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <p style="text-align: center;">//</p> <p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p>Note: Remarks are private unless you show it to other parties.</p>
--

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17023946/M1D3E2
Date: 08/03/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. **Policy No:** B27227899QMY
Claimant Vehicle No : SKA4948D **Insured Vehicle No :** SJB2444K
Date of Loss: 15/12/2017 **Nature of Claim:** TP **Claim No:** 541128

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKA4948D
Make & Model: BMW 320I, 2.0 (A) **Engine No:** N46B20BA019I303
Reg. Date: 11/12/2008 (Man. Year: 2008) **Chassis No:** WBAWK52030PE13651
Colour: Black **Odometer:** 134529 km
Engine Capacity: 1995 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:** Yes

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 **Rear Tyre Size:** 235/40 R18
Front Left Side: Neuton 8 mm **Rear Left Side:** Michelin 8 mm
Front Right Side: Neuton 8 mm **Rear Right Side:** Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 18/12/2017
Date Inspected: 18/12/2017 **Inspected At:** Mje Motor (HQ)
 BLK 7 SIN MING SECTOR C, #01-82
 Singapore 575642
Estimated Period of Repair: 0.0 days

Adjuster: MA CHIN FOOK**Manager:** Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

3/8/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 - \$7,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 08 Mar 2018)
Parts: N/A	BMW 320I 2.0 (A) (Model not available in database)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA4948D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >