

Survey Department Check List (Case Handler)

Reference No.: 103 MSG 17023957 Arb

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin () : Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor () : Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

23/3/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CC3/MSG17023957/Avb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 18-12-2017	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FT 4555M	Veh. Inspected	SFT 4845B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	18/12/2017	Inspection Date	18/12/2017
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Dec 2017		20 Dec 2017 14:48 Edit Adj Rpt		Last:IA 23 Mar 2018 11:46		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MOHAMED AMIRUL FIRDAUS BIN MOHAMED HUSOR, ID: S9533140H		
Main Claimant:	MUHAMMAD BUANG BIN TEK, ID: S0210369I		
Vehicle Reg. No.:	SFT4845B	Date of Loss:	18/12/2017 10:00 - :59
Claim Type:	TP / MSC/V/17-001965	Policy/Cover Note No.:	MSD/VMT/17-367560 (Third Party Only) Coverage: 10/07/2017 - 09/07/2018
Vehicle Reg. No. (Insured):	FT4555M	Policy No. (Claimant):	
		Excess:	
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 19/01/2018]		
Adj Asg. Remarks:	DIRECT SURVEY DONE		

[View All](#)
[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Catherine Thia Shi Yi	Date: 23 Mar 2018

Preliminary Advice

Insured Vehicle No	: FT4555M		
TP Vehicle No	: SFT4845B	Accident Date	: 18/12/2017
Make	: NISSAN SUNNY	Assignment Date	: 20/12/2017
Date of Inspection	: 18/12/2017	Est. Duration of Repair	: 4.00
Inspection At	: HUA MENG SPRAY PAINTING WORKSHOP (HQ) NO 1 KAKI BUKIT AVENUE 6, #01-61 AUTOBAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,496.03
Revised Amount	:S\$	2,501.16
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,501.16

Lump Sum Repair (estimated)	:S\$	2,000.00
-----------------------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

☐ The vehicle is economical/not economical for repair.

☒ The above survey was conducted on a 'without prejudice' basis.

Ai Phing (LKKAUTO)

From: Ai Phing (LKKAUTO)
Sent: Tuesday, 19 December, 2017 3:37 PM
To: 'Catherine Thia'; 'Lee Sheng Zhong'
Cc: Christopher Chionh; KKLau; Accounts (LKKAUTO); SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - HUA MENG SPRAY PAINTING ,
DOA: 18/12/2017 , SFT 4845B (TP), FT 4555M (OI)
Attachments: GIA.pdf

Dear Catherine,

Please be informed that we had inspected the vehicle SFT 4845B at M/s: Hua Meng Spray Painting.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Ai Phing on behalf Veron | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0369I
Vehicle Details	
Vehicle No.:	SFT4845B
Vehicle to be Exported:	Yes
Intended De-registration Date:	18 Dec 2017
Vehicle Make:	NISSAN
Vehicle Model:	SUNNY 1.6EXM
Primary Colour:	Gold
Manufacturing Year:	2005
Engine No.:	QG16364721
Chassis No.:	JN1CFAN16Z0090322
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$11,734.00
Original Registration Date:	31 Mar 2005
First Registration Date:	31 Mar 2005
Transfer Count:	0
Actual ARF Paid:	\$12,908.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Mar 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$31,933.00
COE Rebate Amount:	\$14,575.00
Total Rebate Amount:	\$14,575.00
Message	


 Experience rich culture and
 history with a modern twist
 Because you can...

One way direct

Clark

Username / Email Add

password



Connect

Sign Up New Account

Forgot Password

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Year Coe Renewal 2007 Honda Stream 1.8A RSZ


 \$2800 Downpayment Monthly
 From \$738 Driveaway. Lowest
 1.88%APR @GV Cars Financing
 GV Credit Pte Ltd. Shool

HIN LUNG AUTO
 Ho Bee Group
One Stop Car Hub
 Finance, Insurance, Workshop
 New and Used Cars
 30 years of car sale

Browse by Category

Sort by Date Posted

20 results/page

9 vehicles

Nissan Sunny

Advanced Search

Photo	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Nissan Sunny	Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Nissan Sunny 1.5M (COE till 12/2018)	\$4,800	\$4,630 /yr	01-Feb-1999	1,498 cc	-	Sedan	Available
Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only.								
Boeki Auto & Marine								
Posted: 07-Dec-2017 Tags: 1999 Nissan Sunny, 1999 Nissan Sunny, Nissan Sunny, Nissan Sunny, Nissan Sunny, Nissan, Sunny, Sunny, Used Nissan								
	Nissan Sunny 1.6A LE (COE till 03/2020)	\$19,999	\$8,750 /yr	20-Apr-2005	1,597 cc	107,490 km	Sedan	Available
Very Reliable, Accident Free Ride With New Pioneer Audio/DVD System With AUX Input. New Battery And New Tires. Includes Front And Rear Cameras. View To Believe. Viewings Strictly Via Appointment Only.								
Carro								
Posted: 12-Dec-2017 Tags: 2005 Nissan Sunny, 2005 Nissan Sunny, Nissan Sunny, Nissan Sunny, Nissan Sunny, Nissan, Sunny, Sunny, Used Nissan								
	Nissan Sunny 1.6A EX (COE till 11/2020)	\$21,800	\$7,380 /yr	01-Dec-2005	1,597 cc	-	Sedan	Available
Car In Mint Condition, Call Now To Arrange For A Viewing. Trade In Welcome. Flexible Loan Readily Available For Your Convenience.								
Posted: 15-Dec-2017 Tags: 2005 Nissan Sunny, 2005 Nissan Sunny, Nissan Sunny, Nissan Sunny, Nissan Sunny, Nissan, Sunny, Sunny, Used Nissan								
	Nissan Sunny 1.6A EX (COE till 11/2020)	\$20,888	\$7,070 /yr	29-Dec-2005	1,597 cc	160,000 km	Sedan	Available
Very Well Maintained, Neat And Tidy Interior, Low Downpayment To Drive Away, Trade In Welcome.								
Posted: 05-Dec-2017 Tags: 2005 Nissan Sunny, 2005 Nissan Sunny, Nissan Sunny, Nissan Sunny, Nissan Sunny, Nissan, Sunny, Sunny, Used Nissan								
Car Buying			Car Selling		Car Aftermarket			
Car Ownership			On The Move		Lifestyle			
Buy Tires Online! Latest Special Offers from Tyrepack!								
	Nissan Sunny 1.6M EX (COE till 01/2021)	\$20,900	\$6,850 /yr	06-Jan-2006	1,597 cc	87,000 km	Sedan	Available
Sporty Fuel Efficient Sunny With A Factory Spoiler, Genuine Low Mileage (87k Km), Well Kept Condition In And Out, On Time Regular Servicing, Tires Are Installed Just Before CNY And Paint Job Done Before...								
Posted: 07-Dec-2017 Tags: 2006 Nissan Sunny, 2006 Nissan Sunny, Nissan Sunny, Nissan Sunny, Nissan Sunny, Nissan, Sunny, Sunny, Used Nissan								
	Nissan Sunny 1.6A EX (COE till 04/2021)	\$20,888	\$6,220 /yr	27-Apr-2006	1,597 cc	130,500 km	Sedan	Available
Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only.								
Boeki Auto & Marine								
Posted: 10-Nov-2017 Tags: 2006 Nissan Sunny, 2006 Nissan Sunny, Nissan Sunny, Nissan Sunny, Nissan Sunny, Nissan, Sunny, Sunny, Used Nissan								
	Nissan Sunny 1.6A EX (COE till 05/2021)	\$20,200	\$5,970 /yr	08-May-2006	1,597 cc	-	Sedan	Available
Loan Up To 95%, Monthly Only \$654, No Gimmicks. All Our Vehicles Has Undergone A 120 Points Safety Check By Our In House Mechanics With Assessment Report And Come With One Year In House Warranty. Purc...								
Compare								

NAME OF OWNER Muhammad Khary Bin Tek MSIG

TELP NO 97210525

NRIC S02103691

CLAIM TYPE OD / THIRD PARTY / Reporting Only

INSURANCE CO. NTUC

TYPE OF COVERAGE Comprehensive / Third Party / Third Party Fire & Theft

POLICY NO. 5005090429-12

NAME OF DRIVER As above / If No: Muhammad Sulaimi Bin Khary

NRIC S8621938G Any passengers: -

DATE OF BIRTH 01/10/1981

OCCUPATION Outdoor / Indoor -

DATE OF DRIVING PASS 27/Nov/2006

GENDER Male / Female

CONTACT NO. 97737125 Office Home

ADDRESS B1K 205 Tampines St 21 # 06-1299 . S(520205)

DRIVER HAVE ANY OWN Vehicle NO / If yes, Reg No.

RELATIONSHIP Employee / If No. parent

WEATHER CONDITION Clear / Raining / Other

ROAD SURFACE Dry / Wet / Other

ANY INJURIES No / If yes, Who?

CONTACT NO.

POLICE REPORT No / If yes, Where?

VEHICLE B NO. FT 4555M Any Passenger: -

NAME Mohamed Anwar Firdaus (S9533140H)

CONTACT NO. 91466405

VEHICLE C NO. Any Passenger:

VEHICLE D NO. Any Passenger:

VEHICLE E NO. Any Passenger:

VEHICLE F NO. Any Passenger:

ANY WITNESS

WITNESS CONTACT NO.

Have you been approach by unknown person soliciting (s) / YES / NO

Offering accident claims assistance?

ARTICULAR WORKSHOP khamef@me.com.sg

TELP NO

CONTACT PERSON

EX NO.


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling straight along in Slip Road of Ennos Link towards Wai Ave 2 on 18.12.2017 @ 1010 hrs. I was stationary at that time to wait the vehicles clear along the main road. After I stopped for few seconds, I heard a bang sound and felt an impact from my rear suddenly. Vehicle B was collided onto rear right portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

JNICFAN1620090322

MUHAMMAD BUANG BIN TEK
BLK 205 TAMPINES ST 21
#06-1299
S 520205

TP 10316
Veran

Date : 11.01.2018
Vehicle no : SFT 4845 B
Make/Model : NISSAN SUNNY
Accident date : 18.12.2017

No	Description	Qty	Amount (\$\$)
Nett Items			
1	Rear windscreen rubber <i>not new</i>	1	\$ 173 N X.
2	Rear bumper <i>reformed</i>	1	\$ 497.8 L ✓
3	Rear bumper side holder @ \$34.00 <i>RN NA</i>	2	\$ 68 L 34
4	Rear bumper moulding <i>new</i>	1	\$ 192.7 L 168.60
5	Rear bumper clips (1set) <i>new</i>	1	\$ 60 L 30.
6	Rear bumper bracket @ \$95.30 <i>not new</i>	2	\$ 190.6 L X
7	Rear RH lamp <i>cooled</i>	1	\$ 396.2 N 283.20
8	Rear RH lamp housing <i>Repair</i>	1	\$ 167.9 L X.
9	Rear RH fender <i>Repair</i>	1	\$ 853.9 L X
10	Rear RH fender inner shield <i>not new</i>	1	\$ 256.6 N X.
			\$ 2856.7
Less 10% Disc			\$ 285.67
Total			\$ 2571.03

Special Nett Items

1	Rear bumper lower lip <i>not new</i>	1	\$ 380 X.
2	Rear bumper reverse sensor(1set) <i>not new</i>	1	\$ 380 X
3	Rear RH sport rim <i>cut</i>	1	\$ 680 + 50 (cut)
4	Rear RH tyre <i>not new</i>	1	\$ 380 X
5	Rear RH sport rim NISSAN cover <i>cut</i>	1	\$ 55 ✓
Total			\$ 1875

Labour Costs

1	To supply rear windscreen sealant	\$ 50 X
2	Remove & reinstall rear windscreen	\$ 150 X
3	Remove & reinstall reverse sensor	\$ 150 40
4	Remove & Reinstall roof lining & cushion	\$ 150 90
5	Remove, replace & repair consistent to the accident	\$ 1300 + 50
6	Respray painting	\$ 1000 600
7	Tuff kote	\$ 150 X
8	To check wheel alignment	\$ 100 80
Total		\$ 3050

Grand Total \$ 7496.03

total 2501.16.
1/5
OA Days

LKK AZ10
the Repairer must hence notify
the Renter of the car to proceed
• To survey before after spray painting
• To display damaged parts during repairs
• Parts prices in light of estimation
• Third party survey is on a without Pre-accident
• No illegal modifications is allowed
• Supplementary details must be provided and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Dec 2017		20 Dec 2017 14:48 Edit Adj Rpt	S\$2,000.00 Edit Estimates	S\$2,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	MOHAMED AMIRUL FIRDAUS BIN MOHAMED HUSOR, ID: S9533140H	
Main Claimant:	MUHAMMAD BUANG BIN TEK, ID: S0210369I	
Vehicle Reg. No.:	SFT4845B	Date of Loss: 18/12/2017 10:00 - :59
Claim Type:	TP / MSC/V/17-001965	Policy/Cover Note No.: MSD/VMT/17-367560 (Third Party Only) Coverage: 10/07/2017 - 09/07/2018
Vehicle Reg. No. (Insured):	FT4555M	Policy No. (Claimant):
		Excess:
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 19/01/2018]	
Adj Asg. Remarks:	DIRECT SURVEY DONE	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SFT4845B (MSC/V/17-001965)
[FT4555M]**

TP

MUHAMMAD BUANG BIN TEK

Dec 18 2017 10:00AM

[MOHAMED AMIRUL FIRDAUS BIN MOHAMED HUSOR]

Hua Meng Spray Painting Workshop

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/03/18 11:46	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
2	22/03/18 09:37	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
4	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
5	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
6	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
7	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
8	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
9	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
10	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
11	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
12	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
13	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
14	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
15	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
16	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
17	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
18	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
19	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
20	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
21	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
22	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
23	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
24	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
25	22/03/18 09:37	General View	Load JPG	<input checked="" type="checkbox"/>
26	22/03/18 09:37	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
27	22/03/18 09:37	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
28	22/03/18 09:37	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	22/03/18 09:37	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	22/03/18 09:37	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	22/03/18 09:37	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	22/03/18 09:37	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

33	22/03/18 09:37	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
34	22/03/18 09:37	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
35	22/03/18 09:37	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
36	22/03/18 09:37	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
37	22/03/18 09:37	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
38	22/03/18 09:37	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
39	22/03/18 09:37	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
40	22/03/18 09:37	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
41	22/03/18 09:37	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
42	22/03/18 09:37	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
43	22/03/18 09:37	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
44	22/03/18 09:37	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	22/03/18 09:37	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

Documentation1 per page ☒

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/12/17 14:48	LKK Email for direct survey	1 Load PDF	
2	20/12/17 14:48	TP GIA REPORT	1 Load PDF	

Documents Checklist**DOCUMENTS CHECKLIST**

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG17023957/AVBQ2

Date: 26/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/17-367560		
Claimant Vehicle No :	SFT4845B	Insured Vehicle No :	FT4555M		
Date of Loss:	18/12/2017	Nature of Claim:	TP	Claim No:	MSC/V/17-001965

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFT4845B	Engine No:	QG16364721
Make & Model:	NISSAN SUNNY, 1.6 EX (M)	Chassis No:	JN1CFAN16Z0090322
Reg. Date:	31/03/2005 (Man. Year: 2005)	Odometer:	349719 km
Colour:	Gold		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Michelin Energy 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin Energy 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,446.03	1,271.16	3,174.87	71.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	1,230.00	1,820.00	59.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,496.03	2,501.16	4,994.87	66.63
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	7,496.03	2,000.00	5,496.03	73.32

INSPECTION

Date of Assignment:	20/12/2017		
Date Inspected:	18/12/2017 Inspected At:	Hua Meng Spray Painting Workshop (HQ)	
		No 1 Kaki Bukit Avenue 6, #01-61	
		Autobay@Kaki Bukit	
		Singapore 417883	
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Mar 2018)
Parts: 143	NISSAN SUNNY 1.6 EX (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SFT4845B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN RUBBER	Not Necessary	173.00 FN	*- FN
2	1		*REAR BUMPER	Deformed	497.80 FL	*497.80 FL
3	1		*REAR BUMPER SIDE HOLDER	O/S Necessary	68.00 FL	*34.00 FL
4	1		*REAR BUMPER MOULDING	Necessary	192.70 FL	*168.60 FL
5	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
6	1		*REAR BUMPER BRACKET	Not Necessary	190.60 FL	*- FL
7	1		*REAR RH LAMP	Cracked	396.20 FN	*283.20 FN
8	1		*REAR RH LAMP HOUSING	Repair	167.90 FL	*- FL
9	1		*REAR RH FENDER	Repair	853.90 FL	*- FL
10	1		*REAR RH FENDER INNER SHIELD	Not Necessary	256.60 FN	*- FN
11	1		*REAR BUMPER LOWER LIP	Not Necessary	380.00 FS	*- FS
12	1		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	380.00 FS	*- FS
13	1		*REAR RH SPORT RIM	Cut	680.00 FS	*450.00 FS
14	1		*REAR RH TYRE	Not Necessary	380.00 FS	*- FS
15	1		*REAR RH SPORT RIM NISSAN COVER	Cut	55.00 FS	*55.00 FS
					Sub Total (S\$)	4,731.70 1,518.60
					- List Item Discount on L Items 10.00/30.00% (S\$)	203.09 219.12
					- Nett Item Discount on N Items 10.00/10.00% (S\$)	82.58 28.32
					Total Parts (S\$)	4,446.03 1,271.16

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY REAR WINDSCREEN SEALANT	New	50.00	0.00
2	REMOVE & REINSTALL REAR WINDSCREEN	New	150.00	0.00
3	REMOVE & REINSTALL REVERSE SENSOR	New	150.00	50.00
4	REMOVE & REINSTALL ROOF LINING & CUSHION	New	150.00	50.00
5	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,300.00	450.00
6	RESPRAY PAINTING	New	1,000.00	600.00
7	TUFF KOTE	New	150.00	0.00
8	TO CHECK WHEEL ALIGNMENT	New	100.00	80.00
Gross Labour Cost (\$\$)			3,050.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >