

Smeijer

REF:

CC3/MSH17023 958 / Aqbnz

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SKB 8254RPolicy No. A 80377 982 811 XClaims No. 542441

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKR6873H Yr Regn: 2015 Feb.Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Jetta cc 1390Colour: Black A/C: Insured / Std / NI / NASp. Reading: 20990 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZZ216ZEM 063304Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / R/R SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 18/12/17Survey held at: NHT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP MSH.SKR 6873H - XSKB 8254R - R6 / ALG 110 24340 / MSH 292

DUA: 28.11.11

19/12/17 @ 5.01 PM Email GIA report to Jasmine & Margaret.US 0260, 4 days (Red 0411.65, 67%)12/3/1811.21am revised to Jasmine low the maximum.12/3/2018

RECEIVED 12 MAR 2018

Date/Time, File Pass to?

☐

: Prel. Report

1) 12/3 12/18☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS (\$)

Photos

Others

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Insp (\$)

☐

: Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

Inter-P260

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CC3/MSG17023958/Aqb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 18-12-2017	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKB 8254R		Veh. Inspected	SKR 6873H
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	18/12/2017
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/12/2017		Inspection Date	18/12/2017
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SKR 68734

Case Handler

Typist

(1) Office Assign Form

C	Reference No.			
C	Customer Code			
N	Assign From			
C	Assign Date			
C	Veh No (Inspected)			
C	Veh No (Insured)			
C	D.O.A			
C	Policy No			
C	Claim No			
C	Insurance Authorisation (CA /REV/REP)			
C	Report Type			
C	Weekend Charges			
N	Survey held at/Repairer			
C	Excess			


(1) Assignment Form

1) Assignment Form		
C	Vehicle No	
C	Regn Month/Year	
N	Vehicle Type	
N	Make & Model	
C	Engine Capacity. (C.C)	
N	Colour	
C	Odometer. (Sp.Reading)	
C	Chassis No	
N	General Condition	
N	Steering	
N	Brake	
N	Modification (Modi)	
C	Tyre Size	
N	Tyre Make	
C	Tyre Balance	
C	Date of Inspection	
N	Survey held	
N	Des.of Damages	

C Damaged Vehicle Photographs Uploaded

N	ALL Parts condition
C	Market Value for OD cases
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)
C	Days of repair
C	Finalised Amount
C	Re-inspection Cases to Finalize within 5 Days

C Resurvey photo Uploaded

	12/3/18
Case Handler	Date

Case Handler

Date _____

*C: Critical *N: Non-Critical

21/05/2014

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 12 Mar 2018

Preliminary Advice

Insured Vehicle No	: SKB8254R	Accident Date	: 13/12/2017
TP Vehicle No	: SKR6873H	Assignment Date	: 27/12/2017
Make	: VOLKSWAGEN JETTA	Est. Duration of Repair	: 4.00
Date of Inspection	: 18/12/2017		
Inspection At	: NEW HOCK TECK MOTOR WORKSHOP (HQ) BLK 1, KAKI BUKIT AVENUE 6 #01-43, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,811.65
Revised Amount	:S\$	3,251.95
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,251.95
Lump Sum Repair	:S\$	2,600.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 19 December, 2017 5:01 PM
To: 'Jasmine Lok Kheng Kwei'; 'Margaret Loh'
Cc: Christopher Chionh; KKLau; SUR; Accounts (LKKAuto)
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - NEW HOCK TECK MOTOR WORKSHOP,
DOA: 13/12/2017 , SKR 6873H (TP VEHICLE), SKB 8254R (OI VEHICLE)
Attachments: SKR6873H GIA.pdf

Dear Jasmine and Margaret,

Please be informed that we had inspected the vehicle SKR 6873H at M/s: NEW HOCK TECK MOTOR WORKSHOP, BLOCK 1, KAKI BUKIT AVE 6 #01-43 SINGAPORE 417883.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	0627A

Vehicle Details

Vehicle No.	SKR6873H
Vehicle to be Exported	Yes
Intended De-registration Date	16 Dec 2017
Vehicle Make	VOLKSWAGEN
Vehicle Model	JETTA 1.4 TSI A/T ABS D/AIRBAG 2WD
Primary Colour	Black
Manufacturing Year	2014
Engine No.	CAXE81354
Chassis No.	WVWZZZ16ZEM063304
Maximum Power Output	90.0 kW (120 bhp)
Open Market Value	\$19,152.00
Original Registration Date	27 Feb 2015
First Registration Date	27 Feb 2015
Transfer Count	0
Actual ARF Paid	\$9,152.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	26 Feb 2025
PARF Rebate Amount	\$6,864.00

Intended COE Rebate Details

COE Expiry Date	26 Feb 2025
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$57,199.00
COE Rebate Amount	\$41,162.00
Total Rebate Amount	\$48,026.00

The information contained herein is correct as at 16 Dec 2017

(Draft)

MVGS17164392 / Volkswagen Centre Singapore - HQ
ENTRY DATE & TIME: 14/12/2017 11:35

SINGAPORE ACCIDENT STATEMENT**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/12/2017 11:35
Date Of Accident	13/12/2017 19:50
Exact Location Of Accident	ALONG BALESTIER ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR6873H
Insured/Policyholder	
Name Of Registered Owner	TEO BENG HWEE
NRIC No	S6920627A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96974873
Alternative Phone No	Office-96974873

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA A6 1.4 TSI DSG 90KW HL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ALLIED WORLD ASSURANCE COMPANY, LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	BVPPSB0548481700
Cover Note Number	

Driver

Name of Driver	TEO BENG HWEE
NRIC No	S6920627A
Date Of Birth	18/06/1969
Occupation	INDOOR

Date Of Driving Pass	26/11/1998
Driving Experience	19 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96974873
Fax Number	
Contact Number	OFFICE-96974873
EMail Address	NOEMAIL
Address	BLK 207B COMPASSVALE LANE #15-18
Postcode	543207
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKB8254R
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	CHYE HEE SHING
NRIC/Passport Number	S1759414A

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:




81030002
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

14/12/17

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13/12/17 @ about 19:50 HRE.

There was an accident ahead and there was a heavy Jam, suddenly SKB 8254R change lane and hit onto my rear. I wish to state that the accident happen on SKB 8254R lane, thus he needs to change lane in order to move.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

VOLKSWAGEN
GROUP
SINGAPORE
Reporting Centre Personnel's Signature
Name: 81030002
NRIC/Passport No:



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

TEO BENG HWEE

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

20/12/2017

TPMS16

XiaoChen

WVW222162EM063304

12/12/17

Accident date: 13/05/2017

Estimated repair cost for vehicle no: SKR6873H VOLKSWAGEN JETTA 1.4 A '15

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Rear Bumper <i>behind</i>		\$1,322.70 <i>1023</i>
2	8	Rear Bumper Clip <i>m</i>	\$6.50	\$52.00 <i>30</i>
3	1	Rear Bumper Side Retainer <i>new</i>		\$52.00 <i>x</i>
4	1	Rear RH Bumper Reflector <i>cut</i>		\$105.00 <i>✓</i>
5	1	Rear RH Tail Lamp <i>new</i>		\$377.85 <i>x</i>
6	1	Rear RH Fender <i>qps</i>		\$1,758.05 <i>x</i>
7	1	Rear RH Rim <i>cut</i>		\$1,144.05 <i>✓</i>
8	1	Rear RH Tyre <i>new</i>		\$350.00 <i>x</i>

240.05

2281.94

Subtotal:- \$5,161.65

Labour charges

To remove & refit reverse sensor

\$100.00 *50*

To check wheel alignment

\$150.00 *80*

To check wiring

\$50.00 *30*

Tuff kote

\$100.00 *x*

970

\$500.00 *300*

\$750.00 *500*

Subtotal:- \$1,650.00

Total:- \$6,811.65

- Panel beating** - hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - Spray painting** - during resurvey
 - To resurvey after paint to confirm
 - Third party survey is on a 'Without Prejudice' basis
 - No 'legal modification' is allowed
 - Supplementary demerit points involved and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

2.6lc 04hrs

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG17023958/AQBN2

Date: 13/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80377982QMX
Claimant Vehicle No :	SKR6873H	Insured Vehicle No :	SKB8254R
Date of Loss:	13/12/2017	Nature of Claim:	TP
		Claim No:	542441

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR6873H	Engine No:	CAXE81354
Make & Model:	VOLKSWAGEN JETTA, 1.4 TSI (A)	Chassis No:	WVWZZZ16ZEM063304
Reg. Date:	27/02/2015 (Man. Year: 2014)	Odometer:	20990 km
Colour:	Black		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,161.65	2,281.95	2,879.70	55.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	970.00	680.00	41.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,811.65	3,251.95	3,559.70	52.26
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	6,811.65	2,600.00	4,211.65	61.83
+ GST 7.00/7.00% (S\$)	476.82	182.00	294.82	61.83
Nett Amount (S\$)	7,288.47	2,782.00	4,506.47	61.83

INSPECTION

Date of Assignment: 27/12/2017

Date Inspected: 18/12/2017 Inspected At:

New Hock Teck Motor Workshop (HQ)
Blk 1, Kaki Bukit Avenue 6 #01-43,
AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Mar 2018)
Parts:	143	VOLKSWAGEN JETTA 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR6873H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,322.70 F	*1,123.00 FL
2	8		*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
3	1		*REAR BUMPER SIDE RETAINER	Not Necessary	52.00 F	*- FL
4	1		*REAR RH BUMPER REFLECTOR	Cut	105.00 F	*105.00 FL
5	1		*REAR RH TAIL LAMP	Not Necessary	377.85 F	*- FL
6	1		*REAR RH FENDER	Repair	1,758.05 F	*- FL
7	1		*REAR RH RIM	Cut	1,144.05 F	*1,144.05 FL
8	1		*REAR RH TYRE	Not Necessary	350.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,161.65	2,402.05
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	120.10
Total Parts (\$\$)	5,161.65	2,281.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	60.00
2	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
3	TO CHECK WIRING	New	50.00	30.00
4	TUFF KOTE	New	100.00	-
5	PANEL BEATING	New	500.00	300.00
6	SPRAY PAINTING	New	750.00	500.00
Gross Labour Cost (S\$)			1,650.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >