

22/03/2002

ASS. REC. BY:

REF:

CS3/EG117024010/WB

Special Instruction:

Range &amp; days

Surveyor:

Wilson

ASSIGNMENT (Office)

From (Person):

Bazlin Ahmad

of

EQE

Date/Time:

19/12/07 9.06am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKE 9072B

Insured:

GL 52D

at Workshop m/s

Chuan HO

Tel:

9069 1985

of

160 Sin Ming Drive # 07-09

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/22017

CA / REV / REP. / REV 24 HRS 'wpi

09-01-2018 @ after 12pm

H.O.D. Endorsement:

Date/Time:

19/12/07 10.11am

Person Contacted:

Sharin

Vehicle IN / OUT


Date/Time	Action/Instruction (✓) Estimate
	SKE 9072B - X
	GL 52D - X
	Dismantle : 10/1/2018

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
 To inspect Vehicle No: SKE 9072 B  
 at Workshop m/s Chuan Ho  
 of 160 Sun Ming Ave #07  
 Insured  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKE 9072 B yr Regn: 30/6/2010  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: KIA FORTE cc 1591  
 Colour: Dark Grey AC Insured / Std / NI / NA  
 Sp. Reading: 106295 T Radic: Insured / Std / NI / NA  
 Eng No: \_\_\_\_\_  
 C/No: KN AFW 611 M A S 232602  
 Gen Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Ni / S/Rim / STD A/Rim or  
 Tyre Size F: 215/45ZR17  
 R: 215/45ZR17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Kumho  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: 4 mm R/Bal: 4 mm  
 L/Bal: 4 mm L/Bal: 4 mm  
 D/OA: \_\_\_\_\_ DOI: 9/11/2018  
 Survey held at: At Above 9/12/2018  
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

9/1/2018 Chuan Collision - 1st Con.

Range \$2500 - \$3000

3 Days

Handwritten signature and initials

RECEIVED 9 APR 2018

Date/Time File Pass to:

☐ : Preli. Report

Days Of Repair: 3

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time File Return to:

Survey Fee

Transportation

\$ - \$ - \$

Photo

Chart

Total

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Insp (\$)

☐ Weekend (\$)

Report Format: PRE

Lump Sum / I.B.I: (\$)

## Catherine Chong (LKK Auto)

---

**From:** Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>  
**Sent:** Tuesday, 19 December, 2017 9:06 AM  
**To:** assignments  
**Subject:** FW: NEW PRS FOR ACCIDENT INVOLVING SKE9072B & GL52D ON 16.12.2017 ALONG CTE BEFORE BRADDELL ROAD  
**Attachments:** img-Z18155302-0001.pdf

Hi Cath,

FYNA please.

Thank you.

Best Regards,

Mei Kwan | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Bazlin Ahmad [mailto:[bazlin.ahmad@eqinsurance.com.sg](mailto:bazlin.ahmad@eqinsurance.com.sg)]  
**Sent:** Monday, 18 December, 2017 4:48 PM  
**To:** Ho Eng Chuan <[chuanhoautoservice@gmail.com](mailto:chuanhoautoservice@gmail.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** RE: NEW PRS FOR ACCIDENT INVOLVING SKE9072B & GL52D ON 16.12.2017 ALONG CTE BEFORE BRADDELL ROAD

Dear Sirs,

We object to all the surveyors as proposed. We shall be appointing our surveyor, **LKK Auto Consultants**, to attend to the pre-repair survey of your client's vehicle.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Aside to LKK,  
Please arrange to attend to the said Pre-repair survey.

Thank You.

Regards,

**Lynn Ahmad**

Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190

[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of*

---

**From:** Ho Eng Chuan [<mailto:chuanhoautoservice@gmail.com>]

**Sent:** Monday, December 18, 2017 4:03 PM

**To:** Bazlin Ahmad

**Subject:** Re: NEW PRS FOR ACCIDENT INVOLVING SKE9072B & GL52D ON 16.12.2017 ALONG CTE BEFORE BRADDELL ROAD

Hi,

Please refer to attached.

Please note that the car is not in yet, please inform the surveyor to give us a call to arrange.

Thank you

Regards,

Sharin

CHUAN HO AUTO SERVICE

160 SIN MING DRIVE, #07-09 SIN MING DRIVE (S) 575722

Hp: 9069 1985

On Mon, Dec 18, 2017 at 3:54 PM, Bazlin Ahmad <[bazlin.ahmad@eqinsurance.com.sg](mailto:bazlin.ahmad@eqinsurance.com.sg)> wrote:

**Without Prejudice**

Dear Sir,

We refer to your Notice of Accident of even date.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

<b>1) AJAX Inspection Services Pte Ltd</b>  Tel: 6255 0808  Fax: 6849 9155  Contact person : Joey/Joseh	<b>2) Automobile Inspection Services Pte Ltd</b>  Tel: 6286 0155  Fax: 6284 1539  Contact Person: Sophia
---	--

<b>3) LBS Automotive Appraisal Pte Ltd</b> <b>L.B.S. Auto Consultants Pte Ltd</b> Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	<b>4) Priority Services</b> <b>Tel: 62934822</b> <b>Fax: 62963283</b> <b>Contact Person: Sharon Kho</b>
<b>5) RT Appraisal Pte Ltd</b> Tel: 67486076 Fax: 67480361 Contact Person: Ricky Teng	<b>6) LKK Auto Consultants Pte Ltd</b> Tel: 6256-3561 Fax: 6741-4108
<b>7) Kelvin Automotive Appraising Services</b> Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	<b>8) Automotive Appraiser &amp; Surveying Services</b> Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
<b>9) JP Knights Pte Ltd</b> Tel: 63450068 Fax: 63445328 Contact Person: Edna Lee	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Thank You.

Regards,

**Lynn Ahmad**  
Executive | Claims



**EQ Insurance Company Limited**  
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6496 9881 | tel 65 6223 9433 ext 881 | fax 65 6223 4190  
[www.eqnsurance.com.sg](http://www.eqnsurance.com.sg)

 A Member of Citystate



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.*

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/12/2017 15:32
Date Of Accident	16/12/2017 16:50
Exact Location Of Accident	CTE BEFORE BRADDELL EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKE9072B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM MIN ZHI MICHAEL
NRIC No	S8631323E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92722787
Alternative Phone No	OFFICE-92722787

### Vehicle Particulars

Manufacturer	KIA
Model	-
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5092143948
Cover Note Number	

### Driver

Name of Driver	LIM MIN ZHI MICHAEL
NRIC No	S8631323E
Date Of Birth	30/10/1986
Occupation	INDOOR
Date Of Driving Pass	10/11/2008
Driving Experience	9 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-92722787
Fax Number	
Contact Number	OFFICE-92722787
EMail Address	NOEMAIL

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

**DETAILS OF OTHER VEHICLE PROPERTY 3**

Vehicle Registration Number GBB770B

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

**DETAILS OF OTHER VEHICLE PROPERTY 4**

Vehicle Registration Number SLS7931A

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness**

Name


Phone Number

Email Address



# Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 16/12/17 around 1650HRS I was driving my vehicle SKE9072B along CTE, before reaching the Braddell exit. Traffic was very congested as it was Raining, I slowly came to a stop when suddenly felt an impact from GL52D.

After getting down from the vehicle, I realized that vehicle Number SLS7431A Knocked onto GBB770B and pushed to SGC3641G which pushed to GL52D to hit my vehicle.

I was stationary when it happened.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

CLARENCE SketchPlanForm V08

## Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SKE9072B
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	With Sun Roof
Vehicle Scheme :	Normal
Vehicle Make :	KIA
Vehicle Model :	CERATO FORTE KOUP 1.6 AT SX ABS D/AB SR
Chassis No. :	KNAFW611MA5232602
Propellant :	Petrol
Engine No. :	G4FCAH389375
Engine Capacity :	1591 cc
Maximum Power Output :	92.7 kW ( 124 bhp )
Maximum Laden Weight :	1720 kg
Unladen Weight :	1232 kg
Year Of Manufacture :	2010
Original Registration Date :	30 Jun 2010
Lifespan Expiry Date :	-
COE Category :	A - Car (1600cc & below)
Quota Premium :	\$31,510.00
COE Expiry Date :	29 Jun 2020
Road Tax Expiry Date :	29 Jun 2018
PARF Eligibility Expiry Date :	29 Jun 2020
Inspection Due Date :	29 Jun 2019

Intended Transfer Date : 10 Jan 2018

CO2 Emission : -

CO Emission : -

HC Emission : -

NOx Emission : -

PM Emission : -

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

#### Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
<b>Total Amount Payable :</b>			<b>25.00</b>

You may print this page for reference.

OK

Print



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
EQ INSURANCE COMPANY LTD		Ref: CS3/EQI17024010/Wbs2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date: 12-04-2018		
		Code: EQI		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	GL 52D	Veh. Inspected	SKE 9072B	
Policy No.		Coverage (\$)	0.00	
Claim No.	DM17HO02869/FN	Excess (\$)	0.00	
Assign From	BAZLIN AHMAD	Assign Date	19/12/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	KIA FORTE	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	KNAFW611MA5232602	Colour	DARK GREY	
Odometer	106295 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/45ZR17	KUMHO	4 mm	
L/H Front Tyre	215/45ZR17	KUMHO	4 mm	
R/H Rear Tyre	215/45ZR17	KUMHO	4 mm	
L/H Rear Tyre	215/45ZR17	KUMHO	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
<b>5. General Information</b>				
Accident Date	16/12/2017	Inspect Date / Time	09/01/2018 ( 09:12 AM )	
Survey held at	160 SIN MING DRIVE #07-09			
Repairer	CHUAN HO AUTO SERVICE			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,000				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

Report Ref No. CS3/EQI17024010/Wbs2

Inspected By



WILSON TEO CHENG MING

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.