

ASS. REC. BY:

REF: CS3/MSG17024045/wd302

Special Instruction:

SUPERVISOR:

Menmen

Wilson

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

MSIG

Date/Time:

19/12/17 @ 1.44pm

Estimated Cost:

Bill to:

OD ☒ TP WS+TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDT 9642K

Insured:

SJL 1688C

at Workshop m/s

Twin Car Automotive

Tel:

6842 0051

of BIK 2 kaki Bukit # 01-17/18, 417921

Policy No: A28 695028QMX

Claim No:

541348

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 16/12/2017

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 2.10pm @ 19/12/17

Person Contacted:

Melody

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate	
	SDT 9642K - NA/INC17023988/24	D.O.A: 16/12/17
	SJL 1688C - NA/INC17023988/24	D.O.A: 16/12/17
	Dismantle Part: 21/22018	

PRS
W-16m

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: **SDT 9642K**
 at Workshop m/s: **Town Car**
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum. Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: **SDT 9642K** Regn: **14/12/2018**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or
 Make: **Nissan Jetta** cc: **1498**
 Colour: **white** AC Insured / Std / NI / NA
 Sp Reading: **218602** T Radio: Insured / Std / NI / NA
 Eng No: _____

C No: **JN1BAAC1125559563**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: **in order** / Jammed / Leaked / Burnt or
 Brake: **in order** / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **195/60R15**
 R: **195/60R15**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Mahella**

Front Rear
 R. Bal. **2** mm R. Bal. **2** mm
 L. Bal. **2** mm L. Bal. **2** mm

D.O.A: **16/12/2017** D.O.I: **20/12/2017**
 Survey held at: **As Above**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Left Frt.

The U/C / Chassis frame / Body Structure affected due to collision

Range \$4900 - \$5900

3 Days Repairing

RECEIVED 06 APR 2018

John
 4/4/2018

Date/Time File Pass to: ☐ : Preli. Report
06/04/2018 ☐ : Final Report

Date/Time File Return to:

Days Of Repair:
 Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Invs (\$) ☐ Weekend (\$)

Survey Fee
 Transportation

120
90
10
180

Report Format: **PR9**
 Lump Sum / I.B.I: (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt.	Adj. Submitted	Ins. Auth'd
Main	18 Dec 2017		19 Dec 2017 13:44 Assign			
						New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHENG KOK WAH, ID: S1740183A, Tel: +6597553289		
Main Claimant:	DAVID TPT, Co. Reg. No.: 53324419J		
Vehicle Reg. No.:	SDT9642K	Date of Loss:	16/12/2017 10:00 - :59
Claim Type:	TP / 541348	Policy/Cover Note No.:	A28695028QMX (Comprehensive) Coverage: 01/03/2017 - 28/02/2018
Vehicle Reg. No. (Insured):	SJL1688C	Policy No. (Claimant):	
		Excess:	
Repairer:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/12/2017]		
Driver/Custodian (Insured):	CHENG KOK WAH (51 / Male), NRIC: S1740183A, Tel: +6597553289		
Adj. Asg. Remarks:	Third Party Pre-Repair Survey		

ASSOCIATED MAIL RECEIVED
 There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Margaret Loh

From: Woon Choo Kwok
Sent: Tuesday, 19 December, 2017 10:07 AM
To: Monica Chung; Margaret Loh
Cc: Christopher Chionh; Foo Ai Ngoh; Jason Sim
Subject: FW: SDT9642K & SJL1688C - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS
Attachments: 18122017174228-0001.pdf

Dear MC & ML,

FYA

Best Regards

Kwok Woon Choo
Senior Administrative Officer, Claims Services
Direct line +65 6643 1330 | Direct fax +65 6225 7402 | woonchoo_kwok@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Agnes Lee
Sent: Tuesday, December 19, 2017 9:30 AM
To: Woon Choo Kwok <WoonChoo_Kwok@sg.msig-asia.com>
Subject: FW: SDT9642K & SJL1688C - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

From: Chin Hui Xin [<mailto:huixin@n51.com.sg>]
Sent: 18 December 2017 17:47
To: Claims <claims@sg.msig-asia.com>
Subject: SDT9642K & SJL1688C - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,


As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors.

Thank you...

Regards,
Melody Chin
TWINCAR Automotive Pte Ltd
Office : 6842 0051
Fax : 6741 0510
www.n51.com.sg



CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Ave 2, #01-17

Singapore 417921

Tel No. : +65 6744 0510 / 6842 0051 Fax No. : +65 6741 0510

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

Our Ref: SDT 9642 K

Your ref: SJL 1688 C

18 December 2017

MSIG INSURANCE(SINGAPORE) PTE LTD

4 SHENTON WAY

#21-01 SGX CENTRE 2

SINGAPORE 068807

Attn: Motor Claims Department

**BY FAX 6827-2708 & EMAIL :
claims@sg.msig-asia.com**

Dear Sir/Madam,

DATE OF ACCIDENT: 16 Dec 2017

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

PURSUANT TO PARAGRAPH 2.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We are instructed by **DAVID TPT** to notify you of a road traffic accident on **16 Dec 2017** at about **10:50 HOURS** At **BENCOOLEN ST MIDDLE RD (OUTSIDE BURLINGTON SQUARE)** involving our client's vehicle **SDT 9642 K & SJL 1688 C** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be inform that we don't excess to Merimen System and kindly reply to us by Email / Fax.

Yours faithfully,



Twincar Automotive Pte Ltd

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/12/2017 18:22
Date Of Accident	16/12/2017 10:50
Exact Location Of Accident	BENCOOLEN ST TWDS MIDDLE RD (OUTSIDE BURLINGTON)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDT9642K
Insured/Policyholder	
Name Of Registered Owner	DAVID TPT
Co Reg No	53324419J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91065441
Alternative Phone No	OFFICE-91065441

Vehicle Particulars

Manufacturer	NISSAN
Model	LATIO 1.5L T
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5088333907
Cover Note Number	

Driver

Name of Driver	NG HENG HENG
NRIC No	S1731298G
Date Of Birth	30/06/1965
Occupation	OUTDOOR
Date Of Driving Pass	06/11/1985
Driving Experience	32 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91012166
Fax Number	
Contact Number	OFFICE-91012166
Email Address	NOEMAIL

Address	BLK 418 CHOA CHU KANG AVENUE 4 #04-294
Postcode	680418
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- -

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJL1688C
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1

Name	NG HENG HENG
------	--------------

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

SDT9642K

Were seat belts worn?

YES

Was injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders


DAVID TPT
Reg: 53324419J
Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above date and time, I was driving along Benscolen St toward Middle road on the 1 lane of a 4 lanes road. Somewhere at Burlington square vehicle B (53C 1688C) that was travelling on the left (on my left side), suddenly filtered to the right, without any signal thus encroaching into my path. I sounded the horn at vehicle (B) however, vehicle (B) continued to filtered. As result, the right portion of vehicle (B) collided onto the left portions of my vehicle.

A - T9642K

B - 53C 1688C

DECLARATION

I/We declare the foregoing particulars are true in every respect.

DAVID TPT
Reg: 53324419J

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/FIN No:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Dec 2017		19 Dec 2017 13:44 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHENG KOK WAH, ID: S1740183A, Tel: +6597553289		
Main Claimant:	DAVID TPT, Co. Reg. No.: 53324419J		
Vehicle Reg. No.:	SDT9642K	Date of Loss:	16/12/2017 10:00 - :59 [114 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 541348	Policy/Cover Note No.:	A28695028QMX (Comprehensive) Coverage: 01/03/2017 - 28/02/2018
Vehicle Reg. No. (Insured):	SJL1688C	Policy No. (Claimant):	
		Excess:	
Repairer:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 20/12/2017]		
Driver/Custodian (Insured):	CHENG KOK WAH (51 / Male), NRIC: S1740183A, Tel: +6597553289		
Adj Asg. Remarks:	Third Party Pre-Repair Survey		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

































ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDT9642K (541348)**
[SJL1688C]
TP
DAVID TPT
Dec 16 2017 10:00AM
[CHENG KOK WAH]
Twincar Automotive Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
2	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
3	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
4	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
5	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
6	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
7	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
8	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
9	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
10	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
11	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
12	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
13	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
14	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
15	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
16	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
17	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
18	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
19	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
20	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
21	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
22	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
23	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
24	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
25	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
26	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
27	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
28	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
29	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
30	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
31	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
32	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
33	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
34	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
35	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
36	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	
37	06/04/18 11:08	General View						Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	06/04/18 16:23	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/12/17 11:53	E-FILE REPORT (SDT9642K)	 Load PDF	
2	19/12/17 12:01	TP PRI	 Load PDF	
3	19/12/17 13:43	TP LIST OF SJE & OUR REJECTION REPLY & NOMINATED LKK	 Load PDF	
4	19/12/17 15:29	TP LETTER DD 19.12.17 QJ VIDEOS IN X:\For Motor Section Only\Video\541348	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17024045/WD3E2

Date: 09/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28695028QMX

Claimant Vehicle No : SDT9642K

Insured Vehicle No : SJL1688C

Date of Loss: 16/12/2017

Nature of Claim: TP

Claim No: 541348

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDT9642K

Make & Model: NISSAN LATIO, 1.5 L (A)

Engine No: HR15248648A

Reg. Date: 14/06/2008 (Man. Year: 2007)

Chassis No: JN1BAAC11Z0009063

Colour: White

Odometer: 218602 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Michelin 2 mm

Rear Left Side: Michelin 2 mm

Front Right Side: Michelin 2 mm

Rear Right Side: Michelin 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/12/2017

Date Inspected: 20/12/2017 Inspected At:

Twincar Automotive Pte Ltd (Kaki Bukit)
BLK 2 KAKI BUKIT, #01-17/18 KAKI
BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 0.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,900.00 - \$5,900.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Apr 2018)
Parts:	143	NISSAN LATIO 1.5 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDT9642K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >