



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

III Insured's Veh No : SH9233T

Date of Accident : 15 December 2017

Miss Tan Siew Guek

Date : 18 December 2017

Estimate To Repair SJV4915A - Volkswagen JETTA 1.4 TSI AT 1K23Q5 SA
Chassis No : WVVZZZ1KZAU001135

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	Front bumper	\$ 0.00
02	1 pc	Front bumper reinforcement	\$ 0.00
03	2 ps	Front bumper spot light @ \$.00	\$ 0.00
04	1 pc	Front bumper spot light chrome rim	\$ 0.00
05	1 pc	Front bumper spot light grille	\$ 0.00
06	1 pc	Front bumper side pad	\$ 0.00
07	1 pc	Front bumper side pad chrome molding	\$ 0.00
08	2 ps	Front bumper air guide @ \$.00	\$ 0.00
09	10 ps	Front bumper clips @ \$.00	\$ 0.00
10	1 pc	Front bumper lower garnish	\$ 0.00
11	2 ps	Head lamp @ \$.00	\$ 0.00
12	1 pc	Front support panel assy	\$ 0.00
13	1 pc	Front support panel air baffle	\$ 0.00
14	1 pc	o/s Front fender	\$ 0.00
15	1 pc	Front fender inner cowling	\$ 0.00
16	4 ps	Front fender inner cowling clips @ \$.00	\$ 0.00
17	1 pc	Radiator grille assy	\$ 0.00
18	1 pc	Radiator grille emblem badge	\$ 0.00
			\$ 0.00
		Less 10 %	\$ 0.00
			\$ 0.00
		<u>SPECIAL NETT ITEMS</u>	
19	1 pc	Front licence plate	\$ 0.00
			\$ 0.00
		<u>LABOUR & MISC. CHARGES</u>	
01		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 780.00
02		Putty and spray painting of the affected portion.	\$ 880.00
03		To check electrical lighting concerned.	\$ 60.00
04		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 180.00
05		To check steering geometry and computer wheel alignment.	\$ 150.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

III Insured's Veh No : SH9233T
Date of Accident : 15 December 2017

Miss Tan Siew Guek

Date : 18 December 2017

Estimate To Repair SJV4915A - Volkswagen JETTA 1.4 TSI AT 1K23Q5 SA
Chassis No : WVVZZZ1KZAU001135

S/No	Quantity	Description	Amount
06		<u>LABOUR & MISC. CHARGES</u>	
		To rust-proofing of the affected areas.	\$ 100.00
			\$ 2,150.00
		Total	\$ 2,150.00