

22/03/2002

ASS. REC. BY:

REF:

CS/ASM17024097/ArbST

Special Instruction:

Supervisor:

From (Person):

Rusul

Kitty Tio

ASSIGNMENT (Office)

of ASM

Date/Time: 19/12/2017 542pm

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

SKS 9707E

Insured:

Tel: 6272 3892

To Inspect Vehicle No:

at Workshop m/s

MOVA

of

15 Fan Yang Road

Policy No:

GA104087

Claim No:

SM005TA

Excess:

NIL

Sum Insured:

D.O.A. 14/12/2017

Make of Veh:

(Client's Record)

CA/REV/REP./REV 24 HRS

20.12.2017

H.O.D. Endorsement:

Date/Time:

19.12.2017 544pm

Person Contacted:

Anni

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SKS 9707E - X

Sent preli through smart claim

SYNOPSIS

REF: AXA

0358A

ASSIGNMENT

From:

Date: 20/12/17

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKS 9707 E

at Workshop m/s

MOVA

of

15 Fan Yang Rd

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

NIL

(Client's Record)

Make of Veh:

Avni

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

140K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

☒ CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKS 9707 E

Yr Regn:

2015 / MY

Type:

☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

JAGUAR XF 2.0PT83

c.c 1999

Colour:

GREY

A/C:

Insured / Std / NI / NA

Sp. Reading

53788

T/Radio:

Insured / Std / NI / NA

Eng/No:

SAJAC05M4FP478546

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45ZR18

R:

-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

14/12/17

D.O.I.

20/12/17

Survey held at

MMA (FY)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Final Sig \$12,532 (Red 3137, 20%)

RECEIVED 16 JUL 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

7

Resurvey No. of Trip:

1

Survey Fee:

Transportation

Add Fee:

☐

Site Insp (\$

\$ + \$5 \$)

☐

Interview (\$

Photos

☐

Tech. Invs (\$

Others

☐

Weekend (\$

Report Format:

OD

Lump Sum / (B): (\$

12,532)

TOTAL

250

Survey Department Check List (Case Handler)

Reference No.: CE/AXA17024097/R1rb
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Catherine): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)				
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type				
C	Weekend Charges	✓			
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (Racul): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	✓			
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

Celine 16/7/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CS/AXA17024097/R1rb	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 20-12-2017	
			Code : AXA2	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SKS 9707E
Policy No.		Coverage (\$)		0.00
Claim No.	S7M005TA	Excess (\$)		0.00
Assign From	SMART CLAIM (KITTY TEO)	Assign Date		19/12/2017
2. Vehicle Particulars & Condition				
Make & Model		c.c		0
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/12/2017	Inspection Date	20/12/2017	
Survey held at	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				



Service Request Details

Claim

S7M005TA

Reference

None 

Loss Date

December 14, 2017

Request Date

December 19, 2017

Due Date

December 27, 2017

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKS9707E

Make

JAGUAR

Service Address

Blk 1008, , , 159722

Primary Contact/Insured

SUN KWEE CHONG

BLK 1D PINE GROVE, #04-16 PINE GROVE APARTMENT, 593001, Singapore, Singapore

NLEMKNG@SINGNET.COM.SG

Claim Handler

Kitty TEO

6568804602

kitty.teo@axa.com.sg

Additional Instructions

EXCESS NIL

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

TYPE



SENT

12/19/17 5:43 PM

FROM

Kitty TEO

SUBJECT

SKS9707E - Car @ Mova

BODY

Hi Please survey. Thanks.





Preliminary Revised for SKS 9707E

Type

🔗 Question

Message

Repairer's Estimate (Gross) : S\$ 15,544.00. Revised Estimate Amount : S\$ 11,023.00

"Check" Items (Estimated) : S\$ 1,884.00 . Total Repair cost : S\$ 12,907.00 . Pre-Accident Value : S\$ 140,000.00 . COE/PARF value : S\$ 99,750.00 . Nett Value : S\$ 40,250.00. Survey date and time: 20/12/2017 at 5.00pm. We have authorize repair. Days of repair: 7 days. Janice

Reply

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/12/2017 13:47
Date Of Accident	14/12/2017 12:20
Exact Location Of Accident	JUNCTION OF JLN FIRMA 1 & JLN FIRMA 1/5 MALAYSIA
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS9707E
Insured/Policyholder	
Name Of Registered Owner	CHONG SUN KWEE
NRIC No	S1850358A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96706095
Alternative Phone No	OFFICE-96706095

Vehicle Particulars

Manufacturer	JAGUAR
Model	-

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA104087/1
Cover Note Number	

Driver

Name of Driver	CHONG SUN KWEE
NRIC No	S1850358A
Date Of Birth	11/10/1947
Occupation	INDOOR
Date Of Driving Pass	01/04/1974
Driving Experience	43 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96706095
Fax Number	
Contact Number	OFFICE-96706095
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? YES

Foreign Vehicle Registration Number WTE9704 (COMMERCIAL VEHICLE)

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name CLEMENTI NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: NO. 20 CLEMENTI AVENUE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-8729999 - FAX NO: 67748639

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

refer attached police report.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number WTE9704

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer [collectively the "Personal Information"] and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 1 of 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Attach Singapore police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Source: SketchPlanPad, V8



**SINGAPORE
POLICE FORCE**



D/20171215/2019

1 of 2

Report No. D/20171215/2019

POLICE REPORT (NP299)

Police Station Of Origin
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

Date/Time Report Made 15/12/2017 10:19	Vide Report No.	Station Diary No. 46
Name Of Informant CHONG SUN KWEE	Address APT BLK 1D PINE GROVE #04-16 SINGAPORE 593001	
ID Type / ID No. NRIC NO / S1850358A	Contact No. Home/Office	Mobile 96706095
Nationality SINGAPORE CITIZEN	Email Address	
Occupation Company director	Sex Male	Age 70
Institution/School Name	Date of Birth 11/10/1947	Race Chinese
Date/Time Of Incident 14/12/2017 12:20	Language	
	Location Of Incident Junction of Jalan Firma 1 and Jalan Firma 1/5 MALAYSIA	

Brief details.

On 14/12/2017 at about 1220hrs, I was at Johor Bahru.

While I was stalled at the road junction at the time, the Malaysia lorry (WTE9704) reversed and hit my car (SKS9707E) at the front right hand side, the lorry driver never stops but sped away.

There were a few people at the spot including some of my staffs and they witnessed the accident.

Signature Of Officer Recording The Report:

D / Sgt 1 NUR WIRDAH BINTE MUHAMMAD WAZIR

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
D / Clementi Police Divisional Investigation Branch /
Staff Sgt CHUA BOON PIN
Contact No.: 68727920

Authentication Stamp



Signature Of Informant:

Date/Time:
15/12/2017 10:19

Classification Of Case:

**SINGAPORE
POLICE FORCE**

D/20171215/2019

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. D/20171215/2019

My front bumper, front sideguard, right hand side front lightning and front bonnet were badly damaged.

No ambulance and police at scene, and no one injured.

I am lodging this report for insurance claim purposes.

Signature Of Officer Recording The Report:

D / Sgt 1 NUR WIRDAH BINTE MUHAMMAD WAZIR

Signature Of Interpreter:
Not applicableOfficer In-Charge Of Case:
D / Clementi Police Divisional Investigation Branch /
Staff Sgt CHUA BOON PIN
Contact No: 68727920

Authentication Stamp



Signature Of Informant:

Date/Time:
15/12/2017 10:19

Classification Of Case:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 0358A

Vehicle Details

Vehicle No.: SKS9707E

Vehicle to be Exported: Yes

Intended De-registration Date: 18 Dec 2017

Vehicle Make: JAGUAR

Vehicle Model: XF 2.0P TSS

Primary Colour: Silver

Manufacturing Year: 2015

Engine No.: 015026033526204PT

Chassis No.: SAJAC05M4FPU75546

Maximum Power Output: 177.0 kW (237 bhp)

Open Market Value: \$49,966.00

Original Registration Date: 18 May 2015

First Registration Date: 18 May 2015

Transfer Count: 0

Actual ARF Paid: \$61,953.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 17 May 2025

PARF Rebate Amount: \$46,464.00

Intended COE Rebate Details

COE Expiry Date: 17 May 2025

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$71,889.00

COE Rebate Amount: \$53,286.00

Total Rebate Amount: \$99,750.00

140,000
99,750

40,250

The information contained herein is correct as at 18 Dec 2017

OK

Total \$15,544



English (default) ▼ MOVA AUTOMOTIVE PTE LTD ▼



SERVICE REQUESTS

MESSAGES

CLAIMS

ACN 96069278

CK130265
87MO057A

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Workshop Details

Involving

1 2015 JAGUAR XF 2.0 (SKS9707E)

Date of Loss

December 14, 2017

Time of Loss

12.20

Loss Description

SIDE SWIPE

Assigned Workshop

MOVA AUTOMOTIVE PTE LTD

Target Date of Completion

12/29/2017



Comment

Days of work completion

10


[Home](#) [SERVICE REQUESTS](#) [MESSAGES](#) [CLAIMS](#)

Assessment Details

[General & Workshop Details](#) [Vehicle & Driver Details](#) [Vehicle Condition](#) [Taxes & Ratio](#) [Parts & Labour](#) [Miscellaneous](#) [Summary](#)

Parts

Add

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC QUANTITY	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1	1			FRONT BUMPER	DE			1989		1989	Reviewing	
	2	1			FRONT GRILLE	CP4			1092		1092	Reviewing	
	3	1			FRONT GRILLE LOGO	2. New			103		103	Reviewing	
	4	1			FRONT BUMPER LOWER COVER	2. cut			437		437	Reviewing	
	5	1			FRONT RH WASHER JET COVER	X sur			95		95	Reviewing	
	6	1			FRONT BUMPER BRACKET RH	DE			42		42	Reviewing	
	7	1			FRONT BUMPER SIDE RETAINER RH	DE			63		63	Reviewing	

12/19/2017

0

3

#

Claim Portal

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISCOUNT%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	8	1			FRONT FENDER RH	RA			1150		1150	Reviewing	
	9	1			FRONT FENDER INNER SHIELD RH	DE			310		310	Reviewing	
	10	10			FRONT FENDER INNER SHIELD CLIPS	new X 117			55		55	Reviewing	
	11	1			FRONT BUMPER SPONGE	X 500			390		390	Reviewing	
	12	1			FRONT BUMPER REINFORCEMENT	X 500			667		667	Reviewing	
	13	1			BONNET	new			2925		2925	Reviewing	
	14	2			BONNET HINGE	X 500			126		252	Reviewing	
	15	1			HEADLAMP ASSY RH	new			2386		2386	Reviewing	
	16	1			RADIATOR TOP SUPPORT	R			1115		1115	Reviewing	
	17	1			RH FRONT WHEEL HOUSE BRACKET	new X 117			157		157	Reviewing	
	18	1			RH FRONT WHEEL HOUSE SUPPORT	new X 117			36		36	Reviewing	

Labour

12/19/2017

Add

Claim Portal

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR RER	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1	O/H	TO INSPECT FRONT LIGHTING WATER & LEAKAGE TEST	0	40 /	0	Reviewing		
	2		TO REMOVE & INSTALL A/C CONDENSER, RADIATOR IN ORDER TO REPLACE TOP SUPPORT PANEL	0	190 / 100	0	Reviewing		
	3		TO REPLACE TO SUPPORT PANE, STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS	0	800 / 700	0	Reviewing		
	4		TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	0	0	800 / 750	Reviewing		
	5		TO REPROGRAMMING AFTER REPAIR	0	300 / 200	0	Reviewing		
	6		TO CHECK WHEEL ALIGNMENT	0	80 / 60	0	Reviewing		



English (default) ▾

MOVA AUTOMOTIVE PTE LTD ▾

HOME SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Add

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	1	RADIATOR COOLANT	Reviewing	8060	SPECIAL NET <i>nel</i>	

Total = \$15,564



English (default) - MOVA AUTOMOTIVE PTE LTD

[Home](#)
[SERVICE REQUESTS](#)
[MESSAGES](#)
[CLAIMS](#)

 CK130265
 97m0057A

Accn 96869278



Assessment Details

General & Workshop Details

[Vehicle & Driver Details](#)
[Vehicle Condition](#)
[Taxes & Ratio](#)
[Parts & Labour](#)
[Miscellaneous](#)
[Summary](#)

General Details

Workshop Details

Involving

1 2015 JAGUAR XF 2.0 (SKS9707E)

Date of Loss

December 14, 2017

Time of Loss

12:20

Loss Description

SIDE SWIPE

Comment

Supplementary Parts.

1) Front RH fender bracket \$125

or

Total Repair cost \$12,532

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

SR	EDIT	QUAN	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC COUNTS	PART PRICE(NET)	ACTION (PARTS)	REMOVE
1	/	1			FRONT BUMPER	DE -			1989		1989	Reviewing	/
2	/	1			FRONT GRILLE	1. - loop Code			1092		1092	Reviewing	/
3	/	1			FRONT GRILLE LOGO	7. - REDS			103		103	Reviewing	/
4	/	1			FRONT BUMPER LOWER COVER	1. - tore.			437		437	Reviewing	/
5	/	1			FRONT RH WASHER-JET COVER	X			95		95	Reviewing	/
6	/	1			FRONT BUMPER BRACKET RH	DE -			42		42	Reviewing	/
7	/	1			FRONT BUMPER SIDE RETAINER RH	DE -			63		63	Reviewing	/

12/19/2017

FAN YOONG

19-12-17 12:07

Claim Portal

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC COUNTS	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	8	1			FRONT FENDER RH	RA			1150		1150	Reviewing	
	9	1			FRONT FENDER INNER SHIELD RH	DE			310		310	Reviewing	
	10	10			FRONT FENDER INNER SHIELD CLIPS	per			5.5		55	Reviewing	
	11	1			FRONT BUMPER SPONGE	X			390		390	Reviewing	
	12	1			FRONT BUMPER REINFORCEMENT	X			667		667	Reviewing	
	13	1			BONNET	forw			2925		2925	Reviewing	
	14	2			BONNET HINGE	7			126		252	Reviewing	
	15	1			HEADLAMP ASSY RH	sto			2386		2386	Reviewing	
	16	1			RADIATOR TOP SUPPORT	R			1115		1115	Reviewing	
	17	1			RH FRONT WHEEL HOUSE BRACKET	CRX ST			157		157	Reviewing	
	18	1			RH FRONT WHEEL HOUSE SUPPORT	ST			36		36	Reviewing	

Labour

12/19/2017

Add

Claim Portal

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1	O/H	TO INSPECT FRONT LIGHTING WATER & LEAKAGE TEST	0	40 ✓	0	Reviewing		
	2		TO REMOVE & INSTALL A/C CONDENSER, RADIATOR IN ORDER TO REPLACE TOP SUPPORT PANEL	0	190 ✓ 100	0	Reviewing		
	3		TO REPLACE TO SUPPORT PANE, STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS	0	800 ✓ 700	0	Reviewing		
	4		TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	0	0	800 ✓ 750	Reviewing		
	5		TO REPROGRAMMING AFTER REPAIR	0	300 ✓ 200	0	Reviewing		
	6		TO CHECK WHEEL ALIGNMENT	0	90 ✓ 60	0	Reviewing		

LC-1850
P-10,622
SH-60.00
12,532



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	RADIATOR COOLANT	Reviewing	8060	SPECIAL NET	



SERVICE REQUESTS
 MESSAGES
 CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Parts & Labour Miscellaneous Summary

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: Taxes & Ratio
Date:

Claim Amount \$15,544.00

CATEGORY

ESTIMATE

REVISED AMOUNT

Spare Parts

\$13,264.00

\$13,264.00

Labour

\$1,400.00

\$1,400.00

Paint

\$800.00

\$800.00

Miscellaneous

\$80.00

\$80.00

Total = \$15,544.



UNICO MOTOR (PTE) LIMITED 友和汽車(私人)有限公司
HEAD OFFICE: Blk 9 Selegie Road, #01-23 Selegie House Singapore 180009
BRANCH OFFICE: Blk 22 Sin Ming Road, #01-242 Singapore 570022
EMAIL: sales@unicomotor.com.sg | kee@unicomotor.com.sg
WEBSITE: www.unicomotor.com.sg

GST REG NO: M2-0017235-3
CO. REG NO: 197302096R

(HO) Tel: (65) 6336 1828 (4 lines) Fax: (65) 6337 2043
(BR) Tel: (65) 6453 5221 (3 lines) Fax: (65) 6453 2878

TAX INVOICE

MOVA AUTOMOTIVE PTE LTD

BLK 1008 BUKIT MERAH LANE 3 #01-04
SINGAPORE 159722

INVOICE NO.: 17C1120318
DATE: 22/12/2017
A/C NO.: LMOVA

Customer
Copy

REMARKS:

ITEM PART NOS. DESCRIPTION

17CDO120597 - Mr Alan Chng(5K59707E/Jaguar XF-SAJAC05M4FPU75546)

ITEM	PART NOS.	DESCRIPTION	QTY	UNIT	PRICE	TOTAL
1	C2Z13199	FRONT GRILLE	1	PC	1,092.00	1,092.00
2	C2Z13208XXX	FRONT BUMPER	1	PC	1,989.00	1,989.00
3	C2Z16531	FRONT RH BUMPER BRACKET	1	PC	42.00	42.00
4	C2Z16958	FENDER RH,FRT	1	PC	1,150.00	1,150.00
5	C2Z19536	BUM LOWER COVER,FRT(8X23-17626) (C2Z23088)	1	PC	437.00	437.00
6	C2Z22403	WHEEL ARCH RH,FRT	1	PC	310.00	310.00
7	C2Z29968	BONNET(12-)	1	PC	2,925.00	2,925.00
8	C2Z31124	RAD GRILLE EMBLEM(C2C38927/Black Base With Smaller Diameter Than C2Z31123)	1	PC	103.00	103.00
9	C2Z31443	HEAD LAMP RH(With H/Lamp Wiper Jet)	1	PC	2,386.00	2,386.00
10	C2Z6420	FRT RH FENDER BRACKET	1	PC	63.00	63.00

AUTHORISED SIGNATURE:

CREDIT TERM: C.O.D

SUBTOTAL : SGD 10,497.00
GST 7.0% : SGD 734.79
TOTAL : SGD 11,231.79

KEE -

ALL CHEQUES TO BE MADE PAYABLE TO "UNICO MOTOR (PTE) LTD"



All enquiries are welcome.

CUSTOMER COPY

PAGE 1 OF 1



UNICO MOTOR (PTE) LIMITED 友和汽車(私人)有限公司

HEAD OFFICE: Blk 9 Selegie Road, #01-23 Selegie House Singapore 180009

BRANCH OFFICE: Blk 22 Sin Ming Road, #01-242 Singapore 570022

EMAIL: sales@unicomotor.com.sg | kee@unicomotor.com.sg

WEBSITE: www.unicomotor.com.sg

GST REG NO: M2-0017235-3

CO. REG NO: 197302096R

(HO) Tel: (65) 6336 1828 (4 lines) Fax: (65) 6337 2043

(BR) Tel: (65) 6453 5221 (3 lines) Fax: (65) 6453 2878

INVOICE NO.: 17CII120343

DATE: 22/12/2017

A/C NO.: LMOVA

TAX INVOICE

MOVA AUTOMOTIVE PTE LTD

BLK 1008 BUKIT MERAH LANE 3 #01-04

SINGAPORE 159722

Customer
Copy

REMARKS:

ITEM PART NOS. DESCRIPTION

17CDO120642 - Mr Alan Chng(SKS9707E/Jaguar XF-SAJAC05M4FPU75546)

1 C2222218

FRONT RH FENDER BRACKET

QTY UNIT PRICE TOTAL

1 PC

125.00

125.00

—S

Slmon
23/12/17
1108am

AUTHORISED SIGNATURE:

KEE -

ALL CHEQUES TO BE MADE PAYABLE TO "UNICO MOTOR (PTE) LTD"

CREDIT TERM: C.O.D



SUBTOTAL : SGD 125.00
GST 7.0% : SGD 8.75
TOTAL : SGD 133.75

CUSTOMER COPY

PAGE 1 OF 1

SERVICE REQUESTS MESSAGES CLAIMS

<< Service Request Details

Claim	S7M005TA
Reference	
None 	Loss Date
December 14, 2017	Request Date
December 19, 2017	Due Date
March 19, 2018	Vendor Name
LKK AUTO CONSULTANTS PTE LTD (OD)	Type of Loss
Own Damage	Services

Vehicle Information

Incident Vehicle	SKS9707E	
Registration #	Make	Service Address
	JAGUAR	Blk
Model	XF 2.0	
	1008, , ,	159722

Actions

Next Step

PAST DUE: Report that your block modify the Expected Completion Date.

Complete Work More

Primary Contact/Insured

CHONG SUN KWEE
BLK 1D PINE GROVE, 593001,
Singapore
NLEMKNG@SINGNET.COM.SG

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
IC&DL.pdf	Forms / Claim Documents	Driver's License / IDP	MOVA AUTOMOTIVE PTE LTD	December 19, 2017

SERVICE REQUESTS

MESSAGES

CLAIMS

<< Service Request Details

Claim	S7M005TA	Vehicle Information	
Reference		Incident Vehicle	SKS9707E
None 	Loss Date	Registration #	Service Address
December 14, 2017	Request Date	Model	Blk
December 19, 2017	Due Date		
March 19, 2018	Vendor Name		
LKK AUTO CONSULTANTS PTE LTD (OD)	Type of Loss		
Own Damage	Services		

Actions

Next Step

PAST DUE: Report that your report is blocked

Complete Work More

Expected Completion Date.

1008, , , 159722

Primary Contact/Insured

CHONG SUN KWEE
BLK 1D PINE GROVE, 593001,
Singapore

NLEMKNKG@SINGNET.COM.SG



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving
1 2015 JAGUAR XF 2.0 (SKS9707E)

Date of Loss
December 14, 2017

Time of Loss
12.20

Loss Description
SKS9707E(INSR) HIT BY WTE9704

Comment

Workshop Details

Total Rebate Amount

99750

Nett Loss Amount
\$40,250.00

Assigned Workshop
LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

12/29/2017

Days of work completion *

0



SERVICE REQUESTS

MESSAGES

CLAIMS

English (default) ▾

LKK AUTO CONSULTANTS PTE LTD (OD) ▾



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SKS9707E

Purchase Date

mm/dd/yyyy

Registration State

SINGAPORE

Registration Date *

05/18/2015

Mileage

53788

Age of Vehicle

2

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2015

CATEGORY

Driver Name

ASSESSMENT INFO... 2015

FNOL INFORMATI...

SUN KWEE CHONG

POST SURVEY INF...

ASSESSMENT INFO... SAJAC05M4FPU75546

CATEGORY Engine No

POLICY INFORMAT... 015026033526204PT

ASSESSMENT INFO... 015026033526204PT

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 1999 cc

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 140000

FNOL INFORMATI... 44

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI... 51850358A

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI... 3

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... April 1, 1974

POST SURVEY INF... mm/dd/yyyy

CATEGORY License Expiration Date

FNOL INFORMATI... December 12, 2000

POST SURVEY INF... mm/dd/yyyy

FNOL INFORMATI... S1850358A

POST SURVEY INF...

-  SERVICE REQUESTS
- MESSAGES
- CLAIMS

<<

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary					

Front left side

PIRELLI 6mm

Rear left side

PIRELLI 6mm

Front right side

PIRELLI 6mm

Rear right side

PIRELLI 6mm

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details				Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary	Parts			
Add Approve Deny Salvage All	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
☐		1	1			FRONT BUMPER			Deformed	1989				1989
☐		2	1			FRONT GRILLE			Cracked	1092				1092
☐		3	1			FRONT GRILLE LOGO			Necessary	103				103
☐		4	1			FRONT BUMPER LOWER COVER			Cut	437				437
☐		5	1			FRONT RH WASHER JET COVER			Serviceable	0				0
☐		6	1			FRONT BUMPER BRACKET RH			Deformed	42				42
☐		7	1			FRONT BUMPER SIDE RETAINER RH			Deformed	63				63
☐		8	1			FRONT FENDER RH			Bent	1150				1150
☐		9	1			FRONT FENDER INNER SHIELD RH			Deformed	310				310

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
 	3		TO REPLACE TO SUPPORT PANE, STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS.	700	0	0	Reviewing	
 	4		TO SPRAY PAINT ON REPLACED, REPAIRED AREAS.	750	0	0	Reviewing	
 	5		TO REPROGRAMMING AFTER REPAIR.	200	0	0	Reviewing	
 	6		TO CHECK WHEEL ALIGNMENT.	60	0	0	Reviewing	

SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

RADIATOR COOLANT

Reviewing

60

NECESSARY



2

DAYS OF REPAIR

Reviewing

7



SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary	Claim Amount	\$12,532.00	Claim Amount	\$12,532.00	

CATEGORY	ESTIMATE	REVISED AMOUNT
----------	----------	----------------

Labour	\$1,850.00	\$1,850.00
--------	------------	------------

Miscellaneous	\$60.00	\$60.00
---------------	---------	---------

Spare Parts	\$10,622.00	\$10,622.00
-------------	-------------	-------------

Submit for Review