

22/03/2012

ASS. REC. BY:

REF:

CS/AT17A024111/UT602

Special Instruction:

Surveyor: MARUG.

ASSIGNMENT (Office)

From (Person):

Lim Sheng Yang

of

ATC1

Date/Time: 20.12.2017 10.13am

Estimated Cost:

Bill to:

OD ~~TH~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJL 451A

Insured:

SLK 89442

at Workshop m/s

Hiap Hong

Tel:

6745 9633

of

2 Kak Bukit Ave 2 #02-13

Policy No:

Claim No:

9197333141861003

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16.12.2017

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

20.12.2017 10.45am

Person Contacted:

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJL 451A - NO / INCL 0331 13
	SLK 89442 - X

D.O.A. 16.12.17

Document: *merous*

REF:

A16/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: *SJL 451A*
 at Workshop m/s *hony 02-13*
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 CIA / PR Seen: *2* Consistent? : Yes or No
 Est. Repairs: *4* days Res.: Yes or No
 Lum Sum: *20* % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: *SJL 451A* Vc Regn: *4 17*
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or *CA/*
 Make: *Hyundai Elantra* cc *1591*
 Colour: *Red* A.O: Insured / Std / NI / NA
 Sp.Reading: *15618* T Radior: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *KMMH0841CMMH436658*
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ Inorder / Jammed / Leaked / Burnt or
 Brake: ☒ Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: *205/55R16*
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or *Kumho*
 Front *6* Rear *6*
 R/Bal. *6* mm R/Bal. *6* mm
 L/Bal. *6* mm L/Bal. *6* mm
 D.O.A. _____ D.O.I. *20/12/17*
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Rec-
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<i>20/12/17</i>	<i>honey video at holder</i>
<i>20/12/17</i>	<i>confirmed L/S to 3350 with AM hgh.</i>
<i>20/12/17</i>	<i>cred: 3900.64 (53%)</i>

Date/Time: File Pass to? ☐ : Preli. Report
☒ : Final Report
 28/12 Typist
 Date/Time: File Return to?

Days Of Repair: *4*
 Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp. \$
☐ : Interview \$
☐ : Tech. Insp. \$
☐ : Weekend \$

Survey Fee:
 Transportation
 Photos
 Other

Report Format: *TP*
 Lump Sum ☒ I.B.I.S *3350*

<i>250</i>
<i>20</i>
<i>270</i>




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AK	PACIFIC INSURANCE PTE LTD	Ref :	CS/AIG17024111/Utb
78	ON WAY #08-16	Date :	20-12-2017
CH	BUILDING	Code :	AIG
SING	E 079120		
1. Policy Particulars : THIRD PARTY CLAIM			
Vehicle	SLK 8944Z	Veh. Inspected	SJL 451A
No.		Coverage (\$)	0.00
No.	9197333141SG003	Excess (\$)	0.00
From	LIM SHENG YANG	Assign Date	20/12/2017
2. Vehicle Particulars & Condition			
Model		c.c	0
No.	HIDDEN	Year of Reg.	
Is No.		Colour	
oter	-	Steering	
		Modification	
3. Conditions of Tyres			
	Size	Make	Balance
nt Tyre			mm
nt Tyre			mm
r Tyre			mm
Tyre			mm
Ver Description of Damages			
General Information			
Date	16/12/2017	Inspection Date	20/12/2017
ed at	HIAP HONG MOTOR REPAIR 2 KAKI BUKIT AVE 2 #02-13 SINGAPORE 417921		
Remarks			
ECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. DANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Catherine Chong (LKK Auto)

From: Lim, Sheng Yang <ShengYang.Lim@aig.com>
Sent: Wednesday, 20 December, 2017 10:13 AM
To: assignments@lkkauto.com; Admin A
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Chan, Yoke Shi
Subject: AIGENCRYPT - Pre repair inspection request - SJL451A VS SLK8944Z (OI) DOA 16/12/2017
Attachments: FaxD13A.TIF; Fax16EE.TIF

Hi,

Please refer to the enclosed request from **TNG SOON CHYE & CO.**

Claim no : 9197333141SG003
Case Owner : Chee Heng

If you have any queries/concerns, please let us know.
Kindly assist to assign Adrian Ling as Single Joint Expert as requested.

Thank you.

Best Regards,

Lim Sheng Yang
AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012101 | Fax +6 03 2685 5898

ShengYang.Lim@aig.com | www.aig.com

From: Lim, Sheng Yang
Sent: Tuesday, December 19, 2017 12:06 PM
To: 'tsclcx@singnet.com.sg'
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Chan, Yoke Shi
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLK8944Z AND SJL451A ON 16/12/2017

Without Prejudice

Your Reference : TSC.SJL451A.Accid.2017 (HH)-c
Our Reference : 9197333141SG003

Dear Sir/Madam,

We refer to your Notice of Accident on 18/12/2017.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Best Regards,

Lim Sheng Yang

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012101 | Fax +6 03 2685 5898

ShengYang.Lim@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

湯順才律師樓
TNG SOON CHYE & CO.

ADVOCATES & SOLICITORS
NOTARY PUBLIC
COMMISSIONER FOR OATHS
UEN NO: 53131141D

150 South Bridge Road #02-19 Fook Hai Building Singapore 058727

Tel: 6438 3133 • Fax: 6438 6066

(Service of Court documents via fax is not acceptable)

Our Ref: TSC.SJL451A.Accid.2017 (HH)-c
Your Ref: 9197333141SG003

19th December 2017

M/S AIG ASIA PACIFIC INSURANCE PTE LTD

Motor Claim Department

78 Shenton Way

#07-16

Singapore 079120

(Insurer of vehicle no. SLK8944Z)

URGENT ATTENTION

By Fax/Email/Certificate of Posting

(Fax: 6835 7416/ ShengYang.Lim@aig.com)

Dear Sirs,

ACCIDENT ON 16th DECEMBER 2017 @ 1735HRS INVOLVING MOTOR-VEHICLES NOS. SJL451A & SLK8944Z ALONG TPE TOWARDS UPPER CHANGI ROAD

We refer to your email dated 19 December 2017 to us.

Our client instructs that he agrees to the appointment of Mr Adrian Ling of M/s LKK Auto Consultants Pte Ltd as the single joint expert for the pre-repair inspection of the vehicle SJL451A at the workshop, Hiap Hong Motor Repair, situated at 2 Kaki Bukit Avenue 2 #02-13 Auto Hub Singapore 417921 (tel: 67459633).

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you. Our client's rights are hereby expressly reserved.

Yours faithfully

Tng Soon Chye

cc. client – via fax: 6747 8602 only
(ref: SJL451A)

湯 順 才 律 師 樓
TNG SOON CHYE & CO.

ADVOCATES & SOLICITORS
NOTARY PUBLIC
COMMISSIONER FOR OATHS
UEN NO: 53131141D

150 South Bridge Road #02-19 Fook Hai Building Singapore 058727

Tel: 6438 3133 • Fax: 6438 6066
(Service of Court documents via fax is not acceptable)

Our Ref: TSC.SJL451A.Accid.2017 (HH)-c
Your Ref: SLK8944Z

18th December 2017

M/S AIG ASIA PACIFIC INSURANCE PTE LTD

Motor Claim Department

78 Shenton Way

#07-16

Singapore 079120

(Insurer of vehicle no. SLK8944Z)

URGENT ATTENTION

By Fax/Certificate of Posting/Hand

(Fax: 6835 7416/ 6835 3727)

cc. to:

LIM CHEW SIAM

20 Pasir Ris Link

#05-10

Singapore 518157

(Owner of vehicle no. SLK8944Z)

By Certificate of Posting

Dear Sirs,

**ACCIDENT ON 16th DECEMBER 2017 @ 1735HRS INVOLVING MOTOR-VEHICLES
NOS. SJL451A & SLK8944Z ALONG TPE TOWARDS UPPER CHANGI ROAD**

We are instructed by Tang Kam Wah to notify you of a road traffic accident on 16th December 2017 at about 1735hrs along TPE towards Upper Changi Road involving our client's vehicle registration number SJL451A and vehicle registration number SLK8944Z driven by your insured driver at the material time. A copy of the Singapore accident statement/ traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle at 2 Kaki Bukit Avenue 2 #02-13 Auto Hub Singapore 417921.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you. Our client's rights are hereby expressly reserved.

Yours faithfully

Tng Soon Chye

enc

cc. client – via fax: 6747 8602 only
(ref: SJL451A)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

7495F

Vehicle Details

Vehicle No.:

SJL451A

Vehicle to be Exported:

No

Intended De-registration Date:

20 Dec 2017

Vehicle Make:

HYUNDAI

Vehicle Model:

ELANTRA AD 1.6 GLS AT

Primary Colour:

Red

Manufacturing Year:

2017

Engine No.:

G4FGGU041732

Chassis No.:

KMHD841CMHU366562

Maximum Power Output:

93.8 kW (125 bhp)

Open Market Value:

\$18,083.00

Original Registration Date:

04 Apr 2017

First Registration Date:

04 Apr 2017

Transfer Count:

0

Actual ARF Paid:

\$18,083.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

03 Apr 2027

PARF Rebate Amount:

\$13,562.00

Intended COE Rebate Details

COE Expiry Date:

03 Apr 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$51,765.00

COE Rebate Amount:

\$48,078.00

Total Rebate Amount:

\$61,640.00

The information contained herein is correct as at 20 Dec 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 18/12/2017 12:52
Date Of Accident 16/12/2017 17:35
Exact Location Of Accident TPE TWDS UPP CHANGI RD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJL451A
Name Of Registered Owner TANG KAM WAH
NRIC No S0567495F
Email Address RICHARDTANGKW@YAHOO.COM.SG
Mobile Phone No (LOCAL) +65-96155781
Alternative Phone No OTHERS-96155781

Manufacturer HYUNDAI
Model ELANTRA
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5090549139
Cover Note Number

Name of Driver TANG KAM WAH
NRIC No S0567495F
Date Of Birth 04/04/1947
Occupation INDOOR
Date Of Driving Pass 13/02/1975
Driving Experience 42 YEARS AND 10 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-96155781
Fax Number
Contact Number OTHERS-96155781
Email Address RICHARDTANGKW@YAHOO.COM.SG


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.





Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

 18/12/17

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Loyang Ave

Tanpines Ave 7

↑
From
TPE

Hiap Hong Motor Repair

Blk 2 Kaki Bukit Ave 2#02-13 Singapore 417921

Tel: 6745 9633 Fax: 6747 8602 Email: hiap.hong.motor@gmail.com

Company Reg. No. 42051700-J

Date: 19 December 2017

The Motor Claims Department
AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way
#07-16
Singapore 079120
Fax: 6835 7416

REPAIR QUOTATION FOR SJL451A HYUNDAI ELANTRA

	Qty		(\$)	Discount	(\$)
Rear bumper	1	Deep cut	1,218.90	20%	975.12
Rear bumper side retainer	2	O/S cut	264.20	20%	211.36
Rear bumper clip	10	1 set	129.00	20%	103.20
RH taillamp assy	1	17	287.70	20%	230.16
RH rear fender	1	3.17	981.25	20%	785.00
Rear windscreen moulding	1	1 set	172.85	20%	138.28
RH rear lower arm	1	17	371.00	20%	296.80
RH rear shock absorber	1	17	378.40	20%	302.72
RH rear knuckle arm	1	17	553.00	20%	442.40
RH rear knuckle arm bearing c/w hub	1	17	332.00	20%	265.60
Rear windscreen sealant	1	1 set	80.00	0%	80.00
Rear sport rim	1	1 set	650.00	0%	650.00
			Total Cost of parts		4,480.64

LABOUR

To check wiring.	60.00
To remove and reinstall reverse sensors and check sensing range.	120.00
To remove and replace rear right undercarriage parts.	17 380.00
To perform computerised 4-wheel alignment to realign wheels.	90.00
To apply anti-rust undercoating.	120.00
Labour charges to remove and replace, to cut and weld, to knock and reshape affected parts/areas.	1,200.00
Spray painting charges to putty and spray all affected parts/areas.	800.00

Total Cost of labour 2,770.00

Total Repair Cost 7,250.64

Yours faithfully

Chua Meng Liang

Not Alred

2/5 83350
4 day

Take photo After repair
HP: 9009 6608

1- 2490.60
1992.48
4202.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Dec 2017 Edit Reg		20 Dec 2017 00:00 Edit Adj Rpt	S\$3,350.00 Edit Estimates	S\$3,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LIM CHEW SIAM , ID: S7469145E		
Main Claimant:	TANG KAM WAH , ID: S0567495F		
Vehicle Reg. No.:	SJL451A	Date of Loss:	16/12/2017 17:00 - :59
Claim Type:	TP / 9197333141SG	Policy/Cover Note No.:	2100499894 (Comprehensive)
Vehicle Reg. No. (Insured):	SLK8944Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Hiap Hong Motor Repair () 2 Kaki Bykit Avenue 2, #02-13, 417921 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 02/01/2018]		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

- AIG_SG (21/12/2017): **TP GIA REPORT**

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJL451A (9197333141SG)

[SLK8944Z]

































TP

TANG KAM WAH

Dec 16 2017 5:00PM

[LIM CHEW SIAM]

Hiap Hong Motor Repair

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser <input type="button" value="v"/>	
Assessment Reports						1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print		
1	21/12/17 10:48	Accident Statement From: SC - Reg. No: SLK8944Z, Claimant: LIM CHEW SIAM		Load HTM			
Photos/Images						3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	20/12/17 15:15	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>		
2	20/12/17 15:15	General View		Load JPG	<input checked="" type="checkbox"/>		
3	20/12/17 15:15	Chassis Number		Load JPG	<input checked="" type="checkbox"/>		
4	20/12/17 15:15	General View		Load JPG	<input checked="" type="checkbox"/>		
5	20/12/17 15:15	General View		Load JPG	<input checked="" type="checkbox"/>		
6	20/12/17 15:15	General View		Load JPG	<input checked="" type="checkbox"/>		
7	20/12/17 15:15	General View		Load JPG	<input checked="" type="checkbox"/>		
8	20/12/17 15:15	General View		Load JPG	<input checked="" type="checkbox"/>		
9	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
10	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
11	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
12	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
13	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
14	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
15	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
16	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
17	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
18	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
19	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
20	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
21	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
22	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
23	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
24	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
25	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
26	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
27	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
28	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
29	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
30	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		
31	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>		

32	20/12/17 15:16	General View		Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/12/17 15:04	TP Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div><div></div><div> </div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG17024111/UTBE2

Date: 04/01/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100499894
 Claimant Vehicle No: SJL451A Insured Vehicle No: SLK8944Z
 Date of Loss: 16/12/2017 Nature of Claim: TP Claim No: 9197333141SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJL451A
 Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGGU041732
 Reg. Date: 04/04/2017 (Man. Year: 2017) Chassis No: KMHD841CMHU366562
 Colour: Red Odometer: 15618 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm
 Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,480.64	2,482.96	1,997.68	44.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,770.00	1,720.00	1,050.00	37.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,250.64	4,202.96	3,047.68	42.03
Approved Total (Overridden) (\$\$)		3,350.00		
Nett Amount (\$\$)	7,250.64	3,350.00	3,900.64	53.80

INSPECTION

Date of Assignment: 20/12/2017
 Date Inspected: 20/12/2017 Inspected At: Hiap Hong Motor Repair
 2 Kaki Bykit Avenue 2, #02-13
 Singapore 417921
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deep Cut	1,218.90 FL	*1,218.90 FL
2	1		*REAR BUMPER SIDE RETAINER	O/S Bent	264.20 FL	*68.20 FL
3	10		*REAR BUMPER CLIP	Necessary	129.00 FL	*50.00 FL
4	1		*RH TAILLAMP ASSY	Not Necessary	287.70 FL	*- FL
5	1		*RH REAR FENDER	Badly Dented	981.25 FL	*981.25 FL
6	1		*REAR WINDSCREEN MOULDING	Necessary	172.85 FL	*172.85 FL
7	1		*RH REAR LOWER ARM	Not Necessary	371.00 FL	*- FL
8	1		*RH REAR SHOCK ABSORBER	Not Necessary	378.40 FL	*- FL
9	1		*RH REAR KNUCKLE ARM	Not Necessary	553.00 FL	*- FL
10	1		*RH REAR KNUCKLE ARM BEARING C/W HUB	Not Necessary	332.00 FL	*- FL
11	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
12	1		*REAR SPORT RIM	Cut	650.00 FS	*450.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,418.30	2,981.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	937.66	498.24
Total Parts (\$\$)	4,480.64	2,482.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	60.00	20.00
2	TO REMOVE AND REINSTALL REVERSE SENSORS AND CHECK SENSING RANGE	New	120.00	50.00
3	TO REMOVE AND REPLACE REAR RIGHT UNDERCARRIAGE PARTS	New	380.00	0.00
4	TO PERFORM COMPUTERISED 4-WHEEL ALIGNMENT TO REALIGN WHEELS	New	90.00	80.00
5	TO APPLY ANTI-RUST UNDERCOATING	New	120.00	40.00
6	LABOUR CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE AFFECTED PARTS / AREAS	New	1,200.00	850.00
7	SPRAY PAINTING CHARGES TO PUTTY AND SPRAY ALL AFFECTED PARTS / AREAS	New	800.00	680.00
Gross Labour Cost (S\$)			2,770.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >