

22/03/2012

ASS. REC. BY:

REF: CS/GAI17024122/Kvd3n2

Special Instruction:

Survivor: Kenneth

ASSIGNMENT (Office)

From (Person): Sharon Ng

of

GAIDate/Time: 19/12/17 @ 5.02pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 8325R

Insured:

GBA 4879B

at Workshop m/s

Cheng Hoe Motor

Tel:

6755 6142of B1K 1019, Yishun Ind Park A # 01-374

Policy No:

Claim No:

CLMD MVC 00 000 2071

Sum Insured:

Excess:

Make of Veh:

D.O.A. 17/12/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time: 9:04am 20/12/17

Person Contacted:

Mr. AngVehicle ☒ IN/OUT

Date/Time Action/Instruction (✓) Estimate

GBD 8325R - XGBA 4879B - X26/12/17 Email preli revised to Sharon

REF: GAI

ASSIGNMENT

From: _____ Date: 20/12/17

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: GBD 8325R
at Workshop m/s Cheng Hoe Motor
of BIK1019 Yishun Ind. Park A #01-374/382

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 131 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS wp

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBD 8325R Yr Regn: 05 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS NV200 c.c. 1461Colour: Black A/C: Insured / Std / NI / NASp. Reading: 77543 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: USKYBAM 208 0094458Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: ☒ NIT / S/Rim / STD A/Rim orTyre Size: F: 175/14 XR

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 9 mmL/Bal. 9 mmL/Bal. 9 mmD.O.A. 17/12/17D.O.I. 20/12/17

Survey held at _____

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/12 File pass to Catherine22/12 \$4565.80 Car frame & body (Red 513.14, 1090)

[Signature]
23/2/2018

RECEIVED 26 FEB 2018

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 44

1)

☐

Final Report

Resurvey No. of Trip: 22

Date/Time, File Return to?

2) 23/2 - typist

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

B-RS \$:

Phone:

Others:

Report Format: TPLump Sum / I.B.I.: (\$ 4565.80)

TOTAL

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI17024122/Kvd3	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 20-12-2017	
		Code : GAI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBA 4879B	Veh. Inspected	GBD 8325R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	SHARON NG	Assign Date	20/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/12/2017	Inspection Date	20/12/2017
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: PLEASE ADVISED
Our ref: CS/GAI17024122/Kvd3

Date: 26/12/2017

The Motor Claims Department
M/s: GREAT AMERICAN INSURANCE COMPANY

WITHOUT PREJUDICE

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. GBD 8325R


We thank you for your instruction on 19/12/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/12/2017 at the premises of M/s CHENG HOE MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$5,078.94
Revised Estimate Amount	: S\$4,490.20
"Check" Items Amount	: S\$178.74
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

Survey Department Check List (Case Handler)

Reference No.: CS/GA217024122/Kvd3

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 23/2/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 23 February 2018 11:56 AM
To: 'Ng, Sharon'
Cc: SUR
Subject: RE: PRE-REPAIR INSPECTION - GBD8325R || GA ref: GBA4879B - DOA: 17/12/2017
|| GA ref: CLMOMVC000002071

Dear Sharon,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng, Sharon [mailto:Sharon.Ng@sg.gaig.com]
Sent: Friday, 23 February 2018 11:09 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: PRE-REPAIR INSPECTION - GBD8325R || GA ref: GBA4879B - DOA: 17/12/2017 || GA ref: CLMOMVC000002071

Ref: CLMOMVC000002071

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Thursday, February 22, 2018 12:48 PM
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: FW: PRE-REPAIR INSPECTION - GBD8325R || GA ref: GBA4879B - DOA: 17/12/2017

Dear Sharon,

Kindly provides us the claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 26 December 2017 10:11 AM
To: 'Ng, Sharon' <Sharon.Ng@sg.gaig.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: PRE-REPAIR INSPECTION - GBD8325R || GA ref: GBA4879B - DOA: 17/12/2017

Dear Sharon,

Enclosed preliminary revised of vehicle GBD 8325R
Date of survey: 20/12/2017
Number of days:4 days

Kindly provides us the claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 20 December, 2017 9:17 AM
To: 'Ng, Sharon' <Sharon.Ng@sg.gaig.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: PRE-REPAIR INSPECTION - GBD8325R || GA ref: GBA4879B - DOA: 17/12/2017

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng, Sharon [<mailto:Sharon.Ng@sg.gaig.com>]
Sent: Tuesday, 19 December, 2017 5:02 PM
To: Survey
Cc: assignments
Subject: RE: PRE-REPAIR INSPECTION - GBD8325R || GA ref: GBA4879B - DOA: 17/12/2017

Dear Catherine

Please arrange to survey TP vehicle no. GBD8325R and verify damages consistency.

Regards
Sharon
GAIC

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [mailto:chmotor@singnet.com.sg]
Sent: Tuesday, December 19, 2017 3:18 PM
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Subject: Re: PRE-REPAIR INSPECTION - GBD8325R

Hi Sharon,

Our selection as below :-

5. LKK Auto Consultants

Pls assist to arrange for survey asap.

Thank you.

Rgds
June Phua
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: Ng, Sharon
Sent: Tuesday, December 19, 2017 3:12 PM
To: Cheng Hoe Motor Pte Ltd (Yishun-June)
Subject: RE: PRE-REPAIR INSPECTION - GBD8325R

WITHOUT PREJUDICE

Dear June

Below is our list of surveyors. Please confirm on SJE and let us have your repair estimate and client's report soon.

1. AJAX Adjusters & Surveyors Pte Ltd
2. L.B.S. Automotive Appraisal Pte Ltd
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants
6. JP Knights Pte Ltd

Regards
Sharon
GAIC

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [mailto:chmotor@singnet.com.sg]
Sent: Tuesday, December 19, 2017 2:44 PM
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Subject: PRE-REPAIR INSPECTION - GBD8325R

Dear Sir,

OUR CLIENT – GBD 8325R
DOA - 17/12/17 @4.32PM
YR INSURED : GBA4879B

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards
June
Cheng Hoe Motor Pte Ltd
Blk 1019 Yishun Ind Park A
01-374, Singapore 768761
Tel :67556142
Fax : 67557719

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 26 December, 2017 10:11 AM
To: 'Ng, Sharon'
Cc: SUR
Subject: RE: PRE-REPAIR INSPECTION - GBD8325R || GA ref: GBA4879B - DOA: 17/12/2017
Attachments: GBD 8325R PRELI REVISED.pdf

Dear Sharon,

Enclosed preliminary revised of vehicle GBD 8325R
Date of survey: 20/12/2017
Number of days:4 days

Kindly provides us the claim number.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 20 December, 2017 9:17 AM
To: 'Ng, Sharon' <Sharon.Ng@sg.gaig.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: PRE-REPAIR INSPECTION - GBD8325R || GA ref: GBA4879B - DOA: 17/12/2017

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng, Sharon [<mailto:Sharon.Ng@sg.gaig.com>]
Sent: Tuesday, 19 December, 2017 5:02 PM
To: Survey
Cc: assignments
Subject: RE: PRE-REPAIR INSPECTION - GBD8325R || GA ref: GBA4879B - DOA: 17/12/2017

Dear Catherine

Please arrange to survey TP vehicle no. GBD8325R and verify damages consistency.

Regards
Sharon
GAIC

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [mailto:chmotor@singnet.com.sg]
Sent: Tuesday, December 19, 2017 3:18 PM
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Subject: Re: PRE-REPAIR INSPECTION - GBD8325R

Hi Sharon,

Our selection as below :-

5. LKK Auto Consultants

Pls assist to arrange for survey asap.

Thank you.

Rgds
June Phua
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: Ng, Sharon
Sent: Tuesday, December 19, 2017 3:12 PM
To: Cheng Hoe Motor Pte Ltd (Yishun-June)
Subject: RE: PRE-REPAIR INSPECTION - GBD8325R

WITHOUT PREJUDICE

Dear June

Below is our list of surveyors. Please confirm on SJE and let us have your repair estimate and client's report soon.

1. AJAX Adjusters & Surveyors Pte Ltd
2. L.B.S. Automotive Appraisal Pte Ltd
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants
6. JP Knights Pte Ltd

Regards
Sharon
GAIC

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [mailto:chmotor@singnet.com.sg]
Sent: Tuesday, December 19, 2017 2:44 PM

To: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Subject: PRE-REPAIR INSPECTION - GBD8325R

Dear Sir,

OUR CLIENT – GBD 8325R
DOA - 17/12/17 @4.32PM
YR INSURED : GBA4879B

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards

June

Cheng Hoe Motor Pte Ltd
Blk 1019 Yishun Ind Park A
01-374, Singapore 768761
Tel :67556142
Fax : 67557719

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Nivitha (LKK Auto)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Sent: Tuesday, 19 December, 2017 5:02 PM
To: Survey
Cc: assignments
Subject: RE: PRE-REPAIR INSPECTION - GBD8325R || GA ref: GBA4879B - DOA: 17/12/2017
Attachments: TP - GBD8325R.PDF; Insd - GBA4879B.PDF

Dear Catherine

Please arrange to survey TP vehicle no. GBD8325R and verify damages consistency.

Regards
Sharon
GAIC

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [mailto:chmotor@singnet.com.sg]
Sent: Tuesday, December 19, 2017 3:18 PM
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Subject: Re: PRE-REPAIR INSPECTION - GBD8325R

Hi Sharon,

Our selection as below :-

5. LKK Auto Consultants

Pls assist to arrange for survey asap.

Thank you.

Rgds
June Phua
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: Ng, Sharon
Sent: Tuesday, December 19, 2017 3:12 PM
To: Cheng Hoe Motor Pte Ltd (Yishun-June)
Subject: RE: PRE-REPAIR INSPECTION - GBD8325R

WITHOUT PREJUDICE

Dear June

Below is our list of surveyors. Please confirm on SJE and let us have your repair estimate and client's report soon.

1. AJAX Adjusters & Surveyors Pte Ltd
2. L.B.S. Automotive Appraisal Pte Ltd
3. Priority Services
4. RT Appraisal Pte Ltd

- 5. LKK Auto Consultants
- 6. JP Knights Pte Ltd

Regards
Sharon
GAIC

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [<mailto:chmotor@singnet.com.sg>]
Sent: Tuesday, December 19, 2017 2:44 PM
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Subject: PRE-REPAIR INSPECTION - GBD8325R

Dear Sir,

OUR CLIENT – GBD 8325R
DOA - 17/12/17 @4.32PM
YR INSURED : GBA4879B

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards
June
Cheng Hoe Motor Pte Ltd
Blk 1019 Yishun Ind Park A
01-374, Singapore 768761
Tel :67556142
Fax : 67557719

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	4564M
Vehicle Details	
Vehicle No.:	G8D832SR
Vehicle to be Exported:	Yes
Intended De-registration Date:	18 Dec 2017
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5L MT ABS AIRBAG 2WD 6DR EURO 5
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	K9KC400D054309
Chassis No.:	VSKYBAM20Z0094458
Maximum Power Output:	-
Open Market Value:	\$20,544.00
Original Registration Date:	29 May 2015
First Registration Date:	29 May 2015
Transfer Count:	0
Actual ARF Paid:	\$1,028.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	

COE Expiry Date:	28 May 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$39,451.00
Total Rebate Amount:	\$39,451.00

The information contained herein is correct as at 18 Dec 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/12/2017 09:43
Date Of Accident	17/12/2017 16:30
Exact Location Of Accident	ALONG LENTOR AVE TWDS ANG MO KIO
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD8325R
Insured/Policyholder	
Name Of Registered Owner	BEST SERVICES & TRADING
Co Reg No	52994564M
Email Address	THOMAS@BEST.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-96897976
Vehicle Particulars	
Manufacturer	NISSAN
Model	NV200 1.5L MT ABS AIRBAG 2WD 6DR EURO 5
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MW004902-R02
Cover Note Number	29/05/17 - 28/05/18
Driver	
Name of Driver	GOH TIOW KWEE(WU TIAOGUI)
NRIC No	S7212484G
Date Of Birth	09/04/1972
Occupation	INDOOR
Date Of Driving Pass	27/01/1992
Driving Experience	25 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96897976
Fax Number	
Contact Number	
Email Address	THOMAS@BEST.COM.SG

Address	BLK 357A ADMIRALTY DRIVE #11-154
Postcode	751357
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Upon noticing front vehicles brake to stop, I followed and managed to stop in time. However vehicle B could not react in time and collided onto the rear of my car. No one was injured.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO


DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBA4879B
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	LIM POH POH
NRIC/Passport Number	S7503951D
Contact Number	94598268
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Upon noticing front vehicles brake to stop, I followed and managed to stop in time. However vehicle B could not react in time and collided onto the rear of my car.

No one was injured.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: (YS)
NRIC/FIN No.:

GA/RMC Service Platform V2 () Claim Own Policy (X) Claim Third Party () Reporting Only
() Claim OD/TP at other workshop ()

SKETCH PLAN

VEHICLE NO.: GBD 8325R
INSURER : Tokio Marine
DATE & TIME: 18/12/17 @ 4.32 pm

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: (YS)
NRIC/FIN No.:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : GREAT AMERICAN INSURANCE COMPANY

3 TEMASEK AVE,
 16-01 CENTENNIAL TOWER
 SINGAPORE 039190

TEL: 68046037

FAX: 62353354

ATTN: Motor Claim Department

WS Ref: TP-GA

Claim Type: Third Party

Accident Date: 17/12/2017

TP Veh Reg No: GBA4879

Estimate No: ES1791417/WS

Date: 20 Dec 2017

Policy No: 17-MW004902-R02

Veh Reg No: GBD8325R

Make/Model: NISSAN NV200 VAN

Chassis No: VSKYBAM20Z0094458

Engine No: K9KC400D054309

Reg. Date: 29/05/2015

Estimate Repair Cost to Vehicle No :GBD8325R

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Net Price				
1 REAR BUMPER	650.40	1 PC	650.40	✓
2 REAR BUMPER SPONGE	84.00	1 PC	84.00	✓
3 REAR BUMPER RH SIDE RETAINER	33.90	1 PC	33.90	✓
4 REAR BUMPER CLIPS	5.00	6 PCS	30.00	✓
5 REAR BUMPER REFLECTOR	57.30	2 PC	114.60	✓
6 LH TAILGATE	1,281.10	1 PCS	1,281.10	✓
7 LH TAILGATE LOGO	59.70	1 PCS	59.70	✓
8 LH TAILGATE EMBLEM 'MV200'	97.00	1 PCS	97.00	✓
9 LH TAILGATE EMBLEM 'LIMITED'	87.10	1 PCS	87.10	✓
10 RH TAILGTE	960.90	1 PCS	960.90	✓
11 RH TAILGATE EMBLEM 'DCI'	77.90	1 PCS	77.90	✓
			3,476.60	
		Less 10%	347.66	3,128.94
Special Net				
12 TAILGATE GLASS GUM	30.00	2 PC	60.00	✓
13 70KM/H STICKER	10.00	1 PCS	10.00	✓
14 REVERSE SENSOR	200.00	1 PC	200.00	✓
			270.00	270.00
Labour				
15 REMOVE AND REFIX LH TAILGATE GLASS	80.00	1 LA	80.00	601
16 REMOVE AND REFIX RH TAILGATE GLASS	60.00	1 LA	60.00	501
17 REMOVE AND REFIX REAR BUMPER ASSY, TAIL LAMP, TAILGATE AND ATTACHMENT, REAR WIPER ASSY, THIRD BRAKE LIGHT, TO KNOCK AND REPAIR REAR RH FENDER, REAR BUMPER REINFORCEMENT, REAR END PANEL AND REALIGN THE SAME	800.00	1 LA	800.00	501
18 PUTTY AND RESPRAY ON TAILGATE, REAR RH FENDER, REAR END PANEL AND REAR BUMPER REINFORCEMENT	680.00	1 LA	680.00	601
19 RUSTPROOFING	60.00	1 LA	60.00	✓

KKK Consultants 1 LA notify the Repairer of the following:
 • To resurvey before/after spray painting 60.00
 • To display damaged part(s) during resurvey 1,680.00
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVE,
16-01 CENTENNIAL TOWER
SINGAPORE 039190

TEL: 68046037 FAX: 62353354

ATTN: Motor Claim Department

WS Ref: TP-GA

Claim Type: Third Party

Accident Date: 17/12/2017

TP Veh Reg No: GBA4879

Estimate No: ES1791417/WS

Date: 20 Dec 2017

Policy No: 17-MW004902-R02

Veh Reg No: **GBD8325R**

Make/Model: NISSAN NV200 VAN

Chassis No: VSKYBAM20Z0094458

Engine No: K9KC400D054309

Reg. Date: 29/05/2015

Estimate Repair Cost to Vehicle No :GBD8325R

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			Total	SS 5,078.94
			Add GST @ 7%	355.53
			Total Amount Payable	SS 5,434.47

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI17024122/Kvd3n2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 27-02-2018



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 4879B	Veh. Inspected	GBD 8325R
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000002071	Excess (\$)	0.00
Assign From	SHARON NG	Assign Date	19/12/2017

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VSKYBAM20Z0094458	Colour	BLACK
Odometer	77543	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/14 X8	BRIDGESTONE	9 mm
L/H Front Tyre	175/14 X8	BRIDGESTONE	9 mm
R/H Rear Tyre	175/14 X8	BRIDGESTONE	9 mm
L/H Rear Tyre	175/14 X8	BRIDGESTONE	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/12/2017	Inspection Date	20/12/2017
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 8325R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (N)	BUCKLED	650.40	650.40
1	REAR BUMPER SPONGE (N)	CRACKED	84.00	84.00
1	REAR BUMPER RH SIDE RETAINER (N)	DISTORTED	33.90	33.90
6	REAR BUMPER CLIPS @\$5.00 (N)	NECESSARY	30.00	30.00
2	REAR BUMPER REFLECTOR @\$57.30 (N)	SERVICEABLE	114.60	-
1	LH TAILGATE (N)	BENT	1,281.10	1,281.10
1	LH TAILGATE LOGO (N)	NECESSARY	59.70	59.70
1	LH TAILGATE EMBLEM "MV200" (N)	NECESSARY	97.00	97.00
1	LH TAILGATE EMBLEM "LIMITED" (N)	NECESSARY	87.10	87.10
1	RH TAILGATE (N)	BENT	960.90	960.90
1	RH TAILGATE EMBLEM "DCI" (N)	NECESSARY	77.90	77.90
	LESS 10% DISCOUNT		-347.66	-336.20
			3,128.94	3,025.80
<u>SPECIAL NETT ITEMS</u>				
2	TAILGATE GLASS GUM @\$30.00 (SN)	NECESSARY	60.00	60.00
1	70KM/H STICKER (SN)	NECESSARY	10.00	10.00
1	REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			270.00	270.00
<u>LABOUR</u>				
	REMOVE AND REFIX LH TAILGATE GLASS.		80.00	60.00
	REMOVE AND REFIX RH TAILGATE GLASS.		60.00	50.00
	REMOVE AND REFIX REAR BUMPER ASSY, TAIL LAMP, TAILGATE AND ATTACHMENT, REAR WIPER ASSY, THIRD BRAKE LIGHT. TO KNOCK AND REPAIR REAR RH FENDER, REAR BUMPER REINFORCEMENT, REAR END PANEL AND REALIGN THE SAME.		800.00	500.00
	PUTTY AND RESPRAY ON TAILGATE, REAR RH FENDER, REAR END PANEL AND REAR BUMPER REINFORCEMENT.		680.00	600.00
	RUSTPROOFING.		60.00	60.00
			1,680.00	1,270.00
GRAND TOTAL			5,078.94	4,565.80
RECOMMENDED COST OF REPAIRS				4,565.80

Report Ref No. CS/GAI17024122/Kvd3n2



Report Ref No. CS/GAI17024122/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.