

22/03/2012

REF: CS/MSG17024132/Kvd3

Special Instruction:

ASS: BY:

ASSIGNMENT (Office)

From (Person): Kenneth Menmen  
Muhd Ashik

of MSG

Date/Time: 20/12/17 @ 9:17am

Estimated Cost:

Bill to:

OD / (IP) / WS / TP RES / OD RES / EVA / INV / MV / CS

Insured: XD 7869J

To Inspect Vehicle No: SGH 575 H

Tel: 6453 1235

at Workshop m/s City Auto

of 160 Sin Ming Drive #05-01

Policy No: 28624722 MKF

Claim No:

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 18/12/17

CA / REV / REP. / REV 24 HRS

'wp'

Blk 8, Sin Ming Rd #01-08

H.O.D. Endorsement:

Date/Time: 9:55am @ 20/12/17

Person Contacted: Veronica

Vehicle  IN  OUT

Date/Time	Action/Instruction (✓) Estimate	
	SGH575H-CC3/TMT15009105/T1vbd1	D.O.A: 29/05/2015
	XD 7869J-CC6/AXA17009143/yb3	D.O.A: 04/05/2017
4/1/18	11Lp @ 52001 Carbon (Red 1694.95, 2470)	
	Muhd Ashik ← 6594 2548	
	MSG	

ACC. REC. BY:

REF: MSG /

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_ City Auto

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SGH 575H Yr Regn: 05, 06

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS Sunny c.c. 1597

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 28800 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JNICK AN168 0101975

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 18/12/17

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 20/12/17

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/12 File parts to Customer

21/12/17 REV preli in merimen.

RECEIVED 28 JUN 2018

Date/Time, File Pass to?

Preli. Report Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

1)

Date/Time, File Return to?

2) 28/6 - typst

Add Fee: Site Insp (\$), Interview (\$), Tech Invs (\$), Weekend (\$)

Survey Fee: 260

Transportation: \$ + RS, \$

Photos

Others

TOTAL

Report Format: Merimen

Lump Sum / I.B.I: (\$ 5200)

Stamp: LIA, TGA, 24/1/18

Table with columns for Survey Fee, Transportation, Photos, Others, and TOTAL.

## Survey Department Check List (Case Handler)

Reference No.: CS | MSG 17024132 | Krd3

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

**(2) System - (Views/Merimen)**

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

**(3) Workshop Estimate/Assignment Form**

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

**(4) System - (Views/Merimen)**

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 28/6/18  
Case Handler Date

\*C: Critical \*N: Non-Critical



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17024132/Kvd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 20-12-2017	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XD 7869J	Veh. Inspected	SGH 575H
Policy No.	28624722MKF	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	20/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	18/12/2017	Inspection Date	
Survey held at	BLK 8 SIN MING RD # 01-08		
Repairer	CITY AUTO PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Dec 2017 17:52 <a href="#">Sendback Est</a>	19 Dec 2017 18:05 <b>S\$6,894.95</b>	20 Dec 2017 09:17 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	<b>HONG FU CONSTRUCTION PTE LTD</b> , Co. Reg. No.: 199003776H, Tel: +6596361140		
Main Claimant:	<b>KOH ENG BENG</b> , ID: S1631495A		
Vehicle Reg. No.:	<b>SGH575H</b>	Date of Loss:	18/12/2017 11:00 - :59
Claim Type:	<b>TP</b>	Policy/Cover Note No.:	28624722MKF (Comprehensive) Coverage: 28/10/2017 - 27/10/2018
Vehicle Reg. No. (Insured):	<b>XD7869J</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>City Auto Pte Ltd (HQ)</b> 160 Sin Ming Drive #05-01,, Sin Ming AutoCity,, 575722 Sin Ming - Tel: 6453 1235		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Muhd Ashik B Madi</b> - 6594 2548]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [ <b>Imm.Advice due 21/12/2017</b> ]		
Driver/Custodian (Insured):	KOH ENG BENG (53 / Male), NRIC: S1631495A, Tel: +6596361140		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 27 December, 2017 9:45 AM  
**To:** Naz (LKKAuto); Bryan Ang (LKKAuto)  
**Cc:** SUR; 'Muhd Ashik B Madi'  
**Subject:** FW: Our ref: 541558 Your ref: SGH575H doa 18.12.17 (URGENT)  
**Attachments:** OI report.pdf

Dear Investigation Team,

Kindly assist to do a height measurement.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Wednesday, 27 December, 2017 9:40 AM  
**To:** Muhd Ashik B Madi <ashik\_madi@sg.msig-asia.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** Our ref: 541558 Your ref: SGH575H doa 18.12.17 (URGENT)

Dear Ashik,

Thank you for the email.

This case is handle by Veron.

Dear Veron,

FYNA. [CS/MSG17024132/Kvd3](#)

***WISHES YOU A HAPPY NEW YEAR 2018***

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Muhd Ashik B Madi [[mailto:ashik\\_madi@sg.msig-asia.com](mailto:ashik_madi@sg.msig-asia.com)]  
**Sent:** Wednesday, 27 December, 2017 9:07 AM

To: Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>

Cc: SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

Subject: Our ref: 541558 Your ref: SGH575H doa 18.12.17 (URGENT)

Dear Shiau Chan,

Enclosed our insured's report for your attention.

Our insured has reported that there was no collision with the third party vehicle.

Please arrange for a survey of our insured's vehicle & to do a height measurement.

Kindly check if the damages on both vehicles are fresh or old damages.

We shall look forward to your findings.

Thank you.

Ashik Madi

Executive, Claims Services (Motor)

Direct line +65 6594 2548 | Direct fax +65 6225 7402 | [ashik\\_madi@sg.msig-asia.com](mailto:ashik_madi@sg.msig-asia.com)



Insurer Claims  
Team of the Year  
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 21 Dec 2017

**Preliminary Advice**

Insured Vehicle No	: XD7869J	Accident Date	: 18/12/2017
TP Vehicle No	: SGH575H	Assignment Date	: 20/12/2017
Make	: NISSAN SUNNY	Est. Duration of Repair	: 6.00
Date of Inspection	: 20/12/2017		
Inspection At	: CITY AUTO PTE LTD (HQ) 160 SIN MING DRIVE #05-01,, SIN MING AUTOCITY, SINGAPORE 575722		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,377.60
Revised Amount	:S\$	5,659.20
Check Items (Estimated)	:S\$	103.50
Total	:S\$	5,762.70

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/12/2017 09:11
Date Of Accident	18/12/2017 11:45
Exact Location Of Accident	ALONG RD 1 TRAVELING TOWARD RD 2 BEDOK NORTH AVE 3
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGH575H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KOH ENG BENG
NRIC No	S1631495A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96361140
Alternative Phone No	OTHERS-96361140

### Vehicle Particulars

Manufacturer	NISSAN
Model	SUNNY
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095151602
Cover Note Number	

### Driver

Name of Driver	KOH ENG BENG
NRIC No	S1631495A
Date Of Birth	28/11/1964
Occupation	OUTDOOR
Date Of Driving Pass	29/10/1992
Driving Experience	25 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96361140
Fax Number	
Contact Number	OTHERS-96361140
EMail Address	NOEMAIL

Email Address





**SINGAPORE  
POLICE FORCE**



T/20171218/2065

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

2 of 3

Report No: T/20171218/2065

**CONTINUATION OF REPORT**

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	KOH ENG BENG	ID No	S1631495A
Related Vehicle	SGH575H (Car)	Contact No	96361140
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the 18/12/2017 at 1145hrs, I was travelling (SGH575H) along Bedok north ave 3 towards ECP at the junction of block 136. The weather clear and traffic was moderate. I was travelling on the left lane of a 2 lane road when I saw up ahead on lane 2 that there was road work ongoing. I signalled to the right and when the traffic was clear I changed lane. While my vehicle was on the move, I felt a hit from the rear and I looked to the rear mirror and saw this lorry (XD7869J) collided into my vehicle. The said vehicle continued to push my vehicle forward for 20 meters. I accelerated and broke off from the lorry. I stopped my vehicle by the side of the road waiting for the lorry to stop as well. However, the lorry did not stop and was driving off. I managed to take a picture of the lorry before it drove away. I then proceeded into the nearby OSCP to make a check on my vehicle. The damages to my vehicle is the rear boot dented. There is no in-car camera installed. I am lodging this report for insurance claim and police investigation.

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1495A
Vehicle Details	
Vehicle No.:	SGH575H
Vehicle to be Exported:	No
Intended De-registration Date:	23 Dec 2017
Vehicle Make:	NISSAN
Vehicle Model:	SUNNY 1.6EXA
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	QG16412519
Chassis No.:	JN1CFAN16Z0101975
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$12,665.00
Original Registration Date:	29 May 2006
First Registration Date:	29 May 2006
Transfer Count:	2
Actual ARF Paid:	\$13,932.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	

COE Expiry Date:	28 May 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$22,789.00
COE Rebate Amount:	\$15,633.00
<b>Total Rebate Amount:</b>	<b>\$15,633.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 23 Dec 2017

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/12/2017 08:44
Date Of Accident	18/12/2017 11:45
Exact Location Of Accident	BEDOK NORTH AVE 3
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD7869J
-----------------------------	---------

### Insured/Policyholder

Name Of Registered Owner	HONG FU CONSTRUCTION PTE LTD
Co Reg No	199003776H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-67532328

### Vehicle Particulars

Manufacturer	VOLVO
Model	FMX370-10.8 D 64R SC WB3900 (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A28624722MKF
Cover Note Number	

### Driver

Name of Driver	CHIA CHEE KHIANG
NRIC No	S7250479H
Date Of Birth	01/06/1972
Occupation	OUTDOOR
Date Of Driving Pass	19/02/2009
Driving Experience	8 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87208046
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Punggol Way. 5th LRT.  
Construction site.  
Punggol 16th Avenue.

Address  
Postcode

BLK 655 SENJA RD #10-270  
670655

Was driver an employee of the Insured's Company YES  
If No, Relationship of the Driver with the Insured  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
-  
Insurance Company of Driver's Own Vehicle -  
-  
-

#### General Information of the Accident

Type Of Accident NO COLLISION  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s)  
soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

MY COMPANY RECEIVED A LETTER DATED 20/12/2017 FROM INSURANCE COMPANY SAID THAT I INVOLVED IN AN ACCIDENT ON 18/12/2017 ALONG BEDOK NORTH AVE 3. I THEN RECALL BACK, ON 18/12/2017 I WAS TRAVELLING ALONG BEDOK NORTH AVE 3 BUT I NEVER INVOLVED IN ANY ACCIDENT. THAT'S ALL.

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGH575H  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repu diate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to circumstances of accident

Claim options: Claim own policy, Claim third party, Claim OD / TP at other works hop, For record purpose (checked). Policy No. A 28624922 MKF, Insurer MSIG (C), Veh.No. X09865J

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature, Date & Time

Driver's Signature (if driver is not the policyholder), Date & Time

Reporting Centre Personnel's Signature, Name, NRIC/FIN No.

Accident Photo



Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo



## City Auto Pte Ltd (Co.Reg No:199503435C)

160 Sin Ming Drive #05-01, Sin Ming AutoCity,  
Singapore 575722

Tel: 6453 1235 Fax: 6453 7944 Email: jason@cityauto.com.sg

TP INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

KOH ENG BENG

Singapore

## PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	18/12/2017
Vehicle Reg. No.:	SGH575H	Driveable?	
Party At Fault:	UNKNOWN	Driver	KOH ENG BENG
Driver (TP):	KOH ENG BENG	(Insured):	

Make/Model:	NISSAN SUNNY, 1.6 EX (A)	Vehicle Reg. Date:	29/05/2006
Vehicle Colour:	SILVER	Chassis No:	JN1CFAN16Z0101975
Engine No:	QG16412519		
Odometer:	0 KM		
Paint Type:			<i>Not Authored</i>
Total Loss?	NO		<i>Liberty?</i>
Est. Duration of Repair (day)	6 ✓		<i>Repair After Paint</i>

Description of Accident/Loss: REFER TO SKETCH PLAN  
Present Location: CITY AUTO PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	4,169.95
Miscellaneous Items	0.00
Labour	2,725.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	<b>6,894.95</b>
+ GST 7.00% (S\$)	482.65
Nett Amount (S\$)	<b>7,377.60</b>

This claim is handled by: VRONICA

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 19 Dec 2017)  
**Parts:** 143      NISSAN SUNNY 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** City Auto Pte Ltd/SGH575H/19/12/2017 18:05  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*REAR BUMPER	Br	0.00	0.00	*350.00 F ✓
2	2		*REAR BUMPER RETAINER	35 clip	0.00	0.00	*70.00 F ✓
3	2		*REAR BUMPER BRACKET		0.00	0.00	*90.00 F ✓
4	1		*REAR BUMPER CHROME MOULDING	new clip	0.00	0.00	*155.00 F ✓
5	4		*REAR BUMPER HOLDER CLIP	new	0.00	0.00	*12.00 F ✓
6	8		*REAR BUMPER CLIP	new	0.00	0.00	*16.00 F ✓
7	4		*REAR BUMPER RIVET	new	0.00	0.00	*20.00 F ✓
8	1		*REAR BOOT	Br	0.00	0.00	*450.00 F ✓
9	1		*REAR BOOT LOCK	Br	0.00	0.00	*85.00 F ✓
10	1		*REAR BOOT WEATHERSTRIP	DI/1/1/1	0.00	0.00	*85.00 F ✓
11	1		*REAR BOOT STRIKER	R	0.00	0.00	*25.00 F ✓
12	1		*REAR BOOT LOGO	new	0.00	0.00	*45.00 F ✓
13	1		*REAR BOOT EMBLEM - SUNNY	new	0.00	0.00	*35.00 F ✓
14	1		*REAR BOOT EMBLEM - EX-SALOON	new	0.00	0.00	*35.00 F ✓
15	1		*REAR BOOT EMBLEM - E THROTTLE	new	0.00	0.00	*28.00 F ✓
16	1		*REAR BOOT CHROME MOULDING - UPPER	Br	0.00	0.00	*155.00 F X
17	1		*REAR BOOT CHROME MOULDING - LOWER	CPM	0.00	0.00	*155.00 F ✓
18	1		*RH TAILLAMP	Br	0.00	0.00	*165.00 F ✓
19	1		*RH TAILLAMP PANEL	Br	0.00	0.00	*125.00 F ✓
20	1		*REAR RH FENDER	Br	0.00	0.00	*550.00 F ✓
21	1		*REAR RH FENDER INNER TRIM	new	0.00	0.00	*220.00 F ✓
22	6		*REAR RH FENDER INNER TRIM CLIP	new	0.00	0.00	*12.00 F ✓
23	1		*REAR WINDSCREEN GLASS MOULDING	new	0.00	0.00	*95.00 F ✓
24	1		*REAR WINDSCREEN GLASS MOULDING SEALANT	new	0	0.00	*40.00 FS ✓
25	1		*REAR END PANEL	Br	0.00	0.00	*250.00 F ✓
26	1		*REAR END PANEL TOP GARNISH	Br	0.00	0.00	*85.00 F ✓
27	1		*INSULATOR PASTE	new	0	0.00	*120.00 FS X
28	1		*REVERSE SENSOR	Br	0	0.00	*200.00 FS X

F=Franchise part. S=SpcNett.

Sub Total (S\$)	3,673.00
+ Margin on L,N Items 15.00% (S\$)	496.95
<b>Total Parts (S\$)</b>	<b>4,169.95</b>

City Auto Pte Ltd/SGH575H/19/12/2017 18:05. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	*REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00 ✓
2	*CHECK LIGHTING AND WIRING	New	55.00 201
3	*SUPPLY PANEL SEALANT TO SEAL OFF ALL WELD SPOT SEAM AND GAPS	New	100.00 301
4	*SPRAY UNDERCOATING	New	150.00 901
5	*TO KNOCK JACKOUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS	New	1,100.00 1000
6	*SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	1,200.00 901
<b>Gross Labour Cost (S\$)</b>			<b>2,725.00</b>

City Auto Pte Ltd/SGH575H/19/12/2017 18:05. Not valid without Reference section.  
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No (legal) mediation is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Dec 2017 <a href="#">Sendback Est</a>	19 Dec 2017 18:05 <b>S\$6,894.95</b>	20 Dec 2017 09:17 <a href="#">Edit Adj Rpt</a>	<b>S\$5,200.00</b> <a href="#">Edit Estimates</a>	<b>S\$5,200.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

### CLAIM SUBFOLDER DETAILS

Insured:	<b>HONG FU CONSTRUCTION PTE LTD</b> , Co. Reg. No.: 199003776H, Tel: +6596361140		
Main Claimant:	<b>KOH ENG BENG</b> , ID: S1631495A		
Vehicle Reg. No.:	<b>SGH575H</b>	Date of Loss:	18/12/2017 11:00 - :59 [138 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 541558</b>	Policy/Cover Note No.:	28624722MKF (Comprehensive) Coverage: 28/10/2017 - 27/10/2018
Vehicle Reg. No. (Insured):	<b>XD7869J</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>City Auto Pte Ltd (HQ)</b> 160 Sin Ming Drive #05-01,, Sin Ming AutoCity,, 575722 Sin Ming - Tel: 6453 1235		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Muhd Ashik B Madi</b> - 6594 2548]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 19/01/2018]		
Driver/Custodian (Insured):	KOH ENG BENG (53 / Male), NRIC: S1631495A, Tel: +6596361140		

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**SGH575H (541558)**  
**[XD7869J]**  
**TP**  
**KOH ENG BENG**  
**Dec 18 2017 11:00AM**  
**[HONG FU CONSTRUCTION PTE LTD]**  
**City Auto Pte Ltd**

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			View	View in Browser ▼	
<b>Assessment Reports</b>			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	City Auto Pte Ltd (HQ)		Thumbnail	Print
1	19/12/17 18:05	<b>Repairer Estimates</b>	1	Load HTM	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	26/12/17 16:08	<b>Accident Statement</b> From: SC - Reg. No: XD7869J, Claimant: HONG FU CONSTRUCTION PTE LTD	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/12/17 17:46	<b>Adjuster Immediate Advice</b>	1	Load HTM	
<b>Photos/Images</b>			3 per page ▼	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/12/17 17:41	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
2	21/12/17 17:41	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
3	21/12/17 17:41	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
4	21/12/17 17:41	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
5	21/12/17 17:41	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
6	21/12/17 17:41	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
7	21/12/17 17:41	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
8	21/12/17 17:41	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
9	21/12/17 17:41	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
10	21/12/17 17:41	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
11	21/12/17 17:41	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
12	21/12/17 17:41	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
13	21/12/17 17:41	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
14	21/12/17 17:41	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
15	21/12/17 17:41	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
16	21/12/17 17:41	<b>General View</b>	1	Load JPG	<input checked="" type="checkbox"/>
17	28/06/18 08:18	<b>Reinspection Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>
18	28/06/18 08:19	<b>Reinspection Photo</b>	1	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page ▼	<input checked="" type="checkbox"/>	
No	Finalized On	City Auto Pte Ltd (HQ)		Thumbnail	Print
1	20/12/17 08:56	<b>GIA report</b>	1	Load PDF	
2	23/04/18 17:50	<b>Letter of Demand from Third Party</b>	1	Load JPG	<input checked="" type="checkbox"/>
3	23/04/18 17:50	<b>Tax invoice</b>	1	Load JPG	<input checked="" type="checkbox"/>
4	23/04/18 17:50	<b>Letter of Authorization</b>	1	Load JPG	<input checked="" type="checkbox"/>
5	23/04/18 17:50	<b>GIA search receipt</b>	1	Load JPG	<input checked="" type="checkbox"/>
6	23/04/18 17:50	<b>GIA search receipt</b>	1	Load JPG	<input checked="" type="checkbox"/>
7	23/04/18 17:50	<b>Rental agreement</b>	1	Load JPG	<input checked="" type="checkbox"/>
8	23/04/18 17:50	<b>Rental agreement</b>	1	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				
No	Finalized On	City Auto Pte Ltd (HQ)		Thumbnail Print
9	23/04/18 17:50	DV	1	Load JPG
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	28/12/17 13:15	Scene photo (not conclusive)	i	Load PDF
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	28/06/18 13:46	INVESTIGATION REPORT	1	Load PDF

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

#### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:  Repairer  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17024132/KVD3S2

Date: 28/06/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28624722MKF
Claimant Vehicle No :	SGH575H	Insured Vehicle No :	XD7869J
Date of Loss:	18/12/2017	Nature of Claim:	TP
		Claim No:	541558

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>SGH575H</b>	Engine No:	QG16412519
Make & Model:	NISSAN SUNNY, 1.6 EX (A)	Chassis No:	JN1CFAN16Z0101975
Reg. Date:	29/05/2006 (Man. Year: 2006)	Odometer:	298680 km
Colour:	Metallic Silver		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 8 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,169.95	3,048.00	1,121.95	26.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,725.00	2,160.00	565.00	20.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,894.95</b>	<b>5,208.00</b>	<b>1,686.95</b>	<b>24.47</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,200.00</b>		
<b>(S\$)</b>	6,894.95	5,200.00	1,694.95	24.58
<b>+ GST 7.00/7.00% (S\$)</b>	482.65	364.00	118.65	24.58
<b>Nett Amount (S\$)</b>	<b>7,377.60</b>	<b>5,564.00</b>	<b>1,813.60</b>	<b>24.58</b>

## INSPECTION

Date of Assignment:	20/12/2017	Present Location:	City Auto Pte Ltd (HQ) 160 SIN MING DRIVE #05-01 Repairer: City Auto Pte Ltd BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643
Date Inspected:	20/12/2017	Inspected At:	
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2018)
<b>Parts:</b> 143	NISSAN SUNNY 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SGH575H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*REAR BUMPER</b> (WCP)	Buckled	350.00 F	*350.00 F
2	1		<b>*REAR BUMPER RETAINER</b> (WCP)	O/s Cracked	70.00 F	*35.00 F
3	2		<b>*REAR BUMPER BRACKET</b> (WCP)	Repair	90.00 F	*- F
4	1		<b>*REAR BUMPER CHROME MOULDING</b> (WCP)	Necessary	155.00 F	*155.00 F
5	4		<b>*REAR BUMPER HOLDER CLIP</b> (WCP)	Necessary	12.00 F	*12.00 F
6	8		<b>*REAR BUMPER CLIP</b> (WCP)	Necessary	16.00 F	*16.00 F
7	4		<b>*REAR BUMPER RIVET</b> (WCP)	Necessary	20.00 F	*20.00 F
8	1		<b>*REAR BOOT</b> (WCP)	Bent	450.00 F	*450.00 F
9	1		<b>*REAR BOOT LOCK</b> (WCP)	Dented	85.00 F	*85.00 F
10	1		<b>*REAR BOOT WEATHERSTRIP</b> (WCP)	Distorted / Dented	85.00 F	*85.00 F
11	1		<b>*REAR BOOT STRIKER</b> (WCP)	Repair	25.00 F	*- F
12	1		<b>*REAR BOOT LOGO</b> (WCP)	Necessary	45.00 F	*45.00 F
13	1		<b>*REAR BOOT EMBLEM - SUNNY</b> (WCP)	Necessary	35.00 F	*35.00 F
14	1		<b>*REAR BOOT EMBLEM - EX-SALOON</b> (WCP)	Necessary	35.00 F	*35.00 F
15	1		<b>*REAR BOOT EMBLEM - E THROTTLE</b> (WCP)	Necessary	28.00 F	*28.00 F
16	1		<b>*REAR BOOT CHROME MOULDING - UPPER</b> (WCP)	Serviceable	155.00 F	*- F
17	1		<b>*REAR BOOT CHROME MOULDING - LOWER</b> (WCP)	Cracked	155.00 F	*155.00 F
18	1		<b>*RH TAILLAMP</b> (WCP)	Broken	165.00 F	*165.00 F
19	1		<b>*RH TAILLAMP PANEL</b> (WCP)	Bent	125.00 F	*125.00 F
20	1		<b>*REAR RH FENDER</b> (WCP)	Buckled	550.00 F	*550.00 F
21	1		<b>*REAR RH FENDER INNER TRIM</b> (WCP)	Deformed	220.00 F	*220.00 F
22	6		<b>*REAR RH FENDER INNER TRIM CLIP</b> (WCP)	Necessary	12.00 F	*12.00 F
23	1		<b>*REAR WINDSCREEN GLASS MOULDING</b> (WCP)	Necessary	95.00 F	*95.00 F
24	1		<b>*REAR WINDSCREEN GLASS MOULDING SEALANT</b>	Necessary	40.00 FS	*40.00 FS
25	1		<b>*REAR END PANEL</b> (WCP)	Bent	250.00 F	*250.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
26	1		*REAR END PANEL TOP GARNISH (WCP)	Buckled	85.00 F	*85.00 F	
27	1		*INSULATOR PASTE	Serviceable	120.00 FS	*- FS	
28	1		*REVERSE SENSOR	Serviceable	200.00 FS	*- FS	
					<b>Sub Total (\$\$)</b>	<b>3,673.00</b>	<b>3,048.00</b>
					<b>+ Margin on L,N Items 15.00/0.00% (\$\$)</b>	<b>496.95</b>	<b>0.00</b>
					<b>Total Parts (\$\$)</b>	<b>4,169.95</b>	<b>3,048.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	*REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
2	*CHECK LIGHTING AND WIRING	New	55.00	20.00
3	*SUPPLY PANEL SEALANT TO SEAL OFF ALL WELD SPOT SEAM AND GAPS	New	100.00	30.00
4	*SPRAY UNDERCOATING	New	150.00	90.00
5	*TO KNOCK JACKOUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS	New	1,100.00	1,000.00
6	*SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	1,200.00	900.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,725.00</b>	<b>2,160.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >