Menu

Handbrake (Serviceable)

Engine Modification

Pre-accident condition

Excellent

Tyre Condition

Age of Tyres

Front Tyre Size

Front left side

Front right side

Spare wheel

Rear Tyre Size

Rear left side

Rear right side

Menu

13

Driver License #

S7441917H

License Type

3

1

License Issue Date

June 16, 2004

mm/dd/yyyy

License Expiration Date

June 16, 2024

mm/dd/yyyy

Address

Singapore

Address type

Menu

COROLLA ALTIS 1.6

Type

Listed on policy

Type of Paint

Chassis No

MR053ZEC107141334

Engine No

3ZZ4630587

Engine Capacity

Sum Insured

0

Menu

Menu

Model
COROLLA ALTIS 1.6

Service Address

Blk 1 Sin Ming Industrial, , , 575636

Primary Contact/Insured

MOHAMAD MOHAMED RAFII BIN
777 WOODLANDS CRESCENT, 730777, Singapore
67472888

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Additional Instructions
EXCESS $500

Messages Invoices History Documents Assessment Metrics Notes

Add

TEO Kitty

12/20/17 2:58 PM

$0.00

$0.00

Open

Share

Clone

Menu

December 27, 2017

SGT 2397D ESTIMATE.pdf

Forms / Claim Documents

Estimate / Quotation

LKK AUTO CONSULTANTS PTE LTD (OD)

December 22, 2017

SAS2326008.pdf

Reports & Statement

GIA Report

BH AUTO SERVICES PTE LTD

December 20, 2017

Menu

Model
COROLLA ALTIS 1.6

Service Address

Blk 1 Sin Ming Industrial, , , 575636

Primary Contact/Insured

MOHAMAD MOHAMED RAFII BIN
777 WOODLANDS CRESCENT, 730777, Singapore
67472888

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Additional Instructions
EXCESS $500

Messages Invoices History Documents Assessment Metrics Notes

Document Type	Document SubType

Upload Documents

LTA REBATE.pdf

Forms / Claim Documents

Others

LKK AUTO CONSULTANTS PTE LTD (OD)

March 14, 2018

SGT 2397D LKKPhotosIn4-15.pdf