

22/02/2017

ASS: REC BY:

REF: CS/FCI17024144/R2rd3

Special Instruction:

Surveyor:

CWS

Resul

ASSIGNMENT (Office)

From (Person):

Lureh jaw

of

FCI

Date/Time:

12.23 pm / 20/12/17

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SG Y 7917U

Insured:

SHA 9987T

at Workshop m/s:

Mora

Tel:

627 23892

of BIK 1008, Bkt Merah Lune 3 # 01-04

Policy No:

Claim No:

D17011624MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 15/12/2017

CA / REV / REP. / REV 24 HRS

'DS'

15, Fan Yong Rd

R.O.D. Endorsement

Date/Time: 12.24 pm @ 20/12/17

Person Contacted

Avril

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SG Y 7917U - CCG / AIG / 15015382 / Rpa3q2

D.O.A. : 05/09/2015

SHA 9987T - X

Confirm

LIS \$5850.00 @ 9 days

led: \$2857.50, 33%.

SINGAPORE

REF: FCL

3066F

COE EXPIRY: 2022/10/1

ASSIGNMENT

From: _____ Date: 20-12-2017

Estimated Cost: _____

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGY 7917U

at Workshop m/s: MOVU

of 15 Tan Yang Road

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 35K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGY 7917U Yr Regn: 2007 O/S

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA VIOS E A C/C 1497

Colour: Rtn A/C: Insured / Std / NI / NA

Sp. Reading: 176641 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRO53HY93 6501975

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 195/50R15

R: 2"

BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal: S mm R/Bal: S mm

L/Bal: S mm L/Bal: S mm

D.O.A: 15/12/17 D.O.I: 20/12/17

Survey held at: MOVU (FY)

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 01 AUG 2018

Date/Time File Pass to?

1) typist

Date/Time File Return to?

2) _____

Report Format: 7P

Lump Sum / LBI: (\$ 5850.00)

Days Of Repair: 9

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation

Photos

Others

TOTAL

180
50
50
79
359

MOTOR SURVEY ASSIGNMENT

Date	18-12-2017	Our Ref No. D17011624MFSH
Accident Date	15-12-2017	Claim Type. Third Party
Insured Vehicle	SHA9987T	Third Party Vehicle. SGY7917U
Survey Location	BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08	
Contact Person.	NITHA	
Contact No.	62723892/ 0	Fax No. 62708314
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOVA AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/232062)



PRI Documents



Close



PRI Header Details

Claim No	D17011624MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & MOVA AUT
Workshop Name	MOVA AUTOMOTIVE PTE LTD (Contact Person : NITHA)	Survey Location & Contact Details	BLOCK 1008 BUKIT MERAH LANE 3 #01-04/06/08 Mobile: 0 , Phone: 62723892 , Fax: 62708314 EmailId: NITHA@MOVA.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9987T	TP Vehicle No	SGY7917U
PRI Recieved Date	18-12-2017 07:55:41 PM	Surveyor Appointed Date	20-12-2017 12:22:21 PM	Surveyor Accept Date	20-12-2017 1

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	20-12-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17024144/R1rd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9987T	Veh. Inspected	SGY 7917U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17011624MFSH	Excess (\$)	0.00	
Assign From	CWS (LURENE JAW)	Assign Date	20/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/12/2017	Inspection Date	20/12/2017	
Survey held at	15,FAN YOONG ROAD, 629792			
Repairer	MOVA AUTOMOTIVE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Automotive Pte Ltd

Main Office

Mova Building
No. 22, Jalan Kilang
Singapore 159411
Tel : (65) 6476 3333
Fax : (65) 6271 589
www.mova.com.sg

Workshop Dept

Block 1008
Bukit Merah Lane 3
#01-04/06/08/9
Singapore 159721

Tel : (65) 6272 389
Fax : (65) 6270 831

Co. Reg. 198904033C
GST Reg. M2-0088864-

Estimate

18/12/2017

FIRST CAPITAL INSURANCE LTD
36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

Page # :- 1

Veh # :- SGY7917U

Veh Model :- YOYOTA VIOS

Estimate# :- CK416809

Claim # :-

ACC. Date :- 15/12/17

Terms :- C.O.D Days

Remarks :-

Alan 96869276

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER	1 PC	485.00 DE	485.00
2.	REAR BUMPER SIDE RETAINER	2 PC	60.00 neu	120.00
3.	REAR BUMPER CLIPS	10 PC	5.00 neu	50.00
4.	REAR BUMPOER REFLECTOR LAMP RH	1 PC	130.00 neu	130.00
5.	BOOT LID	1 PC	675.00 PH	675.00
6.	BOOT LID GARNISH X	1 PC	280.00 neu	280.00
7.	BOOT LID LOCK	1 PC	230.00 PH	230.00
8.	BOOT LID LOGO	1 PC	50.00 neu	50.00
9.	BOOT LID (E) EMBLEM	1 PC	40.00 neu	40.00
10.	BOOT LID (VIOS) EMBLEM	1 PC	50.00 neu	50.00
11.	BOOT LID HINGE	2 PC	130.00 PH	260.00
12.	TAILLAMP	2 PC	298.00 C RA	596.00
13.	TAILLAMP SEAL	2 PC	20.00 neu	40.00
14.	TRUCK LID WEATHERSTRIP	1 PC	210.00 neu	210.00
15.	END PANEL GARNISH	1 PC	195.00 DE	195.00
16.	END PANEL ASSY	1 PC	495.00 PH	495.00
17.	SPARE TYRE BOARD X	1 PC	490.00 X su	490.00
18.	SPARE TYRE LEFT & RIGHT SPANGE	2 PC	390.00 DE	780.00
19.	FLOOR PANEL ASSY	1 PC	789.00 neu	789.00
20.	REAR EXHAUST CHROME PIPE	1 PC	160.00 S RA	160.00
21.	REAR EXHAUST ASSY	1 PC	495.00 neu	495.00
22.	REAR FENDER INNER SHIELD RH	1 PC	60.00 DE	60.00
23.	SPARE TYRE INNER SPANGE X	1 PC	390.00 X su	390.00
LIST TOTAL S\$				7,070.00
25% DISCOUNT S\$				-1,767.50
				5,302.50
SPECIAL NET ITEMS :				
1.	REAR NUMBER PLATE	1 PC	50.00 35 su	50.00
2.	REAR PARKING SENSOR	1 SET	200.00 neu	200.00
3.	ACCIDENT TOWING TO FAN YOUNG	1 PC	55.00	55.00
SPECIAL NET TOTAL S\$				305.00
LABOUR :				
TO INSPECT REAR RIGHT LIGHTING WATER & LEAKAGE TEST				40.00
TO REMOVE & INSTALL REAR GARNISH, CARPET, ETC IN ORDER TO CUT OFF END PANEL, FLOOR PANEL				100 200.00
TO CUT OFF END PANEL, FLOOR PANEL, STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGEDS PARTS				1000 1200.00
TO SET VEHICLE ON CHASSIS BENCH IN ORDER TO STRAIGHTEN & CUT OFF DAMAGED PARTS				250 200ph 200.00



Automotive Pte Ltd

Main Office
Mova Building
No. 22, Jalan Kilang
Singapore 159411
Tel : (65) 6476 333
Fax : (65) 6271 589
www.mova.com.sg

Workshop Dept
Block 100E
Bukit Merah Lane 3
#01-04/05/08/9
Singapore 15972
Tel : (65) 6272 389
Fax : (65) 6270 831
Co. Reg. 198904033K
GST Reg. M2-0088864-

Estimate

18/12/2017

FIRST CAPITAL INSURANCE LTD
36 Robinson Road
#16-01 City House
Singapore 068877.

Page # :- 1 130255

Veh # :- SGY7917U

Veh Model :- YOYOTA VIOS

Estimate# :- CK416809

Claim # :-

ACC. Date :- 15/12/17

Terms :- C.O.D Days

Remarks :-

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
	TO APPLY BODY JOINT SEALANT ON CUTTING ARAES		46	60.00
	TO APPLY RUST PROOF ON AFFECETED ARAES		80	100.00
	TO SPRAY PAINT ON REPLACED , REPAIRED AREAS		1100	1200.00
	LABOUR TOTAL S\$			3,100.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 8,707.50

GST @ 7 % 609.53

AMOUNT DUE S\$ 9,317.03

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
4p 90010068
9 days
4/5
20/12/17 P1640
Repy after repri.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	3066F
Vehicle Details	
Vehicle No.	SGY7917U
Vehicle to be Exported	Yes
Intended De-registration Date	16 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	VIOS E AUTO
Primary Colour	Red
Manufacturing Year	2007
Engine No.	1NZX593616
Chassis No.	MR053HY9305019175
Maximum Power Output	80.0 kW (107 bhp)
Open Market Value	\$12,607.00
Original Registration Date	09 Oct 2007
First Registration Date	09 Oct 2007
Transfer Count	2
Actual ARF Paid	\$13,868.00
Intended PARF Rebate Details	
PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	30 Sep 2022
COE Category	A - Car (1600cc & below)
COE Period(Years)	5
PQP Paid	\$22,041.00
COE Rebate Amount	\$21,110.00
Total Rebate Amount	\$21,110.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 16 Dec 2017

OK

38,000
21,110

16,890

TP First Capital

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	16/12/2017 09:05
Date Of Accident	15/12/2017 16:55
Exact Location Of Accident	JUNC OF CHANGI NORTH ST 1 & UPPER CHANGI RD NORTH
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGY7917U
Insured/Policyholder	
Name Of Registered Owner	PARAMESWARI D/O SANKARAPANDI CHAMI
NRIC No	S7803066F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90250106
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VIOS E AUTO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5094018868
Cover Note Number	
Driver	
Name of Driver	PRASAD S/O VIJAYAN
NRIC No	S7801169F
Date Of Birth	03/02/1978
Occupation	INDOOR
Date Of Driving Pass	10/08/2010
Driving Experience	7 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90250106
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	PD7801@YAHOO.COM

Address
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured SPOUSE
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions RAINING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA9987T
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver LEE NG CHYE
NRIC/Passport Number S1547896I
Contact Number 97848327
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]
16/12/17 9:21am
Policyholder's Signature / Date & Time

[Signature] / 16/12/2017 / 09:21 AM
Driver's Signature (If driver is not the policyholder) / Date & Time

[Signature]
Witnessed by Reporting Centre Personnel

Sketch Plan





Sketch Plan Pg. 2

Describe Circumstances of the Accident		LICENSE PLATE NUMBER: SG47917 U
ACCIDENT DATE: 15/12/2017	CONTACT NUMBER: 94234075 / 90250106	
ACCIDENT TIME: 04 58 PM	EMAIL: p67801@yahoo.com	
LOCATION: JUNCTION of Changi North Street 1 & upper Changi Rd NORTH.		
<p>MY CAR WAS AT Changi North Street 1, waiting to turn left at traffic junction, to go into Upper Changi Rd North. When light was green for motorists, my car turn left but had to stop for pedestrian since it was green for them also at their traffic crossing, but the city cab taxi must have continued without noticing my car in front of his. And his car crashed into my rear of my car.</p> <p>We moved to the sides to settle the issues since my car had moved off in the middle of the traffic crossing for pedestrians, due to the impact of the crash. And took down the photos of the damages and our particulars. He moved on while I waited for the orange force advisor.</p>		
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY.		
PLEASE CHECK YOUR POLICY FOR MORE INFORMATION.		
Please state:		
<input type="checkbox"/> Claim Own Policy <input checked="" type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input type="checkbox"/> Reporting Only		

Declaration

I/We declare the foregoing particulars are true in every respect.


 16/12/17 9:21am
 Policyholder's Signature / Date & Time


 16/12/2017/09 21 AM
 Driver's Signature (If driver is not the policyholder) / Date & Time


 Witnessed by Reporting Centre Personnel



Automotive Pte Ltd

Main Office

Mova Building
No. 22, Jalan Kilang
Singapore 159411
Tel : (65) 6476 3331
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept

Block 100E
Bukit Merah Lane 3
#01-04/06/08/9
Singapore 159722

Tel : (65) 6272 3892
Fax : (65) 6270 8311

Co. Reg. 198904033C
GST Reg. M2-00888642

Estimate

18/12/2017

FIRST CAPITAL INSURANCE LTD

36 Robinson Road

#16-01 City House

Singapore 068877.

Page # :- 1

Veh # :- SGY7917U

Veh Model :- YOYOTA VIOS

Estimate# :- CK416809

Claim # :-

ACC. Date :- 15/12/17

Terms :- C.O.D Days

Remarks :-

Alan 96869276

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BUMPER	1 PC	485.00	485.00
2.	REAR BUMPER SIDE RETAINER	2 PC	60.00	120.00
3.	REAR BUMPER CLIPS	10 PC	5.00	50.00
4.	REAR BUMPER REFLECTOR LAMP RH - <i>CRIDE</i>	1 PC	130.00	130.00
5.	BOOT LID	1 PC	675.00	675.00
6.	BOOT LID GARNISH	1 PC	280.00	280.00
7.	BOOT LID LOCK	1 PC	230.00	230.00
8.	BOOT LID LOGO	1 PC	50.00	50.00
9.	BOOT LID (E) EMBLEM	1 PC	40.00	40.00
10.	BOOT LID (VIOS) EMBLEM	1 PC	50.00	50.00
11.	BOOT LID HINGE	2 PC	130.00	260.00
12.	TAILLAMP	2 PC	298.00	596.00
13.	TAILLAMP SEAL	2 PC	20.00	40.00
14.	TRUCK LID WEATHERSTRIP	1 PC	210.00	210.00
15.	END PANEL GARNISH	1 PC	195.00	195.00
16.	END PANEL ASSY	1 PC	495.00	495.00
17.	SPARE TYRE BOARD	1 PC	490.00	490.00
18.	SPARE TYRE LEFT & RIGHT SPANGE	2 PC	390.00	780.00
19.	FLOOR PANEL ASSY	1 PC	789.00	789.00
20.	REAR EXHAUST CHROME PIPE	1 PC	160.00	160.00
21.	REAR EXHAUST ASSY - <i>BATT</i>	1 PC	495.00	495.00
22.	REAR FENDER INNER SHIELD RH	1 PC	60.00	60.00
23.	SPARE TYRE INNER SPANGE	1 PC	390.00	390.00
LIST TOTAL S\$				7,070.00
25% DISCOUNT S\$				-1,767.50
				5,302.50
SPECIAL NET ITEMS :				
1.	REAR NUMBER PLATE	1 PC	50.00	50.00
2.	REAR PARKING SENSOR	1 SET	200.00	200.00
3.	ACCIDENT TOWING TO FAN YOUNG	1 PC	55.00	55.00
SPECIAL NET TOTAL S\$				305.00
LABOUR :				
TO INSPECT REAR RIGHT LIGHTING WATER & LEAKAGE TEST				40.00
TO REMOVE & INSTALL REAR GARNISH, CARPET, ETC IN ORDER TO CUT OFF END PANEL, FLOOR PANEL				100
TO CUT OFF END PANEL, FLOOR PANEL, STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS				1000
TO SET VEHICLE ON CHASSIS BENCH IN ORDER TO STRAIGHTEN & CUT OFF DAMAGED PARTS				250

P-5910

P-4432.50

CIN-290

HC-2610

7332.50 CIN-290

20848

5866

35

50.00

200.00

55.00

305.00

40.00

100

1000

250

2000

3000



Automotive Pte Ltd

Main Office
Mova Building
No. 22, Jalan Kilang
Singapore 159411
Tel: (65) 6476 3331
Fax: (65) 6271 589
www.mova.com.sg

Workshop Dept
Block 1006
Bukit Merah Lane 3
#01-04/05/08/9
Singapore 15972
Tel: (65) 6272 3891
Fax: (65) 6270 831
Co. Reg. 1989040331
GST Reg. M2-0088864-

Estimate

18/12/2017

FIRST CAPITAL INSURANCE LTD
36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

Page # :- 1 130255

Veh # :- SGY7917U

Veh Model :- YOYOTA VIOS

Estimate# :- CK416809

Claim # :-

ACC. Date :- 15/12/17

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	TO APPLY BODY JOINT SEALANT ON CUTTING ARAES		40	50.00
	TO APPLY RUST PROOF ON AFFECETED ARAES		80	100.00
	TO SPRAY PAINT ON REPLACED , REPAIRED AREAS		1100	1200.00
	LABOUR TOTAL S\$			3,100.00

LC-2610

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 8,707.50

GST @ 7 % 609.53

AMOUNT DUE S\$ 9,317.03

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
4p 90010068
9 days
4/s
20/12/17 P1640
Resy after repm.

🔄 Reply all | ▾ 🗑 Delete Junk | ▾ ...

FW: finalization for veh no:SGY7917U

MK

Mei Kwan (LKKAuto)

Today, 11:55 AM

Shiau Chan (LKKAuto); SUR ▾

👤 🔄 Reply all | ▾

Inbox

24012018144520-0001.... ▾

408 KB

Download

CS/FCI17024144/R1rd3

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Alan Chng [mailto:tuckmeng@mova.com.sg]

Sent: Thursday, 19 July, 2018 10:30 AM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: finalization for veh no:SGY7917U

Dear Rasul,

Please confirm the COR & working days by ASAP. Sorry! My Boss Chasing.

Thanks!

Best Regards

Alan Chng

Claims Estimator

Mova Automotive Pte Ltd

H/P 9686 9276

Office No:6262 3377

Fax No:6264 3151

-----Original Message-----

From: Alan Chng [mailto:tuckmeng@mova.com.sg]

Sent: Friday, 13 July 2018 12:32 PM

To: 'Rasul (LKKAuto)'

Reminder

Dear Rasul,

Please confirm the COR & working days by ASAP.

Thanks!

Best Regards
Alan Chng
Claims Estimator
Mova Automotive Pte Ltd
H/P 9686 9276
Office No:6262 3377
Fax No:6264 3151

-----Original Message-----

From: Alan Chng [<mailto:tuckmeng@mova.com.sg>]
Sent: Tuesday, 13 March 2018 12:36 PM
To: 'Rasul (LKK Auto)'
Cc: 'admin-a@lkkauto.com'
Subject: FW: finalization for veh no:SGY7917U

Dear Rasul,

Please confirm the COR & working days by ASAP.
Thank you!

Best Regards
Alan Chng
Claims Estimator
Mova Automotive Pte Ltd
H/P 9686 9276
Office No:6262 3377
Fax No:6264 3151

-----Original Message-----

From: Alan Chng [<mailto:tuckmeng@mova.com.sg>]
Sent: Wednesday, 24 January 2018 3:04 PM
To: 'Rasul (LKK Auto)'
Cc: 'admin-a@lkkauto.com'
Subject: finalization for veh no:SGY7917U

Dear Rasul,

Please refer the attach all photos & estimate to confirm the COR & working days.
Repair cost lump sum \$5850 & 9 working days, please confirm the COR & working days reply by email.

 Reply all |   Delete  Junk |  

Best Regards

Alan Chng

Claims Estimator

Mova Automotive Pte Ltd

H/P 9686 9276

Office No:6262 3377

Fax No:6264 3151




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17024144/R1rd3q2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9987T	Veh. Inspected	SGY 7917U	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17011624MFSH	Excess (\$)	0.00	
Assign From	LURENE JAW	Assign Date	20/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS E A	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	MR053HY9305019175	Colour	RED	
Odometer	176641	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R15	DUNLOP	5 mm	
L/H Front Tyre	195/50 R15	DUNLOP	5 mm	
R/H Rear Tyre	195/50 R15	DUNLOP	5 mm	
L/H Rear Tyre	195/50 R15	DUNLOP	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/12/2017	Inspection Date	20/12/2017	
Survey held at	15.FAN YOONG ROAD, 629792			
Repairer	MOVA AUTOMOTIVE PTE LTD			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGY 7917U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	485.00	485.00
2	REAR BUMPER SIDE RETAINER @\$60.00	NECESSARY	120.00	120.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER REFLECTOR LAMP RH	CRACKED	130.00	130.00
1	BOOT LID	BENT	675.00	675.00
1	BOOT LID GARNISH	SERVICEABLE	280.00	-
1	BOOT LID LOCK	BENT	230.00	230.00
1	BOOT LID LOGO	NECESSARY	50.00	50.00
1	BOOT LID (E) EMBLEM	NECESSARY	40.00	40.00
1	BOOT LID (VIOS) EMBLEM	NECESSARY	50.00	50.00
2	BOOT LID HINGE @\$130.00	BENT	260.00	260.00
2	TAILLAMP @\$298.00	CRACKED	596.00	596.00
2	TAILLAMP SEAL @\$20.00	NECESSARY	40.00	40.00
1	TRUCK LID WEATHERSTRIP	NECESSARY	210.00	210.00
1	END PANEL GARNISH	DEFORMED	195.00	195.00
1	END PANEL ASSY	BENT	495.00	495.00
1	SPARE TYRE BOARD	SERVICEABLE	490.00	-
2	SPARE TYRE LEFT & RIGHT SPANGE @\$390.00	DEFORMED	780.00	780.00
1	FLOOR PANEL ASSY	BUCKLED	789.00	789.00
1	REAR EXHAUST CHROME PIPE	SCRATCHED	160.00	160.00
1	REAR EXHAUST ASSY	BENT	495.00	495.00
1	REAR FENDER INNER SHIELD RH	DEFORMED	60.00	60.00
1	SPARE TYRE INNER SPANGE	NOT NECESSARY	390.00	-
	LESS 25% DISCOUNT		-1,767.50	-1,477.50
			5,302.50	4,432.50
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	SCRATCHED	50.00	35.00
1	SET REAR PARKING SENSOR (SN)	NOT WORKING	200.00	200.00
			250.00	235.00

Report Ref No. CS/FC117024144/R1rd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	ACCIDENT TOWING TO FAN YOONG .		55.00	55.00
	TO INSPECT REAR RIGHT LIGHTING WATER & LEAKAGE TEST.		40.00	40.00
	TO REMOVE & INSTALL REAR GARNISH ,CARPET,ETC IN ORDER TO CUT OFF END PANEL ,FLOOR PANEL.		200.00	100.00
	TO CUT OFF END PANEL ,FLOOR PANEL,STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGEDS PARTS.		1,200.00	1,000.00
	TO SET VEHICLE ON CHASSIS BENCH IN ORDER TO STRAIGHTEN & CUT OFF DAMAGED PARTS.		300.00	250.00
	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS.		60.00	40.00
	TO APPLY RUST PROOF ON AFFECTED AREAS.		100.00	80.00
	TO SPRAY PAINT ON REPLACED ,REPAIRED AREAS.		1,200.00	1,100.00
			3,155.00	2,665.00
	GRAND TOTAL		8,707.50	7,332.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,850.00

Report Ref No. CS/FCI17024144/R1rd3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.