

(08/11/13) wef

ASS. REC. BY:

REF: EQI

ASSIGNMENT

From: _____ Date: 19/7/18

Estimated Cost: _____

OT / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGC 7210R

at Workshop m/s Poon Siang Siew

of 160 Sin Ming Drive #05-13

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up) 01/21

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGC 7210R Yr Regn: 01, 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Edix c.c. 1668

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 205815 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: BE1 1010602

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Austin 205/55R16

R: Pass

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 14/12/17

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I. 19/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Acc

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/7 File pass to Lethem
11 Pm @ 900 end

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

____ S + RS, ____ SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$)

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 0044B

Vehicle Details

Vehicle No.: SGC7210R

Vehicle to be Exported: Yes

Intended De-registration
Date: 26 Aug 2017

Vehicle Make: HONDA

Vehicle Model: EDIX 1.7 A

Primary Colour: Grey

Manufacturing Year: 2005

Engine No.: D17A4012156

Chassis No.: BE11010602

Maximum Power Output: 96.0 kW (128 bhp)

Open Market Value: \$26,548.00

Original Registration
Date: 21 Jan 2006

First Registration Date: 21 Jan 2006

Transfer Count: 3

Actual ARF Paid: \$29,203.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 20 Jan 2021

COE Category: B - Car (1601cc & above)

COE Period(Years): 5

PQP Paid: \$29,308.00

COE Rebate Amount: \$19,932.00

Total Rebate Amount: \$19,932.00**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 25 Aug 2017

OK



Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 20 Aug 2017 at 12:36 AM