

ASS. REC. BY:

REF:

TP / 09/TP17024179/Kqbez

Keneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S11D 9583J Yr Regn: Jul, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Chevrolet Epica c.c. 1991

Colour: White/Red AC: Insured / Std / NI / NA

Sp.Reading: 378709 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KL1LA69RTAB 097692

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: WHL/161K 195/65R15

R: Giti

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front: 7 mm Rear: 8 mm

R/Bal. 7 mm R/Bal. 8 mm

L/Bal. 7 mm L/Bal. 8 mm

D.O.A. 19/12/17 D.O.I. 20/12/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S 1st body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
21/12	File sent to Customer
	21 Sep 2017 34501 Credit of 9367.05, 73% no resurvey photo.
	S11D 9583J - 104/AXA/17024179/Kqbez
	DUK: 02067

RECEIVED

Date/Time, File Pass to?

: Prell. Report

19/12/17

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

170+30
50
16
80
346

Report Format: TP

Lump Sum / L.B.I. (\$) 3450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TRANS-CAB AUTO SERVICES PTE LTD

Ref : CS/TP17024179/Kqb

NO.2 ANG MO KIO STREET 63 SINGAPORE 569111

Date : 21-12-2017



Code : TP378

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SHD 9583J
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	20/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/12/2017	Inspection Date	20/12/2017
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHD9583J

Vehicle to be Exported: No

Intended De-registration Date: 22 Dec 2017

Vehicle Make: CHEVROLET

Vehicle Model: EPICA 2.0DSL AT ABS
D/AB 2WD 4DR TURBO

Primary Colour: Red

Manufacturing Year: 2011

Engine No.: Z20S1455869K

Chassis No.: KL1LA69RJBB097692

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$14,384.00

Original Registration Date: 16 Jul 2012

First Registration Date: 16 Jul 2012

Transfer Count: 0

Actual ARF Paid: \$14,384.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 15 Jul 2020

PARF Rebate Amount: \$10,068.00

Intended COE Rebate Details

COE Expiry Date: 15 Jul 2020

COE Category: A - Car (1600cc & below)

COE Period(Years): 8

QP Paid: \$47,203.00

COE Rebate Amount: \$15,119.00

Total Rebate Amount: \$25,187.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/12/2017 15:03
Date Of Accident	19/12/2017 11:40
Exact Location Of Accident	SIXTH AVENUE TOWARDS LEMON AVENUE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9583J
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	TEO ING LONG
NRIC No	S1247909C
Date Of Birth	30/03/1957
Occupation	OUTDOOR
Date Of Driving Pass	02/11/1982
Driving Experience	35 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97212048
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 916 HOUGANG AVENUE 9
#13-12

Postcode 530916

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? YES

Foreign Vehicle Registration Number JJS1672 (MOTORCYCLE)

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name BISHAN NEIGHBOURHOOD POLICE CENTRE

Police Station Address **ROAD:** 20 BISHAN STREET 23 , **POSTCODE:** 579757 , **COUNTRY:** SINGAPORE

Police Station Contact **TEL NO:** 1800-5529999 - **FAX NO:** 65561905

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20171219/2072

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: FILE TOO BIG

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number JJS1672

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver CHENG FARN KUAN

NRIC/Passport Number G8181512M

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


pls see attach police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20171219/2072

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

1 of 3

Report No. T/20171219/2072

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/12/2017 13:46		Vide Report No.:		Station Diary No.: 60	
Informant's Particulars					
Name of Informant: TEO ING LONG			Address: APT BLK 916 HOUGANG AVENUE 9 #13-12 SINGAPORE 530916		
ID Type / ID No.: NRIC NO / S1247909C			Contact No.:		Mobile: 97212048
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 60	Date of Birth: 30/03/1957	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: Taxi driver		Driving Licence Information: Class: 3		Date of Expiry:	

General Information of the Accident				
Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 19/12/2017 11:40	Type of Location: T-Junction
Location: Along Road 1 SIXTH AVENUE JUNCTION OF SIXTH AVENUE AND LEMON AVENUE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JJS1672						0
SHD9583J	Car					0

Detail of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20171219/2072

2 of 3

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20171219/2072

CONTINUATION OF REPORT

Rider			
Name	CHENG FARN KUAN	ID No.	G8181512M
Related Vehicle	JJS1672	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TEO ING LONG	ID No.	S1247909C
Related Vehicle	SHD9583J (Car)	Contact No.	97212048
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 19/12/2017 at about 1140hrs, I was travelling along Sixth Avenue towards Holland Road. At the junction of Sixth Avenue and Lemon Avenue, I on the turn signal and while I was about to turn into the Lemon Avenue, One motorcycle from behind dash out and hit onto my right side mirror. Then I stepped out of the vehicle and called for the police. I also exchanged the particulars with the rider. Ambulance came, but no one was conveyed.

I am lodging this report for insurance claim purposes.



**SINGAPORE
POLICE FORCE**



T/20171219/2072

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

3 of 3
Report No. T/20171219/2072

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 2 ZHU JIANBIN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 19/12/2017 13:46
Officer In Charge Of Case: TP / AEIT / SI ANG YI TING, STEPHANIE  Contact No.: 65476414	Classification Of Case:

Authentication Stamp
NP168 Singapore Police Force

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9583J -*Not Authorised*

AAD1712-197

21 Nov \$3450

Vehicle No.: **SHD9583J - CANDY**
 Chassis No.: **KL1LA69RJBB097692**
 Vehicle Make: **CHEVROLET**
 Vehicle Model: **CHEVROLET EPICA 2.0**
 Date of Accident : **19.12.2017**
 Third Party Insurer : **MALAYSIAN**

PART		LIST
1	1 Front Bumper	\$ <i>Sn</i> 1,202.00
2	1 Front Bumper Lower Absorber	\$ <i>Sn</i> 180.00
3	1 Front Bumper Reinforcement	\$ <i>R</i> 356.00
4	1 Front Bumper Retainer RH	\$ <i>Sn</i> 102.00
5	1 Front Bumper Retainer LH	\$ <i>Sn</i> 102.00
6	1 Front Bumper Lower Grille	\$ <i>Sn</i> 78.00
7	1 Front Bumper Lower Stiffener	\$ <i>R</i> 134.37
8	1 Bumper Fog Lamp Cover RH	\$ <i>Sn</i> 32.40
9	1 Front Headlamp RH	\$ <i>Sn</i> 816.00 ✓
10	1 Front Fender RH	\$ <i>R</i> 837.60 ✓
11	1 Front Fender Liner RH	\$ <i>Sn</i> 47.00 ✓
12	1 Windscreen Washer Tank - Filler Neck	\$ <i>Sn</i> 4.80 X
13	1 Windscreen Washer Tank	\$ <i>Sn</i> 62.00 X
14	1 Windscreen Washer Tank Motor	\$ <i>Sn</i> 51.00 X
15	1 Radiator Grille (Grille A-Rad)	\$ <i>Sn</i> 367.00 X
16	1 Front Door RH	\$ <i>R</i> 1,133.00 ✓
17	1 Front Side View Mirror RH	\$ <i>R</i> 939.00 ✓

TOTAL	\$	6,444.17
10%	\$	644.42
	\$	5,799.75

Special Nett

1	1 Set Front Bumper Fastener Clip	\$ <i>nn</i> 30.00 X
2	1 Set Front Fender Liner Clip RH	\$ <i>nn</i> 30.00 X
3	1 Front Wheel Rim Hub Cap RH	\$ <i>Sn</i> 166.30 X
4	1 Front Tyre RH	\$ <i>nn</i> 180.00 X
5	1 Front Tyre Rim RH	\$ <i>nn</i> 126.00 X
6	1 Door Sticker "Trans-cab" RH	\$ <i>nn</i> 80.00 <i>60.00</i>

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-197

NO.2 ANGELO MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9583J -

TOTAL	\$	612.30
TOTAL PARTS	\$	6,412.05

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	<i>90d</i>
To Rust-Proofing Of The Affected Areas.	\$	220.00	<i>60d</i>
Putty and Spray Painting Of The Affected Portion.	\$	2,700.00	<i>40d</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>20d</i>
To check steering geometry and computer wheel alignment	\$	<i>22</i> 220.00	<i>X</i>
Towing Fees.	\$	120.00	<i>50d</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>22</i> 170.00	<i>X</i>

TOTAL	\$	6,400.00
Over All Total	\$	12,812.05

REPAIR DAYS

10 DAYS
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey by the repairer may printing
- To discontinue the repairer during resurvey
- Parts and materials to be replaced
- To repair the vehicle on a "Without Prejudice" basis
- No liability for damage to the vehicle and
- Such work is to be performed and is to be completed by the repairer's insurance company

Accepted by _____
S. _____
D. _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TRANS-CAB AUTO SERVICES PTE LTD	Ref : CS/TP17024179/Kqbe2
NO.2 ANG MO KIO STREET 63SINGAPORE 569111	Date : 02-01-2018
	Code : TP378



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SHD 9583J
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	20/12/2017

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET EPICA (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	KL1LA69RJBB097692	Colour	WHITE / RED
Odometer	379709	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	7 mm
L/H Front Tyre	195/65 R15	WEST LAKE	7 mm
R/H Rear Tyre	195/65 R15	GITI	8 mm
L/H Rear Tyre	195/65 R15	GITI	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	19/12/2017	Inspection Date	20/12/2017
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9583J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	SERVICEABLE	1,202.00	-
1	FRONT BUMPER LOWER ABSORBER	SERVICEABLE	180.00	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	356.00	-
1	FRONT BUMPER RETAINER RH	SERVICEABLE	102.00	-
1	FRONT BUMPER RETAINER LH	SERVICEABLE	102.00	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	78.00	-
1	FRONT BUMPER LOWER STIFFENER	TO REPAIR SEE LABOUR	134.37	-
1	BUMPER FOG LAMP COVER RH	SERVICEABLE	32.40	-
1	FRONT HEADLAMP RH	CUT	816.00	816.00
1	FRONT FENDER RH	BENT	837.60	837.60
1	FRONT FENDER LINER RH	SERVICEABLE	47.00	-
1	WINDSCREEN WASHER TANK - FILLER NECK	SERVICEABLE	4.80	-
1	WINDSCREEN WASHER TANK	SERVICEABLE	62.00	-
1	WINDSCREEN WASHER TANK MOTOR	SERVICEABLE	51.00	-
1	RADIATOR GRILLE (GRILLE A-RAD)	SERVICEABLE	367.00	-
1	FRONT DOOR RH	BENT	1,133.00	1,133.00
1	FRONT SIDE VIEW MIRROR RH	BROKEN	939.00	939.00
	LESS 10% DISCOUNT		-644.42	-372.56
			5,799.75	3,353.04
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER FASTENER CLIP (SN)	NOT NECESSARY	30.00	-
1	SET FRONT FENDER LINER CLIP RH (SN)	NOT NECESSARY	30.00	-
1	FRONT WHEEL RIM HUB CAP RH (SN)	SERVICEABLE	166.30	-
1	FRONT TYRE RH (SN)	NOT NECESSARY	180.00	-
1	FRONT TYRE RIM RH (SN)	NOT NECESSARY	126.00	-
1	DOOR STICKER "TRANS-CAB" RH (SN)	NECESSARY	80.00	60.00
			612.30	60.00
LABOUR				
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT AND FRONT BUMPER LOWER STIFFENER.		2,800.00	400.00

Report Ref No. CS/TP17024179/Kqbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our/Adjusted (\$)
	TO RUST-PROOFING OF THE AFFECTED AREAS.		220.00	60.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,700.00	400.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TOWING FEES.		120.00	50.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
			6,400.00	930.00
	GRAND TOTAL		12,812.05	4,343.04
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,450.00

Report Ref No. CS/TP17024179/Kqbe2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.