

ASS. REC BY:

REF CS/SM017024213/Gqd3nz

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Grace Teo

SMO

Date/Time: 4:10pm @ 20/12/17

Estimated Cost: _____ Bill to: _____

OD: TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKN 7726P

Insured: SBU 209G

at Workshop in/s: SM Spray Painting

Tel: 6384 1755 / 1766

of: 25 kaki Bkt Rd 4 # 08-30 Synergy

Policy No: _____ Claim No: CMTD1704598/NSW

Sum insured: _____ Excess: _____

Make of Veh: _____
(Client's Record)

D.O.A: 18/12/2017

CA / REV / REP. / REV 24 HRS ^{'wp'}

R.O.D. Endorsement: _____

Date/Time: 8:56am @ 21/12/17 Person Contacted: Wendy

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKN 7726P - X
	SBU 209G - X
<u>21/12/17 @ 4:56pm</u>	<u>revised to Grace Teo by email.</u>

3/1
Bimayer

Xed.

REF: SMO

ASSIGNMENT

From: _____ Date: 21/12/17

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKN 7726P

at Workshop m/s S M Spray Painting

of 25 kaki Bkt Rd 4 # 08-30 synergy

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

before 1pm



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKN 7726P Yr Regn: 01 May 2009

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: BMW 320i CC 1995

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 134789 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAPG 56070 NL 23511

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD Rim or

Tyre Size: F: 255/35ZR18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 21-12-17

Survey held at w/s 1:15 pm

Des. of Damages: Frt / Rear / N/S / U/C / Rooftop or

o/s body

The U/C / Chassis frame / Body Structure affected due to collision: _____

Date / Time	Action / Instruction
<u>21/12</u>	<u>Finalized \$ 1200 with Daren. (Red \$ 7401.58, 86%)</u> <u>no lump sum.</u>
	<u>26/12 only labor</u>

RECEIVED 27 DEC 2017

Date/Time. File Pass to? : Preli. Report

21/12 twist : Final Report

Date/Time. File Return to? _____

Report Format: TP

Lump Sum / I.B.I: (\$) 1200

Days Of Repair: 2

Resurvey No. of Trip: _____

Add Fee: Site Insp (\$) _____

Interview (\$) _____

Tech. Invs (\$) _____

Weekend (\$) _____

Survey Fee: _____
Transportation: _____
Photos: _____
Others: _____
TOTAL: <u>250</u>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO17024213/Gqd3	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 21-12-2017	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SBU 209G	Veh. Inspected	SKN 7726P
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1704598/NSW	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	21/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	18/12/2017	Inspection Date	21/12/2017
Survey held at	SM SPRAY PAINTING NO. 25 KAKI BUKIT ROAD 4 #08-30 SYNERGY @ KAKI BUKIT SINGAPORE 417800		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1704598/NSW

Date: 22nd December 2017

Our Ref: CS/SMO17024213/Gqd3

Without Prejudice

The Motor Claims Department
Sompo Insurance

Attn: Grace

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SKN 7726P .


We thank you for the instruction on 20/12/2017.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/12/2017 at the premises of M/s SM SPRAY PAINTING and have the following to report:-

Workshop Estimate Amount	: S\$ <u>8,601.58</u> .
Revised Estimate Amount	: S\$ <u>1,200.00 (Lump Sum)</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the o/s body.



Comments/ Present Status:

Damages consistent.

Days of repair: 2 days.

We have not authorized repair.

Yours faithfully

XING GUO QIANG
Automobile Assessor

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Wednesday, 20 December, 2017 4:10 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Janice Kee; Wendy @ S M Spray Painting; Jesslyn@SM; Ngo, Sau Wei Shawn; Henry, Irene James
Subject: CMTD1704598/NSW - Accident invlg SBU209G & SKN7726P on 18.12.2017
Attachments: 20171220102805225.pdf

Dear Sir/Madam,

Please make arrangement to conduct the survey for SKN7726P.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Janice Kee [mailto:janice.kee@ksteoptr.com]

Sent: Wednesday, December 20, 2017 3:35 PM

To: Teo, Grace

Cc: Wendy @ S M Spray Painting; Jesslyn@SM; Ngo, Sau Wei Shawn; Henry, Irene James

Subject: Re: CMTD1704598/NSW - Accident invlg SBU209G & SKN7726P on 18.12.2017 \ Yr. Ref: TKSF/S666-ACC-39478.17/sf)

Dear Sir

Our client has agree to the usage of LKK Auto Consultants – Mr Marcus Chua as the Single Joint Expert to conduct the Pre-Repair Survey.

Kindly proceed to engage LKK Auto Consultants – Mr Marcus Chua to perform the said Pre-Repair Survey in accordance to the NIMA Protocol.

Thank you.

Regards

Janice

Regards,
Janice Kee
c/o Teo Keng Siang LLC
111 North Bridge Road,
#29-07/08 Peninsula Plaza,
Singapore 179098
Tel: 6333 4222 Fax: 6333 5676

On Wed, Dec 20, 2017 at 1:44 PM, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Your Reference: TKSF/S666-ACC-39478.17/sf
Our Reference: CMTD1704598/NSW

Without Prejudice

Date: 20th December 2017

**Attention:
M/S TEO KENG SIANG LLC**

Accident invlg SBU209G & SKN7726P on 18.12.2017

Dear Janice,

We refer to your Notice of Accident dated 20/12/2017.

Please be informed that Shawn Ngo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	

		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Yours faithfully,

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Janice Kee [mailto:janice.kee@ksteoptr.com]

Sent: Wednesday, December 20, 2017 10:28 AM

To: Claims - Motor Survey

Cc: Wendy @ S M Spray Painting; Jesslyn@SM

Subject: Pre repair Survey for SKN 7726 P (Your Ref: SBU 209 G Our Ref: TKSf/S666-ACC-39478.17/sf)

Dear Sir

We attach herewith our Pre-repair survey letter for your attention.

Kindly let us have the surveyor list for our attention.

Thank you.

Regards,

Janice Kee

c/o Teo Keng Siang LLC

*111 North Bridge Road,
#29-07/08 Peninsula Plaza,
Singapore 179098
Tel: 6333 4222 Fax: 6333 5676*

张景祥
大律師樓
(律師兼公証及宣誓官)

Teo Keng Siang LLC

Advocates & Solicitors • Notary Public • Commissioner For Oaths

111 North Bridge Road #29-07/08 Peninsula Plaza Singapore 179098
ROC: 201510228C GST Reg No.: 201510228C

PDX Intercompany Exchange Pte Ltd



010808292101

FROM **TEO KENG SIANG LLC**
PDX Box No. **8902**

Tel: 6333 4222 Fax: 6333 5676 / 5688
Email: KSTBOCO@singnet.com.sg
(FAX - NOT FOR SERVICE OF COURT DOCUMENTS)

Our Ref : TKSF/S666-ACC-39478.17/sf (mc)
Your Ref : SBU 209 G
Date : 20 December 2017

Secretary in charge: Janice
Tel : 6333 4222 (ext 60)
Fax : 6333 5676 / 6333 5688
Email : janice.kee@ksteoptr.com

Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623

WITHOUT PREJUDICE
BY PDX #8174 & FAX: 6221 3147

Attn: Motor Claims Dept

Kee Keng Choo Jeannie (Owner)
26 Keris Drive
Singapore 456989

BY POST ONLY

Dear Sirs

RE: ACCIDENT INVOLVING SKN 7726 P / SBU 209 G ON 18/12/17 ALONG AYE TOWARDS MCE

We are instructed by Ng Kim Li to notify you of a road traffic accident on 18/12/17 at about 15:40 hours at **ALONG AYE TOWARDS MCE** involving our client's vehicle registration number **SKN 7726 P** and vehicle registration number **SBU 209 G** driven by you at the material time. A copy of our client's Singapore accident statement is enclosed. Kindly let us have a copy your Singapore accident statement report on an urgent basis.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please note that our client's motor vehicle **SKN 7726 P** is now at the following workshop:-

S M Spray Painting
25 Kaki Bukit Road 4
#08-30 Synergy @ KB
Singapore 417800
Contact Person: Wendy 6384 1755/1766

Yours faithfully,

M/s Teo Keng Siang LLC
encs

**Survey was conducted by:-

Name of Surveyor:

Date of Survey:

Time of Survey:

Signature

Teo Keng Siang
LL.M(Singapore),
LL.B (Hons) (Singapore)

Wong Yong Sheng, Kenneth
LL.B (Hons) University of Bristol

Joseph Tan Chin Aik
LL.B (Hons) Singapore
PGDE (NTU/NIE)

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 22 December, 2017 4:56 PM
To: 'Teo, Grace'; assignments
Cc: SUR
Subject: RE: CMTD1704598/NSW - Accident invlg SBU209G & SKN7726P on 18.12.2017
Attachments: CSSMO17024213Gqd3.pdf

Dear Grace,

Enclosed herewith preliminary advice of SKN 7726P.

Wishes you a Merry Christmas & Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 21 December, 2017 9:17 AM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: CMTD1704598/NSW - Accident invlg SBU209G & SKN7726P on 18.12.2017

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Wednesday, 20 December, 2017 4:10 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Janice Kee; Wendy @ S M Spray Painting; Jesslyn@SM; Ngo, Sau Wei Shawn; Henry, Irene James
Subject: CMTD1704598/NSW - Accident invlg SBU209G & SKN7726P on 18.12.2017

Dear Sir/Madam,

Please make arrangement to conduct the survey for SKN7726P.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6416Z
Vehicle Details	
Vehicle No.:	SKN7726P
Vehicle to be Exported:	No
Intended De-registration Date:	22 Dec 2017
Vehicle Make:	B.M.W.
Vehicle Model:	320I AT 2.0L ABS D/AIRBAG HID 2WD 4DR
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	B278I330N46B20BD
Chassis No.:	WBAPG56070NL23511
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$40,154.00
Original Registration Date:	01 May 2009
First Registration Date:	01 May 2009
Transfer Count:	1
Actual ARF Paid:	\$40,154.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Apr 2019
PARF Rebate Amount:	\$22,084.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2019
COE Category:	E - Open Category

COE Period(Years):	10
QP Paid:	\$7,789.00
COE Rebate Amount:	\$1,015.00
Total Rebate Amount:	\$23,099.00

The information contained herein is correct as at 22 Dec 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/12/2017 17:59
Date Of Accident	18/12/2017 15:40
Exact Location Of Accident	AYE TOWARDS MCE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKN7726P
Insured/Policyholder	
Name Of Registered Owner	NG KIM LI (HUANG JINLI)
NRIC No	S8806416Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93882534
Alternative Phone No	OFFICE-93882534
Vehicle Particulars	
Manufacturer	BMW
Model	320I
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5067030714-03
Cover Note Number	
Driver	
Name of Driver	NG KIM LI (HUANG JINLI)
NRIC No	S8806416Z
Date Of Birth	19/02/1988
Occupation	INDOOR
Date Of Driving Pass	18/10/2010
Driving Experience	7 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-93882534
Fax Number	
Contact Number	OFFICE-93882534
EEmail Address	NOEMAIL

Address APT BLK 59 TELOK BLANGAH HEIGHTS #03-07
 Postcode 100059
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SBU209G
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

DETAILS OF INJURED PERSON 1

Name NG KIM LI (HUANG JINLI)
 Approximate Age

Injuries Sustain

Injured person in which vehicle?	SKN7726P
Were seat belts worn?	YES
Was injured conveyed to hospital by ambulance?	NO
Address	APT BLK 59 TELOK BLANGAH HEIGHTS #03-07
Postcode	100059

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be **truthful and accurate as possible**. Any willful misrepresentation or withholding of material information may allow the insurer to **repudiate policy liability**.
4. The use and disclosure of the Form by the insurer constitutes an admission of policy liability on the part of the Insured/Complainant.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be archived by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report both initiators, you hereby consent to the archiving of this report at the centre and to copies of this report being made available (where).

2. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer (my working unit/the General Insurance Association of Singapore ("GIA")) may/are permitted to collect, store, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurers who have insured vehicles involved in this accident (all insurers) who have insured vehicles involved in this accident shall be collectively referred to as the "**Insurers**"), the insurers, lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claim and any necessary investigations relating to the claim;
 - (ii) investigating the accident and for my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me - which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of size/size/mailed packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**").
- (b) all insurers who have insured vehicles involved in this accident and the insurers, lawyers/law firms, may/are permitted to collect, store, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party (service providers or agents) (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will/can be collected and used to compile claims history for the purpose of fraud detection investigations and management of present and all future claims;
- (e) the information collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC / N No

Sketch Plan #2

SKETCH PLAN



A: SKN7726P

B: 3BU209G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling toward MCE tunnel, I suddenly feel a ~~side~~ impact on my right side of my vehicle.

There's in-car camera on the other party.

DECLARATION

(We declare the foregoing particulars are true in every respect.)


Policyholder Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SM SPRAY PAINTING

No.25 Kaki Bukit Road 4, #08-30 Synergy@KB Singapore 417800
 Tel : 6384 1755 / 63841766 Fax : 63841744

Name : Ng Kim Li (Huang Jinli)
 Address : No.25 Kaki Bukit Road 4
 #08-30 Synergy@KB
 Singapore 417800

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • Damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey on "Without Prejudice" basis
 • No legal modification(s) is allowed
 • Any ancillary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Date : 19-Dec-17
 Acknowledged by Repairer
 Signature:
 Date: Vehicle No: SKN 7726 P

ESTIMATED REPAIR OF BMW 320i SKN 7726 P

QTY	DESCRIPTION	AMT (\$S)
<u>List Items</u>		
1	Front door X repair	\$ 1,069.70
1	Front door glass outer moulding X	\$ 43.43
1	Front door hinge lower X	\$ 105.00
1	Front door lock X	\$ 528.10
1	Front door outer handle X	\$ 115.30
1	Front door regulator X	\$ 387.30
1	Front door rubber X	\$ 579.21
1	Front door side mirror X	\$ 368.87
1	Rocker panel sider skirt	\$ 750.00
1	Rear door X repair X repair	\$ 1,210.60
1	Rear door glass outer moulding X NN	\$ 89.60
1	Rear door rubber X NN	\$ 186.90
1	Front fender X repair	\$ 562.70
1	Front fender lamp X NN	\$ 33.69
		\$ 6,030.40
	Less 5.0%	\$ 301.52
		\$ 5,728.88
<u>Special Nett Items</u>		
1	Front fender shield clip (1 set) X NN	\$ 12.70
		\$ 12.70
<u>Labour Charge</u>		
1	To remove and refit headlamps.	\$ 80.00 X NN
2	To remove and refit the door lock mechanism	\$ 280.00 X NN
3	Panel beating	\$ 1,100.00 200
4	Spray painting	\$ 1,400.00 1000
		\$ 2,860.00

Total : \$1200.
 Guo Qiang @ lkkawto.com Total : \$ 8,601.58

Dollars : Eight Thousand Six Hundred One And Cents Fifty Eight Only
 Guo Qiang - 8228 0222
 21/12/17 After paint photos.
 2 days.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17024213/Gqd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 02-01-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SBU 209G	Veh. Inspected	SKN 7726P
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1704598/NSW	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	20/12/2017

2. Vehicle Particulars & Condition

Make & Model	BMW 320I	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	WBAPG56070NL23511	Colour	WHITE
Odometer	134789	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/35 ZR18	MICHELIN	6 mm
L/H Front Tyre	255/35 ZR18	MICHELIN	6 mm
R/H Rear Tyre	255/35 ZR18	MICHELIN	6 mm
L/H Rear Tyre	255/35 ZR18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/12/2017	Inspection Date	21/12/2017
Survey held at	SM SPRAY PAINTING NO. 25 KAKI BUKIT ROAD 4 #08-30 SYNERGY @ KAKI BUKIT SINGAPORE 417800		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------