

12/06/2007

ASS. REC. BY:

REF: CS3/CTI17024219/Wd302

range & days
Special Instruction

Surveyor: Wilson

ASSIGNMENT (Office)

Menimen

From (Person): Sawyn Tay

of CTI

Date/Time: 19/12/17 @ 3:16 pm

Estimated Cost:

Bill to:

OD (IP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKW1217 J

Insured: SJQ 5510 D

at Workshop m/s: 1st Auto

Tel: 8152 7611

of 15 kaki Bkt Rd 4 #01-53

Policy No: DMPCSN3048941700

Claim No: SNM17D07097C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 13/12/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement

Date/Time: 10:41am @ 21/12/17

Person Contacted:

Mr Ong

Vehicle (IN) OUT

Date/Time	Action/Instruction (X) Estimate
	SKW1217 J- NS/INCH023783/K7rb
	SJQ 5510 D - X
	Dismantle Part: 27.12.2017
	After repair: 03012018

D.O.A: 13/12/17

PRS
Wilson

REF.

ASSIGNMENT

From Date

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No SKW 1217 J

at Workshop m/s 1st Auto

of 15 Kaler Bulat Rd 4 # 21-52

Insured

Policy No

Claims No

Sum Insured


Excess

(Client's Record)

Make of Ven

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

314 PR Seen

Consistent? : Yes or No

Est. Repairs:

days

Res:

Yes or No

Lump Sum:

Rs

3 Val:

Yes or No

CA / REV / REP / 24HRS

Date:

Person Contacted

Vehicle: IN / OUT

Date / Time Action / Instruction

21/12/17 Told By w/ship - check all over But Not Accurately Report Given

Range \$5900 - \$6500

5 Days Repair

RECEIVED 12 APR 2018

Date/Time File Pass to:

11-04-2018

☐

Preli. Report

☐

Final Report

Date/Time File Return to:

Report Format:

PRS

Lump Sum / I.B.I. (\$) :

Veh No SKW 1217 S

Vr Regn

(Car might be sold off)

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make Toyota Altis

1598

Colour Silver

Insured / Std / NI / NA

Sp. Reading 135130

T Radio Insured / Std / NI / NA

Eng No

C No

MROS3 RICH 104537822

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

205/55R16

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Crucero 889 (R) / Yokohama (R)

Front

R/Bal

4

mm

R/Bal

4

mm

L/Bal

4

mm

L/Bal

4

mm

D.O.A

D.O.I

21/12/2017

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

6/4/2018

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

3 x RS

Phone

Other

Add Fee:

☐

Site Insp \$

☐

Interview \$

☐

Tech. Insp \$

☐

Weekend \$

150

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Dec 2017		19 Dec 2017 15:16 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHOW YEW KEE, ID: S7706943G		
Main Claimant:	NEO R AND R PTE LTD, Co. Reg. No.: 201026086E		
Vehicle Reg. No.:	SKW1217J	Date of Loss:	13/12/2017 08:00 - :59
Claim Type:	TP / SNM17D07097C02	Policy/Cover Note No.:	DMPCSN3048941700 (Comprehensive) Coverage: 16/06/2017 - 15/06/2018
Vehicle Reg. No. (Insured):	SJQ5510D	Policy No. (Claimant):	5091812882
		Excess:	S\$0.00
Repairer:	1st Auto Pte Ltd (HQ) 13 Kaki Bukit Road 4, #01-05 Bartley Biz Centre, 417807 Kaki Bukit - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/12/2017]		
Adj Asg. Remarks:	NO ESTIMATES ASSIGNED FOR WP PRS		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/12/2017 15:12
Date Of Accident	13/12/2017 08:40
Exact Location Of Accident	PIE CHANGI BEFORE LORNIE ROAD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKW1217J
Insured/Policyholder	
Name Of Registered Owner	NEO R AND R PTE LTD
Co Reg No	201026086E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-90919947
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS
Exact Purpose for which vehicle was being used at time of accident	LIMOUSINE SERVICE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5091812882
Cover Note Number	DRIVO CLASSIC
Driver	
Name of Driver	NG BOON KIAT
NRIC No	S1714846Z
Date Of Birth	27/02/1965
Occupation	INDOOR
Date Of Driving Pass	22/06/1983
Driving Experience	34 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91003038

Fax Number

Contact Number

EMail Address

NOEMAIL

Address

BLK 235 TAMPINES STREET 21
#09-501

Postcode

521235

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle

-
-
-

Insurance Company of Driver's Own Vehicle

-
-
-**General Information of the Accident**

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Was any body injured in the Accident?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

TOA PAYOH NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING ,
POSTCODE: 319194 , COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-2519999 - FAX NO: 63548749

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT T/20171213/2048

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHD4854K

Vehicle Make/Model/Colour

Details Of Properties

TAXI

Name of Driver

NG

NRIC/Passport Number

Contact Number

976666131

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJQ5510D

Vehicle Make/Model/Colour

HYUNDAI AVANTE

Details Of Properties

Name of Driver

ANDY

NRIC/Passport Number

Contact Number

90023912

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

INSURANCE MOTOR SERVICE CENTRE Vehicle No. SKW12172 Report Date & Start Time: 13/12/17 / 15:08
 Report No. MT/ D.O.A. 13/12/2017 Make / Model TOYOTA COROLLA Reporting Type: End Time: /
 Time: 0840 hrs
 hrs

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 13/12/17 / 15:08
 Policyholder's Signature / Date & Time


 13/12/17 / 15:08
 Driver's Signature (if driver is not the policyholder) / Date & Time

Aaron Chuan (S991302) 
 Customer Care Executive
 Motor Service Centre
 Witnessed by Reporting Centre Personnel

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Brief Details.

I am a part-time GrabCar driver. On 13/12/2017 at about 10.40am, I was driving my car, SKW1217J, silver Toyota Altis, travelling on the first lane along PIE towards Changi. I had just travelled past the speed camera when the car in front of me slowed down and eventually came to a stop. I slowed down my car too and just after it came to a stop, suddenly I felt something knocked onto the rear of my car. As a result, my car moved forward and knocked onto the car in front of me. When I came out to make a check, I realized that it was a chain collision involving three vehicles. The first vehicle is a car bearing registration number SJQ5510D, maroon Hyundai Avante, the second vehicle is my car and the third vehicle is a Comfort Delgro taxi bearing registration number SHD4854K, blue Hyundai Elantra. I wish to state that I have a passenger seated at the rear and both of us complaint of body pain. The driver in front of me was alone and the taxi has a passenger. I am not sure if they were injured as well. All the drivers exchanged contact numbers. I had gone to seek medical treatment and was given four days of MC. My car, both front and rear bumper damaged. I am lodging this Accident Report for insurance claim.

Declaration

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature / Date & Time
 12/13/2017 15:08


 Driver's Signature (if driver is not the policyholder) / Date & Time
 12/13/2017 15:08

Aaron Chua (5091882) 
 Customer Care Executive
 Motor Service Centre
 Witnessed by Reporting Centre Personnel

POLICE REPORT

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Dec 2017		19 Dec 2017 15:16 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: CHOW YEW KEE , ID: S7706943G									
Main Claimant: NEO R AND R PTE LTD , Co. Reg. No.: 201026086E									
Vehicle Reg. No.: SKW1217J		Date of Loss: 13/12/2017 08:00 - :59							
Claim Type: TP / SNM17D07097C02		Policy/Cover Note No.: DMPCSN3048941700 (Comprehensive) Coverage: 16/06/2017 - 15/06/2018							
Vehicle Reg. No. (Insured): SJQ5510D		Policy No. (Claimant): 5091812882							
		Excess: S\$0.00							
Repairer: 1st Auto Pte Ltd (HQ) 13 Kaki Bukit Road 4, #01-05 Bartley Biz Centre, 417807 Kaki Bukit - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 29/12/2017]									
Adj Asg. Remarks: NO ESTIMATES ASSIGNED FOR WP PRS									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKW1217J (SNM17D07097C02)
[SJQ5510D]
TP
NEO R AND R PTE LTD
Dec 13 2017 8:00AM
[CHOW YEW KEE]
1st Auto Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Video

1 per page

No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)		Thumbnail	Print
1	13/12/17 15:21	Video - Accident [Linked Accident Report Documents]		Load MP4	

Assessment Reports

1 per page

No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)		Thumbnail	Print
1	14/12/17 12:47	Accident Statement		Load HTM	

Photos/Images

3 per page

No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)		Thumbnail	Print
1	13/12/17 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	
2	13/12/17 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	
3	13/12/17 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	
4	13/12/17 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	
5	13/12/17 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	
6	13/12/17 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	
7	13/12/17 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	
8	13/12/17 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	
9	13/12/17 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	
10	13/12/17 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	

Documentation

1 per page

No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	15/12/17 15:47	E-filed GIA report		Load PDF	
2	15/12/17 15:48	Pre-Repair Survey		Load PDF	
3	19/12/17 15:16	OI GIA REPORT		Load PDF	
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)		Thumbnail	Print
1	13/12/17 15:17	POLICE REPORT [Linked Accident Report Documents]		Load TIF	
2	14/12/17 12:47	Sketch Plan [Linked Accident Report Documents]		Load TIF	
3	14/12/17 12:47	Sketch Plan #2 [Linked Accident Report Documents]		Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/04/18 20:02	LKKPhotosIn6-1		Load PDF	
2	11/04/18 20:02	LKKPhotosIn6-2		Load PDF	
3	11/04/18 20:02	LKKPhotosIn6-3		Load PDF	

Linked Accident Report Documents

View View in Browser			
Video			
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail Print
1	13/12/17 15:21	Video - Accident	 Load MP4
Assessment Reports			
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail Print
1	14/12/17 12:47	Accident Statement	 Load HTM
Photos/Images			
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail Print
1	13/12/17 15:17	Accident Photo	 Load JPG
2	13/12/17 15:17	Accident Photo	 Load JPG
3	13/12/17 15:17	Accident Photo	 Load JPG
4	13/12/17 15:17	Accident Photo	 Load JPG
5	13/12/17 15:17	Accident Photo	 Load JPG
6	13/12/17 15:17	Accident Photo	 Load JPG
7	13/12/17 15:17	Accident Photo	 Load JPG
8	13/12/17 15:17	Accident Photo	 Load JPG
9	13/12/17 15:17	Accident Photo	 Load JPG
10	13/12/17 15:17	Accident Photo	 Load JPG
Documentation			
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail Print
1	13/12/17 15:17	POLICE REPORT	 Load TIF
2	14/12/17 12:47	Sketch Plan	 Load TIF
3	14/12/17 12:47	Sketch Plan #2	 Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT117024219/WD3E2

Date: 12/04/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3048941700

Claimant Vehicle
No: SKW1217JInsured Vehicle
No: SJQ5510D

Date of Loss: 13/12/2017

Nature of Claim: TP

Claim
No: SNM17D07097C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW1217J

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: HIDDEN

Reg. Date: (Man. Year:)

Chassis No: MR053REH104537822

Colour: Silver

Odometer: 135130 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Crucero 4 mm

Rear Left Side: Yokohama 4 mm

Front Right Side: Crucero 4 mm

Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/12/2017

Date Inspected: 21/12/2017 Inspected At:

15 KAKI BUKIT ROAD 4# 01-53,417808

Repairer : 1st Auto Pte Ltd (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,900.00 -\$6,500.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Apr 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW1217J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >