

22/03/2001

ASS: REC BY:

REF CS/CTI17024226/Ktd3e2

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

Menmen

From (Person):

Irene Tay

of

CTI

Date/Time:

21/12/17 @ 12:03pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE681R

Insured:

SBV22674

at Workshop m/s

Hui Yang Motor

Tel:

6451 5752

of

176 Sin Ming Drive #04-02

Policy No:

DMPCSN3052131701

Claim No:

SNM17D07178C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

B.O.A.

15/12/2017

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

12:28pm @ 21/12/17

Person Contacted:

Sandra

Vehicle:

☒ IN ☐ OUT

Date/Time

Action/Instruction

☒

Estimate

SLE681R - x

SBV22674 - x

ASS. REC. BY:

REF:

C72 /

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S2E 681R Yr Regn: 07, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda C.C. 1698

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 65335 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ACU 1113825

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / 8Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: _____

BS / JUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 3 mm

L/Bal. 3 mm

D.O.A. 15/12/17

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

112 The pass to Catherine

5 312024 email (Red. 1771.32 : 36%)

RECEIVED 15 JAN 2018

Date/Time, File Pass to?

1) 15/1 Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B. (\$) 3120-24

☐ : Prell. Report☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

220

220




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17024226/Ktd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 21-12-2017	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SBV 2267U	Veh. Inspected	SLE 681R
Policy No.	DMPCSN3052131701	Coverage (\$)	0.00
Claim No.	SNM17D07178C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	21/12/2017
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/12/2017	Inspection Date	21/12/2017
Survey held at	HUI YANG MOTOR SERVICE BLOCK 176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	21 Dec 2017		21 Dec 2017 12:03 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LIAU LING YING FLORENCE, ID: S8503212G		
Main Claimant:	NEO TECK MING (LIANG DEMING), ID: S7324790Z		
Vehicle Reg. No.:	SLE681R	Date of Loss:	15/12/2017 20:00 - :59
Claim Type:	TP / SNM17D07178C02	Policy/Cover Note No.:	DMPCSN3052131701 (Comprehensive) Coverage: 08/06/2017 - 07/06/2018
Vehicle Reg. No. (Insured):	SBV2267U	Policy No. (Claimant):	7VPCP1725400
		Excess:	S\$0.00
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/01/2018]		
Adj. Asg. Remarks:	1) REQUESTED FOR KENNETH 2) PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE BASIS.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

輝 陽 汽 車 有 限 公 司
HUI YANG MOTOR PTE LTD

Address: SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) Fax: 64514658
Reg No. 201629438M

Fax

To: China Taiping Insurance (Singapore) Pte. Ltd. **From:** Hui Yang Motor Pte Ltd

Phone: 64515752 **Fax:** 64514658

Pages: 6 Pages (Including this page)

Time: 02:55 PM

Date: December 18, 2017

Accident involving SLE681R and SBV2267U along Upper Serangoon Road turn left to

Re: Buangkok Drive on 15/12/2017.

Hi,

- Please help to arrange surveyor to survey the vehicle SLE681R tomorrow **TUESDAY**
(19/12/2017) after 11 AM.

Thank you

Sandra

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/12/2017 14:33
Date Of Accident	15/12/2017 20:10
Exact Location Of Accident	ALONG UPPER SERANGOON RD TURN LEFT TO BUANGKOK DR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE681R
Insured/Policyholder	
Name Of Registered Owner	NEO TECK MING (LIANG DEMING)
NRIC No	S7324790Z
Email Address	NEE0073@YAHOO.COM
Mobile Phone No	(LOCAL) +65-98222901
Alternative Phone No	OFFICE-98222901

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5S CVT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	NO

Policy Number

Cover Note Number 7VPCP1725400

Driver

Name of Driver	NEO TECK MING (LIANG DEMING)
NRIC No	S7324790Z
Date Of Birth	05/07/1973
Occupation	OUTDOOR
Date Of Driving Pass	30/08/1994
Driving Experience	23 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98222901
Fax Number	
Contact Number	OFFICE-98222901
Email Address	NEE0073@YAHOO.COM

Address BLK 475A UPPER SERANGOON CRESCENT
#13-519
Postcode S531475
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s)
soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO THE ATTACHED SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SBV2267U
Vehicle Make/Model/Colour HONDA CIVIC
Details Of Properties
Name of Driver LIAU LING YING
NRIC/Passport Number S8503212G
Contact Number 91162736

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On 15th December 2017, I was driving my vehicle Reg. no. SLE 681R at around 2010 HR taking a left turn to Buangkok DR from upper Sarangpon Rd as I was hit by vehicle Reg no. SBV 226711.


DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:




Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



MSIG

MSIG Insurance (Singapore) Pte. Ltd. (Co. Reg. No 200412212G)
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
www.msig.com.sg

MOTOR VEHICLE COVER NOTE

Motor Vehicles (Third Party Risks And Compensation) Act (Chapter 189)
Motor Vehicles (Third Party Risks And Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia)

03 Jul 2017

1A0319

MOTORMAX PLUS

COVER NOTE No.

: 7VPCP1725400

1. Index Mark and Registration Number of Vehicle : SLE681R
2. Chassis Number of Vehicle : RU11113825
3. Name of Policyholder : NEO TECK MING
4. Effective date of the Commencement of Insurance for the purposes of the Act : 05 Jul 2017 00:01AM
5. Date of Expiry of Insurance : 04 Jul 2018

6. Persons or Classes of Persons entitled to drive*

- (a) The Policyholder.
- (b) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered and licensed under the Road Traffic Act and its registration and licensing under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

7. Limitations as to Use*

Use only for social, domestic & pleasure purposes and for the Policyholder's business.
The Policy does not cover use for hire or reward, tuition, driving test, racing, pace-making reliability trial, speed-testing, the carriage of goods (other than samples) in connection with any trade, or business or use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks & Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).

For MSIG Insurance (Singapore) Pte. Ltd.

[Signature]

[Signature]

Not valid unless countersigned by Authorized Person

Approved Insurer

IMPORTANT NOTICE

This temporary Cover Note is valid for a maximum of 14 days only.
You must exchange the Cover Note for the Certificate of Insurance from the insurer within 14 days from the date of this Cover Note.
If you are involved in an accident, full details must be forwarded immediately to the Company.

FORM M.X.1 (001)

(For the Issuance of Motor Cover Note only)

輝陽汽車有限公司. HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

15/12/2017

Owner: NEO TECK MING

Not Authorised
1.B.1
Phongy B4 painting
83121.28

ESTIMATE TO REPAIR HONDA VEZEL - SLE681R

1pc rear tailgate
1pc rear tailgate vezel emblem
1pc rear tailgate inner lock
1pc rear tailgate inner rubber
1pc rear bumper
1pc rear end panel
1pc rear end panel inner sensor
1pc rear end panel outer sensor
1pc rear spare tyre lower garnish

R \$ 1,100.90 —
m \$ 55.10 —
R \$ 198.40 X
sm \$ 135.20 X
Bu/m \$ 986.30 ✓
R \$ 530.90 X
cm \$ 195.50 ✓
sm \$ 180.25 X
sm \$ 181.90 X

less 20%


\$ 3,564.45
\$ 712.89
\$ 2,851.56

1 set rear reverse sensor

sm s.nett \$ 280.00 X

remove & refix rear windscreen glass
wiring
tuffkote
sealant
spray painting
labour charges
Total

\$ 120.00 ✓
\$ 80.00 *201*
\$ 80.00 *301*
\$ 80.00 *40sm* — *NEL*
\$ 600.00 *5401*
\$ 800.00 *5001*
\$ 4,891.56



LKK Auto Consultants henceforth
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice"
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Com.

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Dec 2017		21 Dec 2017 12:03 Edit Adj Rpt	S\$3,120.24 Edit Estimates	S\$3,120.24 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	LIAU LING YING FLORENCE, ID: S8503212G		
Main Claimant:	NEO TECK MING (LIANG DEMING), ID: S7324790Z		
Vehicle Reg. No.:	SLE681R	Date of Loss:	15/12/2017 20:00 - :59
Claim Type:	TP / SNM17D07178C02	Policy/Cover Note No.:	DMPCSN3052131701 (Comprehensive) Coverage: 08/06/2017 - 07/06/2018
Vehicle Reg. No. (Insured):	SBV2267U	Policy No. (Claimant):	7VPCP1725400
		Excess:	S\$0.00
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 03/01/2018]		
Adj Asg. Remarks:	1) REQUESTED FOR KENNETH 2) PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE BASIS.		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SLE681R (SNM17D07178C02)
[SBV2267U]
TP
NEO TECK MING (LIANG DEMING)
Dec 15 2017 8:00PM
[LIAU LING YING FLORENCE]
Hui Yang Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hui Yang Motor Pte Ltd (HQ)	Thumbnail	Print
1	18/12/17 14:40	Video - Accident [Linked Accident Report Documents]	Load MP4	











Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/01/18 11:24	General View	Load JPG	<input checked="" type="checkbox"/>
2	15/01/18 11:24	General View	Load JPG	<input checked="" type="checkbox"/>
3	15/01/18 11:24	General View	Load JPG	<input checked="" type="checkbox"/>
4	15/01/18 11:24	General View	Load JPG	<input checked="" type="checkbox"/>
5	15/01/18 11:24	General View	Load JPG	<input checked="" type="checkbox"/>
6	15/01/18 11:24	General View	Load JPG	<input checked="" type="checkbox"/>
7	15/01/18 11:24	General View	Load JPG	<input checked="" type="checkbox"/>
8	15/01/18 11:24	General View	Load JPG	<input checked="" type="checkbox"/>
9	15/01/18 11:24	General View	Load JPG	<input checked="" type="checkbox"/>
10	15/01/18 11:24	General View	Load JPG	<input checked="" type="checkbox"/>
11	15/01/18 11:24	General View	Load JPG	<input checked="" type="checkbox"/>
12	15/01/18 11:24	General View	Load JPG	<input checked="" type="checkbox"/>
13	15/01/18 11:24	General View	Load JPG	<input checked="" type="checkbox"/>
14	15/01/18 11:24	General View	Load JPG	<input checked="" type="checkbox"/>
15	15/01/18 11:24	General View	Load JPG	<input checked="" type="checkbox"/>
16	15/01/18 11:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
17	15/01/18 11:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
18	15/01/18 11:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
19	15/01/18 11:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/12/17 12:12	E-filed GIA report	Load PDF	
2	21/12/17 12:12	Quotation/Replacement/Repair invoice	Load PDF	

Linked Accident Report Documents

View View in Browser

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hui Yang Motor Pte Ltd (HQ)	Thumbnail	Print
1	18/12/17 14:40	Video - Accident	Load MP4	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hui Yang Motor Pte Ltd (HQ)	Thumbnail	Print
1	18/12/17 14:42	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hui Yang Motor Pte Ltd (HQ)	Thumbnail	Print
1	18/12/17 14:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	18/12/17 14:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	18/12/17 14:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	18/12/17 14:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	18/12/17 14:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	18/12/17 14:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hui Yang Motor Pte Ltd (HQ)	Thumbnail	Print
1	18/12/17 14:40	Sketch Plan	 Load TIF	
2	18/12/17 14:40	Sketch Plan #2	 Load TIF	
3	18/12/17 14:40	Sketch Plan #3	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div> <div></div> <div> ^ v </div> </div> </div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17024226/KTD3E2

Date: 17/01/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3052131701
Claimant Vehicle No :	SLE681R	Insured Vehicle No :	SBV2267U
Date of Loss:	15/12/2017	Nature of Claim:	TP
		Claim No:	SNM17D07178C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE681R	Engine No:	L15B4033831
Make & Model:	HONDA VEZEL, 1.5 S (A)	Chassis No:	RU11113825
Reg. Date:	05/07/2016 (Man. Year: 2016)	Odometer:	65335 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Dunlop 3 mm	Rear Left Side:	Dunlop 2 mm
Front Right Side:	Dunlop 3 mm	Rear Right Side:	Dunlop 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,211.56	1,910.24	1,301.32	40.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	1,210.00	470.00	27.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,891.56	3,120.24	1,771.32	36.21
+ GST 7.00/7.00% (\$\$)	342.41	218.42	123.99	36.21
Nett Amount (\$\$)	5,233.97	3,338.66	1,895.31	36.21

INSPECTION

Date of Assignment:	21/12/2017	
Date Inspected:	20/12/2017 Inspected At:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Jan 2018)
Parts: 143 HONDA VEZEL 1.5 S (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLE681R)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,100.90 FL	*1,100.90 FL
2	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	55.10 FL	*55.10 FL
3	1		*REAR TAILGATE INNER LOCK	Repair	198.40 FL	*- FL
4	1		*REAR TAILGATE INNER RUBBER	Serviceable	135.20 FL	*- FL
5	1		*REAR BUMPER	Buckled / Dented	986.30 FL	*986.30 FL
6	1		*REAR END PANEL	Repair	530.90 FL	*- FL
7	1		*REAR END PANEL INNER SENSOR	Cracked	195.50 FL	*195.50 FL
8	1		*REAR END PANEL OUTER SENSOR	Serviceable	180.25 FL	*- FL
9	1		*REAR SPARE TYRE LOWER GARNISH	Serviceable	181.90 FL	*- FL
10	1		*SET REAR REVERSE SENSOR	Serviceable	280.00 FS	*- FS
11	1		*SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,924.45	2,377.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	712.89	467.56
Total Parts (\$\$)	3,211.56	1,910.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	WIRING	New	80.00	20.00
3	TUFF KOTE	New	80.00	30.00
4	SPRAY PAINTING	New	600.00	540.00
5	LABOUR CHARGES	New	800.00	500.00
Gross Labour Cost (\$\$)			1,680.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >