

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add Approve Deny						
EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	1	DAYS OF REPAIR : 4 DAYS	Reviewing			
☐	2	PARTS SUPPLIED BY AXAS SUPPLIER \$1471.00	Reviewing			
☐	3	FRONT NUMBER PLATE C/W HOLDER	Reviewing	45	DENTED	
☐	4	RADIATOR COOLANT	Reviewing	40	NECESSARY	
☐	5	FRONT BRACE PANEL	Reviewing		BENT (SUPPLEMENTARY)	