

INVEST

Marcus

ASSIGNMENT (Officer)

CWS

Sithara

FCI

Date/Time 4:38pm @ 21/12/17

Estimated Cost

Bill to

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PKG 7628

Insured

SHA 9163D

at Workshop for

Focus Auto

Tel

68869097

of No.1 Kaki Bkt Ave 6 Autobay #02-50

Policy No

Claim No

D17011554 MFS17

Sum Insured

Excess

Make of Veh:

D.O.A 13/12/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wup'

R.O.D. Endorsement

Date/Time 8:46am @ 22/12/17

Person Contacted

Wong

Vehicle IN/OUT

Date/Time

Action/Instruction (4) Estimate

PKG 7628 - X

SHA 9163D - X

26/12/17

Email FCI informed pending workshop est from repairer

Heip

1000

Survey Department Check List (Case Handler)

Reference No.: (S) FC17034253 Uve/3

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17024253/Uvd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 22-12-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9163D	Veh. Inspected	PKG 7628
Policy No.		Coverage (\$)	0.00
Claim No.	D17011554MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	22/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/12/2017	Inspection Date	22/12/2017
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	15-12-2017	Our Ref No. D17011554MFSH
Accident Date	13-12-2017	Claim Type. Third Party
Insured Vehicle	SHA9163D	Third Party Vehicle. PKG7628
Survey Location	NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-50	
Contact Person.	MS SIN	
Contact No.	68869097/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FOCUS AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231947)



PRI Documents



Close X

PRI Header Details

Claim No	D17011554MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & FOCUS AL
Workshop Name	FOCUS AUTO PTE LTD (Contact Person : MS SIN)	Survey Location & Contact Details	NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-50 Mobile: 0 , Phone: 68869097 , Fax: 0 EmailId: FOCUS.AUTOPTELTD@YAHOO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9163D	TP Vehicle No	PKG7628
PRI Recieved Date	21-12-2017 05:52:52 PM	Surveyor Appointed Date	21-12-2017 04:37:42 PM	Surveyor Accept Date	22-12-2017 0:

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	22-12-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 26 December, 2017 8:15 AM
To: 'Claim Workflow System'
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011554MFSH/1, PKG 7628

Dear Sir/Madam,

Please be informed that we have inspected the vehicle PKG 7628 on 22/12/2017.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 22 December, 2017 9:47 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011554MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

"Wishes you a Merry Christmas & Happy New Year 2018"

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Thursday, 21 December, 2017 4:37 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SITHARA@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011554MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

JABATAN PENGANGKUTAN JALAN MALAYSIA

PERAKUAN PENDAFTARAN KENDERAAN

No. Siri B 1782884

NO. PENDAFTARAN: PKG7628



Nama Pemunya
Berdaftar

KHOR GATK KHIM

870124075358
[MAL]

Alamat

1-25-G HALAMAN KRISTAL LINGKOK FREE SCHOOL
11800 GEORGETOWN PULAU PINANG

No. Enjin : G399FE034724
No. Casis : PMYKGD540B0034724
Buat : YAMAHA
Nama Model : YAMAHA 135LV
Keupayaan Enjin : 135 S.P.
Bahan Bakar : PETROL
Warna : MERAH
Kelas Kegunaan : MOTOSIKAL
Jenis Badan : MOTOSIKAL
Tahun Dibuat : 2011
Tarikh Pendaftaran : 14/08/2011
Status Pemunya : PERSENDIRIAN
Muatan Tempatan :
Duduk : 2
Kadar Lesen :
Kenderaan Motor : 6 bulan 12 bulan

B.O.M/B.G.K
B.T.T.
Berat Kerb
B.T.M.
B.G.1
B.G.2
B.G.3
B.G.4
B.G.5
B.G.6
B.G.7
B.G.8
B.G.9
B.G.10
B.G.11
B.G.12

RM2.00

RM2.00

Tandatangan Pemunya Berdaftar

Perakuan Pendaftaran ini dikeluarkan

oleh Pengerah JPJ Negeri CAWANGAN BATU UBAR

UNTUK KEGUNAAN PEJABAT

1. PEMASANGAN TEMPATAN

1.
2.
3.
4.
5.
6.
7.
8.
9.
10.
11.
12.
13.

NOTA PENTING

1. Simpan perakuan ini di tempat yang selamat. Jika perakuan ini hilang, anda dikehendaki melaporkan kepada balai polis dengan segera dan memohon salinan perakuan pendaftaran daripada Pengerah Jabatan Pengangkutan Jalan [JPJ].
2. Semak butir-butir kenderaan di muka ini dan laporkan dengan segera kepada Pengerah JPJ jika terdapat sebarang perubahan.
3. Lesen kenderaan motor yang sah hendaklah sentiasa dipamerkan. Anda boleh membarui lesen 60 hari sebelum tempohnya tamat.
4. Anda dikehendaki melaporkan secara bertulis dengan segera kepada Pengerah JPJ sekiranya kenderaan anda tidak berlesen.
5. Jika anda menjual kenderaan, serahkan perakuan pendaftaran ini kepada pembeli. Anda dan pembeli dikehendaki mengisi dan mengemukakan borang JPJK3/JPJK3A kepada Pengerah JPJ dalam tempoh tujuh hari dan tarikh penjualan itu.
6. Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran milikan telah disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik baru.
7. Jika alamat anda bertukar, kemukakan perakuan pendaftaran ini kepada Pengerah JPJ dalam tempoh tujuh hari dari tarikh pertukaran itu.



SINGAPORE POLICE FORCE



T/20171220/7001

1 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20171220/7001

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/12/2017 10:28	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: CHEW WEI KEAT			Address:		
ID Type / ID No.: FIN NO / G2697864K			Contact No.: Home/Office: Mobile: 91720932		
Nationality: MALAYSIAN			Email: anson_chew1314@hotmail.com		
Sex: Male	Age: 28	Date of Birth: 07/12/1989	Type of Informant: PKG7628		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Audit clerk			Driving Licence Information: Class: 2B,3C Date of Expiry: 07/08/2022		

General Information of the Accident

Type of Accident:	Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 13/12/2017 18:40	Type of Location: Flyover
Location: BARTLEY ROAD EAST Along Bartley Flyover towards CTE				
Weather: Raining		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PKG7628	Motorcycle	YAMAHA	LC135	Blue	Slightly Damaged	1
SHA9163D	Car		TAXI	Yellow	No Damage	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
PKG7628	PACIFIC & ORIENT INSURANCE CO. BERHAD			



**SINGAPORE
POLICE FORCE**



T/20171220/7001

3 of 3

Report No. T/20171220/7001

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
YEO GEAK ENG CECILIA
Contact No.: 65476404

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
20/12/2017 10:28

Classification Of Case:



2012 Yamaha LC 135 Japan GP Limited Low Mile 1pakcik

Today, 16:49

(<https://www.mudah.my/Yamaha+LC+135+Japan+GP+Limited+Low+Mile+1pakcik-67060814.htm>) Kuala Lumpur

RM 6 890

Used



2013 2013 Yamaha 135LC Millage only 17K

Today, 16:49

(<https://www.mudah.my/2013+Yamaha+135LC+Millage+only+17K-67061196.htm>) Kuala Lumpur

RM 5 100

Used



2016 Yamaha 135lc/135lc es/135lc v1

Today, 16:48

(<https://www.mudah.my/Yamaha+135lc+135lc+es+135lc+v1-67060750.htm>) Selangor

RM 4 500

Used



2008 Yamaha lc v1

Today, 16:45

(<https://www.mudah.my/Yamaha+lc+v1-67061083.htm>) Negeri Sembilan

RM 4 200

Used



2015 2015 YAMAHA135LC to let go

Today, 16:41

(<https://www.mudah.my/2015+YAMAHA135LC+to+let+go-67060881.htm>) Selangor

RM 4 500

Used

IKLAN

X



Keep clients in line with SolarWinds RMM's Take Control & Remote Background Management

Keep clients in line with SolarWinds RMM's Take Control & Remote Background Management

VISIT SITE

SolarWinds MSP



2015 Lc 135 Untuk Di Jual

Today, 16:33

(<https://www.mudah.my/Lc+135+Untuk+Di+Jual-67060536.htm>) Kuala Lumpur

RM 5 000

Used

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT

FIRST CAPITAL INSURANCE LTD

Ref: CS3/FCI17024253/Ud3s2

36 ROBINSON ROAD

Date: 06-07-2018

#16-01 CITY HOUSESINGAPORE 068877



Code: FCI2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHA 9163D	Veh. Inspected	PKG 7628
Policy No.	D-15072702MFSH	Coverage (\$)	0.00
Claim No.	D17011554MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	21/12/2017

2. Vehicle Particulars & Condition

Make & Model	YAMAHA 135LC	c.c	135
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	PMYKG0540B0034724	Colour	BLUE
Odometer	67204 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	70/90-17	DUNLOP	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	80/90-17	DUNLOP	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND O/S BODY.

**5. General Information**

Accident Date	13/12/2017	Inspect Date / Time	22/12/2017 (10:51 AM)
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY 02-48 SINGAPORE 417883		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
 THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
 D) MARKET VALUE RM4,000.00

Report Ref No. CS3/FCI17024253/Ud3s2

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.