





| PRE-REPAIR INSPECTION REPORT | | | | |
|--|--|---------------------------|-------------------------|---|
| GREAT AMERICAN INSURANCE COMPANY | | Ref: CS3/GAI17024288/Gbe2 | | |
| 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWERSINGAPORE 039190 | | Date: 28-03-2018 | |  |
| | | Code: GAI | | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | |
| Insured Veh. | XE 883H | Veh. Inspected | FBF 5172Z | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | CLMOMVC000002139 | Excess (\$) | 0.00 | |
| Assign From | RACHEL TAN | Assign Date | 21/12/2017 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | RIEJU RS3 125 | c.c | 124 | |
| Engine No. | HIDDEN | Year of Reg. | 2011 | |
| Chassis No. | VTPRS320D00A00155 | Colour | WHITE | |
| Odometer | 62798 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | NIL | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 110/70-17 | PIRELLI | 4 mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | 140/70-17 | PIRELLI | 4 mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. | | |  |
| 5. General Information | | | | |
| Accident Date | 21/11/2017 | Inspect Date / Time | 22/12/2017 (04:30 PM) | |
| Survey held at | HENG MOTOR ENTERPRISE NO.471, 5 1/2ms CHANGI ROAD SINGAPORE 419889 | | | |
| 5a. Remarks | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$3,500 | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 4 Working Days | |

Report Ref No. CS3/GAI17024288/Gbe2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.