

INS CASE OWNER: Bayergen | CC 4/ LCR170 24530 / Kja3 | LXX: IDAC:

Surveyor: KENNETH | DOI: 26/2/7 | Date / Time: 26/2/7 | Registered in Merimen: 26/2/7

Pre-assign / CCU / FTE



Insured Vehicle No. : SLD 42076
 Name of Insured : LCR PPL
 Insured Tel No. : _____ HP: _____
 Excess Sec II :SS _____ D.O.A: 19/2/7
 Is driver the owner? (YES / NO) Nature of Accident : _____
 If NO, Driver Name / Age : _____
 Driver Tel No. : _____ (V/L: YES / NO)

Claim No. : 98672 24735 89
 Policy No. : 00000000000000000000
 Make / Model : Honda Vezel
 Place of Accident : JW P110H

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
 Insured Liability : % Final ? Yes / No

FW 1614E →



INSRS: GA MOTOR
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____

Date/Time	STAGE	DATE / PIC
02/01/18 (Joy)	FW 1614E - X ; SLD 42076 - X # OI NR - SEND FIRST EMAIL TO LCR.	Non-Reporting ltr (1st): -2-1-18
02-01-18	LETTER SENT TO OI TO REPORT	Non-Reporting ltr (2nd):
5-1-18	NO OI GIA IN MERIMEN	Non-Reporting ltr (Final):
		Notification ltr (if non-pickup):
		Call OI: 5-1-18 Joy
10-1-18	PENDING FINALIZATION	After call ltr to OI:
		Documentation Check List: Handler Typist
		Notification ltr (if non-pickup)
		After call ltr to OI: <input checked="" type="checkbox"/>
		Authorisation To Act: <input type="checkbox"/>
		Release Voucher: <input type="checkbox"/>
		Final Repair Bill: <input type="checkbox"/>
		Car Rental Invoice: <input type="checkbox"/>
		Towing Invoice: <input type="checkbox"/>
		LTA / GIA : <input type="checkbox"/>
		Medical Bill: <input type="checkbox"/>
		FIR: <input type="checkbox"/>
		Mandate/Reject Instruction: <input type="checkbox"/>
		LOD: <input type="checkbox"/>
		Payment Breakdown Form: <input type="checkbox"/>
		Post-Repair Photos: <input type="checkbox"/>
		Others: <input type="checkbox"/>

RECEIVED 2 MAY 2018

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: \$\$ _____ (_____ days) Reduction: _____ % Email Call

FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27

Repair Cost: \$\$

Loss of Rental (LOR): \$\$ (_____ days)

Loss of Use (LOU): \$\$ (5 x days)

Loss of Income (LOI): \$\$ (5 x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

HA/LTA Search: \$\$

Medical: \$\$

Disbursement: \$\$ (e.g. Tow/Independent)

Legal Cost: \$\$

Total: \$\$ _____ Global Sum \$\$: _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Issue 1: \$\$ Name 1: _____

Issue 2: (Strike if N.A.) \$\$ Name 2: _____

Issue 3: (Strike if N.A.) \$\$ Name 3: _____

CLAIM SETTLEMENT

WP

1) Claim status: Normal/Reject/Private Settle
 2) Report Format:
 3) Survey fee: \$ 320

REF: **ALG**

ASSIGNMENT

From _____ Date: **26/12/17**

Estimated Cost: _____

OD / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **FW1614E**

at Workshop m/s: **GA Motor**

of **Blk 32 Sin Ming Drive # 01-331**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: **FW1614E** Yr Regn: **01 03**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____

Make: **Honda CB400** cc **399**

Colour: **Multi Colour** A/C: Insured / Std / NI / NA

Sp. Reading: **111768** T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: **NC39 1034023**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD / R/Rim or _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Bal. or Market Value: **8k**

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **04** days Res: Yes or No

Lum Sum: **20** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ¹ up **1/23**

Date _____ Person Contacted: _____ Vehicle IN / OUT

Tyre Size: F: **120/60ZR17**
R: **160/60R17**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. **3** mm R/Bal. **4** mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. **19/12/17** D.O.I. **26/12/17**

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear & o/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/12 file part to Carhome

4/5 \$ 4,650 ✓

R (\$ 3,330 / 419.)

Date/Time File Pass to? : Prel. Report

1) : Final Report

Date/Time File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

3 + 25 = \$ _____

Photo _____

Costs _____

Add Fee: Site Insp. \$ _____

Interview \$ _____

Tech. Invs \$ _____

Weekend \$ _____

TOTAL _____



盛 摩 哆 GA MOTOR

Block 32, Sin Ming Drive, #01-331, Singapore 575706

TEL: 4539903, 4539904 FAX: 4539904

Importer & Exporter - New & Used Motorcycles, Spare Parts & Accessories.
Dealer of Honda, Yamaha, Suzuki and Vespa, etc. Repair & Service all motorcycles, scooters.



Date: 22-12-2017

Estimated repair list for the accident motorcycle Honda Super 4 V-Tec Spec 2
Vehicle No. FW1614S

*Not Authored
L1 Sing B?
Recovery After Paint*

4 days

1 set	Head light	<i>nd</i>	\$350.00	✓
1 pc	Handle bar	<i>Ry</i>	\$120.00	✓
1 set	Handle balancer	<i>R</i>	\$30.00	X
1 set	Mirror	<i>nd</i>	\$80.00	✓
1 pc	Brake lever	<i>Ry</i>	\$40.00	✓
1 pc	Signal light (right)	<i>Sm</i>	\$50.00	X
1 set	Meter	<i>nd / G</i>	\$850.00	✓
1 pc	Front mudguard	<i>R</i>	\$135.00	X
1 pc	front Disc plate	<i>R</i>	\$360.00	X
2 pcs	Front fork inner tubes		\$440.00	?
1 pc	Fork leg	<i>nd</i>	\$250.00	✓
2 pcs	fork oil seal & fork oil		\$60.00	?
1 pc	Bottom steering stem		\$220.00	?
1 set	Steering come & bearing		\$80.00	?
1 pc	Radiator assembly	<i>R / R</i>	\$650.00	✓
1 pc	Bottom fairing	<i>nd</i>	\$250.00	* 60% 200% 200%
1 pc	Tank	<i>nd</i>	\$900.00	200%
1 pc	Clutch cover	<i>nd</i>	\$360.00	✓
1 pc	Front footrest (right)	<i>nd</i>	\$60.00	✓
1 pc	Rear footrest (right)	<i>nd</i>	\$75.00	✓
1 pc	Brake pedal	<i>nd</i>	\$80.00	✓
1 pc	Rear Box	<i>nd / R</i>	\$180.00	✓
1 pc	Rear carrier	<i>R</i>	\$150.00	✓
1 pc	Exhaust pipe (Yushimura)	<i>nd</i>	\$1800.00	✓
	Towing		\$30.00	✓
	Labour		\$380.00	280%

10%

Total : \$7980.00

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





盛 摩 哆 GA MOTOR

Block 32, Sin Ming Drive, #01-331, Singapore 575706
TEL: 64539903, 64539904 FAX: 64539904

Importer & Exporter - New & Used Motorcycles, Spare Parts & Accessories.
Dealer of Honda, Yamaha, Suzuki and Vespa, etc. Repair & Service all motorcycles, scooters.



Date: 22-12-2017

Estimated repair list for the accident motorcycle Honda Super 4 V-Tec Spec 2
Vehicle No. FW1614S

*Not Authorized
61 Sing @ #650
Rerway After Point*

1 set	Head light	Net	\$350.00	✓
1 pc	Handle bar	Net	\$120.00	✓
1 set	Handle balancer	Net	\$30.00	X
1 set	Mirror	Net	\$80.00	✓
1 pc	Brake lever	Net	\$40.00	✓
1 pc	Signal light (right)	Net	\$50.00	X
1 set	Meter	Net/Car	\$850.00	✓
1 pc	Front mudguard	Net	\$135.00	X
1 pc	front Disc plate	Net	\$360.00	✓
2 pcs	Front fork inner tubes	Net	\$440.00	✓
1 pc	Fork leg	Net	\$250.00	✓
2 pcs	fork oil seal & fork oil	Net	\$60.00	✓
1 pc	Bottom steering stem	Net	\$220.00	✓
1 set	Steering come & bearing	Net	\$80.00	✓
1 pc	Radiator assembly	Net/Part	\$650.00	✓
1 pc	Bottom fairing	Net	\$250.00	* 60cm
1 pc	Tank	Net	\$900.00	200cm
1 pc	Clutch cover	Net	\$360.00	✓
1 pc	Front footrest (right)	Net	\$60.00	✓
1 pc	Rear footrest (right)	Net	\$75.00	✓
1 pc	Brake pedal	Net	\$80.00	✓
1 pc	Rear Box	Net/Car	\$180.00	✓
1 pc	Rear carrier	Net	\$150.00	✓
1 pc	Exhaust pipe (Yushimura)	Net	\$1800.00	✓
	Towing		\$30.00	✓
	Labour		\$380.00	2800

108

Total : \$7980.00

Liok Auto Consultants hereby notify the Repairer of the following:

- To return survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to consultation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be returned if it is subject to final approval from Insurer's Company

Acknowledged by Repairer
Signature: _____
Date: _____



Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Friday, 5 January 2018 11:42 AM
To: 'Insurance LCR SG'
Cc: Admin A
Subject: ACCIDENT INVOLVING SLD 4207G(AIG) & FW 1614E ON 19/12/2017

Your Ref: **SLD 4207G**

Our Ref: CC3/LCR17024380/Kjs3

Dear Sir/Madam,

ACCIDENT INVOLVING SLD 4207G(AIG) & FW 1614E ON 19/12/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from FW 1614E against your insurance policy.

Based on the information on hand, we are of the opinion that liability is not in our favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6749-5792 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

Joy Irene (LKKAuto)

From: Boyogan, Joane <Joane.Boyogan@aig.com>
Sent: Wednesday, 2 May 2018 4:03 PM
To: Joy Irene (LKKAuto)
Subject: RE: #9867224735SG003#027#Accident involving SLD4207G (OI) and FW1614E on 19 Dec 2017

Dear Joy,

I will be handing the settlement of the PD matter with the TP solicitor

Please proceed to submit your report in Merimen together with your invoice

Thank you

Regards,

Joane Boyogan
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120
Tel +64191898 | Fax +68357416
joane.boyogan@aig.com | www.aig.com.sg

Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Joy Irene (LKKAuto) [mailto:JoyIrene@lkkauto.com]
Sent: Monday, April 30, 2018 9:10 AM
To: Boyogan, Joane
Subject: RE: #9867224735SG003#027#Accident involving SLD4207G (OI) and FW1614E on 19 Dec 2017

Dear Joane,

Our surveyor's adjusted COR is at lump sum \$4,650/- 4 days for repair.

We would like to know if you'll be handling settlement of PD. If yes, can we proceed to submit our report?

Please advise.

Thank you.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Boyogan, Joane [<mailto:Joane.Boyogan@aig.com>]
Sent: Friday, 27 April 2018 2:42 PM
To: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Subject: RE: #9867224735SG003#027#Accident involving SLD4207G (OI) and FW1614E on 19 Dec 2017

Dear Joy,

May we know the status of the survey report as the third party lawyer is chasing for our offer

Thank you

Regards,

Joane Boyogan
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120
Tel +64191898 | Fax +68357416
joane.boyogan@aig.com | www.aig.com.sg

Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Joy Irene (LKKAuto) [<mailto:JoyIrene@lkkauto.com>]
Sent: Tuesday, April 17, 2018 3:41 PM
To: Boyogan, Joane
Subject: RE: #9867224735SG003#027#Accident involving SLD4207G (OI) and FW1614E on 19 Dec 2017

Dear Joan,

Photos uploaded.

Our status: Pending finalization.

I will check with our surveyor so we can prepare our survey report for your perusal.

Thank you.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Boyogan, Joane [<mailto:Joane.Boyogan@aig.com>]

Sent: Tuesday, 17 April 2018 3:16 PM

To: Joy Irene (LKKAuto) <joyirene@lkkauto.com>

Subject: #9867224735SG003#027#Accident involving SLD4207G (OI) and FW1614E on 19 Dec 2017

Dear Joy,

Kindly advise the status of third party PD claim as we have received LOD from M/s Centro-Legal Law Corporation for the PD matter

In addition, please assist to upload the survey reports & photographs in merimen for our review

Thank you

Regards,

Joane Boyogan

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120

Tel +64191898 | Fax +68357416

joane.boyogan@aig.com | www.aig.com.sg

Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International

Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Dec 2017 Edit Reg		26 Dec 2017 00:00 Edit Adj Rpt	S\$4,650.00 Edit Estimates	S\$4,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF Pte Ltd , Co. Reg. No.: 201624597K								
Main Claimant:	ZULKEFLI BIN JURAIMI , ID: S1543910F								
Vehicle Reg. No.:	FW1614E	Date of Loss:	19/12/2017 00:00 - :59 [179 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 986722473SSG	Policy/Cover Note No.:	0999995065						
Vehicle Reg. No. (Insured):	SLD4207G	Policy No. (Claimant):	MC/00195138/03						
		Excess:							
Repairer:	Ga Motor (HQ) Blk 32 Sin Ming Drive, #01-331, 575706 Sin Ming - Tel: 64539903								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com								
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 05/01/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> • AIG_SG (27/12/2017): TP GIA REPORT • AIG_SG (27/12/2017): NO OI GIA REPORT 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FW1614E (9867224735SG)
[SLD4207G]
TP
ZULKEFLI BIN JURAIMI
Dec 19 2017 12:00AM
[LCRF Pte Ltd]
Ga Motor

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	View in Browser	
Photos/Images											3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
2	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
3	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
4	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
5	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
6	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
7	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
8	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
9	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
10	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
11	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
12	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
13	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
14	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
15	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
16	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
17	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
18	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
19	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
20	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
21	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
22	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
23	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
24	17/04/18 15:25	General View							Load JPG	<input checked="" type="checkbox"/>		
Documentation											1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	26/12/17 17:02	EMAIL FROM AIG DD 26.12.2017							Load PDF			
2	26/12/17 17:02	ACKNOWLEDGEMENT EMAIL TO AIG DD 26.12.2017							Load PDF			
3	26/12/17 17:02	LAWYER FORM							Load PDF			
4	02/01/18 10:13	TP GIA REPORT							Load PDF			
5	02/01/18 10:13	TP ESTIMATE - MARKED							Load PDF			
6	02/01/18 15:18	EMAIL TO INSURED TO FILE REPORT							Load PDF			
7	05/01/18 11:48	LETTER TO INSURED							Load PDF			
8	02/05/18 16:52	WP MANDATE							Load PDF			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print			
1	05/01/18 10:50	E-filed GIA report OI GIA Report							Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR17024380/KJA3Q2

Date: 04/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995065
 Claimant Vehicle No: FW1614E Insured Vehicle No: SLD4207G
 Date of Loss: 19/12/2017 Nature of Claim: TP Claim No: 9867224735SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FW1614E
 Make & Model: HONDA CB400SF2J, 399cc Engine No: HIDDEN
 Reg. Date: 01/01/2003 (Man. Year: 2003) Chassis No: NC391034023
 Colour: Multi-colour Odometer: 111768 km
 Engine Capacity: 399 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/60Z R17 Rear Tyre Size: 160/60 R17
 Front Left Side: Bridgestone 3 mm Rear Left Side: Bridgestone 4 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,570.00	5,520.50	2,049.50	27.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	410.00	310.00	100.00	24.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,980.00	5,830.50	2,149.50	26.94
Approved Total (Overridden) (S\$)		4,650.00		
Nett Amount (S\$)	7,980.00	4,650.00	3,330.00	41.73
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 26/12/2017
 Date Inspected: 26/12/2017 Inspected At: Ga Motor (HQ)
 Blk 32 Sin Ming Drive, #01-331
 Singapore 575706
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET HEAD LIGHT	Dented	350.00 F	*350.00 FL
2	1		*HANDLE BAR	Bent	120.00 F	*120.00 FL
3	1		*SET HANDLE BALANCER	Repair	30.00 F	*- FL
4	1		*SET MIRROR	Dented	80.00 F	*80.00 FL
5	1		*BRAKE LEVER	Bent	40.00 F	*40.00 FL
6	1		*SIGNAL LAMP (RIGHT)	Serviceable	50.00 F	*- FL
7	1		*SET METER	Dented / Cut	850.00 F	*850.00 FL
8	1		*FRONT MUDGUARD	Repair	135.00 F	*- FL
9	1		*FRONT DISC PLATE	Repair	360.00 F	*- FL
10	2		*FRONT FORK INNER TUBES	Twisted	440.00 F	*440.00 FL
11	1		*FORK LEG	Dented	250.00 F	*250.00 FL
12	2		*FORK OIL SEAL & FORK OIL	Necessary	60.00 F	*60.00 FL
13	1		*BOTTOM STEERING STEM	Distorted	220.00 F	*220.00 FL
14	1		*SET STEERING COME & BEARING	Necessary	80.00 F	*80.00 FL
15	1		*RADIATOR ASSEMBLY	Bent / Punctured	650.00 F	*650.00 FL
16	1		*BOTTOM FAIRING	Dented	250.00 FS	*60.00 FS
17	1		*TANK	Dented	900.00 FS	*200.00 FS
18	1		*CLUTCH COVER	Dented	360.00 F	*360.00 FL
19	1		*FRONT FOOTREST (RIGHT)	Dented	60.00 F	*60.00 FL
20	1		*REAR FOOTREST (RIGHT)	Dented	75.00 F	*75.00 FL
21	1		*BRAKE PEDAL	Bent	80.00 F	*80.00 FL
22	1		*REAR BOX	Dented / Cut	180.00 F	*180.00 FL
23	1		*REAR CARRIER	Bent	150.00 F	*150.00 FL
24	1		*EXHAUST PIPE (YUSHIMURA)	Dented	1,800.00 F	*1,800.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	7,570.00	6,105.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	584.50
Total Parts (\$\$)	7,570.00	5,520.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	30.00	30.00
2	LABOUR	New	380.00	280.00
Gross Labour Cost (\$\$)			410.00	310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >