



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2008 TOYOTA CAMRY 2.4 (SDG3733P)

Date of Loss

8 December 2017

Time of Loss

21.00

Loss Description

SDG3733P (INSD) C/W SLB7233X (TP)

Comment

Workshop Details

Total Rebate Amount

14977

Nett Loss Amount

\$3,023.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

25/04/2018



Days of work completion *

120



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SDG3733P

Registration State

SINGAPORE

Mileage

122251

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2008

ASSESSMENT INFO...

2008

Purchase Date

dd/mm/yyyy



Registration Date *

15/04/2008



Age of Vehicle

9

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... TOYOTA

ASSESSMENT INFO...

CATEGORY Model

POLICY INFORMAT... CAMRY 2.4

ASSESSMENT INFO...

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... MR053BK4007025394

CATEGORY Date of Birth

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Age

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Driving Experience

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Driver License #

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... 2AZE095538

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI...
POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...
POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...
POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...
POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

27/12/2017



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

215/55R17

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Spare wheel

Rear Tyre Size

215/55R17

Front left side

YOKOHAMA6mm

Front right side

YOKOHAMA6mm

Rear left side

YOKOHAMA6mm

Rear right side

YOKOHAMA6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
<input type="checkbox"/>		1	1			FRONT BUMPER			Deformed	180				180	Reviewing
<input type="checkbox"/>		2	10			FRONT BUMPER CLIPS			Necessary	1.5				15	Reviewing
<input type="checkbox"/>		3	1			FRONT BUMPER SIDE RETAINER RH			Necessary	20				20	Reviewing
<input type="checkbox"/>		4	1			FRONT FENDER RH			Repair	0	0	0	0	0	Deny
<input type="checkbox"/>		5	10			FRONT FENDER INNER SHIELD CLIPS			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		6	1			FRONT FENDER EMBLEM "VVT-I"			Necessary	20				20	Reviewing
<input type="checkbox"/>		7	1			FRONT DOOR RH			Repair	0	0	0	0	0	Deny
<input type="checkbox"/>		8	1			FRONT DOOR PROTECTOR RH			Cut	40				40	Reviewing
<input type="checkbox"/>		9	1			FRONT DOOR PROTECTOR CHROME MOULDING RH			Cut	12				12	Reviewing

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
	10	1			WING MIRROR RH (NPA)			Cracked	0				0	Reviewing
	11	1			WING MIRROR SIGNAL LAMP RH			Cracked	25				25	Reviewing
	12	1			REAR DOOR RH			Repair	0	0	0	0	0	Deny
	13	1			FRONT DOOR PROTECTOR RH			Cut	35				35	Reviewing
	14	1			REAR DOOR PROTECTOR CHROME MOULDING RH			Cut	10				10	Reviewing
	15	1			REAR FENDER RH			Repair	0	0	0	0	0	Deny

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		REPAIR - FRONT SPORT RIM RH	100	0	0	Reviewing		
	2		LABOUR TO FACILITATE REPAIR	600	0	0	Reviewing		
	3		TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30	0	0	Reviewing		
	4		TO SPRAY PAINTING ON AFFECTED AREAS	1000	0	0	Reviewing		
	5		TO CONDUCT ALL WHEEL COMPUTERISED WHEEL ALIGNMENT	80	0	0	Reviewing		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 6 DAYS	Reviewing			
		2	WING MIRROR ASSY RH	Reviewing	250	CRACKED (SUPPLEMENTARY)	

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$2,417.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,810.00	\$1,810.00
Spare Parts	\$357.00	\$357.00
Miscellaneous	\$250.00	\$250.00

Submit for Review