

Ernst P.

CC 4/AXA170 24445, G1K3 Y1

Ins. for:

Xmle

DOI

ASSIGNMENT

24/12/17

Date / Time:

26/12/17

Registered in Merimen:

26/12/17

Pre-assign / CCU / FTE

SHO 9583J

CO464334



Insured Vehicle No.:

Claim No.:

Name of Insured:

Trans-Cab Services Pte

Policy No.:

P168520

Insured Tel No.:

HP:

Make / Model:

C-800CA

Excess Sec II :SS

5,000.00

D.O.A.:

19/12/17

Place of Accident:

GTH AVE 7 Lemon Ave

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

700 Ing Long

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

97212048

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

JJS 1672



INSRS:

WSP:

Tel:

Liability:

RMKS:

Krite.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

8/1/18
win

JJS 1672 - X

SHO 9583J - CC4/AXA170 17958/AXA170; DUA: 23/1/18

- CC4/AXA170 24445/KAB; DUA: 19/12/17

4/1/18 To get video from PH. & ask for V/L

1801208.

Send email / confirming version.

FILES REVIEWED - case of conflicting version.

Send email to OI to notify claim.

Receive video FROM OI

24/1/18

Email to AXA to reject via Merimen

24/1/18

AXA reject if claim via Merimen

10/1/18

Email to workshop reject claim.

OCT 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup):

Call OI:

1801208

After call ltr to OI: 2/2/2018

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

RECEIVED

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.: NIL

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost:

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2:

S\$

Name 2:

Payee 3:

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

reject

\$350.00

COPY SENT
4/10/18


XSL

REF: AXA

ASSIGNMENT

From: _____ Date: 27/12/17
Estimated Cost: _____
OD ☒ WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: JJS 1672
at Workshop via Kivile Enterprise
of Blk 3007 Ubi Rd 1 #01-408, 408701
Insured _____
Policy No _____
Claims No _____
Sum Insured _____ Excess _____
(Client's Record) _____
Make of Veh: _____

ARC - No please get video from PH



Remark: The veh had commenced its repair at the time of inspection.

Est. Repairs: 3 days Res: Yes or No
Lump Sum: 20 % 3 Val: Yes or No
CA / REV / REP. / 24 HRS up
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: JJS1672 Yr Reg: _____
Type: M/Car / M/Truck / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Yanahg LCBS cc 135
Colour: Red A/C: Insured / Std / NI / NA
O/Reading: 29754 T/Radio: Insured / Std / NI / NA
Eng No: _____
C/No: _____
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: ☒ In order / Jammed / Leaked / Burnt or
Brake: ☒ In order / Jammed / Leaked / Burnt or
Mod: ☒ Nil / S/Rim / STD A/Rim or
Tyre Size: F: 20/90-17
R: 80/90-17
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or MAXXIS
Front: _____ Rear: _____
R/Bal: 4 mm R/Bal: 4 mm
L/Bal: _____ mm L/Bal: _____ mm
D/O.A. _____ D.OI: 27-12-17
Survey held at: w/s 6pm
Des. of Damages: Fnt / Rear / O/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction
(L/Sum: \$1700.00 / Rcd: \$2,324.00 / SB /)

Date/Time File Pass to:	<input type="checkbox"/> Prel. Report	Days Of Repair:	Survey Fee:
Date/Time File Return to:	<input type="checkbox"/> Final Report	Resurvey No. of Trip:	Transporter:
Report Format:	Add Fee: <input type="checkbox"/> Site Insp \$	<input type="checkbox"/> I + R \$	Phone:
Lump Sum / I.B.I. \$	<input type="checkbox"/> Interview \$	<input type="checkbox"/> Photo:	Chief:
	<input type="checkbox"/> Tech Insp \$	<input type="checkbox"/> Other:	
	<input type="checkbox"/> Weekend \$		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/AXA17024445/Gka3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 27-12-2017	
			Code : AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 9583J	Veh. Inspected	JJS 1672
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	27/12/2017
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	19/12/2017	Inspection Date	27/12/2017
	Survey held at	KIVILE ENTERPRISE BLK 3007 #01-408 UBI ROAD 1 SINGAPORE 408701 (MOTORCYCLE ONLY)		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



吉维利企业 KIVILE ENTERPRISE

BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2553

EMAIL: KIVILEPC@GMAIL.COM WEBSITE: KIVILEPC.COM

ROC NO.: 53114844X GST REG NO.: M90370110N

VEHICLE NO: JJS1672 MODEL: YAMAHA LC135

HANDLE BAR	/ BT	110	/
BAR HOLDER	X { NN	75	X
HANDLE GRIP	X	38	X
HANDLE BALANCE	/ Cut	35	/
MIRROR	/ Cut	55	/
TOP FAIRING	X / SCR	135	/
FRONT FAIRING	/ CPA	135	/
CENTER FAIRING	X / CPA	135	/
SIDE FAIRING LH	/ CPA	195	/
SIDE FAIRING RH	/ Cut	195	/
FRONT MUDGUARD	/ Cut	85	/
FORK LOWER CLAMP	X NN	160	X
FORK SET	X Repair / BT	440	X
FRONT RIM	X NN	250	X
RADIATOR	/ Cut BT	280	/
RADIATOR HOLDER	/ BT	100	/
AIR INTAKE	/ m's	145	/
FRONT FOOTREST	X	45	X
RUBBER FOOTREST	X	38	X
REAR FOOTREST LH	X	45	X
REAR FOOTREST HOLDER LH	X	75	X
GEAR LEVER	X	65	X
CHAIN COVER	X	38	X
REAR BOX	/ Cut	135	/
EXHAUST PROTECTOR S	/ BT	75	/
EXHAUST PROTECTOR B	/ BT	95	/
IU UNIT	/ Cut	165	/
TRANSPORT		50	40
BODY ALIGHTMENT		280	X NN
LABOUR		350	150
		4024	

3 Days.

lumpsum repair

After repair photos.

Que Qiao - 82860282

27/12/17

2075
10% : 1867.5

SN : 120
labour : 190

2177.5

20% : 1700

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Zaini (LKK Auto)

From: Zaini (LKK Auto)
Sent: Thursday, 18 January 2018 3:00 PM
To: 'claims@transcab.com.sg'
Cc: Hsiao Tong (LKKAuto); 'carrisalee@ava-ins.com'; 'icewong@ava-ins.com'; 'ireneng@ava-ins.com'; 'foonghon@ava-ins.com'
Subject: YOUR REF : P1680520 (SHD 9583J)_ACCIDENT INVOLVING SHD 9583J & JJS 1672 ALONG SIXTH AVENUE TOWARDS LEMON AVENUE ON 19/12/2017

18 January 2018

Transcab Taxi
Singapore

Dear Sir/Madam,

OUR REF : CC4/AXA17024445/Gka3

YOUR REF : P1680520 (SHD 9583J)

ACCIDENT INVOLVING SHD 9583J & JJS 1672 ALONG SIXTH AVENUE TOWARDS LEMON AVENUE ON 19/12/2017

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from KIVILE ENTERPRISE acting on behalf of the owner of JJS 1672 against your motor insurance policy.

Based on the accident report, accident scenario, this is a conflicting version pending concrete evidence from both parties to determine the liable party.

We also wish to advise that there is an excess of **S\$5,000.00** attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim.

AXA shall keep you informed of the third party claim settlement and thereafter kindly let AXA have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

Notwithstanding the excess being applied and/or received by AXA for the above subject matter, AXA expressly reserves all their rights under the policy to refund the excess payment in the event that there arises any known policy breach and or exclusion material to coverage.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to cst@axa.com.sg / Zaini@lkkauto.com or deliver it by hand to our Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorized driver may have committed.

In the event of receiving and handling of any third party injury claim(s), we shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact our Claims Service Team at 1800-880 4888 at our operating hours 9:00am to 5:30pm (press 1 for GI and option 3 for claims) or cst@axa.com.sg / Zaini@lkkauto.com. Please quote our claim reference when you contact us that we can assist you more effectively.

Thank you.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | 3(408933)

View Received Message

This mail is associated with :

*JJS1672 (C0464334)
[SHD95833]TP
CHENG FARN KUAN
Dec 19 2017 12:00AM
[TRANS-CAB SERVICES PTE LTD]
Kivile Enterprise

[Reply](#)
[Reply All](#)
[Mark as Unread](#)
[Print Message](#)
[Delete Message](#)
[Forward](#)

From: AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 28/09/2018 17:59 PM.

To: LKK_HQ
CC: chewht@lkkauto.com; vivianlau@lkkauto.com
Subject: RE: Direct Settlement - Accident Involving SHD95833 (OI : AXA - C0464334) and JJS1672 (TP : LKK REF - CC4/AXA17024445/Gka3) on 19.12.2017

AXA Insurance Pte Ltd
4 Maxwell Rd, #04-01 AXA Tower
Singapore 119612
Customer Service 168812
1800 888 0000
1800 888 0000
www.axa.com.sg
GST Reg No: U990000120
Co. Reg No: 1999000120



PLEASE PROCEED TO REJECT TP

<-- Original Message -->

From: LKK_HQ
To: ernest.tay@axa.com.sg
CC: AXA_SG; chewht@lkkauto.com; vivianlau@lkkauto.com
Sent On: 12/07/2018 02:57 PM
Subject: RE: Direct Settlement - Accident Involving SHD95833 (OI : AXA - C0464334) and JJS1672 (TP : LKK REF - CC4/AXA17024445/Gka3) on 19.12.2017

Dear Ernest

Insured's video sent via Accellion.

Based on QID video, QID making a right turn, TP overtake from the right

As such, we intend to reject TP claim

Kindly advice on your view/opinion/instruction for this claim

Thank you,

Vivian Lau

<-- Original Message -->

From: LKK_HQ
To: richard.angbs@axa.com.sg
CC: AXA_SG
Sent On: 03/07/2018 02:41 PM
Subject: RE: Direct Settlement - Accident Involving SHD95833 (OI : AXA - C0464334) and JJS1672 (TP : LKK REF - CC4/AXA17024445/Gka3) on 19.12.2017

Dear Richard,

Insured's video sent via Accellion.

Based on QID video, QID making a right turn, TP overtake from the right

As such, we intend to reject TP claim

Kindly advice on your view/opinion/instruction for this claim

Thank you,

Vivian Lau

<-- Original Message -->

From: LKK_HQ

To: ernest.tay@axa.com.sg
Sent On: 06/06/2018 05:46 PM
Subject: RE: Direct Settlement - Accident Involving SHD95833 (OI : AXA - C0464334) and JJS1672 (TP : LKK REF - CC4/AXA17024445/Gka3) on 19.12.2017

Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Wednesday, 10 October, 2018 5:43 PM
To: 'Kivile Enterprise'
Cc: Thin Thin (LKKAuto)
Subject: RE: Jjs1672(cc4/axa17024445/gka3)
Attachments: SHD 9583J.mp4; Sketch Plan .pdf

WITHOUT PREJUDICE

Your Ref: JJS 1672
Our Ref: CC4/AXA17024445/Gwa3

Dear Sir/Madam,

ACCIDENT ON 19/12/2017 INVOLVING JJS 1672 & SHD 9583J

We refer to the above matter

Our insured driver has reiterated that the accident was caused due to the entire negligence of your client. Based on our Insured's video, your Insured making a right turn, your client overtake from the right.

We attached herewith our insured's accident report and CCTV video Footage for your perusal.

Under such circumstances, we have our principal's instruction to deny liability of your client's claim

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kivile Enterprise [mailto:kivilepc@gmail.com]
Sent: Tuesday, 24 April, 2018 2:22 PM
To: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>
Subject: Fwd: Jjs1672(cc4/axa17024445/gka3)

...CLAIM SUBFOLDER...(Pending for Survey Report)






































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Dec 2017		26 Dec 2017 16:47 Edit Adj Rpt	S\$1,700.00 Edit Estimates	S\$1,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Main Claimant:	CHENG FARN KUAN, ID: G8181512M								
Vehicle Reg. No.:	JJS1672	Date of Loss:	19/12/2017 00:00 - :59 [139 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / C0464334	Policy/Cover Note No.:	P1680520 (Third Party Only)						
Vehicle Reg. No. (Insured):	SHD95833	Policy No. (Claimant):							
		Excess:	S\$5,000.00						
Repairer:	Kivile Enterprise (HQ) BLK 3007 UBI RD 1 #01-408, 408701 Ubi - Tel: 67488645 , 67479547								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Tan Kwee May]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 05/01/2018]								
Driver/Custodian (Insured):	TED ING LONG (60 / Male), NRIC: S1247909C, Tel: +6597212048								
Adj Asg. Remarks:	ARC - No Please get video from PH								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AXA_SG (28/09/2018): RE: Direct Settlement - Accident Involving SHD95833 (OI : AXA - C0464334) and JJ... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*JJS1672 (C0464334)
 [SHD9583J]
 TP
 CHENG FARN KUAN
 Dec 19 2017 12:00AM
 [TRANS-CAB SERVICES PTE LTD]
 Kivile Enterprise

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Assessment Reports															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	12/04/18 11:13		Adjuster Immediate Advice												1		Load HTM			
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	10/10/18 17:33		General View												1		Load JPG			
2	10/10/18 17:33		General View												1		Load JPG			
3	10/10/18 17:33		General View												1		Load JPG			
4	10/10/18 17:33		General View												1		Load JPG			
5	10/10/18 17:33		General View												1		Load JPG			
6	10/10/18 17:33		General View												1		Load JPG			
7	10/10/18 17:33		General View												1		Load JPG			
8	10/10/18 17:33		General View												1		Load JPG			
9	10/10/18 17:33		General View												1		Load JPG			
10	10/10/18 17:33		General View												1		Load JPG			
11	10/10/18 17:33		General View												1		Load JPG			
12	10/10/18 17:33		General View												1		Load JPG			
13	10/10/18 17:33		General View												1		Load JPG			
14	10/10/18 17:33		General View												1		Load JPG			
15	10/10/18 17:33		General View												1		Load JPG			
16	10/10/18 17:33		General View												1		Load JPG			
17	10/10/18 17:33		General View												1		Load JPG			
18	10/10/18 17:33		General View												1		Load JPG			
19	10/10/18 17:33		General View												1		Load JPG			
20	10/10/18 17:33		General View												1		Load JPG			
21	10/10/18 17:33		General View												1		Load JPG			
22	10/10/18 17:33		General View												1		Load JPG			
23	10/10/18 17:33		General View												1		Load JPG			
24	10/10/18 17:33		General View												1		Load JPG			
25	10/10/18 17:33		General View												1		Load JPG			
26	10/10/18 17:33		General View												1		Load JPG			
27	10/10/18 17:33		General View												1		Load JPG			
28	10/10/18 17:33		General View												1		Load JPG			
29	10/10/18 17:33		General View												1		Load JPG			
30	10/10/18 17:33		General View												1		Load JPG			
31	10/10/18 17:33		General View												1		Load JPG			
32	10/10/18 17:33		General View												1		Load JPG			
33	10/10/18 17:33		General View												1		Load JPG			
34	10/10/18 17:33		General View												1		Load JPG			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
36	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
38	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
39	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
40	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
41	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
42	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
43	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
44	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
45	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
46	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
47	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
48	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
49	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
50	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
51	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
52	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
53	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
54	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
55	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
56	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
57	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
58	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
59	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
60	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
61	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
62	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
63	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
64	10/10/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	26/12/17 09:12	EMAIL_ABS	 Load PDF	
2	26/12/17 09:12	LAND TRANSPORT & AUTHORITY_ABS	 Load PDF	
3	26/12/17 09:12	GIA REPORT OF SHD9583J (INSD)_ABS	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/01/18 14:26	MALAYSIA LOG CARD	 Load PDF	
2	08/01/18 09:26	TP ESTIMATE - MARKED	 Load PDF	
3	08/01/18 18:57	TP CI	 Load PDF	
4	10/10/18 17:45	Email to wkshop reject claim 10.10.18	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17024445/GWA3Q2

Date: 18/10/2018

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant Vehicle No : JJS1672

Insured Vehicle No :

SHD9583J

Date of Loss: 19/12/2017

Nature of Claim:

TP

Claim No: C0464334

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JJS1672

Make & Model: YAMAHA 135LC, 135cc ES

Reg. Date: 04/05/2006 (Man. Year: 2006)

Colour: Red

Engine Capacity: 135 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: G349EE005205

Chassis No: PMYKG016060005205

Odometer: 29754 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90-17

Rear Tyre Size: 80/90-17

Front Left Side: Maxxis 4 mm

Rear Left Side: Maxxis 4 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,344.00	1,987.50	1,356.50	40.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	680.00	190.00	490.00	72.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,024.00	2,177.50	1,846.50	45.89
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	4,024.00	1,700.00	2,324.00	57.75
+ GST 7.00/7.00% (S\$)	281.68	119.00	162.68	57.75
Nett Amount (S\$)	4,305.68	1,819.00	2,486.68	57.75
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 26/12/2017

Date Inspected: 27/12/2017 Inspected At:

Kivile Enterprise (HQ)
BLK 3007 UBI RD 1 #01-408
Singapore 408701

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 Oct 2018)	
Parts:	N/A	YAMAHA 135LC 135cc ES (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JJS1672)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR (CONSISTENT)	Bent	110.00 F	*110.00 FL
2	1		*BAR HOLDER (CONSISTENT)	Not Necessary	75.00 F	*- FL
3	1		*HANDLE GRIP (CONSISTENT)	Not Necessary	38.00 F	*- FL
4	1		*HANDLE BALANCE (CONSISTENT)	Cut	35.00 F	*35.00 FL
5	1		*MIRROR (CONSISTENT)	Cut	55.00 F	*55.00 FL
6	1		*TOP FAIRING (CONSISTENT)	Scratched	135.00 F	*135.00 FL
7	1		*FRONT FAIRING (CONSISTENT)	Cracked	135.00 F	*135.00 FL
8	1		*CENTER FAIRING (CONSISTENT)	Cracked	135.00 F	*135.00 FL
9	1		*SIDE FAIRING LH (CONSISTENT)	Cracked	195.00 F	*195.00 FL
10	1		*SIDE FAIRING RH (CONSISTENT)	Cut	195.00 F	*195.00 FL
11	1		*FRONT MUDGUARD (CONSISTENT)	Cut	85.00 F	*85.00 FL
12	1		*FORK LOWER CLAMP (CONSISTENT)	Not Necessary	160.00 F	*- FL
13	1		*SET FORK (CONSISTENT) (LOCAL REPAIR)	Bent	440.00 FS	*120.00 FS
14	1		*FRONT RIM (CONSISTENT)	Not Necessary	250.00 F	*- FL
15	1		*RADIATOR (CONSISTENT)	Bent	280.00 F	*280.00 FL
16	1		*RADIATOR HOLDER (CONSISTENT)	Bent	100.00 F	*100.00 FL
17	1		*AIR INTAKE (CONSISTENT)	Missing	145.00 F	*145.00 FL
18	1		*FRONT FOOTREST (CONSISTENT)	Not Necessary	45.00 F	*- FL
19	1		*RUBBER FOOTREST (CONSISTENT)	Not Necessary	38.00 F	*- FL
20	1		*REAR FOOTREST LH (CONSISTENT)	Not Necessary	45.00 F	*- FL
21	1		*REAR FOOTREST HOLDER LH (CONSISTENT)	Not Necessary	75.00 F	*- FL
22	1		*GEAR LEVER (CONSISTENT)	Not Necessary	65.00 F	*- FL
23	1		*CHAIN COVER (CONSISTENT)	Not Necessary	38.00 F	*- FL
24	1		*REAR BOX (CONSISTENT)	Cut	135.00 F	*135.00 FL
25	1		*EXHAUST PROTECTOR S (CONSISTENT)	Bent	75.00 F	*75.00 FL
26	1		*EXHAUST PROTECTOR B (CONSISTENT)	Bent	95.00 F	*95.00 FL
27	1		*IU UNIT (CONSISTENT)	Scratched	165.00 F	*165.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,344.00	2,195.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	207.50
Total Parts (\$\$)	3,344.00	1,987.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT	New	50.00	40.00
2	BODY ALIGNMENT	New	280.00	0.00
3	LABOUR	New	350.00	150.00
Gross Labour Cost (\$\$)			680.00	190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >